NATIONAL Assessment Cent		1.10	14/19/10000		
Date In: 17/17/19 - 10129	Jeb description	on	Date &Time Complete	ed Do	ne by
Rei No: Na A 1618 022441/24	SAS e-filin	g			
Veh No: SUSGRIY.	E-mail (with	in Shrs, AIC 2hrs)			Military and a
D.O.A : 10/~1/8 - 07:00	i-Motor Cl	aim Form			
OD / TP / Reporting Only	i-Motor W.	O (Within: OD 2hr:	, TP 4brs)		
OB 717 Reporting Only	i-Photo Up	loaded		-	Y
TP Insurer:	Assessment/	Survey Report			
Tr insurer.	Ass't Report	by Fax / Hand t	Owner/Wksp		
Preferred Wksp / INC Assign Wksp / QW: (Tel:	Fax:	
TP Particulars: Veh No: Jun	2524	. INC ()/Non-INC()		-
Owner / Driver: (Tel:)	
Policy No: () P	eriod: ()	Cover Type: ()	
Confirmed by : (100-50	Date:	Time:)	
Insured/Driver Liability: (%)	[Note-Est. Status	(WO): N: 0-20	%; P: 21-79%. P: 30	0-100%]	-
Year of Registration: ()	Warranty: YES ()/NO()		
Excess: (\$) Loading: \$1,	000()/\$2,00	0()			
General Remarks:		15 15 XXXXXX		<u>्राध्यक्ष प्राप्त</u>	
() Walk-In Customer: Customer's info	ormation strictly C	onfidential & Stri	ctly NO refer of repaire	er.	
() Total Loss Case : to e-mail Insur	er URGENTLY.	8			
Drive-In ()/ Towed-In (); Invoic	e: YES () /	NO (); To	wing Co: ()
Remarks: (INC hotline: 6788 6616)	operation and the second		· · · · · · · · · · · · · · · · · · ·	SETTO ANSWER	N. J. S.
	According to the		Date&Time Completed	Don	e by
				1	-
	Courtesy Car ()			
2) QC Check / Post Repair Inspection	()	*		
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$:	()	*		
2) QC Check / Post Repair Inspection	()	*		
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$: Injury:	()			
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$: Injury:	()			
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$: Injury:	()			
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$: Injury:	()			
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$: Injury:	()			
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$: Injury:	()			
Q) QC Check / Post Repair Inspection B) Upload Resurvey Photo [Repair Cost > \$: Injury: ate/Time Actions	())) Inveige Prair	pration Checklise	Ant (5)	(Amu (
QC Check / Post Repair Inspection B) Upload Resurvey Photo [Repair Cost > \$: Injury: Actions Actions	(aration Checklist	Ant (S)	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$: Injury: Pate/Time Actions Actions umant's Particulars:-	(1) AR : Accident R 2) DA : Damage A	eporting (\$30); seessment (\$100); INC	fit Bill (\$80)	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$: Injury: Pate/Time Actions Actions umant's Particulars:-	(1) AR : Accident R 2) DA : Darwage A 3) TF : Towing Fee 4) FT : Follow-Thr	eporting (\$30); ssessment (\$100); INC (fu Bill	
QC Check / Post Repair Inspection B) Upload Resurvey Photo [Repair Cost > \$: Injury: Pate/Time Actions umant's Particulars:- ver/Owner:	(1) AR: Accident R 2) DA: Damage A 3) TF: Towing Fee 4) FT: Follow-Thr 5) FT: Follow-Thr	eporting (\$30); ssessment (\$100); INC (Sough Survey ough Survey (Resurvey)	(\$80) (\$80) (\$0)\$45 \$120 \$30	
QC Check / Post Repair Inspection B) Upload Resurvey Photo [Repair Cost > \$: Injury : Actions Actions umant's Particulars:- ver/Owner:	(1) AR: Accident R 2) DA: Damage A: 3) TF: Towing Fee 4) FT: Follow-Thr 5) i*T: Follow-Thr For claiming aga 6) TR: Re-inspection	eporting (\$30); ssessment (\$100); INC (sough Survey ough Survey (Resurvey) inst INC Only (wef 10 Jan 20) on	(\$80) \$40/\$45 \$120 \$30 \$575	
QC Check / Post Repair Inspection B) Upload Resurvey Photo [Repair Cost > \$: Injury: Pate/Time Actions Umant's Particulars:- ver/Owner:	(1) AR: Accident R 2) DA: Damage A 3) TF: Towing Fee 4) FT: Follow-Thr 5) i*T: Follow-Thr For claiming aga	eporting (\$30); ssessment (\$100); INC (Sough Survey ough Survey (Resurvey) inst INC Only (wef 10 Jan 20) on iMRT Survey	(\$80) (40/\$45 \$120 \$30 (\$5)	
QC Check / Post Repair Inspection B) Upload Resurvey Photo [Repair Cost > \$: Injury : Pate/Time Actions umant's Particulars :- ver/Owner: naged Portion:	(1) AR: Accident R 2) DA: Damage A 3) TF: Towing Fee 4) FT: Follow-Thr 5) FT: Follow-Thr For claiming aga 6) TR: Re-inspects 7) N1: Idao DA + S 3) NTUC Additions OD*	eporting (\$30); seessment (\$100); INC (Sough Survey pugh Survey (Resurvey) inst INC Only (wef 10 Jan 20) on iMRT Survey al Services:-	(\$80) 40/\$45 \$120 \$30 05) \$75 \$160	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$: Injury : Oute/Time Actions umant's Particulars :- ver/Owner: naged Portion:	(1) AR: Accident R 2) DA: Damage A 3) TF: Towing Fee 4) FT: Follow-Thr 5) FT: Follow-Thr For claiming aga 6) TR: Re-inspects 7) N1: Idao DA + S 3) NTUC Additions OD*	eporting (\$30); seessment (\$100); INC (Sough Survey pugh Survey (Resurvey) inst INC Only (wef 10 Jan 20) on iMRT Survey al Services:-	(\$80) \$40/\$45 \$120 \$30 \$575	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$: Injury : Oute/Time Actions umant's Particulars :- ver/Owner: naged Portion: Checked by (Engr-In-Charge):	(1) AR: Accident R 2) DA: Damage A 3) TF: Towing Fee 4) FT: Follow-Thr 5) FT: Follow-Thr For claiming aga 6) TR: Re-inspecti 7) N1: Idao DA + S 8) NTUC Additions OD* *N5: Courtesy C *N6: Repair Co- *N7: Fost Repair	eporting (\$30); seessment (\$100); INC (Sough Survey ough Survey (Resurvey) inst INC Only (wef 10 Jan 20) on iMRT Survey al Services:- or / Tpt Allowance ordination Inspection	(\$80) \$40/\$45 \$120 \$30 \$55 \$160 \$55 \$10 \$25	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$: Injury : Onte/Time Actions umant's Particulars :- ver/Owner: ntact No: maged Portion: Checked by (Engr-In-Charge):	(1) AR: Accident R 2) DA: Damage A 3) TF: Towing Fee 4) FT: Follow-Thr 5) FT: Follow-Thr For claiming aga 6) TR: Re-inspecti 7) N1: Idao DA + 3 8) NTUC Additions OD* *N5: Courtesy C *N6: Repair Co- *N7: Fost Repair *N8: DV / Collect TP (N11): TP (N	eporting (\$30); seessment (\$100); INC (sough Survey ough Survey (Resurvey) inst INC Only (wef 10 Jan 20) on iMRT Survey al Services:- ser / Tpt Allowance ordination Inspection at Excess Coordination for INC) against INC	(\$80) \$40/\$45 \$120 \$30 \$55 \$160 \$55 \$510 \$25 \$55 \$20	Am (3
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$: Injury: Onte/Time Actions	(1) AR: Accident R 2) DA: Damage A 3) TF: Towing Fee 4) FT: Follow-Thr 5) FT: Follow-Thr For claiming acc 6) TR: Re-inspecti 7) N1: Idao DA + 3 8) NTUC Additions OD* *N5: Courtesy C *N6: Repair Co- *N7: Fost Repair *N8: DV / Collect	eporting (\$30); seessment (\$100); INC (sough Survey ough Survey (Resurvey) inst INC Only (wef 10 Jan 20) on iMRT Survey al Services:- ser / Tpt Allowance ordination Inspection at Excess Coordination for INC) against INC	(\$80) \$40/\$45 \$120 \$30 \$55 \$160 \$55 \$10 \$25 \$55 \$20 \$30	

1 - per 41 1 32

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the ledgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCIDE	NT STA	TEMENT
--------	--------	--------

Date Of Report 13/12/2018 10:29 Date Of Accident 10/12/2018 02:00

Exact Location Of Accident JB TWDS WOODLANDS CHECKPOINT Country/State of Loss MALAYSIA/JOHOR DARUL TAKZIM

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLS6781Y

Insured/Policyholder

Name Of Registered Owner **GUO XIAOLAN** NRIC No S7862917G Email Address NOEMAIL

Mobile Phone No. (LOCAL) +65-96272617 Alternative Phone No OFFICE-96272617

Vehicle Particulars

Manufacturer TOYOTA

Model C-HR HYBRID 1.8 ICON CVT

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken REPORTING ONLY Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 1800113571

Cover Note Number

Driver

Name of Driver LANNY XIAOLAN GUO

NRIC No S7862917G Date Of Birth 07/05/1978 Occupation INDOOR Date Of Driving Pass 23/06/2011

Driving Experience 7 YEARS AND 5 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-96272617

Fax Number

Contact Number OFFICE-96272617

EMail Address NOEMAIL

BLK 278B COMPASSVALE BOW Address

#12-561

Postcode 542278

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO Number of vehicles involved in the accident 2 Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged? YES I have been approached by unknown person(s) NO soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Passenger 1

GENDER: MALE

NAME:

Passenger 2

NAME:

GENDER: : MALE

100

Passenger 3

NAME: : -

GENDER: : MALE

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Police Station Name HOUGANG NEIGHBOURHOOD POLICE CENTRE

YES

ROAD: 60 HOUGANG AVE 9, POSTCODE: 538775, COUNTRY: Police Station Address

SINGAPORE

Police Station Contact TEL NO: 1800-4890999 - FAX NO: 63128989

Was notice of intended Prosecution given?

If Yes, against whom?

NO

Circumstances of Accident

REFER TO POLICE REPORT - F/20181212/2103.

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? YES Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLV757S

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Passenger 1

PRIVATE CAR

2

NAME:

GENDER: :

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature


(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



A: SLSG7814. B: SLV7375.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to	plice report = F/20181.	เกามางา	
		389	
		/	
		/	
	/		

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name:

Name: NRIC/FIN No.:


ACCIDENT STATEMENT

ACCIDENT DATE: 10/12/18) (DD/MM/YYYY), TIME: (0 2 : 00) (HH:MM
LOCATION: JB truds woodland Cheac print
1. DETAILS OF VEHICLE a) VEHICLE NUMBER: 15678 14. b) INSURANCE COMPANY: 15 c) POLICY NUMBER: 1800 13571 a) POLICY TYPE: (COMPREHENSIVE / THIRD PARTY / THIRD PARTY FIRE & THEFT)
f)TYPE:(SALOON / COUPE / MPV /VAN / LORRY / MOTORCYCLE / OTHERS) g) VEHICLE CATEGORY: (PRIVATE / COMMERCIAL / MOTORCYCLE) h) PURPOSE OF USING AT ACCIDENT TIME: Provide MIRE i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (VES MO)
IF NO, PLEASE STATE (THIRD PARTY CLAIM / REPORTING ONLY) 2. INSURED / POLICY HOLDER A) NAME: GO XIGOLO (MALE / FEMALE) b) NRIC/FIN/PASSPORT: S78679126 CONTACT: 9627267 C) ADDRESS: BIK 2786 CONTACT: 9627267
* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER DRIVER ON THE PRISON OF PRI
CIADDRESS: CONTACT:CONTACT:
*d)DATE OF BIRTH: () 5 / (975 1(DD/MM/YYYY) e)OCCUPATION: (INDOOR / OUTDOOR) f) YEARS OF DRIVING EXPRERIENCE: 23 6) 201
IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED. O NO.
b)ROAD SURFACE: DRY / WET / OTHERS
7. a) REPORTED TO POLICE (YES / NO) IF YES, PLEASE STATE WHICH POLICE STATION:
8. THIRD PARTY VEHICLE HIS OF PASSENGER OF VEHICLE NUMBER: SLV 7535. Including driver DI DRIVER'S NAME: MODEL:
() NRIC/FIN/PASSPORT:CONTACT:
No of passagar d) VEHICLE NUMBER: MODEL:
Including driver f) DRIVER'S NAME:

email =

fax =

VIDEO =



F/20181212/2193

81212/2103

Report No. F/20181212/2103

POLICE REPORT (NP299)

Police Station Of Origin Hougang N.P.C 60 Hougang Avenue 9 SINGAPORE 538775 Tel No: 1800-4890999

Date/Time Report Made 12/12/2018 21:49	Vide Report No.		Station Diary No.	
Name Of Informant LANNY XIAOLAN GUO	Address APT BLK 278B COMPASSVALE BOW #12-561 SINGAPORE 542278			
ID Type / ID No. NRIC NO / S7862917G	Contact No. Home/Office		Mobile 96272617	
Nationality SINGAPORE CITIZEN	Email Address			
Occupation	Sex	Age	Date of Birth	Race
MANAGER	Female	40	07/05/1978	Chinese
nstitution/School Name	Language English			
ate/Time Of Incident 0/12/2018 02:00	Location Of Incident At the immigrations checkpoint at Malaysia MALAYSIA			

Brief details.

On 10/12/2018 at about 0200hrs, I was at the Malaysia customs going back to Singapore. I was waiting for my passport to get checked at the Malaysian customs. I was in my car (white Toyota, SLS6781Y) with my husband and 2 children and we were waiting in line for our turn. There are 3 lanes and my car was in the middle lane.

As I was waiting, a car (black Subaru, SLV757S) in the right lane beside me suddenly hit my car on the

Signature Of Officer Recording The Report:

F / Insp JUSTINA PANG BI XUE

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
F / Hougang N.P.C /
SI WEE KIM HUAT, LEONARD

Signature Of Informant:

Date/Time:
12/12/2018 21:49

Classification Of Case:

Authentication Stamp

SN 085

Signature:

Singapore Police Force

Contact No.: 64890999



POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20181212/2103

driver's side. My husband got off the car to talk to the driver and the driver did not want to get out of his car, however, he did lower his window and started shouting at my husband. After a while, my husband came back and the car overtook us and went in front of us.

No one was injured and my car has an approximately 30cm scratch on the driver's side of the car.

I am lodging a report for record purposes.

Signature Of Officer Recording The Report:

F / Insp JUSTINA PANG BI XUE

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

F / Hougang N.P.C / SI WEE KIM HUAT, LEONARD

Contact No.: 64890999

Signature Of Informant:

Date/Time:

12/12/2018 21:49

Classification Of Case:

Authentication Stamp

Signature:_

SN 085

Singapore Police Force

REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$7862917G





Name

LANNY XIAOLAN GUO

郭晓兰

CHINESE


Date of birth 07-05-1978

Country of birth

5/2029F0









CERTIFICATE OF INSURANCE

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder

: GUO XIAOLAN

Period of Insurance

: 29 Sep 2018 To 28 Sep 2019

Engine No.

: 2ZRV444091

Chassis No.

: NMTKZ3BX50R021223

Vehicle No.

: SLS6781Y

Policy No.

: 1800113571

Endorsement No.

Issued Date

: 20 Sep 2018

ABOUT THE COVER

Make/Model

TOYOTA C-HR 1.8

Engine Capacity/Tonnage 1,797 00 CC

Sum Insured : Market Value

First Year of Registration : 2017

Driver Restriction

NA

Off Peak Car : No

Insuring with COE/PARF

Yes

Person or Classes of Persons Entitled to Drive* :

in The Policyholdse bi Any other berson who is driving an the Policyholder's order or with his/liver permission. This Policy will indemnify the Policyholder or any authorised driver only if hershe meets the specified age consisten

You have to pay the add formal ours of \$3,000 as Tribung and of Inexperienced Diliver Excess." ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 ans/or has less than 2

Age Condition

All Age Condition

Limitation as to use*

Use only for social, domestic and previous purposes and for the Policyholder's business. This Policy does not cover use for him or reward, driving test mixing test mixing pace-making, reliability historic social domestic and previous after their samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc 1600cc Optional

Limitations rendered righerative by Section 6 of the Motor Vehicles (Thiro-Party Risks and Compensation) Act (Cap. 189) and Section 65 of the Road Transport Act, 1987 (Malaysia), are not to be intruded under these histories

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$8

Section 2

Property Daniage - \$0

Windscreen : \$100

Named Driver and Excess where approaches

SEICHARDIAN

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Recording Centres AGS Authorised Reparters (For claims related repairs).

Any according pairs to the Vehicle must be carried out by one of our Authorised Reparters. Within the first 3 years of the first registration of the Vehicle in Singapore. You have the option of having the according to the Sale Applied Septiment with some AGS Authorised Reparters. For other Applied Reparters Reparted Reparters AGS Authorised Reparters prouve contact our 24-have accident emergency holline at +65 6336 6200. Alternatively. You may rater to AGS website www.aig.com.aig. or AGS Mobile App. Simply search and download "AGS SO" from Turies or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

Fixe hereby certify that the policy to which this Certificate of Insurance recates is estued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Roses, 1959 (Malaysia)

0504641000

ASSURE INSURANCE AGENCY

29 KELANTAN ROAD #01-111 KELANTAN COURT

SINGAPORE 200029

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE