

22/03/2002

ASS. REC. BY:

REF: CS3/AIG/18022448/JCD31 Special Instruction:

Surveyor: Hwee Jie ASSIGNMENT (Office)From (Person): Chin Lee Ying of AIG Date/Time: 13/12/18 @ 11:30am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GW 7289J Insured: SLT 7942Mat Workshop m/s: SAT Motor Tel: 9859 9677of 24 Dec 2018Policy No: 0999994354 Claim No: 2740154851SG

Sum Insured: Excess:

Make of Veh: D.O.A. 8/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS up14/12/18 @ 11:30am - 12pm

H.O.D. Endorsement:

Date/Time: 12:10pm 13/12/18 Person Contacted: Jessie Vehicle IN OUT

Date/Time	Action/Instruction (x) Estimate
	<u>GW 7289J - NA/INC 17008002/h4</u> <u>DIA: 24/9/2017</u>
	<u>SLT 7942M - NA/INC 17008002/h4</u> <u>DIA: 24/9/2017</u>

PRS
Hwee Jie

REF: AIG

ASSIGNMENT

From: Date: 14/12/18

Estimated Cost:

OD ☒ / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GW 7289J
SAT Motor
2A Defu bene 12

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

11:30am-12pm

Jessie @ 98599677

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GW 7289J Yr Regn: 13 Sep 2017

Type: M.Gar / M.Cycle / Bus / Van / ☒ / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyna

C.C. 2982

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

91804

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFAT35Y00K208712

Gen. Cond: ☒ / Fair / Poor / Burnt

Steering: ☒ / Jammed / Leaked / Burnt or

Brake: ☒ / Jammed / Leaked / Burnt or

Mod: Nil / ☒ / STD A/Rim or

Tyre Size:

F: 155 R12C

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

8/12/18

D.O.I.

14/12/18

Survey held at

Sat motor

Des. of Damages: Frt / ☒ / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?



: Prefl. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: -

Survey Fee:

Transportation

\$ + RS. \$

Photos

Others

TOTAL

Report Format:

DAR

Lump Sum / L.B.I. (\$)

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 13/12/2018 11:38:10 AM
Attachments:  PRI-GW7289J.PDF

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

K. KRISHNA & PARTNERS

Advocates & Solicitors

Commissioner for Oaths/Notary Public

(UEN No. 53131210X)

GST Registration No. M90371530C

101 Cecil Street #24-03/04 Tong Eng Building, Singapore 069533

Tel : 6323 3038

Fax : 6323 2120 (not for service of Court documents)

E-mail : kkrishna@singnet.com.sg

K. Krishnamoorthi
LLB (Hons) (London)
Barrister-at-Law (Gray's Inn)
B.Sc (Hons) (Est. Man) (S'pore)

S. Manohar
LLB (Hons) (S'pore)

Vengadesh s/o Kumaravelu
LLB (Hons)

Our Ref : SM.PRI-SAT- GW7289J (d)

11th December 2018

IMMEDIATE ATTENTION

AIG ASIA PACIFIC INSURANCE PTE LTD

PRE-REPAIR INSPECTION

Attention: Motor Claims Department

Email : MohdFitri.Hassim@aig.com
Imran.ishak@aig.com

Dear Sirs

**PRE-REPAIR INSPECTION OF VEHICLE GW 7289J
ACCIDENT ON 8.12.2018 INVOLVING GW 7289J AND SLT 7942M ALONG MERRYIN
ROAD**

We act for M/s Kian Wah Enterprise, the owner of motor vehicle no. GW 7289J which was involved in the above captioned accident

We are instructed that the accident was caused by the negligence of the rider of motor vehicle no. **SLT 7942M**. Our search shows that you are the insurers of motor vehicle no. **SLT 7942M**.

We are requested to inform you that our clients' vehicle is available for pre-repair inspection at the following address :-

M/S SAT MOTORS
24 Defu Lane 12
Singapore 539131

K. KRISHNA & PARTNERS
Advocates & Solicitors

11th December 2018

AIG ASIA PACIFIC INSURANCE PTE LTD

Please note that our clients wish to appoint their own surveyor to carry out the pre-repair inspection.

Please contact **Ms Jessie Ong of M/s SAT Motors** at her mobile no. **98599677** within **forty-eight (48) hours** from receipt of this fax to arrange for the inspection.

Yours faithfully



cc. workshop - (by fax no. 67491141)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/12/2018 13:55
Date Of Accident	08/12/2018 12:40
Exact Location Of Accident	MERRY ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GW7289J
Insured/Policyholder	
Name Of Registered Owner	KIAN WAH ENTERPRISE
Co Reg No	51472700D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97218196

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ18-006092
Cover Note Number	

Driver

Name of Driver	CHUA LEONG SENG
NRIC No	S1632872C
Date Of Birth	26/04/1964
Occupation	INDOOR
Date Of Driving Pass	21/06/1982
Driving Experience	36 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97218196
Fax Number	
Contact Number	
Email Address	JASONLSCHUA@GMAIL.COM

DETAILS OF INJURED PERSON 1

Name	CHUA LEONG SENG
Approximate Age	
Injuries Sustain	SLIGHT
Injured person in which vehicle?	GW7289J
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	2700D
Vehicle Details	
Vehicle No.:	GW7289J
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	1KD2737996
Chassis No.:	JTFAT35Y00K208712
Maximum Power Output:	-
Open Market Value:	\$26,436.00
Original Registration Date:	13 Sep 2017
First Registration Date:	13 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$1,322.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Sep 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$33,754.00
COE Rebate Amount:	\$29,520.00
Total Rebate Amount:	\$29,520.00

The information contained herein is correct as at 14 Dec 2018

OK

VAN / LORRY (Rear)

Vehicle No: GW 7289J

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
2044	993628	Rear Number Plate Bracket			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper			
1142	993108	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
2045	993081	Rear Bumper Step Panel			
2046	993079	Rear Bumper Step Garnish			
2047	993186	Rear Crash Bar			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			2
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1289	995156	Rear LH Door			
1350	993201	Rear RH Door			
2048	991328	Rear Door Emblem			
2049	993274	Rear Door Outer Handle			
2050	993228	Rear Door Garnish			
2051	993294	Rear Door Rubber			
1291	995194	Rear LH Door Hinge			
1352	995307	Rear RH Door Hinge			
1301	993261	Rear LH Door Lock			
1362	993261	Rear RH Door Lock			
2052	993232	Rear Door Glass			
2053	993955	Rear Door Glass Sealant			
1248	994729	Third Brake Light			
1181	994543	Tailgate		DD R	
2054	993700	Rear Rubber Stopper			
2055	993701	Rear Rubber Stopper Bracket		DB /	1
1182	991328	Tailgate Emblem		NEC	
1183	994643	Tailgate Outer Handle			
1185	994545	Tailgate Garnish			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
2056	994597	Tailgate Extension Mirror			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge		DIS	
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			
2057	993992	Rear Wiper Arm			
2058	993995	Rear Wiper Blade			
2059	993997	Rear Wiper Motor			
2060	993484	Rear Floor Panel			
1204	995065	Spare Tyre			
2061	993785	Spare Tyre Bracket			
1212	993364	Rear Exhaust Pipe			
1214	993361	Rear Exhaust Mounting			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			

[illegible]

No of Items:

Assessor:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Dec 2018 Edit Reg		13 Dec 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	BKW RENT A CAR PTE LTD , Co. Reg. No.: -		
Main Claimant:	-		
Vehicle Reg. No.:	GW7289J	Date of Loss:	08/12/2018 12:00 - :59 [14 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 2740154854SG	Policy/Cover Note No.:	0999994354 (Comprehensive)
Vehicle Reg. No. (Insured):	SLT7942M	Policy No. (Claimant):	
		Excess:	
Repairer:	Sat Motors (HQ) 24 Defu Lane 12, 539131 Defu Lane - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 24/12/2018]		
Claimant's Solicitor:	K KRISHNA & PARTNERS - Tel: 63233038		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (14/12/2018): Request for TP GIA report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.



Claim Documents

***GW7289J (2740154854SG)**
[SLT7942M]

TP

-

Dec 8 2018 12:00PM
[BKW RENT A CAR PTE LTD]
Sat Motors

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View in Browser		
Photos/Images														3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print		
1	14/12/18 13:30	General View												Load JPG	☒		
2	14/12/18 13:30	General View												Load JPG	☒		
3	14/12/18 13:30	General View												Load JPG	☒		
4	14/12/18 13:30	General View												Load JPG	☒		
5	14/12/18 13:30	General View												Load JPG	☒		
6	14/12/18 13:30	General View												Load JPG	☒		
7	14/12/18 13:30	General View												Load JPG	☒		
8	14/12/18 13:30	General View												Load JPG	☒		
9	14/12/18 13:30	General View												Load JPG	☒		
10	14/12/18 13:30	General View												Load JPG	☒		
11	14/12/18 13:30	General View												Load JPG	☒		
12	14/12/18 13:30	General View												Load JPG	☒		
13	14/12/18 13:30	General View												Load JPG	☒		
14	14/12/18 13:30	General View												Load JPG	☒		
Documentation														1 per page		☒	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail	Print		
1	14/12/18 16:20	oi gia report												Load PDF			
2	17/12/18 15:11	TP GIA												Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18022448/JCD3S2

Date: 20/12/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994354
Claimant Vehicle No :	GW7289J	Insured Vehicle No :	SLT7942M
Date of Loss:	08/12/2018	Nature of Claim:	TP
		Claim No:	2740154854SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GW7289J	Engine No:	1KD2737996
Make & Model:	TOYOTA DYNA 1.5T, 3.0 (A)	Chassis No:	JTFAT35Y00K208712
Reg. Date:	13/09/2017 (Man. Year: 2017)	Odometer:	91804 km
Colour:	Blue		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	155 R12C	Rear Tyre Size:	155 R12C
Front Left Side:	Falken 7 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	13/12/2018		
Date Inspected:	14/12/2018	Inspected At:	Sat Motors (HQ) 24 Defu Lane 12 Singapore 539131
Estimated Period of Repair:	2.0 days		

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH TAILLAMP	*Check	0.00 F	*- F
2	1		*TAILGATE	Repair	0.00 F	*- F
3	1		*REAR RUBBER STOPPER BRACKET	Dented	0.00 F	*- F
4	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
5	1		*TAILGATE HINGE	Distorted	0.00 F	*- F
F=Franchise part.						
				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >