

SS. PEC. BY:

REF: CB/FCU 0022458/Kgbrn

Special Instruction:

Survivor:

ASSIGNMENT (Office)

From (Person): WLS Karen Tan of FCL Date/Time: 13-12-2018 5:06pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLV 2952G Insured: SHB 2666K

at Workshop m/s Cheng Hoe Tel: 6755 6142

of Blk 1019 Yishun Ind Park A #01-374

Policy No: _____ Claim No: D18008823MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 11-12-2018
(Client's Record)

CA / REV / REP. / REV 24 HRS DS H.O.D. Endorsement: _____

Date/Time: 13-12-2018 5:14pm Person Contacted: Ereeda Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLV 2952G - X
	SHB 2666K - NS/DNC12008218/41gm DUA: 210212
19/12/18 @ 1:56pm	revised to Karen Tan by email.
18/3	1607.28 Confirmed Ereds (Rad @ 168.64, 9%)

ASS. REC. BY:

REF: 17021


Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s: Cheng Hoo
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 875k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 02 days Res.: Yes or No
 Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLV 2952G Yr Regn: 12, 17
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda Shuttle c.c. 1498
 Colour: M. Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 23016 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: GKD . 1200177
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: NII / S/Rim / STD A/Rim or
 Tyre Size: F: 205/50R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Falken
 Front R/Bal. 8 mm
 L/Bal. 8 mm
 D.O.A. 11/12/18
 Rear R/Bal. 8 mm
 L/Bal. 8 mm
 D.O.A. 17/12/18
 Survey held at _____
 Des. of Damages: Rear O/S / Frit / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>19/12</u>	<u>date fall to Customer</u>

RECEIVED 20 MAR 2019

[Signature]
 18/3/2019

Date/Time, File Pass to?

: Prell. Report
 : Final Report

11/19/3 *[Signature]*

Date/Time, File Return to?

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

100
50
50
13
213

Report Format: TP

Lump Sum / I.B.I. (\$) 1607.28



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008823MFSH

Date: 19 December 2018

Our Ref: CS/FCI18022458/Kqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLV 2952G .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 17/12/2018 at the premises of M/s CHENG HOE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,775.92</u> .
Revised Estimate Amount	: S\$ <u>1,407.28</u> .
"Check" Items Amount	: S\$ <u>221.20</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear o/s portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	13-12-2018	Our Ref No. D18008823MFSH
Accident Date	11-12-2018	Claim Type. Third Party
Insured Vehicle	SHB2666K	Third Party Vehicle. SLV2952G
Survey Location	BLK 1019 YISHUN IND. PARK A #01-374	
Contact Person.	JUNE	
Contact No.	67556142/ 0	Fax No. 67557719
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHENG HOE MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 19 December 2018 1:56 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008823MFSH/1
Attachments: CSFC118022458Kqb.pdf

Dear Karen,

Enclosed herewith preliminary advice of SLV 2952G.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 13 December 2018 5:12 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008823MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin
LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 13 December, 2018 5:06 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008823MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2368A
Vehicle Details	
Vehicle No.:	SLV2952G
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Dec 2018
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5G CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	L15B5460214
Chassis No.:	GK81200177
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,880.00
Original Registration Date:	27 Dec 2017
First Registration Date:	27 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$8,880.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Dec 2027
PARF Rebate Amount:	\$6,660.00
Intended COE Rebate Details	
COE Expiry Date:	26 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,339.00
COE Rebate Amount:	\$38,207.00
Total Rebate Amount:	\$44,867.00

The information contained herein is correct as at 17 Dec 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Vishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLV2952G
 TP/FC

M/S : MS FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

TEL: 65073848 FAX: 65073849
 ATTN: Motor Claim Department

WS Ref: TP/FC/YS
 Claim Type: Third Party
 Accident Date: 11/12/2018
 TP Veh Reg No: SHB2666K

Not Authored
1-B-1
Putty B4 paint
2 days

Estimate No: ES1891420/YISHUN
 Date: 17 Dec 2018
 Policy No: 5096937606
 Veh Reg No: SLV2952G
 Make/Model: HONDA SHUTTLE 1.5G CVT
 Chassis No: GK81200177
 Engine No: L15B5460214
 Reg. Date: 27/12/2017

Estimate Repair Cost to Vehicle No :SLV2952G

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	1,150.60	1 PC	1,150.60	
2 REAR BUMPER RH SIDE RETAINER	21.80	1 PC	21.80	X
3 REAR BUMPER RH FOG LAMP GARNISH	26.50	1 PC	26.50	X
4 REAR BUMPER CLIPS	3.50	6 PCS	21.00	
			1,219.90	
		Less 20%	243.98	975.92
Special Net				
5 REVERSE SENSOR	200.00	1 PC	200.00	
			200.00	200.00
Labour				
6 REMOVE & REFIX REAR BUMPER ASSY,KNOCK & REPAIR REAR PANEL & REALIGN THE SAME	300.00	1 LA	300.00	220
7 PUTTY & RESPRAY ON REAR PANEL,REAR BUMPER	300.00	1 LA	300.00	250
			600.00	600.00
			Total	S\$ 1,775.92
			Add GST @ 7%	124.31
			Total Amount Payable	S\$ 1,900.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

For Cheng Hoe Motor Pte Ltd

[Signature]
 AUTHORIZED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18022458/Kqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-03-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 2666K	Veh. Inspected	SLV 2952G
Policy No.		Coverage (\$)	0.00
Claim No.	D18008823MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	13/12/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA SHUTTLE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	GK81200177	Colour	METALLIC SILVER
Odometer	23016	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/50 R16	FALKEN	8 mm
L/H Front Tyre	205/50 R16	FALKEN	8 mm
R/H Rear Tyre	205/50 R16	FALKEN	8 mm
L/H Rear Tyre	205/50 R16	FALKEN	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/12/2018	Inspection Date	17/12/2018
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 2952G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BUCKLED	1,150.60	1,150.60
1	REAR BUMPER RH SIDE RETAINER	SERVICEABLE	21.80	-
1	REAR BUMPER RH FOG LAMP GARNISH	SERVICEABLE	26.50	-
6	REAR BUMPER CLIPS @\$3.50	NECESSARY	21.00	21.00
	LESS 20% DISCOUNT		-243.98	-234.32
			975.92	937.28
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	SHORTED	200.00	200.00
			200.00	200.00
LABOUR				
	REMOVE & REFIX REAR BUMPER ASSY, KNOCK & REPAIR REAR PANEL & REALIGN THE SAME.		300.00	220.00
	PUTTY & RESPRAY ON REAR PANEL, REAR BUMPER.		300.00	250.00
			600.00	470.00
GRAND TOTAL			1,775.92	1,607.28
RECOMMENDED COST OF REPAIRS				1,607.28

Report Ref No. CS/FCI18022458/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.