

ASS. REC. BY:

REF:

TMI/

CC3/TMLI SD22480/Kgb n2

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

121

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SID 376A

Yr Regn:

06, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c

1995

Colour:

M. White / R

AC:

Insured / Std / NI / NA

Sp. Reading

337051

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1AB15AUC 282605

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

Inorder / Jammed / Leaked / Burnt or

Brake:

Inorder / Jammed / Leaked / Burnt or

Mod:

N/S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Giti

Front

R/Bal.

S

mm

Rear

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

11/12/18

D.O.I.

13/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S/R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/12

File pass to Catherine

B8064.54 (Red B20219.31, 72%)

14/12/18

4pm Email GIA, police report &amp; estimate to TMI.

SID 376A

CC3/CAT140D3300/Kgb302

SJR 1564U

NBA/ms617013252/31

DCA: 24042014

DCA: 05072017

RECEIVED 09 JAN 2019

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1) 09/1/2019

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

250

10

260

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Report Format:

MER-TP

Lump Sum / I.B.I: (\$)

8064.54

**Shiau Chan (LKKAuto)**

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Friday, 14 December 2018 4:00 PM  
**To:** motorclaims@tokiomarine.com.sg  
**Cc:** SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 11/12/2018, SHD 376A (TP VEHICLE), SJR 1564U (OI VEHICLE)  
**Attachments:** SHD376 PR.pdf; SHD376 EST.pdf; SHD376 GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 376A M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63, SINGAPORE 569111.

Enclosed herewith a copy of TP's GIA report, police report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

**Vehicle Details**

Vehicle No.:	SHD376A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	12 Dec 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C003041
Chassis No.:	VF1ABL15AUC282665
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	10 Jun 2016
First Registration Date:	10 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Jun 2024
PARF Rebate Amount:	\$14,998.00

**Intended COE Rebate Details**

COE Expiry Date:	09 Jun 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$37,164.00
COE Rebate Amount:	\$25,516.00
<b>Total Rebate Amount:</b>	<b>\$40,514.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Dec 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/12/2018 10:48
Date Of Accident	11/12/2018 19:20
Exact Location Of Accident	JALAN SULTAN TOWARDS BEACH ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD376A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	CHUA CHOON HOCK
NRIC No	S6934657Z
Date Of Birth	05/10/1969
Occupation	OUTDOOR
Date Of Driving Pass	05/02/1990
Driving Experience	28 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83988819
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 134 BEDOK NORTH STREET 2  
#09-111  
Postcode 460134  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OTHER - HIRER  
Vehicle Registration Number of Driver's Own Vehicle -  
Vehicle -  
Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident 2  
Was any body injured in the Accident? YES  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 3  
Passenger 1 NAME: : UNKNOWN  
GENDER: : MALE  
Passenger 2 NAME: : UNKNOWN  
GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police? YES  
If Yes, Please state which Police Station  
Police Station Name TOA PAYOH NEIGHBOURHOOD POLICE CENTRE  
Police Station Address ROAD: 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING ,  
POSTCODE: 319194 , COUNTRY: SINGAPORE  
Police Station Contact TEL NO: 1800-2519999 - FAX NO: 63548749  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

Please see the attach Police Report T/20181211/2159.

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJR1564U  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name CHUA CHOON HOCK

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHD376A

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

## Sketch Plan Pg. 1

### SKETCH PLAN


#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Sketch Plan #2 Pg. 1

### SKETCH PLAN

SKETCH PLAN

A: SHD 376A  
B: SJR 1564U  
Jalan Sultan  
Towards  
Beach Road

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see the attach police report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Amranda

---

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 376A****AAD1812-098**

*Not Authored*  
*Recovery B4 paint* 88064.54

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHD 376A**

VF1ABL15AUC282665

RENAULT

LATITUDE

11.12.2018

**TOKIO MARINE****PART****LIST**

1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT LH
1	BUMPER SUPPORT FRT
1	BUMPER RETAINER FRT RH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE LH
1	BUMPER BEAM FRT
1	HEADLAMP LH
1	HEADLAMP PANEL FRT LH
1	FENDER PANEL FRT LH
1	WHEELARCH FRT LH
1	FENDER BRACKET LOWER LH
1	FENDER INSULATOR LH
1	DOOR PANEL FRT LH
1	RADIATOR GRILLE
1	RADIATOR GRILLE BADGE 'RENAULT'
1	RADIATOR GRILLE FRAME
1	RADIATOR FAN COWLING
1	RADIATOR FAN MOTOR LH
1	RADIATOR FAN MOTOR RH
1	RADIATOR GRILLE FRAME
1	FRAME FULL SUPPORT PANEL
1	FRAME FULL SUPPORT BRACKET
1	AIR CLEANER BOX
1	AIR CLEANER HOSE

\$	CM	1,259.42	✓
\$	SL	181.75	X
\$	SL	394.68	X
\$	DI	151.41	✓
\$	SL	123.88	X
\$	SL	150.77	X
\$	SL	123.88	X
\$	SL	472.83	X
\$	SL	266.80	X
\$	DI	207.21	✓
\$	R	914.08	✓
\$	CM	1,184.43	✓
\$	R	152.15	X
\$	R	783.83	✓
\$	SL	278.84	} X
\$	SL	15.79	
\$	SL	130.84	
\$	R	2,844.66	} X
\$	mgm	SL	
\$	SL	1,707.78	
\$	SL	225.36	} X
\$	CM	SL	
\$	SL	1,353.75	
\$	SL	820.54	} X
\$	SL	967.36	
\$	SL	1,479.46	
\$	SL	1,353.75	} X
\$	SL	615.90	
\$	R	89.79	
\$	SL	464.20	} X
\$	SL	175.85	

**Trans-cab Auto Services Pte Ltd**

AAD1812-098

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 376A

1	LOWER ARM LH L70Y	\$	685.76	X
1	KUNCKLE ARM LH L70Y	\$	846.98	X
1	ABSORBER FRT LH L70Y	\$	360.54	X

<b>TOTAL</b>	<b>\$</b>	<b>20,784.28</b>
<b>10%</b>	<b>\$</b>	<b>2,078.43</b>
	<b>\$</b>	<b>18,705.85</b>

**Specical Nett**

1SET	BUMPER CLIP FRT	\$	66.00	✓
1	BUMPER BRACKET CLIP FRT LH	\$	12.00	} X
1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	
1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	
1SET	WHEELARCH CLIP FRT RH	\$	30.50	}
1	FRONT LEFT TYRE	\$	300.00	
1	FRONT LEFT TYRE RIM	\$	380.00	

<b>\$</b>	<b>988.00</b>
-----------	---------------

<b>TOTAL PARTS</b>	<b>\$</b>	<b>19,693.85</b>
--------------------	-----------	------------------

**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 3,500.00

4400 500

Putty and spray painting of the affected portion.

\$ 3,000.00

440

To rust-proofing of the affected areas.

\$ 170.00

300

**Trans-cab Auto Services Pte Ltd**

AAD1812-098

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 376A

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	~ 380.00 X
To check steering geometry and computer wheel alignment	\$	~ 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
To transfer of front fender fittings, attachment and perform water seepage test.	\$	~ 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	~ 380.00 X
To replace, refix and top up coolant for radiator	\$	~ 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	~ 170.00 X
To transfer of front door fittings, attachment and perform water seepage test.	\$	~ 380.00 X

**TOTAL \$ 9,090.00****Over All Total \$ 28,783.85****LUMP SUM (REPAIR DAY)****15 DAYS***3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18022480/KQBN2

Date: 10/01/2019

## REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MJ000344
Claimant Vehicle No :	SHD376A	Insured Vehicle No :	SJR1564U
Date of Loss:	11/12/2018	Nature of Claim:	TP
		Claim No:	M1806407

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHD376A	Engine No:	M9R8839C003041
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC282665
Reg. Date:	10/06/2016 (Man. Year: 2015)	Odometer:	337051 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	19,693.84	7,074.54	12,619.30	64.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,090.00	990.00	8,100.00	89.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>28,783.84</b>	<b>8,064.54</b>	<b>20,719.30</b>	<b>71.98</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,014.87</b>	<b>564.52</b>	<b>1,450.35</b>	<b>71.98</b>
<b>Nett Amount (S\$)</b>	<b>30,798.71</b>	<b>8,629.06</b>	<b>22,169.65</b>	<b>71.98</b>

## INSPECTION

Date of Assignment: 17/12/2018

Date Inspected: 13/12/2018 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)

2, Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jan 2019)
Parts:	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD376A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Cracked	1,259.42 FL	*1,259.42 FL
2	1		*BUMPER SPOILER FRT	Serviceable	181.75 FL	*- FL
3	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
4	1		*BUMPER RETAINER FRT LH	Distorted	151.41 FL	*151.41 FL
5	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
6	1		*BUMPER RETAINER FRT RH	Serviceable	150.77 FL	*- FL
7	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
8	1		*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	*- FL
9	1		*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	*- FL
10	1		*BUMPER FOG LAMP GRILLE LH	Distorted	207.21 FL	*207.21 FL
11	1		*BUMPER BEAM FRT	Bent	914.08 FL	*914.08 FL
12	1		*HEADLAMP LH	Cracked	1,184.43 FL	*1,184.43 FL
13	1		*HEADLAMP PANEL FRT LH	Repair	152.15 FL	*- FL
14	1		*FENDER PANEL FRT LH	Bent	783.83 FL	*783.83 FL
15	1		*WHEELARCH FRT LH	Serviceable	278.84 FL	*- FL
16	1		*FENDER BRACKET LOWER LH	Serviceable	15.79 FL	*- FL
17	1		*FENDER INSULATOR LH	Serviceable	130.84 FL	*- FL
18	1		*DOOR PANEL FRT LH	Repair	2,844.66 FL	*- FL
19	1		*RADIATOR GRILLE	Mtg Cracked	1,707.78 FL	*1,707.78 FL
20	1		*RADIATOR GRILLE BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
21	1		*RADIATOR GRILLE FRAME	Cracked	1,353.75 FL	*1,353.75 FL
22	1		*RADIATOR FAN COWLING	Serviceable	820.54 FL	*- FL
23	1		*RADIATOR FAN MOTOR LH	Serviceable	967.36 FL	*- FL
24	1		*RADIATOR FAN MOTOR RH	Serviceable	1,479.46 FL	*- FL
25	1		*RADIATOR GRILLE FRAME	Serviceable	1,353.75 FL	*- FL
26	1		*FRAME FULL SUPPORT PANEL	Serviceable	615.90 FL	*- FL
27	1		*FRAME FULL SUPPORT BRACKET	Repair	89.79 FL	*- FL
28	1		*AIR CLEANER BOX	Serviceable	464.20 FL	*- FL
29	1		*AIR CLEANER HOSE	Serviceable	175.85 FL	*- FL
30	1		*LOWER ARM LH L70Y	Serviceable	685.76 FL	*- FL
31	1		*KNUCKLE ARM LH L70Y	Serviceable	846.98 FL	*- FL
32	1		*ABSORBER FRT LH L70Y	Serviceable	360.54 FL	*- FL
33	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
34	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
35	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
36	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
37	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
38	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
39	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
40	1		*SET WHEELARCH CLIP FRT RH	Not Necessary	30.50 FS	*- FS
41	1		*FRONT LEFT TYRE	Serviceable	300.00 FS	*- FS
42	1		*FRONT LEFT TYRE RIM	Serviceable	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 21,772.27 7,853.27

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			- List Item Discount on L Items 10.00/10.00% (S\$)		2,078.43	778.73
			Total Parts (S\$)		19,693.84	7,074.54

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	3,500.00	500.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	440.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	-
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
6	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	-
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
8	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
9	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER	New	380.00	-
10	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	-
11	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR INTERCOOLER	New	170.00	-
12	TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
<b>Gross Labour Cost (\$\$)</b>			<b>9,090.00</b>	<b>990.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >