

ASS. REC. BY:

REF: CS / III18022484 / Usd301 Special Instruction:

Surveyor: Markus
Memmen

ASSIGNMENT (Office)

From (Person): Gabriel Wee

of

III

Date/Time: 14/12/18 @ 9:24am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL 6553B

Insured:

SHC 8981E

at Workshop m/s

Poly Math Garage

Tel:

97253727

of

1 Kaki Bukit Ave 6 #02-02

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/12/18

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time: 9:54am @ 14/12/18

Person Contacted:

Nigel

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SLL 6553B - CVI / VAL 18017437 / Bs	DUA: 20/9/2018
	SHC 8981E - CS3 / ITS019743 / R/bd 1	DUA: 29/10/2018

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLH 65533

at Workshop m/s Polygraph

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 66

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1065W

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLH 65533 rr Regn: 3 117

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: Ford Focus c.c. 998

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 12920 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WFO5-XXGC.C56K13740

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 205/55ZR16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 12/12/18 D.O.I. 14/12/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear - 8 ft.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 27A51266

26/12/18 4/5 # 8600 confirmed with Nigel

28/12/18 Confirmed HS \$ 8,600/- @ 7 days with Marcus.
(\$ 13,189.52 Rd - 61%)

RECEIVED 20 DEC 2018

Date/Time, File Pass to?

28/12/18

1) Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final Report

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: 450

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I.: (\$ 8,600/- HS)

10

450

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1065W
Vehicle Details	
Vehicle No.:	SLL6553B
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Dec 2018
Vehicle Make:	FORD
Vehicle Model:	FOCUS TITANIUM 1.0 GTDI 5DR
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	GK13740
Chassis No.:	WF05XXGCC5GK13740
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$19,281.00
Original Registration Date:	03 Mar 2017
First Registration Date:	03 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$14,281.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Mar 2027
PARF Rebate Amount:	\$10,710.00
Intended COE Rebate Details	
COE Expiry Date:	02 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,430.00
COE Rebate Amount:	\$40,556.00
Total Rebate Amount:	\$51,266.00

The information contained herein is correct as at 17 Dec 2018

OK

- Shell? Esso? Mobil? Caltex? SPC
- Mitsubishi Attrage.
- When PHV is mentioned, what are your imme

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)





New 5 Years Coe Renewal Toyota Altis 1.6a



2.88%p.a Lowest Interest@GV
Cars Financing \$2000
Downpayment Monthly From
\$568
GV Credit Pte Ltd [StarAd](#)


[Browse by Category](#)
[Sort by Da](#)
4 vehicles

[Advanced S](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
Search Selection	focus		Any	Any	2017	Any	Any
	Ford Focus 1.0A Ecoboost Titanium		\$69,800	\$7,650 /yr	27-Feb-2017	999 cc	17,100
Agent Warranty Intact. Genuine Low Mileage. Fully Agent Maintained. Buy With An Added Peace Of Mind From Vantage Pre-C Sime Darby Group. Complete With Our Comprehensive 72 Points ...							
Vantage Pre-Owned							
Posted: 16-Dec-2018 Tags: 2017 Ford Focus, 2017 ford focus, Ford Focus, ford focus, Ford, Focus, focus, Used Ford							
	Ford Focus Wagon 1.0A GTDI Titanium		\$66,800	\$7,280 /yr	21-Feb-2017	999 cc	30,000
Agent Unit With 5 Years/100,000Km Warranty Intact, Full-Service History With Regent Motors. Owner's 2nd Car. Buy With A f Vantage Pre-Owned, A Member Of The Sime Darby Group. Trade In...							
Vantage Pre-Owned							
Posted: 11-Dec-2018 Tags: 2017 Ford Focus, 2017 ford focus, Ford Focus, ford focus, Ford, Focus, focus, Used Ford							
	Ford Focus RS 2.3M		\$163,800	\$17,110 /yr	09-Jun-2017	2,261 cc	11,800
\$8k Drive Away! Bank Interest Rate From 1.98%! Fully Serviced And Maintained By Ford Agent (Regent Motors) 5 Years War Left With 4 Free Servicing With Agent. Drive Off This Un...							
Dynamic Motoring							
Posted: 06-Dec-2018 Tags: 2017 Ford Focus, 2017 ford focus, Ford Focus, ford focus, Ford, Focus, focus, Used Ford							
	Ford Focus RS 2.3M		\$168,000	\$16,910 /yr	14-Sep-2017	2,261 cc	9,000
New Head. Recall Done!							
Posted: 14-Nov-2018 Tags: 2017 Ford Focus, 2017 ford focus, Ford Focus, ford focus, Ford, Focus, focus, Used Ford							

Save this search criteria, to get email alerts whenever a match is found.

[Compare](#)
[Model](#)
[Price](#)
[Depreciation](#)
[Reg Date](#)
[Eng Cap](#)
[Mileage](#)

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Friday, 14 December 2018 9:24 AM
To: Ruby Ong; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Polymath Garage Pte Ltd; Zuhaidah Samsuri
Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLL 6553B [OUR REF. TCL.GCN.RO.50511.18.PG]

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLL6553B and let us have your report urgently.

This claim will be handled by Ms Aida.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

From: Ruby Ong [mailto:ruby@htapartners.com.sg]
Sent: 13 December, 2018 5:17 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: Polymath Garage Pte Ltd <enquiry@polymathgarage.com.sg>
Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLL 6553B [OUR REF. TCL.GCN.RO.50511.18.PG]
Importance: High

WITHOUT PREJUDICE

URGENT

Dear Sir

We refer to your email of even date.

Our client is agreeable to appoint LKK Auto Consultants Pte Ltd as the single joint expert to carry out the pre-repair survey for SLL 6553B.

Please make the necessary arrangements with the contact person. The details are as follows :

Venue : **POLYMATH GARAGE PTE LTD**
1 Kaki Bukit Avenue 6
#02-02 Autobay

Contact Person : **Mr Nigel Ong @ 9725 3727**

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our client's right to claim for compensation for loss of use for your current request for re-survey.

Best regards,

Ruby Ong

Secretary

M/s Hin Tat Augustine & Partners

20 Upper Circular Road

#02-10/12 The Riverwalk

Singapore 058416

Tel : 6533 0212 ext 278

Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

From: Motor Claim - III <motorclaim@iii.com.sg>

Sent: Thursday, December 13, 2018 4:35 PM

To: Ruby Ong <ruby@htapartners.com.sg>

Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLL 6553B [OUR REF. TCL.GCN.RO.50511.18.PG]

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

From: Ruby Ong [<mailto:ruby@htapartners.com.sg>]

Sent: 13 December, 2018 3:54 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLL 6553B [OUR REF. TCL.GCN.RO.50511.18.PG]
Importance: High

Your ref: SHC 8981E
Our ref: TCL.MH.ro.50511.18.pg

WITHOUT PREJUDICE

13 December
2018

URGENT

India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711
Attn: Motor Claims Dept

By Email only

Dear Sirs

CLAIMANT: PEH KOK BENG

NOTICE OF ACCIDENT AND PRE-REPAIR SURVEY - ACCIDENT INVOLVING SLL 6553B, SHC 8981E, SLU 3804A & SJR 4321J ALONG CTE TOWARDS BRADDELL EXIT ON 12 DECEMBER 2018 @ 2140HRS

We are instructed by Peh Kok Beng to notify you of a road traffic accident on 12 December 2018 at about 2140hrs along CTE towards Braddell exit involving our client's vehicle registration number SLL 6553B and vehicle registration number SHC 8981E driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext 278

Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached

you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/12/2018 14:03
Date Of Accident	12/12/2018 21:40
Exact Location Of Accident	CTE> SLE BEFORE BRADELL EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL6553B
Insured/Policyholder	
Name Of Registered Owner	PEH KOK BENG
NRIC No	S7538525J
Email Address	VICPEH@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-93821635
Alternative Phone No	OTHERS-93821635
Vehicle Particulars	
Manufacturer	FORD
Model	FOCUS TITANIUM 1.0 GTDI 5DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B 28911376 QMY
Cover Note Number	

Driver

Name of Driver	PEH KOK BENG
NRIC No	S7538525J
Date Of Birth	25/12/1975
Occupation	INDOOR
Date Of Driving Pass	30/12/2002
Driving Experience	15 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93821635
Fax Number	
Contact Number	OTHERS-93821635
Email Address	VICPEH@SINGNET.COM.SG

Address	BLK 268A COMPASSVALE LINK #04-43
Postcode	541268
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJR4321J
Vehicle Make/Model/Colour	HONDA VEZEL
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHC8981E
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SLU3804A

Vehicle Make/Model/Colour

KIA CERATO

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

13 DEC 2019
IDAC KAKI BUKIT(VAC)
 23 KAKI BUKIT AVE 4
 Reporting Centre
 Name: 
 Tel: 67416697
 NRIC/FIN No.:
 Fax: 67492305
 Email: vackb@singnet.com.sg

SKETCH PLAN



A = SLL6553B

B = SHC8981E

C = SLV3804A

D = SJR4321J


CTE(SLE) near Braddell exit


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and Time, I vehicle A(SLL6553B) was travelling on the stated venue on lane 1. Suddenly, vehicle D (SJR4321J) slow down and came to a stop and I follow suit and stop in time. Suddenly I felt an impact from the rear and cause my vehicle to propel forward and hit onto Vehicle D. I alighted from my vehicle and realise I'm involve in a chain collision of four vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

13 DEC 2018
IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Reporting Centre
Name: 
Tel: 67416697
NRIC/FIN No.: Fax: 67492305
Email: vackb@singnet.com.sg



14/12/2018

Estimated repair checklist

Vehicle Registration No. : SLL6553B

Vehicle Make/Model : Ford/Focus

Qty List Items

1	Tailgate	
1	Tailgate logo	
1	Tailgate emblem "FOCUS"	
1	Tailgate emblem "TITANIUM"	
2	Tailgate emblem "BOOST"	
1	Tailgate outer garnish	
1	Rear bumper	1320
4	Rear bumper PDC sensors @ 385	145 x 2 = 290
2	Rear bumper reflectors - L/R @ 89.90	
1	Rear bumper PDC sensor wire harness	
1	Rear bumper lower extension	
1	Rear bumper tow cover	
2	Rear bumper reflectors @ 215	
2	Rear bumper side retainers @ 65	
1	Rear bumper reinforcement	460
1	Rear bumper CTR guide	
1	Rear end panel	
1	Rear end panel trim	
1	Rear exhaust silencer	
2	Rear exhaust mountings @ 28	
1	Rear exhaust insulator	
1	Front bonnet	
1	Front bonnet logo	
1	Front bonnet lock	
1	Front bumper	
1	Front bumper lower spoiler	
1	Front bumper sponge	
1	Front bumper reinforcement	520
2	Front bumper side retainers @ 55	
1	Front grille assy	605
2	Front headlamps - L/R @ 2355	1450 x 2 = 2900
2	Front headlamp lower brackets @ 85	
1	Front support panel	810

Amount \$

12	1,490.00	X
11	89.00	X
11	86.00	X
11	112.00	X
11	85.00	X
11	421.60	X
11	1,395.00	X
8	1,540.00	2 pcs
11	179.80	X
11	315.00	X
11	685.00	X
11	36.00	X
11	430.00	X
3	130.00	X
11	756.00	X
11	182.00	X
11	1,085.00	X
11	260.00	X
11	1,265.00	X
11	56.00	X
11	126.00	X
11	1,350.00	X
11	89.00	X
11	225.00	X
11	1,482.00	X
11	442.00	X
11	132.00	X
11	780.00	X
11	110.00	X
11	815.00	X
11	4,610.00	X
11	170.00	X
11	895.00	X
Sub-total		21,824.40
Less 20%		4,364.88
Total List		17,459.52

1-10113.80
202
8091.04



14/12/2018

Estimated repair checklist

Vehicle Registration No. : SLL6553B

Vehicle Make/Model : Ford/Focus

Special Nett Items

1 set Front no. plate with holder

300 60.00 40
Total Special Nett 60.00

Labour charges

To check front & rear electrical wiring
To remove, refix rear exhaust systems
To respray undercoating
To remove, refix rear interior trims to assist repair
To respray painting and etc
Panel beating, cut, weld remove & replacing above parts

80.00 30
150.00 60
120.00 50
120.00 80
1,800.00 1400
2,000.00 1000
Total Labour 4,270.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

21,789.52

LKK Auto Consultants hence notify the Repairer of the following:


- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-809/04
S.N-40
Labour-2620
10,751.04
202
8600

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Jan 2019 08:35 Edit Reg		14 Dec 2018 00:00 Edit Adj Rpt	S\$8,600.00 Edit Estimates	S\$8,600.00 View Rpt		Pending for Survey Report Cancel Case






































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	-								
Vehicle Reg. No.:	SLL6553B	Date of Loss:	12/12/2018 00:00 - :59 [21 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SHC8981E	Policy No. (Claimant):							
		Excess:							
Repairer:	Polymath Garage Pte Ltd (HQ) 1 KAKI BT AVENUE 6 #02-02 AUTOBAY, 417883 Kaki Bukit - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 26/12/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS 		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















































Claim Documents

















































*SLL6553B
[SHC8981E]
TP


-
Dec 12 2018 12:00AM

[-]
Polymath Garage Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/12/18 11:22	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	28/12/18 11:22	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
3	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
4	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
5	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
6	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
7	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
8	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
9	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
10	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
11	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
12	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
13	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
14	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
15	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
16	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
17	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
18	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
19	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
20	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
21	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
22	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
23	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
24	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
25	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
26	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
27	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
28	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
29	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
30	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
31	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
32	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
33	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
34	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
35	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
36	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
37	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
39	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
40	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
41	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
42	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
43	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
44	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
45	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
46	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
47	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
48	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
49	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
50	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
51	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
52	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
53	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
54	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
55	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
56	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
57	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
58	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
59	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
60	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
61	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
62	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
63	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
64	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
65	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
66	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
67	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
68	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
69	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
70	28/12/18 11:22	General View	 Load JPG	<input checked="" type="checkbox"/>
71	28/12/18 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	28/12/18 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	28/12/18 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	28/12/18 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	28/12/18 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	28/12/18 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	28/12/18 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	28/12/18 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	28/12/18 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	28/12/18 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	28/12/18 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	28/12/18 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	28/12/18 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	28/12/18 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	28/12/18 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	28/12/18 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	28/12/18 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	28/12/18 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	28/12/18 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	28/12/18 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	28/12/18 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	28/12/18 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail Print
1	17/12/18 09:06	Singapore Accident Statement		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III18022484/USD3E2

Date: 03/01/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SLL6553B

Insured Vehicle No : SHC8981E

Date of Loss: 12/12/2018

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLL6553B

Make & Model: FORD FOCUS, 999cc Titanium (A)

Engine No: GK13740

Reg. Date: 03/03/2017 (Man. Year: 2016)

Chassis No: WF05XXGCC5GK13740

Colour: Blue

Odometer: 52920 km

Engine Capacity: 999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55Z R16

Rear Tyre Size: 205/55Z R16

Front Left Side: Michelin 7 mm

Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm

Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,519.52	8,131.04	9,388.48	53.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,270.00	2,620.00	1,650.00	38.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,789.52	10,751.04	11,038.48	50.66
Approved Total (Overridden) (S\$)		8,600.00		
Nett Amount (S\$)	21,789.52	8,600.00	13,189.52	60.53

INSPECTION

Date of Assignment: 14/12/2018

Date Inspected: 14/12/2018 Inspected At:

 Polymath Garage Pte Ltd (HQ)
 1 KAKI BT AVENUE 6 #02-02 AUTOBAY
 Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jan 2019)
Parts:	144	FORD FOCUS 999cc Titanium (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL6553B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,490.00 FL	*- FL
2	1		*TAILGATE LOGO	Not Necessary	89.00 FL	*- FL
3	1		*TAILGATE EMBLEM FOCUS	Not Necessary	86.00 FL	*- FL
4	1		*TAILGATE EMBLEM TITANIUM	Not Necessary	112.00 FL	*- FL
5	2		*TAILGATE EMBLEM BOOST	Not Necessary	85.00 FL	*- FL
6	1		*TAILGATE OUTER GARNISH	Not Necessary	421.60 FL	*- FL
7	1		*REAR BUMPER	Distorted	1,395.00 FL	*1,320.00 FL
8	1		*REAR BUMPER PDC SENSORS (4PCS)	Shorted-2pcs only	1,540.00 FL	*290.00 FL
9	2		*REAR BUMPER REFLECTORS - L/R	Cracked	179.80 FL	*179.80 FL
10	1		*REAR BUMPER PDC SENSOR WIRE HARNESS	Torn	315.00 FL	*315.00 FL
11	1		*REAR BUMPER LOWER EXTENSION	Distorted	685.00 FL	*685.00 FL
12	1		*REAR BUMPER TOW COVER	Torn	36.00 FL	*36.00 FL
13	2		*REAR BUMPER REFLECTORS	Repeated	430.00 FL	*- FL
14	2		*REAR BUMPER SIDE RETAINERS	Bent	130.00 FL	*130.00 FL
15	1		*REAR BUMPER REINFORCEMENT	Bent	756.00 FL	*460.00 FL
16	1		*REAR BUMPER CTR GUIDE	Cracked	182.00 FL	*182.00 FL
17	1		*REAR END PANEL	Repair	1,085.00 FL	*- FL
18	1		*REAR END PANEL TRIM	Not Necessary	260.00 FL	*- FL
19	1		*REAR EXHAUST SILENCER	Repair	1,265.00 FL	*- FL
20	2		*REAR EXHAUST MOUNTINGS	Not Necessary	56.00 FL	*- FL
21	1		*REAR EXHAUST INSULATOR	Not Necessary	126.00 FL	*- FL
22	1		*FRONT BONNET	Repair	1,350.00 FL	*- FL
23	1		*FRONT BONNET LOGO	Necessary	89.00 FL	*89.00 FL
24	1		*FRONT BUMPER	Dented / Deformed	1,482.00 FL	*1,482.00 FL
25	1		*FRONT BUMPER LOWER SPOILER	Not Necessary	442.00 FL	*- FL
26	1		*FRONT BUMPER SPONGE	Not fitted	132.00 FL	*- FL
27	1		*FRONT BUMPER REINFORCEMENT	Bent	780.00 FL	*520.00 FL
28	2		*FRONT BUMPER SIDE RETAINERS	Bent	110.00 FL	*110.00 FL
29	1		*FRONT GRILLE ASSY	Cracked	815.00 FL	*605.00 FL
30	2		*FRONT HEADLAMPS - L/R	Cracked	4,610.00 FL	*2,900.00 FL
31	2		*FRONT HEADLAMP LOWER BRACKETS	Not Necessary	170.00 FL	*- FL
32	1		*SUPPORT PANEL	Cracked	895.00 FL	*810.00 FL
33	1		*SET FRONT NO. PLATE WITH HOLDER	Bent	60.00 FS	*40.00 FS
34	1		*FRONT BONNET LOCK	Not Necessary	225.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,884.40	10,153.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,364.88	2,022.76
Total Parts (\$\$)	17,519.52	8,131.04

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT & REAR ELECTRICAL WIRING	New	80.00	30.00
2	TO REMOVE, REFIX REAR EXHAUST SYSTEMS	New	150.00	60.00
3	TO RESPRAY UNDERCOATING	New	120.00	50.00
4	TO REMOVE, REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	80.00
5	TO RESPRAY PAINTING AND ETC	New	1,800.00	1,400.00
6	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS	New	2,000.00	1,000.00
Gross Labour Cost (S\$)			4,270.00	2,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >