

22/03/2002

ASS. REC. BY:

REF: CS3/CTI18022487/Jcd324

Special Instruction:

Surveyor:

Hwee Tee

ASSIGNMENT (Office)

From (Person):

ehong Boon Sen

of

CTI

Date/Time:

13/12/18 @ 5.09pm

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJR 2123C

Insured:

PA 55614

at Workshop m/s

SAT Motor

Tel:

9859 9687

of

24 Defn June 12

Policy No:

DMBISN1745321802

Claim No:

8NM18D05769 C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 31/10/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

9:17am @ 14/12/18

Person Contacted:

jessie

Vehicle ~~IN~~ OUT

Date/Time

Action/Instruction ( x ) Estimate

SJR 2123C - NA / EQI 17022548/h4

DUA: 17/11/2017

PA 55614 - X

PRS

REF: CFI

Signature

Hwee Jie

## ASSIGNMENT

From:

Date:

14/12/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SJR 2123C

at Workshop n/s

SAT Motor

of

24 Defu Lane 12

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>1 up</sup>

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJR 2123C

Yr Regn: 14 Jul 2006

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 24

C.C. 2496

Colour:

white

A/C Insured / Std / NI / NA

Sp. Reading

175966

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBABU12010LH56323

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ R / STD A/Rim or

Tyre Size:

F: 245/39 R19

R: —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

31/10/18

D.O.I.

14/12/18

Survey held at

Sat motor

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range: \$2,800 - \$3,500  
3 days

*[Signature]*  
17/12/2018

Date/Time, File Pass to?



: Preli. Report

Days Of Repair:

3

1)



: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:



: Site Insp (\$)

) \$ + R5. St



: Interview (\$)

) Photos



: Tech. Invs (\$)

) Others



: Weekend (\$)

) TOTAL

Report Format :

PRS.

Lump Sum / I.B.I. (\$)

150

150

**...CLAIM SUBFOLDER...(New Assignment)**

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Dec 2018		13 Dec 2018 17:09 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	<b>ONG KIM GEOK</b>		
Vehicle Reg. No.:	<b>SJR2123C</b>	Date of Loss:	31/10/2018 00:00 - :59
Claim Type:	<b>TP / SNM18D05769C02</b>	Policy/Cover Note No.:	DMB1SN1745321802
Vehicle Reg. No. (Insured):	<b>PA5561U</b>	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	<b>Sat Motors (HQ)</b> 24 Defu Lane 12, 539131 Defu Lane - Tel:		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Final Rpt due 24/12/2018]</b>		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

**ASSOCIATED MAIL RECEIVED**

[View All](#)

Compose Case Mail

There are no mail for this case.

## ALL ASSOCIATED TASKS

[View All](#)

## Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

# K. KRISHNA & PARTNERS

Advocates & Solicitors  
Commissioner for Oaths/Notary Public  
(UEN No. 53131210X)

GST Registration No M90371530C

101 Cecil Street #24-03/04 Tong Eng Building, Singapore 069533  
Tel : 6323 3038 Fax : 6323 2120 (not for service of Court documents)  
E-mail : [kkrishna@singnet.com.sg](mailto:kkrishna@singnet.com.sg)

---

K. Krishnamoorthi  
LLB (Hons) (London)  
Barrister-at-Law (Gray's Inn)  
B.Sc (Hons) (Est. Man) (S'pore)

S. Manohar  
LLB (Hons) (S'pore)

---

Vengadesh s/o Kumaravelu  
LLB (Hons)

Our Ref : SM.PRI-SAT- SJR 2123C (fs)

13<sup>th</sup> December 2018

## IMMEDIATE ATTENTION PRE-REPAIR INSPECTION

FAX : 65 6222 1033 62247175  
Email : [e-claims@sg.cntaiping.com](mailto:e-claims@sg.cntaiping.com)

M/s China Taiping Insurance (Singapore) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

### Attention: Motor Claims Department

Dear Sirs

### **PRE-REPAIR INSPECTION OF VEHICLE SJR 2123C ACCIDENT ON 31.10.2018 INVOLVING SJR 2123C AND PA 5561U ALONG BISHAN STREET 11, SINGAPORE**

We act for Mr Ong Kim Geok, the owner of motor vehicle no. **SJR 2123C** which was involved in the above captioned accident

We are instructed that the accident was caused by the negligence of the driver of motor vehicle no. **PA 5561U**. Our search shows that you are the insurers of motor vehicle no. **PA 5561U**.

We are requested to inform you that our client's vehicle is available for pre-repair inspection at the following address :-

**M/S SAT MOTORS**  
24 Defu Lane 12  
Singapore 539131

**K. KRISHNA & PARTNERS**  
Advocates & Solicitors

---

13<sup>th</sup> December 2018  
M/s China Taiping Insurance (Singapore) Pte Ltd

---

Please contact **Mr Jonathan Lim of M/s SAT Motors** at his mobile no. **91269987** within **forty-eight (48) hours** from receipt of this fax to arrange for the inspection.

Yours faithfully



cc. workshop - (email and Fax : 67491141)

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	4436H
<b>Vehicle Details</b>	
Vehicle No.:	SJR2123C
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Dec 2018
Vehicle Make:	B.M.W.
Vehicle Model:	Z4 ROADSTER 2.5I A
Primary Colour:	White
Manufacturing Year:	2006
Engine No.:	79403760N52B25AE
Chassis No.:	WBABU12010LH56323
Maximum Power Output:	130.0 kW (174 bhp)
Open Market Value:	\$26,882.00
Original Registration Date:	14 Jul 2006
First Registration Date:	12 Jun 2009
Transfer Count:	1
Actual ARF Paid:	\$26,882.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	11 Jun 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$11,889.00
COE Rebate Amount:	\$586.00
<b>Total Rebate Amount:</b>	<b>\$586.00</b>

The information contained herein is correct as at 14 Dec 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	01/11/2018 17:36
Date Of Accident	31/10/2018 18:00
Exact Location Of Accident	BISHAN ST 11
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR2123C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ONG KIM GEOK
NRIC No	S0024436H
Email Address	KOSHISADREAMER@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96797868
Alternative Phone No	OFFICE-96797868

### Vehicle Particulars

Manufacturer	BMW
Model	Z4-2.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	GA374308/1
Cover Note Number	

### Driver

Name of Driver	ONG SHAO HENG, KEMP
NRIC No	S8812023Z
Date Of Birth	03/04/1988
Occupation	INDOOR
Date Of Driving Pass	27/07/2010
Driving Experience	8 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97693796

Fax Number

Contact Number

EEmail Address	KOSHISADREAMER@GMAIL.COM
----------------	--------------------------

Address	BLK 159 BISHAN ST 13 #01-60
Postcode	570159
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	EFILE
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO STATEMENT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PA5561U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SIM SOON HUAT
NRIC/Passport Number	S0209899G
Contact Number	83774697
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name



Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJR2123C

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NR/C/FIN No.:

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


A was stopped at the red light camera and B driver hit A from behind. A aligned felt neck pain and asked B for particulars to make accident report.

Damages sustained on Rear Back of the car impact crack windscreen.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)


































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Dec 2018		13 Dec 2018 17:09 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: -, Co. Reg. No.: -									
Main Claimant: <b>ONG KIM GEOK</b>									
Vehicle Reg. No.: <b>SJR2123C</b>		Date of Loss: 31/10/2018 00:00 - :59 [147 Months and 17 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / SNM18D05769C02</b>		Policy/Cover Note No.: <b>DMB1SN1745321802</b>							
Vehicle Reg. No. (Insured): <b>PA5561U</b>		Policy No. (Claimant):							
		Excess: <b>S\$0.00</b>							
Repairer: <b>Sat Motors (HQ)</b> 24 Defu Lane 12, 539131 Defu Lane - Tel:									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ONG HWEE JIE</b> ] ... [Final Rpt due 24/12/2018]									
Adj Asg. Remarks: NO EST, CASE W/O SJE.									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJR2123C (SNM18D05769C02)  
 [PA5561U]  
 TP  
 ONG KIM GEOK  
 Oct 31 2018 12:00AM  
 [-]  
 Sat Motors

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	14/12/18 13:29	General View		Load JPG	<input checked="" type="checkbox"/>					
2	14/12/18 13:29	General View		Load JPG	<input checked="" type="checkbox"/>					
3	14/12/18 13:29	General View		Load JPG	<input checked="" type="checkbox"/>					
4	14/12/18 13:29	General View		Load JPG	<input checked="" type="checkbox"/>					
5	14/12/18 13:29	General View		Load JPG	<input checked="" type="checkbox"/>					
6	14/12/18 13:29	General View		Load JPG	<input checked="" type="checkbox"/>					
7	14/12/18 13:29	General View		Load JPG	<input checked="" type="checkbox"/>					
8	14/12/18 13:29	General View		Load JPG	<input checked="" type="checkbox"/>					
9	14/12/18 13:29	General View		Load JPG	<input checked="" type="checkbox"/>					
10	14/12/18 13:29	General View		Load JPG	<input checked="" type="checkbox"/>					
11	14/12/18 13:29	General View		Load JPG	<input checked="" type="checkbox"/>					
12	14/12/18 13:29	General View		Load JPG	<input checked="" type="checkbox"/>					
13	14/12/18 13:29	General View		Load JPG	<input checked="" type="checkbox"/>					
14	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					
15	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					
16	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					
17	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					
18	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					
19	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					
20	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					
21	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					
22	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					
23	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					
24	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					
25	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					
26	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					
27	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					
28	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					
29	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					
30	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					
31	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					
32	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					
33	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					
34	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					
35	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					
36	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					
37	24/12/18 11:15	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	24/12/18 11:15	Dismantled Parts		<input checked="" type="checkbox"/>
39	24/12/18 11:15	Dismantled Parts		<input checked="" type="checkbox"/>
40	24/12/18 11:15	Dismantled Parts		<input checked="" type="checkbox"/>
41	24/12/18 11:15	Dismantled Parts		<input checked="" type="checkbox"/>
42	24/12/18 11:15	Dismantled Parts		<input checked="" type="checkbox"/>
43	24/12/18 11:15	Dismantled Parts		<input checked="" type="checkbox"/>
44	24/12/18 11:15	Dismantled Parts		<input checked="" type="checkbox"/>
45	24/12/18 11:15	Dismantled Parts		<input checked="" type="checkbox"/>
46	24/12/18 11:15	Dismantled Parts		<input checked="" type="checkbox"/>
47	24/12/18 11:15	Dismantled Parts		<input checked="" type="checkbox"/>
48	24/12/18 11:15	Dismantled Parts		<input checked="" type="checkbox"/>
49	24/12/18 11:15	Dismantled Parts		<input checked="" type="checkbox"/>
50	24/12/18 11:15	Dismantled Parts		<input checked="" type="checkbox"/>
51	24/12/18 11:15	Dismantled Parts		<input checked="" type="checkbox"/>
52	24/12/18 11:15	Dismantled Parts		<input checked="" type="checkbox"/>
53	24/12/18 11:15	Dismantled Parts		<input checked="" type="checkbox"/>
54	24/12/18 11:15	Dismantled Parts		<input checked="" type="checkbox"/>
55	24/12/18 11:15	Dismantled Parts		<input checked="" type="checkbox"/>
56	24/12/18 11:15	Dismantled Parts		<input checked="" type="checkbox"/>
57	24/12/18 11:15	Dismantled Parts		<input checked="" type="checkbox"/>
58	24/12/18 11:15	Photo After Spray		<input checked="" type="checkbox"/>
59	24/12/18 11:15	Photo After Spray		<input checked="" type="checkbox"/>
60	24/12/18 11:15	Photo After Spray		<input checked="" type="checkbox"/>
61	24/12/18 11:15	Photo After Spray		<input checked="" type="checkbox"/>
62	24/12/18 11:15	Photo After Spray		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/12/18 17:08	PRS		<input checked="" type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18022487/JCD3E2

Date: 28/12/2018

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN1745321802

Claimant Vehicle No: SJR2123C Insured Vehicle No: PA5561U

Date of Loss: 31/10/2018 Nature of Claim: TP Claim No: SNM18D05769C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SJR2123C**

Make & Model: BMW Z4, 2.5 I Roadster (A) Engine No: 79403760N52B25AE

Reg. Date: 14/07/2006 (Man. Year: 2006) Chassis No: WBABU12010LH56323

Colour: White Odometer: 175966 km

Engine Capacity: 2496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 245/39 R19 Rear Tyre Size: 245/39 R19

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 13/12/2018

Date Inspected: 14/12/2018 Inspected At: Sat Motors (HQ)  
24 Defu Lane 12  
Singapore 539131

Estimated Period of Repair: 3.0 days

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.





A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,800.00 -\$3,500.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      **Version:** 1.0 (Last Synchronised: 28 Dec 2018)

**Parts:** M1-COUPE      BMW Z4 2.5 I Roadster (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJR2123C)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >