

Accident Photo




Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/01/2016 10:30
Date Of Accident	06/01/2016 19:00
Exact Location Of Accident	AFT THE JUNCTION OF AMOY ST AND CROSS ST
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKE8591B
Insured/Policyholder	
Name Of Registered Owner	CHAN HONG KEOW
NRIC No	S6839327B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96177089
Alternative Phone No	Office-96177089

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA A6 1.4 TSI DSG 90KW CL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car

Insurance Company

Name of Insurance Company	AXA Insurance Singapore Pte Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	VPA/P1261459
Cover Note Number	

Driver

Name of Driver	CHAN HONG KEOW
NRIC No	S6839327B
Date Of Birth	29/11/1968
Occupation	Indoor
Date Of Driving Pass	12/02/1991
Driving Experience	24 Years And 10 Months
Gender	Female
Mobile Number	(Local) +65-96177089
Fax Number	
Contact Number	Office-96177089
EMail Address	NOEMAIL

Address	75 POH HUAT ROAD #02-14
Postcode	546782
Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Owner
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	Unknown - REFER TO SKETCH PLAN
Weather Conditions	Clear
Road Surface	Dry

Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	No
Was any other material or property damaged?	Yes
Was there any video captured by Car Camera?	No
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	No
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	No
If Yes, against whom?	

Circumstances of Accident

Are accident photos available for attachment?	Yes
---	-----

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKU2569Y
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	LEE YONG CHUAN
NRIC/Passport Number	S8016015A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Yang 7/1/16

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

My car (3KE85916) coming out from Amoy Street. I changes lane slowly (with signal) from bus lane to the next lane. The car B (3KV2569Y) unhappy speed up and overtake car A and scratch the front right side bumper (near to the wheel)

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Tang 7/1/16
Witnessed by Reporting Centre Personnel

Accident Photo



Accident Photo



07/01/2016 11:06

Accident Photo



Accident Photo



Accident Photo



07/01/2016 11:07

VEHICLE RENTAL AGREEMENT

INVOICE : SATPL

HIRER'S PARTICULAR

Name : (as in I/C): LEE YIYU (HUAN)
 NRIC / PASSPORT No: S4016015A
 Address (Res): _____

Name & Address of Employer: _____

Occupation: _____ Email: _____

D/L No: _____ D/L Type: Local / International

Pass Date: _____ Date of Birth: _____

Tel : (O) _____ (R) _____ HP: _____

ADDITIONAL DRIVER'S PARTICULARS

Name : (as in I/C) _____

NRIC / PASSPORT No : _____

Address (Res) : _____

D/L No: _____ D/L Type: Local / International


Pass Date: _____ Date of Birth: _____

Occupation: _____ Email: _____

Tel : (O) _____ (R) _____ HP: _____

Refundable Deposits :

Cash / Nets / Cheque / Visa / MC Card No :



Vehicle No: SKW2931M

Mileage Out: _____

MAKE & Model: Toyota Camry

Auto / Manual

OUT : Date

HIRE EXPIRY :

RENTAL CHARGE	AMOUNT
Daily @\$ <u>150</u>	
Weekly @\$	
Hours @\$	
Others @\$	
CDW @\$	
PAI @\$	
Delivery Service	
SUB - TOTAL	
Extension	
Collection Service	
Misc	
Estimated Total Rental \$	

Hirer is responsible for the first \$ _____ excess for collision / damage to first party. SAT MOTORS vehicle (including windscreen) and also first \$ _____ excess for collision / damage to third party's vehicle for each every accident / damage.

Hirer's Signature [Signature]

Hirer agrees not to SMOKE in the vehicle and not use it in any ILLEGAL ACTIVITIES.

X [Signature]

I / We agree to the terms and conditions above. Overleaf and that all information given is true & correct in all respect. My / Our Driving license (s) is / are current and not disqualified from driving. You may charge all amount due in the rental to my / our credit card.

IMPORTANT

1. ONLY PERSONS ABOVE 26 YEAR OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
2. VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY AND MAY NOT BE DRIVING OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY SAT MOTORS.
3. IN THE EVENT OF AN ACCIDENTS, THE HIRER OR AUTHORISED DRIVER:
 - (i) shall report all accident involving the said vehicle to the Owner immediately.
 - (ii) shall take immediate steps to complete and sign. Form Mar 1 (Motor Accident Report Form) and do all other acts required in compliance with the "NON-INJURY MOTOR ACCIDENT REPORT SCHEME" (the form will be made available when the accident is reported to the owner.
 - (iii) shall report to the police within 24 hours from the occurrence. The following types of accidents :-
 - (a) injury case;
 - (b) non-injury case involving a Government vehicle or damage to Government property ;
 - (c) non-injury case involving a foreign vehicle (to obtain their motor insurance policy, Passport No. / Name
 - (d) non-injury case involving a pedestrian or cyclist.

RETURN OF VEHICLE - THE HIRER / DRIVER IS REQUIRED TO SIGN THE COLUMN SIGNATURE OF HIRER / DRIVER* FAILING WHICH THE DAY AND THE TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND THE TIME THE VEHICLE IS RETURNED TO SAT MOTORS AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN TIME IN

MIL DEPOSIT REFUND

[Signature]
SIGNATURE OF HIRER/DRIVER



Singapore Automobile Trading Pte Ltd

24 Defu Lane 12 Singapore 539131

Tel: 6748 1141 Fax: 6749 1141

Website: www.singaporeautomobiletrading.com.sg

Biz Reg No: 200915171E

INVOICE

Vehicle Model: Toyota Camry
Car Plate No: SKW2837M

Date: January 26, 2016
Invoice #: Satpl 192

To: LEE YONG CHUAN (RENTER NAME)
S8016015A (NRIC)
- (ADDRESS)
-
- (PHONE)

No.	Description	Unit Price	Line Total
1	Rental Cost for the period of 4days starting from 11/01/2016 to 15/01/2016	\$150	\$600

Subtotal \$ 600.00
Sales Tax
Total \$ 600.00

Terms & Conditions:

The deposit will be used in the event of loss of or damage to the vehicle where the Renter will be fully liable on the cost of necessary repairs or replacement and the deposit will be credited towards the Owner. The Renter shall top up for any excess amount for the repair or replacement cost if the deposit amount was insufficient.

In the absence of damage or loss, the deposit will be return to the Renter after handling over the vehicle.

The Renter agree to compensate the Owner for the sum of deposit in the event of breach of contract.

Kindly make all cheque payable to Sat Motors
and mail to 24 Defu Lane 12 Singapore 539131



RW AUTOMOTIVE APPRAISERS SERVICES

(Licensed Appraisers & Claims Adjusters)

256 Bishan St. 22 #12-472 Singapore 570256

Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: + 65 6553 3912

Reg. No. 52821270B

INVOICE

Auto Mega Mall Pte. Ltd.
24, Defu Lane 12
Singapore 539131
On behalf of Vitro Auto

Invoice No : 160011

Date : 22.01.2016

Being:		
Survey Fees (including 16 photographs and transport charges)		S 316.00
S'pore Dollars : Three Hundred and Sixteen only.		<u>S 316.00</u>
Our Reference No. : RW/0011/16TP		
Vehicle No. : SKU 2569 Y		

SURVEYED WITHOUT PREJUDICE



RICHARD WONG
(Licensed Appraiser)



RW AUTOMOTIVE APPRAISERS SERVICES

(Licensed Appraisers & Claims Adjusters)
256 Bishan St. 22 #12-472 Singapore 570256
Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: + 65 6553 3912
Reg. No. 52821270B

Vitro Auto
c/o Auto Mega Mall Pte. Ltd.
24, Defu Lane 12
Singapore 539131

Report No : RW/0011/16TP
Date : 22.01.2016

VEHICLE INSPECTION REPORT

REFERENCE

Requested by : Workshop, owner's behalf
Date of Request : 11.01.2016
Date of Accident : 06.01.2016
Date of Inspection : 11.01.2016
Inspected at : Auto Mega Mall Pte. Ltd.
24, Defu Lane 12
Singapore 539131

VEHICLE DETAILS

Vehicle No.	: SKU 2569 Y	Make & Model	: Mercedes S350
Year Make	: 2011	Colour	: Black
Engine No.	: 27296531644740	Chassis No.	: WDD2211562A360024
Engine Capacity	: 3498 cc	Mileage	: 77,065 km
Air-Con	: Yes	Radio/CD/Cassette	: Yes
Seat Belt	: Yes	Rims	: Sport

GENERAL CONDITION OF VEHICLE

General Condition	: Good	Modification	: Nil
Brakes	: Serviceable	Handbrake	: Serviceable
Steering	: Serviceable		

<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Rim</u>	<u>Tread Balance</u>
Front Right	Continental	245/40 R20	Sport	6 mm
Front Left	Continental	245/40 R20	Sport	6 mm
Rear Right	Continental	245/40 R20	Sport	6 mm
Rear Left	Continental	245/40 R20	Sport	6 mm

ASSESSMENT

	<u>Repairer's Estimate</u>	<u>Recommendation</u>
Spare Parts	: \$ 3,277.95	\$ 3,277.95
Labour Charges	: \$ 1,190.00	\$ 810.00
Paint Work	: \$ 680.00	\$ 500.00
Towing Charges	: \$ -	\$ -
Total	: <u>\$ 5,147.95</u>	<u>\$ 4,587.95</u>
Recommend lump sum repairs	:	\$ 3,670.00
Reduction	:	<u>\$ 1,477.95</u>
Estimated Period Required for Repair	:	<u>4 days</u>



RW AUTOMOTIVE APPRAISERS SERVICES

(Licensed Appraisers & Claims Adjusters)

256 Bishan St. 22 #12-472 Singapore 570256

Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: + 65 6553 3912

Reg. No. 52821270B

Page : 1

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SKU 2569 Y

Report No.: RW/0011/16TP

<u>S/No</u>	<u>QTY</u>	<u>Description</u>	<u>Condition/Remarks</u>	<u>Repairer's Estimates</u>	<u>My Recommendation</u>
<u>REPLACEMENT OF DAMAGED PARTS</u>					
1)	1	Rear bumper	Cracked	\$ 1,267.70 N	\$ 1,267.70 ✓
2)	2	Rear bumper side holders	Necessary	\$ 83.60 N	\$ 83.60 ✓
3)	2	Rear bumper side chrome mouldings	Necessary	\$ 124.20 N	\$ 124.20 ✓
				<u>\$ 1,475.50</u>	<u>\$ 1,475.50</u>
			Less 10%	<u>\$ 147.55</u>	<u>\$ 147.55</u>
				<u>\$ 1,327.95</u>	<u>\$ 1,327.95</u>
4)	1	Rear wheel rim LH	Dented <i>CUT</i>	\$ 1,500.00 SN	\$ 1,500.00 <i>800</i>
5)	1	Rear tyre LH	Cut	\$ 450.00 SN	\$ 450.00 <i>1900</i> <i>x N/A</i>
		Total (Parts):		\$ 3,277.95	\$ 3,277.95

LABOUR CHARGES

6)	Panel beat rear left fender. Remove and replace all damaged parts.			\$ 600.00	\$ 400.00 <i>200</i>
7)	Check wiring and lightings.			\$ 50.00	\$ 30.00 ✓
8)	Remove and replace rear reverse sensors.			\$ 120.00	\$ 80.00 <i>50</i>
9)	Computerise wheel alignment.			\$ 150.00	\$ 120.00 <i>260</i>
10)	Perform diagnostic test.			\$ 150.00	\$ 120.00 <i>x N/A</i>
11)	Rust proofing treatment on affected area.			\$ 120.00	\$ 60.00 <i>x N/A</i>
12)	Spray painting on affected area.			\$ 680.00	\$ 500.00 <i>400</i>
		Total (Labour):		\$ 1,870.00	\$ 1,310.00 <i>740</i>
		Total:		\$ 5,147.95	\$ 4,587.95

2867.95
20% = 2300

3 days



RW AUTOMOTIVE APPRAISERS SERVICES

(Licensed Appraisers & Claims Adjusters)
256 Bishan St. 22 #12-472 Singapore 570256
Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: + 65 6553 3912
Reg. No. 52821270B

Page : 2

Vehicle No: SKU 2569 Y

Report No.: RW/0011/16TP

POINT OF IMPACT

At the left side rear of the vehicle.

RECOMMENDATION

The vehicle was inspected thoroughly based on the repairer's estimate against the actual damages found on the vehicle. My findings and recommendation are listed as per attached.

My adjusted amount for the cost of repair is \$4,587.95.

CONCLUSION

The repairer has agreed to undertake repairs at a lump sum of \$3,670.00 corresponding to labour charges, spray painting and replacement of parts.

SURVEYED WITHOUT PREJUDICE



RICHARD WONG
(Licensed Appraiser)



Your Ref: 18.24709.S.CK.jt

Date: 08th January 2019

Our Ref: CS3/AXA16000473/Gvbs2-1

M/s AXA Insurance Pte Ltd
C/o: Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKU 2569Y
INSURED VEHICLE: SKE 8591B
ACCIDENT DATE: 06/01/2016

We thank you for your instruction on 13/02/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKU 2569Y from M/s RW Automotive Appraisers Services.
- b) Singapore Accident Statement of Vehicles SKU 2569Y and SKE 8591B.
- c) Colour damaged vehicle photographs of SKU 2569Y.

Pre-Repair Inspection Date : 11/01/2016 at M/s SAT Motors, 24 Defu Lane 12
Singapore 539131.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKU 2569Y
Make & Model	: MERCEDES-BENZ S350
Year of Registration	: 2011
Chassis Number	: WDD2211562A360024
Engine Capacity	: 3498 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 2569Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	CRACKED	1,267.70	1,267.70
2	REAR BUMPER SIDE HOLDERS	NECESSARY	83.60	83.60
2	REAR BUMPER SIDE CHROME MOULDINGS	NECESSARY	124.20	124.20
	LESS 10% DISCOUNT		-147.55	-147.55
			1,327.95	1,327.95
SPECIAL NETT ITEMS				
1	REAR WHEEL RIM LH (SN)	CUT	1,500.00	800.00
1	REAR TYRE LH (SN)	NOT NECESSARY	450.00	-
			1,950.00	800.00
LABOUR				
	PANEL BEAT REAR LEFT FENDER. REMOVE AND REPLACE ALL DAMAGED PARTS.		600.00	200.00
	CHECK WIRING AND LIGHTINGS.		50.00	30.00
	REMOVE AND REPLACE REAR REVERSE SENSORS.		120.00	50.00
	COMPUTERISED WHEEL ALIGNMENT.		150.00	60.00
	PERFORM DIAGNOSTIC TEST.	NOT NECESSARY	150.00	-
	RUST PROOFING TREATMENT ON AFFECTED AREA.	NOT NECESSARY	120.00	-
	SPRAY PAINTING ON AFFECTED AREA.		680.00	400.00
			1,870.00	740.00
GRAND TOTAL			5,147.95	2,867.95
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CS3/AXA16000473/Gvbs2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.