



Your Ref: 18.24709.S.CK.jt

Date: 08th January 2019

Our Ref: CS3/AXA16000473/Gvbs2-1

M/s AXA Insurance Pte Ltd

C/o: Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKU 2569Y

INSURED VEHICLE: SKE 8591B

ACCIDENT DATE: 06/01/2016

We thank you for your instruction on 13/12/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKU 2569Y from M/s RW Automotive Appraisers Services.
- b) Singapore Accident Statement of Vehicles SKU 2569Y and SKE 8591B.
- c) Colour damaged vehicle photographs of SKU 2569Y.

Pre-Repair Inspection Date : 11/01/2016 at M/s SAT Motors, 24 Defu Lane 12
Singapore 539131.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKU 2569Y
Make & Model	: MERCEDES-BENZ S350
Year of Registration	: 2011
Chassis Number	: WDD2211562A360024
Engine Capacity	: 3498 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.