

Surveyor:

REF: CS3 / AXA16000473 / GVB-1

Special Instruction:

46-# 3670.00

ASSIGNMENT (Office)

From (Person): Tan Chee Keong of Seahong Date/Time: 13/12/18

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: RW Automotive

Workshop: Auto Mega Mall

OD/TP Re-inspection (Evaluation)

To Inspect Vehicle No: SKU 2569Y Insured: SKE 8591B

at Workshop m/s Auto Mega Mall Tel:

of 24 Dava Lane 12

Policy No: Claim No: 18-24709-S.CK.JT

Sum Insured: Excess:

Make of Veh: D.O.A. 06.01.2016


(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig, days (Red \$ / %; Original 4 days)

Date/Time: 4/1/19 Submit Final Fig 2200, 4 days (Red \$ 1370 / 37 %; Original days)

Date/Time	Action/Instruction
	SKU 2569Y - CS3 / AXA16000473 / Gbd1
	SKE 8591B - X
	DOA: 06012016
	RECEIVED 04 JAN 2019
	
	10/1/2019

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value : _____	Inspected/ Evaluated by:	Fee Charged:	Date: <table border="1"><tr><td> </td></tr><tr><td> </td></tr><tr><td> </td></tr></table>			
Salvage Value : _____	Basic & Add					
Nett Value : _____	Transport					
	Photos					
	Others					
	Total					

- 1) Date/Time 4/1-typist File Pass to \_\_\_\_\_ 2) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_
- 3) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_ 4) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_
- 5) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_ 6) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_