



Your Ref: C0471569

Date: 02nd Jan 2019

Our Ref: CS3/AXA18004045/Btbe2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01
Axa Tower
Singapore 068811
(The Motor Claims Department)

Attn : Gayatri

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKW 8761H
INSURED VEHICLE: PUBLIC LIABILITY
ACCIDENT DATE: 23/02/2018**

We thank you for your instruction on 13/12/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of from M/s Carlink Consultancy.
- b) Singapore Accident Statement of Vehicles SKW 8761H.
- c) Final Repair Bill of SKW 8761H from Bak Heng Motor Repairing Co.
- d) Colour damaged vehicle photographs of SKW 8761H.

Pre-Repair Inspection Date : 02/03/2018 at M/s Bak Heng Motor Repairing Co, Block 5032 Ang Mo Kio Industrial Park II, #01-291, Singapore 569535.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKW 8761J
Make & Model	: Honda Vezel 1.5S A
Year of Registration	: 2015
Chassis Number	: RU11105652
Engine Capacity	: 1496 cc

2. We recommend that the repairs of the entire damage require about 4(Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.