

<<

Service Request Details

Claim

S8M015XQ

Reference

CS/ASM18022502/Ktd3s2 

Loss Date

December 9, 2018

Request Date

December 14, 2018

Due Date

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident Vehicle Registration #

SKX5640M

Make

HONDA

Model

VEZEL 1.5

Service Address

Blk 1 Sin Ming Industrial, , 575636

Primary Contact/Insured

TANG KOK CHIEN
79D TOA PAYOH CENTRAL, #05-59, 314079, Singapore
98554768
mervin.tang@hotmail.com

Claim Handler

KHONG Lynn
68804892
lynn.khong@axa.com.sg

Additional Instructions

BH Auto OD Excess \$300

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
Document Type						
Document SubType						
+ Upload Documents						
NAME	TYPE	SUB-TYPE	AUTHOR	DATE	UPLOADED	
 Accident Statement	Reports & Statement		Merimen			
 LKKInvoice1[5].pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (OD)	January 30, 2019		
 PARTS INVOICE.pdf	Invoice	Spare Part / Accessories Supplier	LKK AUTO CONSULTANTS PTE LTD (OD)	January 30, 2019		
 GIA RPT.pdf	Reports & Statement	GIA Report	LKK AUTO CONSULTANTS PTE LTD (OD)	January 30, 2019		
 SKX 5640M photo.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	January 29, 2019		
 Resurvey photo.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	January 29, 2019		

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 SKX5640M AUDATEX ESTIMATE.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	December 18, 2018
 PRELI ADVISED SKX 5640M.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	December 18, 2018
 BAC00055.pdf	Forms / Claim Documents	Estimate / Quotation	BH AUTO SERVICES PTE LTD	December 13, 2018
 GA288825-Policy Schedule.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	WANG Peter	December 11, 2018