

ASS. REC. BY:

REF

CS/SM018022512/TIVD3

n2

Special Instruction:

Surveyor

Merimen

Taufik

ASSIGNMENT (Office)

From (Person):

Gmoh Pau loong

of

SMO

Date/Time:

14/12/18 @ 3.31pm

Estimated Cost:

Bill to:

OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJU 51781

Insured:

8KA 6699J

at Workshop m/s

zhong cheng Enterprise

Tel:

9338 2859

of

Blk 6, Woodlands Rd, 3995 Yeeew Tee Ind.

Policy No:

D18MTPV01014009

Claim No:

CMTD1805527

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/12/2018

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

3:48pm @ 14/12/18

Person Contacted:

Ms. Sini

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJU 51785-X
	8KA 6699J-CS/MSG14023748/Klvbd1 DOA: 22/12/2014
17/12/18-	VNI yet
19/12/18-	Reputer average on 20/12/2018
	pending Estimate from Reputer.
21/12/18	Informed Pau loong pending workshop est via merimen

REF: 3070

REF: 3070

ASSIGNMENT

From: Date: 20/12/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJU 5178J

at Workshop m/s: Zhong Cheng

of Blk 6, Woodlands Rd, 399J Yew Tee

Insured Ind. Estate

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

415K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date:

Person Contacted:

Vehicle: IN / OUT

Sim

Veh No: SJU 5178J

Yr Regn: 2009 / Dec

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia Cerato EX 1.6 c.c. 1591

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading:

88282

T/Radio: Insured / Std / NI / NA

Eng/No:

-

C/Nr:

1CNA9F0411M45138689

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~order~~ / Jammed / Leaked / Burnt or

Brake: ~~order~~ / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65 R15

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO ~~YOKO~~ or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

20/12/18

Survey held at

Zhong Cheng

Des. of Damages: Frt / Rear / O/S / ~~N/S~~ / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/2/19

confirm

(Red

4/54 4450, 7 days
8576.10, 6695

with Sim's phone

[Signature]

13/2/2019

RECEIVED 29 MAR 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 29/2 - typist

Days Of Repair: 7

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

\$ + R5 \$

) Photos

) Others

)

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format:

merimen

Lump Sum / I.B.I. (\$

4450/2

350

10

360

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Dec 2018		14 Dec 2018 15:31 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIM CHEE TET, ID: S0227728Z, Tel: +6597333378, Email: NOEMAIL		
Main Claimant:	LIM KHIENG SIONG, ID: S7040643H		
Vehicle Reg. No.:	SJU5178J	Date of Loss:	12/12/2018 22:00 - :59
Claim Type:	TP / CMTD1805527	Policy/Cover Note No.:	D18MTPV01014009 (Comprehensive)
Vehicle Reg. No. (Insured):	SKA6699J	Policy No. (Claimant):	
		Excess:	
Repairer:	Zhong Cheng Enterprise Pte Ltd - Woodlands (HQ) BLK 6 WOODLANDS ROAD, 399J YEW TEE INDUSTRIAL ESTATE, 678008 Woodlands - Tel: 67694686		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/12/2018]		
Driver/Custodian (Insured):	LIM CHEE TET (64 / Male), NRIC: S0227728Z, Tel: +6597333378		
Adj Asg. Remarks:	Please assign to Mr Mohd Taufikh to conduct the survey. Contact Person : Ms Sini / Winson Telephone : 9338 2859 / 9750 6777		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Zhong Cheng <zhongchengauto@gmail.com>
Sent: Thursday, 14 February 2019 1:59 PM
To: Veron Chen (LKKAUTO)
Cc: SUR
Subject: Re: SJU 5178J-DOA: 12/12/2018

Dear Veron,

Please check with Taufikh on the dismantled pictures.

Speaker damaged, front door inner lock jammed, RR door upper hinge damaged.

Thanks

Best Regards
Sini Tan
Zhong Cheng Enterprise Pte Ltd
Blk 6, 399J
Yew Tee Industrial Est
S678008
HP: 93382859 Fax: 68942883

On Wed, Feb 13, 2019 at 5:34 PM Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Sini,

WITHOUT PREJUDICE

Offer Lump Sum \$4200/- @ 7 days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Zhong Cheng <zhongchengauto@gmail.com>

Sent: Wednesday, 2 January 2019 3:47 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: Re: SJU 5178J-DOA: 12/12/2018

Dear Veron,

Dismantle and after paint pics fyi.

Thanks

Best Regards

Sini Tan

Zhong Cheng Enterprise Pte Ltd

Blk 6, 399J

Yew Tee Industrial Est

S678008

HP: 93382859 Fax: 68942883

On Wed, Jan 2, 2019 at 2:44 PM Zhong Cheng <zhongchengauto@gmail.com> wrote:

Dear Veron,

Happy New Year.

Please see attached.

Thank you

Best Regards

Sini Tan

Zhong Cheng Enterprise Pte Ltd

Blk 6, 399J

Yew Tee Industrial Est

S678008

HP: 93382859 Fax: 68942883

On Wed, Jan 2, 2019 at 2:41 PM Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Sini,

Kindly forward us vehicle estimate.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: Zhong Cheng <zhongchengauto@gmail.com>
Sent: Wednesday, 2 January 2019 2:45 PM
To: Veron Chen (LKKAUTO)
Cc: SUR
Subject: Re: SJU 5178J-DOA: 12/12/2018
Attachments: Estimate for SJU5178J kia fortexls.pdf; Labour Estimate for SJU5178J kia fortexls.pdf

Dear Veron,

Happy New Year.

Please see attached.

Thank you

Best Regards
Sini Tan
Zhong Cheng Enterprise Pte Ltd
Blk 6, 399J
Yew Tee Industrial Est
S678008
HP: 93382859 Fax: 68942883

On Wed, Jan 2, 2019 at 2:41 PM Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Sini,

Kindly forward us vehicle estimate.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0643H
Vehicle Details	
Vehicle No.:	SJU5178J
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jan 2019
Vehicle Make:	KIA
Vehicle Model:	CERATO EX FORTE 1.6L A/T ABS AB 2WD 4DR
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	G4FC9H304853
Chassis No.:	KNAFU411MA5138689
Maximum Power Output:	92.7 kW (124 bhp)
Open Market Value:	\$10,956.00
Original Registration Date:	15 Dec 2009
First Registration Date:	15 Dec 2009
Transfer Count:	0
Actual ARF Paid:	\$10,956.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Dec 2019
PARF Rebate Amount:	\$5,478.00
Intended COE Rebate Details	
COE Expiry Date:	14 Dec 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$17,189.00
COE Rebate Amount:	\$1,631.00
Total Rebate Amount:	\$7,109.00

The information contained herein is correct as at 02 Jan 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/12/2018 13:20
Date Of Accident	12/12/2018 22:30
Exact Location Of Accident	X-JUNCTION OF JURONG GATEWAY RD & BOON LAY WAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJU5178J
Insured/Policyholder	
Name Of Registered Owner	LIM KHIENG SIONG
NRIC No	S7040643H
Email Address	STORMTROOPER_LKS@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96850189
Alternative Phone No	Office-96850189

Vehicle Particulars

Manufacturer	KIA
Model	CERATO FORTE-1.6 L EX (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	ETIQA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	M0002892
Cover Note Number	

Driver

Name of Driver	LIM KHIENG SIONG
NRIC No	S7040643H
Date Of Birth	12/11/1970
Occupation	INDOOR
Date Of Driving Pass	30/08/1996
Driving Experience	22 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96850189

Fax Number	
Contact Number	OFFICE-96850189
EMail Address	STORMTROOPER_LKS@YAHOO.COM.SG
Address	BLOCK 3 GHIM MOH ROAD #06-290
Postcode	1027
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	CLEMENTI NPC - PLEASE REFER TO THE ATTACHED POLICE REPORT
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Please refer to the attached Police Report and the Sketch Plan for the accident details

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKA6699J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM CHEE TET
NRIC/Passport Number	S0227728Z
Contact Number	97333378

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

 1200HK
12/12/19

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

A: SSUS17BJ
B: SKA6699J

A: 55u5172J
B: 5KA6699J

ON 12 DEC 2018 AT ABOUT 2230HR, I WAS ALONG JUBA GATEWAY ROAD
ON THE
REFER TO POLICE REPORT T~~1300~~ T/20181213/2003
INSURER: ETIQA INSURANCE BERHAD
INS-NO. 1 M0002892.

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20181213/2003

1 of 4

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

Report No. T/20181213/2003

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/12/2018 00:28		Vide Report No.: D/20181212/0131		Station Diary No.: 8	
Informant's Particulars					
Name of Informant: LIM KHIENG SIONG			Address: APT BLK 3 GHIM MOH ROAD #06-290 SINGAPORE 270003		
ID Type / ID No.: NRIC NO / S7040643H			Contact No.: Home/Office: Mobile: 96850189		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 48	Date of Birth: 12/11/1970	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: WAREHOUSE ASSISTANT MANAGER			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident				
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 12/12/2018 22:30	Type of Location: X-Junction
Location: Along Road 1 JURONG GATEWAY ROAD Along Jurong Gateway Road turning right into Boon Lay Way				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJU5178J	Car	KIA	CERATO EX FORTE 1.6L A/T ABS AB 2WD 4DR	Blue	Seriously Damaged	0
SKA6699J	Car	MERCEDES BENZ	E250	Black		0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date



**SINGAPORE
POLICE FORCE**



T/20181213/2003

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

2 of 4

Report No. T/20181213/2003

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJU5178J	ETIQA INSURANCE BERHAD	M0002892	15/12/2017	14/12/2018

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LIM KHIENG SIONG	ID No.	S7040643H
Related Vehicle	SJU5178J (Car)	Contact No.	96850189
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LIM CHEE TET	ID No.	S0227728Z
Related Vehicle	SKA6699J (Car)	Contact No.	97333378
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 12/12/2018 at about 2230hrs, I was along Jurong Gateway Road on the first lane. The traffic light was red and I was waiting to turn right into Boon Lay Way. When the traffic light turned green, I inched my vehicle forward and subsequently stopped as there was oncoming traffic. Suddenly, I felt a knock on the left side of my vehicle. The vehicle then continued its way and then hit onto some part of Ng Teng Fong General Hospital which is diagonal from where I was. I moved my car aside and attended to the driver. Afterwards, I called for the police. My vehicle suffered dents and scratches on both the left doors. Now, it is unable to open and close properly. My wheel alignment is also having issues after the said accident. At that point of time nobody was injured.

Police and Ambulance were at scene. I was advised to lodge a police report at any police station.



**SINGAPORE
POLICE FORCE**



T/20181213/2003

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

3 of 4

Report No. T/20181213/2003

CONTINUATION OF REPORT





**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999



T/20181213/2003

4 of 4

Report No. T/20181213/2003

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /

Sgt 2 MUHAMMAD AIZAT BIN AMIR

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt SYED ZAYID MUHAMMAD BIN
SYED ABDUL WAHID ALHINDUAN

Contact No: 65476394

Authentic  SINGAPORE
POLICE FORCE
NP168

SN 37

SIGNATURE

Signature Of Informant:

Date/Time:

13/12/2018 00:28

Classification Of Case:

Sketch Plan #3



INTERVIEW FORM

Name (Driver) : LIM KHENG SIONG

Policy No : ETIQA M10002892

Vehicle No : SJU 5178 J

Place of Accident : CROSS JUNCTION OF JURONG CATEWAY RD + BOON LAY WAY

Insured Driver's relationship with Insured : SELF

Drink Driving of Insured and/or Insured Driver : N.A.

No of passenger(s) in Insured vehicle : N.A.

Injury to Insured and/or Insured driver, please indicate which hospital:
N.A.

Third Party Vehicle No (if any) : SKA 6699 J

No of passenger(s) in Third Party Vehicle : DRIVER ONLY

Injury to Third Party driver and/or passenger(s), please indicate which hospital:
N.A.

Type of collision and the extensiveness of the damages to all vehicles/Third Party property involved:
SIDE SWIPE

Any witness to the accident (if yes, please indicate Name, Contact No and a copy of the statement):
N.A.

Traffic Police report (enclosed) : ☒ Yes ☐ No

Please obtain a copy of the driving licence of Insured driver and/or work permit (where foreign worker is involved)

K 13/12/18
Driver (Name & Signature)
I, affirmed the above information is given to
my best knowledge

Attended by (Name & Signature)

Workshop Name: _____

Etiqa Insurance Berhad (topi/Coopak)
One Raffles Quay, #22-01 North Tower, Singapore 048583
T +65 6336 0477 F +65 6339 2109 www.etiqa.com.sg

A Member of Maybank Group

Identity Card

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S7040643H



Name

LIM KHIENG SIONG



林景祥

Race

CHINESE

Date of Birth

12-11-1970

Sex

M

Country of Birth

SINGAPORE



1797753

NRIC No. S7040643H



Blood Group

B+

Date of issue

18-03-1994

Address

APT BLK 3 GHIM MOH ROAD
#06-290
SINGAPORE 1027

Driving License

Vehicle no. : SJU5178J
Model : KIA FORTE

Estimate - Parts(s)

S/N	Qty	Descriptions	Amount
LIST ITEMS:-			
1	1	FR door LH	\$ bt 785.00
2	1	FR door hindge upper LH	\$ Ry 55.00
3	1	FR door hindge lower LH	\$ Ry 49.00
4	1	FR door outer moulding LH	\$ nu x 74.00
5	1	FR door weatherstrip LH	\$ ne 150.00
6	1	FR outer handle	\$ wt 83.00
7	1	FR door inner lock	\$ 237.00 jn
8	1	FR outer key cylinder	\$ nu x 234.50
9	1	FR door inner trim board	\$ dex 595.00 395
10	1 set	FR door inner trim board clips	\$ ne 18.00
11	2	FR door frame garnish	\$ nu x 36.00
12	1	FR door window glass	\$ nu x 259.00
13	1	FR door window glass guide	\$ nu x 54.00
14	1	FR window regulator	\$ bt 493.00 370
15	1	FR window regulator motor	\$ nu x 395.00
16	1	RR door LH	\$ bt 785.00
17	1	RR door hindge upper LH	\$ Ry 55.00 bt
18	1	RR door hindge lower LH	\$ Ry 49.00
19	1	RR door outer moulding LH	\$ nu x 74.00
20	1	RR door weatherstrip LH	\$ nu 150.00
21	1	RR outer handle	\$ x 83.00
22	1	RR door inner lock	\$ x 237.00
23	1	RR outer key cylinder	\$ x 234.50
24	1	RR door inner trim board	\$ x 595.00
25	1 set	RR door inner trim board clips	\$ x 18.00
26	2	RR door frame garnish	\$ nu x 36.00
27	1	RR door window glass	\$ x 259.00
28	1	RR door window glass guide	\$ x 54.00
29	1	RR window regulator	\$ x 493.00
30	1	RR window regulator motor	\$ x 395.00
31	1	Centre panel/pillar LH	\$ Ry 975.00
32	1	Centre panel/pillar inner trim	\$ nu x 205.00
33	1	Rocker panel LH	\$ dex 746.00 546
34	1	Side mirror assy LH *	\$ Ry 525.00
35	1	FR lock stricker LH*	\$ nu x 36.00
3	1	RR speaker	\$ 179.00 nu
4	1	FR door inner trim board sponge	\$ nu x 12.00
5	1	FR door sticker black	\$ ne 58.00
6	1	RR door sticker black	\$ ne 58.00
Less 10%			\$ 9,829.00
			\$ 8,846.10

Special Nett

1	1	RR window moulding	\$ x 105.00
2	1	FR window moulding	\$ nu x 105.00
3	1	FR window tinted flim	\$ x 130.00
4	1	RR window tinted flim	\$ x 130.00
			\$ 470.00

Sub - Total \$ 9,316.10

Vehicle no. : SJU5178J
Model : KIA FORTE

Estimate - Labour(s)

S/N	Qty	Descriptions	Amount
-----	-----	--------------	--------

B/F

LABOUR & OTHER CHARGES:-

1		To panel beat and renewal of all necessary damaged body parts	\$ 1,400.00
2		To check wiring and rewire	\$ 30 120.00
3		To remove and reinstall front/rear door components	\$ 120 200.00
5		To anti-rust	\$ 40 140.00
6		To putty and spray-paint of affected areas	\$ 1000 1,600.00
7		To remove/refix/cleanse inner cushion	\$ 60 x 250.00

\$ 3,710.00

13,026.10

250.2090

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parts -

3500.10

Labour -

2090

5590.10

4144450 *

7 days

Grand - Total

\$

-

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18022512/T1VD3N2

Date: 02/04/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01014009
Claimant Vehicle No :	SJU5178J	Insured Vehicle No :	SKA6699J
Date of Loss:	12/12/2018	Nature of Claim:	TP
		Claim No:	CMTD1805527

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU5178J	Engine No:	G4FC9H304853
Make & Model:	KIA CERATO, 1.6 EX (A)	Chassis No:	KNAFU411MA5138689
Reg. Date:	15/12/2009 (Man. Year: 2009)	Odometer:	88282 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,316.10	3,500.10	5,816.00	62.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,710.00	2,090.00	1,620.00	43.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,026.10	5,590.10	7,436.00	57.09
Approved Total (Overridden) (S\$)		4,450.00		
Nett Amount (S\$)	13,026.10	4,450.00	8,576.10	65.84

INSPECTION

Date of Assignment: 14/12/2018

Date Inspected: 20/12/2018 Inspected At:

Zhong Cheng Enterprise Pte Ltd -
Woodlands (HQ)
BLK 6 WOODLANDS ROAD, 399J
YEW TEE INDUSTRIAL ESTATE
Singapore 678008

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 02 Apr 2019)
Parts: 143	KIA CERATO 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJU5178J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FR DOOR LH	Bent	785.00 FL	*785.00 FL
2	1		*FR DOOR HINGE UPPER LH	Repair	55.00 FL	*- FL
3	1		*FR DOOR HINGE LOWER LH	Repair	49.00 FL	*- FL
4	1		*FR DOOR OUTER MOULDING LH	Not Necessary	74.00 FL	*- FL
5	1		*FR DOOR WEATHERSTRIP LH	Necessary	150.00 FL	*150.00 FL
6	1		*FR OUTER HANDLE	Cut	83.00 FL	*83.00 FL
7	1		*FR DOOR INNER LOCK	Jammed	237.00 FL	*237.00 FL
8	1		*FR OUTER KEY CYLINDER	Not Necessary	234.50 FL	*- FL
9	1		*FR DOOR INNER TRIM BOARD	Deformed	595.00 FL	*395.00 FL
10	1		*SET FR DOOR INNER TRIM BOARD CLIPS	Necessary	18.00 FL	*18.00 FL
11	2		*FR DOOR FRAME GARNISH	Not Necessary	36.00 FL	*- FL
12	1		*FR DOOR WINDOW GLASS	Not Necessary	259.00 FL	*- FL
13	1		*FR DOOR WINDOW GLASS GUIDE	Not Necessary	54.00 FL	*- FL
14	1		*FR WINDOW REGULATOR	Bent	493.00 FL	*390.00 FL
15	1		*FR WINDOW REGULATOR MOTOR	Not Necessary	395.00 FL	*- FL
16	1		*RR DOOR LH	Bent	785.00 FL	*785.00 FL
17	1		*RR DOOR HINGE UPPER LH	Bent	55.00 FL	*55.00 FL
18	1		*RR DOOR HINGE LOWER LH	Repair	49.00 FL	*- FL
19	1		*RR DOOR OUTER MOULDING LH	Not Necessary	74.00 FL	*- FL
20	1		*RR DOOR WEATHERSTRIP LH	Necessary	150.00 FL	*150.00 FL
21	1		*RR OUTER HANDLE	Not Necessary	83.00 FL	*- FL
22	1		*RR DOOR INNER LOCK	Not Necessary	237.00 FL	*- FL
23	1		*RR OUTER KEY CYLINDER	Not Necessary	234.50 FL	*- FL
24	1		*RR DOOR INNER TRIM BOARD	Not Necessary	595.00 FL	*- FL
25	1		*SET RR DOOR INNER TRIM BOARD CLIPS	Not Necessary	18.00 FL	*- FL
26	2		*RR DOOR FRAME GARNISH	Not Necessary	36.00 FL	*- FL
27	1		*RR DOOR WINDOW GLASS	Not Necessary	259.00 FL	*- FL
28	1		*RR DOOR WINDOW GLASS GUIDE	Not Necessary	54.00 FL	*- FL
29	1		*RR WINDOW REGULATOR	Not Necessary	493.00 FL	*- FL
30	1		*RR WINDOW REGULATOR MOTOR	Not Necessary	395.00 FL	*- FL
31	1		*CENTRE PANEL /PILLAR LH	Repair	975.00 FL	*- FL
32	1		*CENTRE PANEL /PILLAR INNER TRIM	Not Necessary	205.00 FL	*- FL
33	1		*ROCKER PANEL LH	Deformed	746.00 FL	*546.00 FL
34	1		*SIDE MIRROR ASSY LH	Repair	525.00 FL	*- FL
35	1		*FR LOCK STICKER LH	Not Necessary	36.00 FL	*- FL
36	1		*RR SPEAKER	Cracked	179.00 FL	*179.00 FL
37	1		*FR DOOR INNER TRIM BOARD SPONGE	Not Necessary	12.00 FL	*- FL
38	1		*FR DOOR STICKER BLACK	Necessary	58.00 FL	*58.00 FL
39	1		*RR DOOR STICKER BLACK	Necessary	58.00 FL	*58.00 FL
40	1		*RR WINDOW MOULDING	Not Necessary	105.00 FS	*- FS
41	1		*FR WINDOW MOULDING	Not Necessary	105.00 FS	*- FS
42	1		*FR WINDOW TINTED FLIM	Not Necessary	130.00 FS	*- FS
43	1		*RR WINDOW TINTED FLIM	Not Necessary	130.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (\$\$)	10,299.00	3,889.00
				- List Item Discount on L Items 10.00/10.00% (\$\$)	982.90	388.90
				Total Parts (\$\$)	9,316.10	3,500.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	1,400.00	900.00
2	TO CHECK WIRING AND REWIRE	New	120.00	30.00
3	TO REMOVE AND REINSTALL FRONT /REAR DOOR COMPONENTS	New	200.00	120.00
4	TO ANTI-RUST	New	140.00	40.00
5	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS	New	1,600.00	1,000.00
6	TO REMOVE/REFIX/CLEANSE INNER CUSHION	New	250.00	0.00
Gross Labour Cost (S\$)			3,710.00	2,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >