

ASS. REC. BY:

REF:

CS3/CTI/8022527/Gcd304

Special Instruction:

Surveyor:  
Munir

Gudo Qiang

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

14/12/18 01:51pm

Estimated Cost:

Bill to:

OD ☒ WS/TP RES / OD RES / EVA / INV / MV7 CS

To Inspect Vehicle No:

FBN3456B

Insured:

GX5967T

at Workshop m/s

H. L. Cycle

Tel:

9748 9940

of

1 Kaki Bukit Ave 6 # 02-58 Autobay

Policy No:

DMCVSN 3042661800

Claim No:

JNM18D0571C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

07/12/18

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

207pm 14/12/18

Person Contacted:

Shawn

Vehicle ☒ IN/OUT

Date/Time	Action/Instruction (x) Estimate
	FBN3456B-X
	GX5967T-X
	Dismantle: 18/12/2018

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s H.L. cycle

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: FBV3456B Yr Regn: 30 OCT 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Piaggio Vespa c.c. 278Colour: red A/C: Insured / Std / NI / NASp. Reading: 2015 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: ZAPMA 33000000 4732Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: M / S/Rim / STD A/Rim orTyre Size: F: 120/70-12R: 130/70-12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mm

D.O.A. \_\_\_\_\_

D.O.I. 14-12-18Survey held at W/S3:50pmDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$3000 - \$4000

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 1Survey Fee: 150

Transportation: \_\_\_\_\_

Add Fee:

☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech. Invs (\$)  
☐ : Weekend (\$ )

) \$ + RS. \$ SI

) Photos

) Others

TOTAL

150Report Format : PRS.

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Dec 2018		14 Dec 2018 13:51 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	HAO DA PTE LTD, Co. Reg. No.: 198800426R		
Main Claimant:	RENNIS ROY D'CECIL, ID: S9010920J		
Vehicle Reg. No.:	FBN3456B	Date of Loss:	07/12/2018 16:00 - :59
Claim Type:	TP / SNM18D05710C02	Policy/Cover Note No.:	DMCVSN3042661800 (Third Party Only)
Vehicle Reg. No. (Insured):	GX5967T	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	H L Cycle Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #02-58 Autobay, 417883 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/12/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Lucas Lee**

---

**From:** Alfred Ng <alfred\_ng@juseq.com.sg>  
**Sent:** Friday, 14 December, 2018 9:40 AM  
**To:** Lucas Lee  
**Subject:** ACCIDENT INVOLVING FBN3456B AND GX5967T ON 7 DECEMBER 2018

Your ref: SNM18d05710C02  
Our ref: JEQ/180964/1218/HC/PI

Dear Lucas,

We refer to your email yestersday.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

1. Absolute Appraisal Services Pte Ltd;
2. Sincere Appraisal Services;
3. Mc Coy Appraiser Pte Ltd;
4. Delta V Consultant
5. Prominent Appraisal Services Pte Ltd;
6. Advance Automotive Consultancy Pte Ltd;
7. Pal's Appraiser Pte Ltd;
8. S K Auto Consultants;
9. Oh Appraisal Services;
10. C L Appraiser Pte Ltd.

Please be informed that if the above mentioned surveyors is not agreeable by you, our clients' motor vehicle is available for pre-repair inspection at the under-stated workshop:-

**H L CyclePte Ltd**

1 Kaki Bukit Ave 6  
#02-58/60 , Auto Bay @Kaki Bukit  
Singapore 417883  
Contact Person : Mr Shawn Tan  
Mobile: 9748-9940.  
Fax: 6484-44342

\* Further, please remind your appointed surveyor to request for post repair inspection if you wish to do so under NIMA Protocol Appendix C paragraph 2.11

With Regards

Alfred Ng  
Executive  
On behalf of Mr Michael Yap  
M/s JusEquity Law Corporation  
No. 171 Chin Swee Road  
#02-01/02/06 Singapore 169877  
Tel : 6536 9339  
Fax: 6536 5368

**IMPORTANT NOTICE:**

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0920J
Vehicle Details	
Vehicle No.:	FBN3456B
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Dec 2018
Vehicle Make:	PIAGGIO
Vehicle Model:	VESPA GTS SUPER/SUPERSPORT 300 E4
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	MA33M1003700
Chassis No.:	ZAPMA330000004732
Maximum Power Output:	-
Open Market Value:	\$4,734.00
Original Registration Date:	30 Oct 2018
First Registration Date:	30 Oct 2018
Transfer Count:	1
Actual ARF Paid:	\$711.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Oct 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$3,951.00
COE Rebate Amount:	\$3,896.00
<b>Total Rebate Amount:</b>	<b>\$3,896.00</b>

The information contained herein is correct as at 18 Dec 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/12/2018 15:47
Date Of Accident	07/12/2018 16:50
Exact Location Of Accident	CHOA CHU KANG WAY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBN3456B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	RENNIS ROY D'CECIL
NRIC No	S9010920J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-85336644
Alternative Phone No	OFFICE-85336644

### Vehicle Particulars

Manufacturer	PIAGGIO
Model	VESPA GTS SUPER/SUPERSPORT 300 E4
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5105135998
Cover Note Number	

### Driver

Name of Driver	RENNIS ROY D'CECIL
NRIC No	S9010920J
Date Of Birth	29/03/1990
Occupation	INDOOR
Date Of Driving Pass	28/07/2011
Driving Experience	7 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85336644
Fax Number	

Address	BLK 655 WOODLANDS RING ROAD #09-316
Postcode	730655
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CHEN ZHI HAO GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GX5967T
Vehicle Make/Model/Colour	PICK UP NISSAN SILVER
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	UDCHACHON THAWORN
NRIC/Passport Number	F7355871U
Contact Number	91594979



Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


**DETAILS OF INJURED PERSON 1**

Name	RENNIS ROY D'CECIL
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBN3456B
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 655 WOODLANDS RING ROAD #09-316
Postcode	730655

**DETAILS OF INJURED PERSON 2**

Name	CHEN ZHI HAO
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBN3456B
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan #3 Pg. 1



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## SKETCH PLAN


## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


A hand-drawn sketch plan on a grid background. The sketch depicts a road labeled 'ROAD' and a vehicle labeled 'POLICE'.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# SINGAPORE POLICE FORCE



T/20181212/7006

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 4

Report No. T/20181212/7006

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 12/12/2018 14:00		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: RENNIS ROY D'CECIL			Address: APT BLK 655 WOODLANDS RING ROAD #09-316 SINGAPORE 730655		
ID Type / ID No.: NRIC NO / S9010920J			Contact No.: Home/Office: Mobile: 85336644		
Nationality: SINGAPORE CITIZEN			Email: renniscecil@gmail.com		
Sex: Male	Age: 28	Date of Birth: 29/03/1990	Type of Informant: Rider		
Race: Indian			Language: English		Institution / School Name:
Occupation: SAF REGULAR			Driving Licence Information: Class: 2B,2A,2,3		Date of Expiry:

## General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 07/12/2018 16:50	Type of Location: Straight Road
Location:  CHOA CHU KANG WAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBN3456B	Motorcycle	PIAGGIO	VESPA GTS SUPER/SUPERSPORT 300 E4	Red	Seriously Damaged	1
GX5967T	PICK UP	NISSAN	P/UP LOWBED	Silver	Slightly Damaged	0



Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

**CONTINUATION OF REPORT**

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBN3456B	NTUC Income Insurance Co-Operative Limited	5105135998	30/10/2018	29/10/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA		
Rider				
Name	RENNIS ROY D'CECIL	ID No.	S9010920J	
Related Vehicle	FBN3456B (Motorcycle)	Contact No.	85336644	
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL	
Date Treatment	07/12/2018	Date Discharge	07/12/2018	
No. of Days granted Medical Leave	04	Degree of Injury	Serious	
Pillion				
Name	CHEN ZHI HAO	ID No.	S9322222I	
Related Vehicle	FBN3456B (Motorcycle)	Contact No.	97322549	
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL	
Date Treatment	07/12/2018	Date Discharge	07/12/2018	
No. of Days granted Medical Leave	02	Degree of Injury	Slight	
Driver				
Name	UDCHACHON THAWORN	ID No.	F7355871U	
Related Vehicle	GX5967T (PICK UP)	Contact No.	91594979	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL	
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	



**SINGAPORE  
POLICE FORCE**



T/20181212/7006

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 4

Report No. T/20181212/7006

**CONTINUATION OF REPORT**

Brief Details.

I WAS RIDING MY MOTORCYCLE ALONG CHOA CHU KANG WAY TOWARDS SUNGEI KADUT DRIVE ON THE EXTREME LEFT LANE OF THE THREE LANE ROAD WHEN A PICKUP TRUCK IN THE MIDDLE LANE SUDDENLY SWERVED INTO MY LANE WITHOUT SIGNALLING. THE FRONT PORTION OF THE PICKUP HIT ON THE RIGHT SIDE OF MY MOTORCYCLE, CAUSING ME TO LOSE BALANCE AND FALL.

THE DRIVER STEPPED OUT & ADMITTED HIS MISTAKE & CALLED HIS EMPLOYER TO SCENE. HIS EMPLOYER CAME DOWN TO SCENE & WROTE A PIECE OF PAPER INDICATING THAT THEY ARE TAKING FULL RESPONSIBILITIES FOR THE DAMAGES ON MY MOTORCYCLE & INJURIES OF MY PILLION & MYSELF.

MY PILLION & I THEN PROCEEDED TO KHOO TECK PUAT HOSPITAL TO INSPECT OUR INJURIES. I WAS AWARDED 04 DAYS MC & MY PILLION WAS AWARDED 02 DAYS MC.

AFTER COMPLETION OF MY 04 DAYS MC, I THEN PROCEEDED TO 888 PLAZA FAMILY CLINIC AS MY INJURIES DID NOT GET BETTER & I WAS AWARDED ANOTHER 02 DAYS MC.





**SINGAPORE  
POLICE FORCE**



T/20181212/7006

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

4 of 4

Report No. T/20181212/7006

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPIB /  
ANG YI TING, STEPHANIE  
Contact No.: 65476414

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by SingPass. No signature is  
required.

Date/Time:  
12/12/2018 14:00

Classification Of Case:

Authentication Stamp



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Dec 2018		14 Dec 2018 13:51 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;"><a href="#">[Created by insurer]</a></span>									
Insured: <b>HAO DA PTE LTD</b> , Co. Reg. No.: 198800426R									
Main Claimant: <b>RENNIS ROY D'CECIL</b> , ID: S90109203									
Vehicle Reg. No.: <b>FBN3456B</b>		Date of Loss: 07/12/2018 16:00 - :59 <b>[1 Months and 7 Days From LTA Reg Date (Man Yr)]</b>							
Claim Type: <b>TP / SNM18D05710C02</b>		Policy/Cover Note No.: <b>DMCVSN3042661800 (Third Party Only)</b>							
Vehicle Reg. No. (Insured): <b>GX5967T</b>		Policy No. (Claimant):							
		Excess: <b>S\$0.00</b>							
Repairer: <b>H L Cycle Pte Ltd (HQ)</b> 1 Kaki Bukit Avenue 6, #02-58 Autobay, 417883 Kaki Bukit - Tel:									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Final Rpt due 26/12/2018]</b>									
Adj Asg. Remarks: NO EST, CASE W/O SJE.									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*FBN3456B (SNM18D05710C02)**  
**[GX5967T]**

**TP**  
**RENNIS ROY D'CECIL**  
**Dec 7 2018 4:00PM**  
**[HAO DA PTE LTD]**  
**H L Cycle Pte Ltd**












Upload Documents			Upload Photos			Compose New Letter			View <div>View in Browser</div>		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)							Thumbnail	Print	
1	10/12/18 18:54	Accident Statement							Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)							Thumbnail	Print	
1	10/12/18 18:53	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
2	10/12/18 18:53	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
3	10/12/18 18:53	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
4	10/12/18 18:53	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
5	10/12/18 18:53	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
6	10/12/18 18:53	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	18/12/18 18:45	General View							Load PDF		
2	18/12/18 18:45	Photographs of Damaged Parts							Load PDF		
Documentation									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	14/12/18 13:50	PRS							Load PDF		
2	14/12/18 13:50	OI GIA							Load PDF		
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)							Thumbnail	Print	
1	10/12/18 18:52	Sketch Plan [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
2	10/12/18 18:52	Sketch Plan #2 [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
3	10/12/18 18:52	DL [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
4	10/12/18 18:52	DL [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
5	10/12/18 18:52	S PASS [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
6	10/12/18 18:52	S PASS [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	

## Linked Accident Report Documents

View

View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	10/12/18 18:54	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	10/12/18 18:53	Accident Photo		Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
				<input checked="" type="checkbox"/>
2	10/12/18 18:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	10/12/18 18:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	10/12/18 18:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	10/12/18 18:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	10/12/18 18:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	10/12/18 18:52	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	10/12/18 18:52	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
3	10/12/18 18:52	DL	 Load JPG	<input checked="" type="checkbox"/>
4	10/12/18 18:52	DL	 Load JPG	<input checked="" type="checkbox"/>
5	10/12/18 18:52	S PASS	 Load JPG	<input checked="" type="checkbox"/>
6	10/12/18 18:52	S PASS	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18022527/GCD3E2

Date: 31/12/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN3042661800

Claimant Vehicle  
No: FBN3456BInsured Vehicle  
No: GX5967T

Date of Loss: 07/12/2018

Nature of Claim: TP

Claim  
No: SNM18D05710C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: FBN3456B

Make & Model: PIAGGIO VESPA GTS, 278cc SUPER SPORT 300  
E4

Engine No: MA33M1003700

Reg. Date: 30/10/2018 (Man. Year: 2017)

Chassis No: ZAPMA330000004732

Colour: Red

Odometer: 2015 km

Engine Capacity: 278 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 120/70-12

Rear Tyre Size: 130/70-12

Front Left Side: Michelin 9 mm

Rear Left Side: Michelin 9 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 14/12/2018

Date Inspected: 14/12/2018 Inspected At:

H L Cycle Pte Ltd (HQ)  
1 Kaki Bukit Avenue 6, #02-58 Autobay  
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 28 Dec 2018)

**Parts:** N/A PIAGGIO VESPA GTS 278cc SUPER SPORT 300 E4 (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for FBN3456B)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >