

ASS. REC. BY:

REF: es / SMO18022531 / Jtd3 <sup>n2</sup>

Special Instruction:

SURVEYOR:

Merimen

ASSIGNMENT (Office)

From (Person): Ginoh Paul Ioung of SMO Date/Time: 14/12/18 @ 1:28pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD  / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGV 2921E Insured: SJD 6084

at Workshop m/s: Elite AM Tel: 63397378

of 280 Woodlands Ind. Park ES #01-17

Policy No: D18MTPV0101148 Claim No: CMTD1805177

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 08/12/2018

(Client's Record) CA / REV / REP. / REV 24 HRS lup H.O.D. Endorsement: 17/12/18 @ After 12pm

Date/Time: 2:34pm @ 14/12/18 Person Contacted: Christy Vehicle IN  OUT

Date/Time	Action/Instruction (✓) Estimate
	SGV 2921E - CC6 / AIG / 4002893 / Tlv / 63w2 DUA: 9/01/2014
	SJD 6084 - X:
19/12 @ 11:52AM	REVISED PREL ADVISE VIA MERIMEN.

Hwaee Jee

REF: SMO

ASSIGNMENT

From: Date: 17/12/2008

Veh No: SGV 2921E Yr Regn: 11 Jun 2007

Estimated Cost

Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD  TP WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No: SGV 2921E

Make: Toyota Altis C.C. 1598

at Workshop m/s: Elite AM

Colour: Silver A/C: Insured / Std / NI / NA

of 280 woodlands Ind. park ES # 01-17

Sp. Reading: 248724 T/Radio: Insured / Std / NI / NA

Insured

Eng/No: -

Policy No.

C/No: MROS32EC107145750

Claims No.

Gen. Cond:  Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering:  Good / Jammed / Leaked / Burnt or

(Client's Record)

Brake:  Good / Jammed / Leaked / Burnt or

Make of Veh:

After 12pm

Modi: Nil /  STD A/Rim or

(Policy Condition)

Tyre Size: F: 185/70 R14

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

R: -

BS  HUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rport: Consistent?: Yes or No

R/Bal: 6 mm

R/Bal: 6 mm

GIA / PR Seen: Consistent?: Yes or No

L/Bal: 6 mm

L/Bal: 6 mm

Est. Repairs: days: Res.: Yes or No

D.O.A: 8/12/18

D.O.I: 17/12/18

Lum Sum: % 3 Val.: Yes or No

Survey held at: Elite

CA / REV / REP. / 24 HRS <sup>1up</sup>

Des. of Damages:  Front / Rear / O/S / N/S / U/C / Rooftop or

Date: Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

24/4/19 Confirmed L/s \$700 + 2 days of repair. (Red. 2881.44, 8070)

RECEIVED 26 APR 2019

Date/Time, File Pass to? : Preli. Report

Days Of Repair: 2

26/4 Typst : Final Report

Resurvey No. of Trip: 2

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:  Site Insp (\$ ) S + RS, SI

Interview (\$ ) Photos

Tech. Invs (\$ ) Others

Weekend (\$ )

Report Format:

Lump Sum / L.B.I: (\$ 700) <sup>TP</sup>

TOTAL

250
10
260

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: GNOH PAU LOONG

Date: 19 Dec 2018

**Preliminary Advice**

Insured Vehicle No	: SJD608H	Accident Date	: 08/12/2018
TP Vehicle No	: SGV2921E	Assignment Date	: 14/12/2018
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 2.00
Date of Inspection	: 17/12/2018		
Inspection At	: ELITE AM PTE LTD (HQ) 280 WOODLANDS INDUSTRIAL PARK E5, #01-17 HARVEST @ WOODLANDS SINGAPORE 757322		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,581.44
Revised Amount	:S\$	700.88
Check Items (Estimated)	:S\$	627.08
Total	:S\$	1,327.96
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : Survey on 'WP'

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est-Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Dec 2018		14 Dec 2018 13:28 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	WONG KEE HUANG, ID: S7432425H, Tel: +6596737585, Email: keehuang@gmail.com								
Main Claimant:	TONY LIOM YU SHIONG, ID: S8079692G								
Vehicle Reg. No.:	SGV2921E	Date of Loss:	08/12/2018 09:00 - :59						
Claim Type:	TP / CMTD1805477	Policy/Cover Note No.:	D18MTPV01011148 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJD608H	Policy No. (Claimant):							
		Excess:							
Repairer:	Elite AM Pte Ltd (HQ) 280 Woodlands Industrial Park E5, #01-17 Harvest @ Woodlands, 757322 Woodlands - Tel: 63346276								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/12/2018]								
Driver/Custodian (Insured):	WONG KEE HUANG (44 / Female), NRIC: S7432425H, Tel: +6596737585								
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a> <a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>				<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	10/12/2018 14:40
Date Of Accident	08/12/2018 13:00
Exact Location Of Accident	BLK 125 BKT BATOK CENTRAL OPEN CARPARK
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGV2921E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TONY LIOM YU SHIONG
NRIC No	S8079692G
Email Address	TONYLIOM@YAHOO.COM
Mobile Phone No	(LOCAL) +65-98167811
Alternative Phone No	OFFICE-98167811

#### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

#### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1757011
Cover Note Number	

#### Driver

Name of Driver	TONY LIOM YU SHIONG
NRIC No	S8079692G
Date Of Birth	23/09/1980
Occupation	INDOOR
Date Of Driving Pass	11/08/2007
Driving Experience	11 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98167811
Fax Number	
Contact Number	OFFICE-98167811
E-Mail Address	TONYLIOM@YAHOO.COM

Address	125 BUKIT BATOK CENTRAL #06-399
Postcode	650125
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED STATEMENT & SKETCH

#### Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO


#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJD608H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WONG KEE HUANG
NRIC/Passport Number	S7432425H
Contact Number	96737585
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

veh A: SGV 2421E  
B: SJD 608H



125 Bukit Batuk central Open Carpark

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I park ~~my~~ <sup>my</sup> car overnight at my block. The next day on Saturday around 1pm when I go down to take my car. I saw paper note on my wind screen. The note written that the car owner SJD 608H has ~~hit~~ <sup>hit</sup> to my car. She ask me to call her and she wanted to pay for the accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Individual Statement

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,  
Harvest @ Woodlands Singapore 757322  
Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SGV 2921E

Vehicle Model : TOYOTA ALTIS 1.6 A

Chassis Number : MR053ZEC107145750

Estimated Repair Cost

S/N	Parts Description	Qty	List Price
1	FRONT GRILLE <i>NN</i>	1	572.60 <i>✗</i>
2	HEADLAMP RH <i>NN</i>	1	350.80 <i>✗</i>
3	FRONT BUMPER <i>DI</i>	1	334.50 <i>✓</i>
4	FRONT BUMPER RETAINER RH <i>CRA</i>	1	59.20 <i>✗? ✓</i>
5	FOG LAMP RH <i>MM CRA</i>	1	204.30 <i>✗? ✓</i>
6	FRONT BUMPER REINFORCEMENT <i>NN</i>	1	343.65 <i>✗</i>
7	FENDER SPLASH SHIELD <i>NN</i>	1	52.20 <i>✗</i>
8	FENDER SPLASH SHIELD CLIPS <i>NN</i>	10	58.00 <i>✗</i>
			<hr/>
			\$ 1975.25
		Discount Less 25%	\$ 493.81
		List Prices Total	<hr/> \$ 1,481.44

# ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SGV 2921E

Vehicle Model : TOYOTA ALTIS 1.6 A

Chassis Number : MR053ZEC107145750

S/N	Labour Descriptions	Charges
1	LABOUR CHARGES TO REMOVE & INSTALL FRONT END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; AND FRONT RH FENDER, BONNET, TO REPLACE FRONT DAMAGED PARTS AS LISTED ABOVE.	\$ <del>1000.00</del> 200
2	TO SPRAY PAINTING ON: BONNET, FRONT BUMPER, FRONT RH FENDER.	\$ <del>1000.00</del> 200
3	TO REMOVE & REPLACE HEADLAMP, CHECK LIGHTING & FOCUS HEADLIGHT.	\$ <del>100.00</del> (50) 30

Labour Total \$ 2100.00

Parts & Labour Total \$ 3581.44

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*[Signature]*  
19/12/18

Hwee Jia

17/12/18

L/S 2 days

*[Signature]*

Total - \$700/-

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18022531/JTD3N2

Date: 06/05/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01011148
Claimant Vehicle No :	SGV2921E	Insured Vehicle No :	SJD608H
Date of Loss:	08/12/2018	Nature of Claim:	TP
		Claim No:	CMTD1805477

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SGV2921E	Engine No:	3ZZ4643028
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEC107145750
Reg. Date:	11/06/2007 (Man. Year: 2007)	Odometer:	248724 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	185/70 R14	Rear Tyre Size:	185/70 R14
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,481.44	448.50	1,032.94	69.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	430.00	1,670.00	79.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,581.44</b>	<b>878.50</b>	<b>2,702.94</b>	<b>75.47</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>700.00</b>		
<b>(S\$)</b>	<b>3,581.44</b>	<b>700.00</b>	<b>2,881.44</b>	<b>80.45</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>250.70</b>	<b>49.00</b>	<b>201.70</b>	<b>80.45</b>
<b>Nett Amount (S\$)</b>	<b>3,832.14</b>	<b>749.00</b>	<b>3,083.14</b>	<b>80.45</b>

## INSPECTION

Date of Assignment:	14/12/2018	
Date Inspected:	17/12/2018	Inspected At: Elite AM Pte Ltd (HQ) 280 Woodlands Industrial Park E5, #01-17 Harvest @ Woodlands Singapore 757322
Estimated Period of Repair:	2.0 days	

Adjuster: ONG HWEE JIE

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2019)
<b>Parts:</b> 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SGV2921E)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE	Not Necessary	572.60 FL	*- FL
2	1		*HEADLAMP RH	Not Necessary	350.80 FL	*- FL
3	1		*FRONT BUMPER	Dented	334.50 FL	*334.50 FL
4	1		*FRONT BUMPER RETAINER RH	Cracked	59.20 FL	*59.20 FL
5	1		*FOG LAMP RH	Cracked	204.30 FL	*204.30 FL
6	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	343.65 FL	*- FL
7	1		*FENDER SPLASH SHIELD	Not Necessary	52.20 FL	*- FL
8	10		*FENDER SPLASH SHIELD CLIPS	Not Necessary	58.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,975.25</b>	<b>598.00</b>
- List Item Discount on L Items 25.00/25.00% (\$\$)	493.81	149.50
<b>Total Parts (\$\$)</b>	<b>1,481.44</b>	<b>448.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE & INSTALL FRONT AND ATTACHMENTS & FITTINGS TO ENABLE REPAIRS ,AND FRONT RH FENDER ,BONNET ,TO REPLACE FRONT DAMAGED PARTS AS LISTED ABOVE	New	1,000.00	200.00
2	TO SPRAY PAINTING ON ,BONNET ,FRONT BUMPER,FRONT RH FENDER	New	1,000.00	200.00
3	TO REMOVE & REPLACE HEADLAMP ,CHECK LIGHTING & FOCUS HEADLIGHT	New	100.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,100.00</b>	<b>430.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >