

22/03/2002

ASS. REC. BY:

REF:

CS / CTU8022566 / Kvb

Special Instruction:

Survivor:

**ASSIGNMENT (Office)**

From (Person):

Elaim Cheong

of

CTU

Date/Time:

17/22018 11:45am

Estimated Cost:

Bill to:

**OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS**

To Inspect Vehicle No:

Ym 944L

Insured:

GBH 5608Z

at Workshop m/s

Cheng Hoe Motor.

Tel:

67556142

of

Blk 1019 Yishun Ind Park A #01-374

Policy No:

DMCVSN1820691800

Claim No:

SNM18D05575C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/11/2018

**CA / REV / REP. / REV 24 HRS WP**

H.O.D. Endorsement:

Date/Time:

17/12/2018 11:54am

Person Contacted:

Wei Ling

Vehicle

IN / OUT

Date/Time

Action/Instruction (✓) Estimate

Ym 944L - X

GBH 5608Z - CS / CTU8022566 / Rvb

Date: 29/11/2018

11/3

11 Pm @ 900h Customer (Red 365, 299m)

ASS. REC. BY:

REF:

C721

Kenneh

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

YM 944L

Yr Regn:

08, 05

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Daihatsu V126R

c.c.

4104

Colour

Green

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JDA 00V126 00 001393

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: M / S/Rim / STD A/Rim or

Tyre Size:

F:

700R16X8

R:

155R 12X8(10)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

6

mm

R/Bal.

7

7

mm

L/Bal.

6

mm

L/Bal.

7

7

mm

D.O.A.

29/11/18

D.O.I.

18/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/12 Response to Certificate

RECEIVED 11 MAR 2019

Date/Time, File Pass to?



Prel. Report



Final Report

1)

Date/Time, File Return to?

2) 11/3 - typist

Days Of Repair:

2

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

220

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

220

Report Format:

meimen

Lump Sum / I.B.I. (\$

900/2

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Dec 2018 Sendback Est	14 Dec 2018 15:46 S\$1,265.00	17 Dec 2018 11:45 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	SIBRE BRAKES (S.E.A.) PTE LTD, Co. Reg. No.: 201429859Z								
Main Claimant:	SHIANG MAY CONSTRUCTION WORKS (PTE) LTD, Co. Reg. No.: 198300196D								
Vehicle Reg. No.:	YM944L	Date of Loss:	29/11/2018 07:00 - :59 [159 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D05595C02	Policy/Cover Note No.:	DMCVSN1820691800						
Vehicle Reg. No. (Insured):	GBH5608Z	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/12/2018]								
Driver/Custodian (Insured):	ANG WEI JIAT ( / Male)								
Adj Asg. Remarks:	EST \$1353.55, CASE WITH SJE.								
<b>ASSOCIATED MAIL RECEIVED</b>									
			View All	Compose Case Mail					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>									
<div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	0196D
<b>Vehicle Details</b>	
Vehicle No.:	YM944L
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Nov 2018
Vehicle Make:	DAIHATSU
Vehicle Model:	V126R-HUT-5
Primary Colour:	Green
Manufacturing Year:	2005
Engine No.:	1780136
Chassis No.:	JDA00V12600001393
Maximum Power Output:	-
Open Market Value:	\$25,940.00
Original Registration Date:	10 Aug 2005
First Registration Date:	10 Aug 2005
Transfer Count:	0
Actual ARF Paid:	\$1,297.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	09 Aug 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$25,292.00
COE Rebate Amount:	\$8,580.00
<b>Total Rebate Amount:</b>	<b>\$8,580.00</b>
<b>Message</b>	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 29 Nov 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	29/11/2018 16:00
Date Of Accident	29/11/2018 07:40
Exact Location Of Accident	BT.TIMAH RD TWRDS CLEMENTI
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	YM944L
Insured/Policyholder	
Name Of Registered Owner	SHIANG MAY CONSTRUCTION WORKS (PTE) LTD
Co Reg No	198300196D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64691955
Vehicle Particulars	
Manufacturer	DAIHATSU
Model	V126R-HUT-5
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	DMCV18S008212
Cover Note Number	10/8/18-9/8/19
Driver	
Name of Driver	RIPON ZEHER ALI MONDOL
Passport No/FIN	G8260582M
Date Of Birth	23/01/1989
Occupation	OUTDOOR
Date Of Driving Pass	02/01/2015
Driving Experience	3 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86478232
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address CO SHIANG MAY CONSTRUCTION WORKS (PTE) LTD  
 Postcode  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance?  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1  
 NAME: : WORKER  
 GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

SLOW TRAFFIC MOVING, I FOLLOWED FRONT VEHICLE. THE FRONT VEHICLE HAS STOPPED, I ALSO STOPPED. AT THAT TIME HE HIT MY VEHICLE BEHIND. MY VEHICLE HAS DAMAGED.


#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBH5608Z  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category COMMERCIAL VEHICLE  
 Name of Driver ANG WEI JIAT  
 NRIC/Passport Number S8265848C  
 Contact Number 97680848  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- SLOW TRAFFIC MOVING, I FOLLOWED FRONT VEHICLE
- THE FRONT VEHICLE WAS STOPPED, I ALSO STOPPED
- AT THAT TIME HE HIT MY VEHICLE BEHIND,
- MY VEHICLE WAS DAMAGED

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:   
NRIC/FIN No.:

GIARMC SketchPlanForm\_V3 ( ) Claim Own Policy (✓) Claim Third Party ( ) Reporting Only  
( ) Claim OD/TP at other workshop ( )



**SKETCH PLAN**

VEHICLE NO.: YM 944L  
INSURER : ERGO  
DATE & TIME: 29/11/18


**IMPORTANT NOTICE**


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name: ep  
NRIC/FIN No.: WL



**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

**TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)****SIBRE BRAKES (S.E.A.) PTE LTD**

Singapore

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA (GBH5608Z)
Policy No:		Date of Loss:	29/11/2018
Vehicle Reg. No.:	YM944L	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	RIPON ZEHER ALI MONDOL	Driver (Insured):	ANG WEI JIAT
Make/Model:	DAIHATSU V126R-HUT-5, 4.1 D (M)	Vehicle Reg. Date:	10/08/2005
Vehicle Colour:	GREEN		
Engine No:	1780136	Chassis No:	JDA00V12600001393
Odometer:	0 KM		
Paint Type:			<i>Not Matched</i>
Total Loss?	<b>NO</b>		<i>1/1/18 &amp; ?</i>
Est. Duration of Repair (day)	0		<i>Resurvey After Paint 2 days</i>
Description of Accident/Loss	REFER TO GIA REPORT ATTACHED.		
Present Location:	CHENG HOE MOTOR PTE LTD (WOODLANDS)		

**COST OF CLAIMS**

	LKK Auto Consultants hence notify the Repairer of the following:	Amount
Parts	• To resurvey before/after spray painting	0.00
Miscellaneous Items	• To display damaged part(s) during resurvey	765.00
Labour	• Parts prices are subject to confirmation	500.00
Paintwork Labour	• Third party survey is on a "Without Prejudice" basis	0.00
Towing	• No illegal modification(s) is allowed	0.00
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	0.00
	<b>Gross Total (\$\$)</b>	<b>1,265.00</b>
	Signature: <b>+ GST 7.00% (\$\$)</b>	88.55
	Date:	
	<b>Nett Amount (\$\$)</b>	<b>1,353.55</b>

**This claim is handled by: SHARON CHIONG BENG CHOON**Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

YM 944L

TP/CHINA

**REPAIR DETAILS****Reference****Part Source:** (Last Synchronised: 14 Dec 2018)**Parts:** N/A DAIHATSU V126R-HUT-5 4.1 D (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Cheng Hoe Motor Pte Ltd/YM944L/14/12/2018 15:46**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

There are no new parts selected.

Cheng Hoe Motor Pte Ltd/YM944L/14/12/2018 15:46. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS**Estimates on Miscellaneous Items**

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	1 pc rear number plate	15.00 ✓
2	1	1 pc rear safety bar	750.00 ✓
Sub Total (S\$)			765.00

**Estimates on Labour**

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	To remove & refix rear safety bar, straighten & repair rear chassis	New	300.00
2	To respray rear safety bar	New	200.00
Gross Labour Cost (S\$)			500.00

Cheng Hoe Motor Pte Ltd/YM944L/14/12/2018 15:46. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Dec 2018 Sendback Est	14 Dec 2018 15:46 <b>\$1,265.00</b>	17 Dec 2018 11:45 <a href="#">Edit Adj Rpt</a>	<b>\$900.00</b> <a href="#">Edit Estimates</a>	<b>\$900.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS**

Insured:	<b>SIBRE BRAKES (S.E.A.) PTE LTD</b> , Co. Reg. No.: 201429859Z		
Main Claimant:	<b>SHIANG MAY CONSTRUCTION WORKS (PTE) LTD</b> , Co. Reg. No.: 198300196D		
Vehicle Reg. No.:	<b>YM944L</b>	Date of Loss:	29/11/2018 07:00 - :59 [159 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / SNM18D05595C02</b>	Policy/Cover Note No.:	DMCVSN1820691800
Vehicle Reg. No. (Insured):	<b>GBH5608Z</b>	Policy No. (Claimant):	
		Excess:	\$0.00
Repairer:	<b>Cheng Hoe Motor Pte Ltd (Yishun)</b> Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Elaine Cheong</b> ]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 27/12/2018]		
Driver/Custodian (Insured):	ANG WEI JIAT ( / Male) Email:		
Adj Asg. Remarks:	EST \$1353.55, CASE WITH SJE.		

**ASSOCIATED MAIL RECEIVED**
[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS**
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

YM944L (SNM18D05595C02)

[GBH5608Z]

TP

SHIANG MAY CONSTRUCTION WORKS (PTE) LTD

Nov 29 2018 7:00AM

[SIBRE BRAKES (S.E.A.) PTE LTD]

Cheng Hoe Motor Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
<b>Assessment Reports</b>						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)				Thumbnail	Print
1	14/12/18 15:46	Repairer Estimates				Load HTM	
<b>Photos/Images</b>						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	11/03/19 10:11	General View				Load PDF	
2	11/03/19 10:11	Reinspection Photo				Load PDF	
<b>Documentation</b>						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)				Thumbnail	Print
1	14/12/18 15:45	GIA REPORT				Load PDF	
2	14/12/18 15:45	LTA SEARCH				Load PDF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)				Thumbnail	Print
1	17/12/18 11:44	OI GIA				Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>		<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>				
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118022566/KVBE2

Date: 12/03/2019

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN1820691800

Claimant Vehicle  
No: YM944LInsured Vehicle  
No: GBH5608Z

Date of Loss: 29/11/2018

Nature of Claim: TP

Claim  
No: SNM18D05595C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YM944L

Make &amp; Model: DAIHATSU V126R-HUT-5, 4.1 D (M)

Engine No: 1780136

Reg. Date: 10/08/2005 (Man. Year: 2005)

Chassis No: JDA00V12600001393

Colour: Green

Odometer: 0 km

Engine Capacity: 4104 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 700R16X8

Rear Tyre Size: 155R12X8 (D)

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 7/7 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	765.00	765.00	0.00	0.00
Labour	500.00	350.00	150.00	30.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,265.00</b>	<b>1,115.00</b>	<b>150.00</b>	<b>11.86</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>900.00</b>		
<b>(S\$)</b>	1,265.00	900.00	365.00	28.85
<b>+ GST 7.00/7.00% (S\$)</b>	88.55	63.00	25.55	28.85
<b>Nett Amount (S\$)</b>	<b>1,353.55</b>	<b>963.00</b>	<b>390.55</b>	<b>28.85</b>

### INSPECTION

Date of Assignment: 17/12/2018 Present Location:

Date Inspected: 18/12/2018 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)

Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun Industrial  
Park A

Singapore 768761

Estimated Period of Repair: 2.0 days

---

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 12 Mar 2019)
Parts:	N/A	DAIHATSU V126R-HUT-5 4.1 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YM944L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	1 pc rear number plate (DENTED)	15.00	15.00
2	1	1 pc rear safety bar (BENT)	750.00	750.00
Sub Total (S\$)			<b>765.00</b>	<b>765.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	To remove & refix rear safety bar, straighten & repair rear chassis	New	300.00	200.00
2	To respray rear safety bar	New	200.00	150.00
Gross Labour Cost (S\$)			<b>500.00</b>	<b>350.00</b>

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;