

ASS. REC. BY:

REF:

REF: CS3/IC318022569/Tichez

Special Instruction:

Surveyor:
Mullin.

ASSIGNMENT (Office)

From (Person):

From (Person): Christabelle Tan

of

ICS

Date/Time:

17-12-2018 10:47am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SV 6425J.

Insured:

SJW 2475K

at Workshop m/s

Autofriend Services

Tel:

6268 3065.

of

27A Juning Port Rd #01-15

Policy No:

Claim No:

Dm PC18010456H / 02 / CT

Sum Insured:

Excess:

Make of Veh:

D.O.A.

02.12.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS'WP'

H.O.D. Endorsement:

Date/Time:

17122018 1.290m

Person Contacted:

William

Vehicle IN/OUT

OTT

Date/Time	Action/Instruction (X) Estimate
	STV 6425J - X
	STW 2475K - X

Surveyor: Tanji

REF:


LCS

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
PRS
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SSV 6425J Yr Regn: 2010 Feb
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Alfa C.C. 1598
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MK0537EE/06163655
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. _____		D.O.I. <u>19/12/18 0430p</u>

Survey held at Interfaced
 Des. of Damages: Frt / Rear / O/S N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction No Illuy

27 A Jany Dat ad

Estimated repair range \$1,800 - \$2,300

26/12/2018

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: -

Survey Fee:

Transportation:

1)

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

) \$ + RS. \$

) Photos

) Others

Report Format : PRS

Lump Sum / I.B.I: (\$)

TOTAL

110

Catherine Chong (LKK Auto)

From: Crystabelle Tan Gek Peng (ECICS, Claims) <Crystabelle_Tan@ecics.com.sg>
Sent: Monday, 17 December, 2018 10:47 AM
To: Accident@kscgp.com; assignments
Cc: motor@kscgp.com; ECICS Claims
Subject: RE: 2nd Notice to conduct Pre-Repair Survey (Your Ref: DMPC1800456H/02/CT Our Ref: SJV 6425J/AF/sy/wl)

Dear Wei Lin

Thank you for your email.
We are not agreeable with your surveyor list and we will appoint LKK for the SJE.

Aside to LKK

Please assist to arrange survey for TPV.

Best regards,
Crystabelle Tan
Claims Division
DID: +65 6303 0190
FAX: +65 6338 9267
Email: crystabelle_tan@ecics.com.sg

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

From: Accident@kscgp.com [mailto:Accident@kscgp.com]
Sent: Saturday, 15 December, 2018 9:38 AM
To: Crystabelle Tan Gek Peng (ECICS, Claims)
Cc: motor@kscgp.com; ECICS Claims
Subject: 2nd Notice to conduct Pre-Repair Survey (Your Ref: DMPC1800456H/02/CT Our Ref: SJV 6425J/AF/sy/wl)

Dear Sirs,

Please find enclosed herein the 2nd Notice to conduct Pre-Repair Survey. Our clients are not agreeable to your proposed list of motor surveyors.

The workshop's details are as follows:
Autofriend Services
27A Jurong Port Road
#01-15/27
Singapore 619101
Contact: Ms Lee (tel: 6268 3065)

Thank you.

Wishing you a Merry Christmas and a Happy New Year! 

Regards,
Wei Lin
for and on behalf of Mr Gurdeep Singh Sekhon
KSCGP Juris LLP
10 Hoe Chiang Road

#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0984 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

From: Crystabelle Tan Gek Peng (ECICS, Claims) [mailto:Crystabelle_Tan@ecics.com.sg]
To: Accident@kscgp.com
Cc: motor@kscgp.com, claims@ecics.com.sg
Sent: Fri, 14 Dec 2018 11:05:18 +0000
Subject:

WITHOUT PREJUDICE

Dear Wei Lin

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Best regards,
Crystabelle Tan
Claims Division
DID: +65 6303 0190
FAX: +65 6338 9267
Email: crystabelle_tan@ecics.com.sg

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

From: Accident@kscgp.com [<mailto:Accident@kscgp.com>]
Sent: Friday, 14 December, 2018 5:19 PM
To: ECICS Claims


Cc: motor@kscgp.com

Subject: Notice to conduct Pre-Repair Survey (Your Ref: SJW 2475K Our Ref: SJV 6425J/AF/sy/wl)

Dear Sirs,

Please find enclosed herein the Notice to conduct Pre-Repair survey, for your immediate attention and necessary action.

Thank you.

Wishing you a Merry Christmas and a Happy New Year! 

Regards,

Wei Lin

for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road


#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0984 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4477H
Vehicle Details	
Vehicle No.:	SJV6425J
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	3ZZ4959974
Chassis No.:	MR053ZEE106163655
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,853.00
Original Registration Date:	03 Feb 2010
First Registration Date:	03 Feb 2010
Transfer Count:	1
Actual ARF Paid:	\$17,853.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Feb 2020
PARF Rebate Amount:	\$9,819.00
Intended COE Rebate Details	
COE Expiry Date:	02 Feb 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$20,501.00
COE Rebate Amount:	\$2,271.00
Total Rebate Amount:	\$12,090.00

The information contained herein is correct as at 24 Dec 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/12/2018 13:33
Date Of Accident	02/12/2018 15:45
Exact Location Of Accident	AFTER JOHOR BAHRU IMMIGRATION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV6425J
Insured/Policyholder	
Name Of Registered Owner	OSMAN BIN JAFFAR
NRIC No	S0214477H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98502524
Alternative Phone No	OFFICE-98502524

Vehicle Particulars

Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00010865
Cover Note Number	

Driver

Name of Driver	ELIANNA BINTE OSMAN
NRIC No	S8100597D
Date Of Birth	04/01/1981
Occupation	INDOOR
Date Of Driving Pass	07/09/2004
Driving Experience	14 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98639865
Fax Number	
Contact Number	
Email Address	ELIANNAOO@YAHOO.COM

Address	BLK 115 BEDOK RESERVOIR ROAD #02-126
Postcode	470115
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	KAMPONG UBI NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 9 EUNOS CRESCENT #01-2687 , POSTCODE: 400009 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7479999 - FAX NO: 67453410
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT: G/20181203/2044.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW2475K
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

DRIVER'S SIGNATURE



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer to police report

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



G/20181203/2044

1 of 2

POLICE REPORT (NP299)

Report No. G/20181203/2044

Police Station Of Origin
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

Date/Time Report Made 03/12/2018 12:42		Vide Report No.		Station Diary No. 8	
Name Of Informant ELIANNA BINTE OSMAN		Address APT BLK 115 BEDOK RESERVOIR ROAD #02-126 SINGAPORE 470115			
ID Type / ID No. NRIC NO / S8100597D		Contact No. Home/Office		Mobile 98539865	
Nationality SINGAPORE CITIZEN		Email Address			
Occupation MARKETING		Sex Female	Age 37	Date of Birth 04/01/1981	Race Malay
Institution/School Name		Language			
Date/Time Of Incident 02/12/2018 15:45		Location Of Incident JOHOR BAHRU, AFTER JOHOR CUSTOMS TOWARDS SINGAPORE MALAYSIA			

Brief details.

On 2/12/2018 at about 1545hrs while driving my father's car, a Blue Toyota Altis SJV6425 back to Singapore from Johor Bahru with my husband and daughter.
Just after the Johor Immigration, the traffic was heavy and I kept to my lane. Suddenly as I was moving forward, a Singapore car, Blue Hyundai Elentra SJW2475K just swerved out of his lane, behind my car, the vehicle then hit onto the left rear portion(rear left door & rear left bumper) of my car causing my car to

Signature Of Officer Recording The Report:

G / Sgt 1 SHAUN CHUA YONG QUAN

Signature Of Informant:

Signature Of Interpreter:
Not applicableDate/Time:
03/12/2018 12:42

Officer In-Charge Of Case:
G / Bedok Police Divisional Investigation Branch /
Insp DELVIN NG HAN WEI
Contact No.: 62447200

Classification Of Case:

Authentication Stamp



**SINGAPORE
POLICE FORCE**



G/20181203/2044

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20181203/2044

jerk forward and hitting onto the kerb on the front right which caused my vehicle to be stuck on the kerb. My husband(Musta'in, HP: 90362036) who was seated at the rear passenger seat, wind down his window to check on the car and asked the driver what happened, the driver then ignored my husband. I then got out of the vehicle and asked the other driver to come out, he then got out and shouted at me that nothing is wrong, the driver also refused to reverse his car to allow me to move.

I then had to mount the kerb to be able to move forward, which then caused some scratches on the right underside of the front bumper. I then stopped the car to check for damage and discovered that there was some dent and scratches at the rear left portion of the vehicle.

My husband and I tried to ask the male Chinese driver to exchange particulars however he kept saying that nothing is wrong and refused to provide particulars.

A witness(Saiful, HP:83710612) who was behind us, the driver of SJN1197D, came out and informed me that he has the whole incident recorded on his dash camera and he then send me the video, I will provide the video if required.

I am lodging this report for insurance claims.

Signature Of Officer Recording The Report:

G / Sgt 1 SHAUN CHUA YONG QUAN

Signature Of Informant:

Signature Of Interpreter:
Not applicableDate/Time:
03/12/2018 12:42Officer In-Charge Of Case:
G / Bedok Police Divisional Investigation Branch /
Insp DELVIN NG HAN WEI
Contact No.: 62447200

Classification Of Case:

Authentication Stamp

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Dec 2018 09:49 Edit Reg		17 Dec 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -, Email: EMAIL@EMAIL.COM									
Main Claimant: OSMAN BIN JAFFAR , ID: S0214477H									
Vehicle Reg. No.: SJV6425J		Date of Loss: 02/12/2018 15:00 - :59 [105 Months and 29 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): SJW2475K		Policy No. (Claimant):							
		Excess:							
Repairer: Autofriend Services () 27A Jurong Port Road, #01-15/27, 619101 Jurong West - Tel:									
Handling Insurer: ECICS Limited (HQ) - Tel: 63374779 /6303 0178									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 03/01/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJV6425J
[SJW2475K]
TP
OSMAN BIN JAFFAR
Dec 2 2018 3:00PM
[-]
Autofriend Services

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/12/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>
2	24/12/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>
3	24/12/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>
4	24/12/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>
5	24/12/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>
6	24/12/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>
7	24/12/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>
8	24/12/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>
9	24/12/18 12:29	General View		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin: 5px 0;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/ICS18022569/T1CBE2

Date: 31/12/2018

REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle
No : SJV6425J

Insured Vehicle No :

SJW2475K

Date of Loss: 02/12/2018

Nature of Claim:

TP

Claim No:

N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJV6425J**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 3ZZ4959974

Reg. Date: 03/02/2010 (Man. Year: 2009)

Chassis No: MR053ZEE106163655

Colour: Blue

Odometer: 0 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 17/12/2018

Date Inspected: 19/12/2018 Inspected At:

Autofriend Services
27A Jurong Port Road, #01-15/27
Singapore 619101

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,800.00 -\$2,300.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Dec 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJV6425J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >