

		ENGI	NEERING
Our Ref : CC18120401/ SHC7927U /WT(st)	_		
Your Ref: Date : 20-Dec-18	CDGE Taxi Claims Dept		Engineering Pte Ltd d Singapore 579701
CHINA TAIPING INSURANCE CO LTD	59 Loyang Drive 4th Flr Singapore 508969		nline +65 6383 6280 milie +65 6280 9755
3 ANSON ROAD			www.cdge.com.sg
#16-00 SPRINGLEAF TOWER		Company R	egistration No: 199506048W
SINGAPORE 079909			Workshops
Attn : Motor Claims Department WIT	THOUT PREJUDICE		Braddell 205 Braddell Road Singapore 579701
Dear Sir  ACCIDENT INVOLVING OUR TAXI SHC7927	U YOUR INSURED G	X 227D	Loyang 59 Loyang Drive Singapore 508969
AND OTHER	ON	13.12.18	Sin Ming 383 Sin Ming Drive Singapore 575717
We are the authorised repair workshop for Citycab Pt  SHC7927U which was involved in the captioned ac  The vehicle owner and the taxi driver concerned have	ccident with your insured	vehicle.	Pandan 45 Pandan Road Singapore 609286
them in presenting their claims against the party resp from the damage to the vehicle.			320 Ubi Road 3 Singapore 408649
As the accident was caused by the negligent act of your we are submitting these claims for your consideration		X 227D	Senoko 24 Senoko Loop Singapore 758156
TAXI OWNER'S CLAIM  1 Cost of Repair	\$		Sungei Kadut 7 Sungei Kadut Way Singapore 728791
2 5.5 days Loss of Rental @ \$ 115.00 3 Survey Report Fees (Surveyed by M/s LKK) 4 LTA Search Fees	\$	632.50	<b>Yishun</b> hun Industrial Park A Singapore 768732
5 GIA / Police Report Fees	\$	-	
6 Towing / Medical / Transporation Fees	\$	-	
HIRER'S CLAIM	Sub Total : _\$	3,689.49	
	per days \$	440.00	
	Total Claims: \$	4,129.49	
We enclose herewith the following documents to suppart a) Original repair bill and photocopies of photograph b) LTA search slip/s of: GX 227D SHC7927U	ns :	4 pcs.	
d) Letter of authority from owner / hirer / operator			

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

(x) Downtime/Mileage record

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully William Tan

**CDGE Claims Department** 

( ) Witness statement/s

Tel: 6214 8737 Fax: 6214 1843 Email: williamtan@cdge.com.sg

(X) Photocopies of Accident Scene Photos

This is a computer generated letter. No signature is required.





( ) Certificate of Insurance

(x) Rental Rate letter





LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING

SONATA SHC7927U , GX227D

ON 13-Dec-18 19:40

ALONG

EUNOS CRESCENT . BLK 2A H D B CAR APRK.

(BLK 2A CAR HDB DRIVE WAY)

I / We

KOH WAH KONG

(Hirer) NRIC No.:

S1656137A

and/or

LOOI ENG HOCK

(Relief) NRIC No.:

S2500515E

Taxi Number

SHC7927U

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of

"ComfortDelGro Engineering Pte Ltd".

Date

14-Dec-2018

Name of Hirer

KOH WAH KONG

Hirer NRIC

S1656137A

Signature :

× SM.

Address

494G TAMPINES ST 45 #04-568

527494

Contact No.

97913804

Name of Relief

LOOI ENG HOCK

Relief NRIC

S2500515E

Signature :

Total.

Address

131 BEDOK RESERVOIR RD #11-1327

470131

Contact No.

94462869



A member of COMFORIDELGRO

GST REG. NO. M2-8921817-3

## TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 76873/ 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286

320 Ubi Road 3 Singapore 408649 REG. NO.: 199506048W

Page: 1

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD SPRINGLEAF TOWER

3 ANSON ROAD #16-00 SINGAPORE 079909

CONTACT NO: 62222366

VEHCLE NO

NO/DATE 91414918 18.12.2018

MAKE HYUNDAI

305250946

MODEL I - 40

ODOMETER READING

DATE OF REG 27.01.2015

CHASSIS CODE KMHLB41UMFU064787

JOB TYPE

Description: 3P 13.12.2018

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt 7.000 %

Total Invoice amount

3,049.50

Issued by : CHEWBEELENG 18.12.2018 16:37:31 Repair Type : CFSO/57/57 Payment Type/Term : /Credit 30 days

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

ACCOUNT No. INVOICE No. BANK/CHQ No. **AMOUNT** 

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Our Ref: CC18120401

Date: 18 December 2018



## TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

13/12/2018 @ 19:40 hrs

ALONG

**EUNOS CRESENT** 

INVOLVING

GX227D

We refer to the above-mentioned accident and wish to inform that CityCab Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHC7927U (the "Taxi"). The Taxi was hired to KOH WAH KONG IC NO S1656137A a registered hirer-operator of CityCab Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$115.00 per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

	rit 6bt ons			HOURS OPER	HOURS OPERATED (TIME)
DATE	NAME OF DRIVER	MILEAGE READING	TRAVELLED (KM)	FROM	10
Ó	LOS NOK	42321730	340	oppo	oogi
11/2/10	las Fra Mat	33433		7071 8.35	0200
01 -71 -11	,	42268	248	occo	1535
12 13 10	1 To Hach	333916		27.6 1711	0246
01 51 -71	8 ,	434109	193	afoi	65.51
13 12 18	Imi Fra Hack	34169	8	17071	
0/10	Loon	)	Byang	1940	
2/10	Reposit		7		1100
07/			5		
1 2					

NA

DATE

Enquire Vehicle Insurer

Vehicle No. Incident Date/Time Search Status Insurance Company Code Insurance Company Name

GX227D 13 Dec 2018 / 19:40:00 Successful C01 CF

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Previous

OK

Suc 792741







