

INS. CASE OWNER:

PW

CC

4, Asm

180

22593, R1 pa39

LKK:

IDAC:

87831

Sponsor:

Rensu1

DOI:

ASSIGNMENT

21/2/18

Date / Time:

14/2/18

Registered in Merimen:

S8m016KJ

Pre-assign / CCU / FTE

SHC5156R



Insured Vehicle No.:

710 SUS PIC

Claim No.:

Name of Insured:

710 SUS PIC

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II : \$5

5,000.00

D.O.A.:

25/10/2018

Place of Accident:

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SJW1686A



INSRS:

WSP:

Tel:

Liability:

RMKS:

MOVE



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

21/2/18  
CH1

SJW1686A. X;  
 SHC5156R. CC2/16/180203/9/16/18 : 009 9/1/18  
 - CC2/16/180203/9/16/18 : 009 3/1/18  
 - CC3/16/180203/9/16/18 : 009 8/1/18  
 - CC4/16/180203/9/16/18 : 009 3/1/18  
 - CC4/16/180203/9/16/18 : 009 3/1/18  
 - CC4/16/180203/9/16/18 : 009 18/1/18

13/1/18 BINA. first out 1st left. (via email)

21/2/18 - TP withdraw claim.

26/2/18 - File pass to me: even to close (up)

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LCD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 2R, Ass. Lia:

Repair Cost:

\$5

Loss of Rental (LOR):

\$5

(

days)

Loss of Use (LOU):

\$5

(\$

x

days)

Loss of Income (LOI):

\$5

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/Independent)

Legal Cost

\$5

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$250.00

Total:

\$5

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

Name 1:

Payee 2 (Strike if N.A.):

\$5

Name 2:

Payee 3 (Strike if N.A.):

\$5

Name 3:



**MOVA AUTOMOTIVE PTE  
LTD**

**MOVA BUILDING  
22 JALAN KILANG  
SINGAPORE 159419**

**Claim Reference:**  
**Assessment Number: CK133506**  
**Version: MOVAAUTO/1**  
**Date Calculated: 13/12/2018 08:52**

**Full Report - V1**  
**Registration: SJW1686A**  
**Printed: 13/12/2018 16:52**

**Summary Information**

**Claim**

Location:	Singapore (SG)	Currency:	SGD
Printed by:	CAREN TEOH	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:	TP	Actual Repair Days:	
Third Party:	True	Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

**Vehicle Details**

**Vehicle**

Manufacturer:	VOLVO
Model:	XC60
Sub Model:	BASE MODEL
Model Sheet Number:	K50 01
Registration:	SJW1686A
Registration Month:	
Registration Year:	
VIN Number:	PNVDZ475BC5333141
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

**Model Specs**

FROM VIN 309022	AUTO AIR CON
KEYLESS ENTRY	ELEC CHILD LOCKING
ILLUMINATED MIRROR	FOLDING DOOR MIRRORS
REAR HEADPHONES	ADAPT XENON HEADLAMP
HEADLAMP WASHERS	TRIM PARTIAL LEATHER
REAR CENTRE ARMREST	NAVIGATION SYSTEM
ELEC DRIVER SEAT MEM	WOOD TRIM
TRIM CHROME	W/FRAME CHROMED MLDG
RAIN SENSOR	ANTI THEFT ALARM
DIP REAR VIEW MIRROR	RR INTEG CHILD SEAT
ULTRASONIC PARK SYS	2.0 LTR 177KW
FRONT DRIVE	6-SPEED AUTOMATIC
PWR STRG SPEED CONT	ELECT PARKING BRAKE
RR DUAL EXHAUST PIPE	COLLISION WARN SYS
TYRES 235/60 VR 18	WHEELS 7.5J X 18 ALU
RR B/DISC VENTILATED	ROOF RACK ALU
AUTOMATIC TAILGATE	TWO COAT METALLIC

**Vehicle Condition**

**Vehicle Status**

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	13/12/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

# MOVA AUTOMOTIVE PTE LTD

Claim Reference:

Assessment Number: CK133506



Version: MOVAAUTO/1

Date Calculated: 13/12/2018 08:52

Full Report - V1

Registration: SJW1686A

Printed: 13/12/2018 16:52



## Addresses

## Cost Summary

Total Labour	\$432.00
Total Paint/Material	\$101.32
Total Parts	\$4,795.50
Excess:	TBA
Grand Total Exc GST:	\$5,328.82
7 % GST:	\$373.02
Grand Total Inc GST:	\$5,701.84

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR  
Price/Dent = \$45.00/HR

### Repair /

### Guide Number Repair Details

		WU	Cost Price (\$)
86101-2	R + R REAR BUMPER CPL	5.0	22.50
NO NUMBER	R + R REAR BUMPER PROTECTION	4.0	18.00
86131-3	R + R L/R INNER BUMPER CARRIER	3.0	13.50
86131-3	R + R R/R INNER BUMPER CARRIER	3.0	13.50
86112-3	R + R BUMPER ABSORBER	1.0	4.50
84543-2	R + R REAR END PANEL TRIM	3.0	13.50
36701-3	R + R L/R PARKING SYSTEM SENSOR	1.0	4.50
36700-2)	ADD/WORK FOR PARKING SYSTEM	1.0	4.50
36700-2)	R + R PARKING SYSTEM SENSOR	2.0	9.00
82652-2)	R + R L/REAR INNER WING	2.0	9.00
82652-2)	R + R R/REAR INNER WING	2.0	9.00
25210-2	R + R REAR SILENCER	3.0	13.50
NO NUMBER	R + R HEAT PROTECTIVE PANEL	1.0	4.50
77061-2	R + R LEFT REAR WHEEL	1.0	4.50
77061-2	R + R RIGHT REAR WHEEL	1.0	4.50
2581	REPAIR REAR BUMPER	15.0*	67.50
2668	CHECK R/R PARK SYS SENSOR		
2731	CHECK REAR BUMPER SUPPORT		

### LABOUR COST

Total Work Units	48.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	4.8HRS	\$216.00
Paint Labour	4.8HRS	\$216.00
Total Labour	9.6HRS	\$432.00

### PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

### Guide Number Description

WU Cost Price (\$)

# MOVA AUTOMOTIVE PTE LTD

Claim Reference:

Assessment Number: CK133506

Version: MOVAAUTO/1

Date Calculated: 13/12/2018 08:52

Full Report - V1

Registration: SJW1686A

Printed: 13/12/2018 16:52

	- TWO COAT METALLIC		
2581	REAR BUMPER REPAIR PAINT PLASTIC	14.0	
2614	REAR BUMPER COVER SURFACE PAINT PLAST.	3.0	
2931	BOOTLID/TAILGATE SURFACE PAINT PLAST.	10.0	
<b>LABOUR COST - PAINT</b>			
	TIME(PAINT)	27.0	
	Preparation Main Work Plastic	21.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	48.0	
	Total Paintwork Labour	4.8HRS	\$216.00
<b>MATERIAL COST - PAINT</b>			
	Surface Paint Plastic		Cost Price \$47.58
	Repair Painting Plastic		\$35.64
	Material-Const Main Work Plastic		\$18.10
	Total Excluding Pearlescent Uplift		\$101.32
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$101.32

## PARTS

				Price Valid: 01/01/2001	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
2640	1	CTR RR BUMPER REINF	30763441		0% 1,380.00*
2641	1	L/R INN BUMPER BRKT	31214458		0% 85.00*
2617	1	L/R OUT BUMPER BRKT	30763437		0% 90.00*
2667	1	L/R PARK SYS SENSOR	31445162		0% 185.00*
2642	1	R/R INN BUMPER BRKT	31214458		0% 85.00*
2618	1	R/R OUT BUMPER BRKT	30763438		0% 90.00*
8830	1	REAR HEAT SHIELD	31353531		0% 550.00*
8833	1	REAR SILENCER	31355821		0% 905.00*
2606	1	REAR SPOILER	31294291		0% 455.00*
2650	1	RR BUMPER CLAMP KIT	USE SINGLE PARTS		0% 120.00*
2610	1	RR BUMPER CTR COVER	30764525		0% 225.00*
f: OEM Parts				Sub Total	\$4,170.00
g: Original				Mark Up From Cost (15 %)	\$625.50
h: Secondhand				<b>Total Parts</b>	<b>\$4,795.50</b>
p: Parallel					
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

**Total Extras \$0.00**

## Final Calculation

<b>Total Parts</b>	<b>\$4,795.50</b>
<b>Labour</b>	
Total Panel/Mechanical	\$216.00
Total Paintwork	\$216.00
<b>Total Labour</b>	<b>\$432.00</b>
<b>Total Paint/Material Costs</b>	<b>\$101.32</b>
<b>Grand Total Excludes GST</b>	<b>\$5,328.82</b>
GST @ 7 %	\$373.02
<b>Grand Total Includes GST</b>	<b>\$5,701.84</b>

## Assessment Notes

Claim Reference:

Assessment Number: CK133506

Version: MOVAAUTO/1

Date Calculated: 13/12/2018 08:52

Full Report - V1

Registration: SJW1686A

Printed: 13/12/2018 16:52

*Revised*

*Hp 900/100 68*

*4/s*

*3 ~~4~~ days*

*21/12/18 @ 1110 hrs*

*Resurvey after repair*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## ◀ Service Request Details

Claim

S8M016KJ

Reference

None 

Loss Date

25 October 2018

Request Date

14 December 2018

Due Date

21 December 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

17-12-2018 @ 1033am  
Nithu veh not in.

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

SJW1686A

Make

TPVD VOLVO

## Service Address

...

## Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD  
No.2 ANG MO KIO STREET 63, 569111, Singapore

## Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

NON-REPORTED

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

**Catherine Chong (LKK Auto)**

---

**From:** Nitha <nitha@moval.com.sg>  
**Sent:** Thursday, 13 December, 2018 5:22 PM  
**To:** SG AXA Insurance SM AXA SGP - Motor Survey  
**Cc:** ongbobo@moval.com.sg; 'Suann'  
**Subject:** TP CLAIMS - SJW1686A AGAINST SHC5156R DOA 25/10/2018 AT STEVENS ROAD  
**Attachments:** RPT.pdf; EST.pdf

**Categories:** Santosh

Dear All,

Please assist to assign surveyor and officer in charge for the above mention case.

Thank you.

Best Regards,  
Nitha  
Claims Officer  
Mova Automotive Pte Ltd  
Tel: 6272 3892 Fax: 6270 8314



## Mei Kwan (LKKAUTO)

---

**From:** Mei Kwan (LKKAUTO)  
**Sent:** Monday, 17 December, 2018 4:23 PM  
**To:** claims@transcab.com.sg  
**Cc:** foonghon@ava-ins.com; carrisalee@ava-ins.com; Hsiao Tong (LKKAUTO); CS A Team; Admin A  
**Subject:** ACCIDENT INVOLVING SHC5156R AND SJW1686A ALONG/AT STEVENS ROAD ON 25/10/2018

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

17<sup>th</sup> DEC 2018

Transcab Taxi  
Singapore

Dear Sir,

**OUR REF : CC4/ASM18022593/pa3 // S8M016KJ**  
**YOUR REF : SHC 5156R**  
**ACCIDENT INVOLVING SHC 5156R AND SJW 1686A ALONG/AT STEVENS ROAD ON 25/10/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **Mova Automotive Pte Ltd** acting on behalf of the owner of **SJW 1686A** against your motor insurance policy.

We highlight that this accident has not been reported to your insurer. Under the Motor Claims Framework (MCF), you are required to report any accident with the accident vehicle (whether damaged or not) within 24 hours or by the next working day after the accident. The primary purpose of this reporting is to provide your version of the accident to AXA. We would appreciate it if you could urgently file a report at approved reporting centre.

We also wish to advise that there is an excess of S\$5000/- is attached with Third Party Claims. Please be informed that you shall be liable for the excess following any settlement of the third party claim. The applicability of the excess is as follows:

- 1) Any settlement equal to or above the excess, you shall be liable to make the payment of \$5000/-; or
- 2) Any settlement below the excess, you shall be liable for the amount settled.

We shall keep you informed of the third party claim settlement and thereafter kindly let us have the excess payment in your cheque payable to "AXA Insurance Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

Notwithstanding the excess being applied and/or received by us for the above subject matter, we expressly reserve all our rights under the policy to refund the excess payment in the event that there arises any known policy breach and or exclusion material to coverage.

As Insurers, we shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

## Hsiao Tong (LKKAUTO)

---

**From:** Suann <suann@mova.com.sg>  
**Sent:** Friday, 21 December 2018 2:19 PM  
**To:** Mei Kwan (LKKAUTO); 'Nitha'  
**Cc:** ongbobo@mova.com.sg; Hsiao Tong (LKKAUTO); Admin A; assignments  
**Subject:** RE: TP CLAIMS - SJW1686A AGAINST SHC5156R DOA 25/10/2018 AT STEVENS ROAD \*\*\* LKK REF: CC4/ASM18022593/pa3  
**Attachments:** 21122018141442.tif

Dear Mei Kwan

My client would like to withdraw third party claim.

Thank you

Best Regards  
**Suanne Chiu**  
Claims Asst. Manager  
**MOVA Automotive Pte Ltd**  
Tel: +65 6272 3892  
Fax: +65 6270 8314



Connect with us on  

Privileged/Confidential Information may be contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. All opinions, conclusions and other information expressed in this message not of an official nature shall not be deemed as unless otherwise indicated by an authorized representative independent of this message.

---

**From:** Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]  
**Sent:** Monday, 17 December 2018 16:18  
**To:** Nitha  
**Cc:** ongbobo@mova.com.sg; 'Suann'; Hsiao Tong (LKKAUTO); Admin A; assignments  
**Subject:** RE: TP CLAIMS - SJW1686A AGAINST SHC5156R DOA 25/10/2018 AT STEVENS ROAD \*\*\* LKK REF: CC4/ASM18022593/pa3

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Dear Sir / Madam,

We refer to the above matter.

Please be informed that OI has yet to report the accident and we are currently **pending verification for direct settlement**.

**Please provide us the following and arrange for TP survey.**

- **evidence i.e. video/ scene photo**
- **SMS conversation record regarding private settlement discussion**

Please note that for liability, claim negotiation and settlement, please contact Hsiao Tong at 6742 3197.

Our respective case handler will look into the matter and revert to you in due course.

*To check availability of the case handler, you may contact the undersigned.*

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Nitha <[nitha@moval.com.sg](mailto:nitha@moval.com.sg)>

**Sent:** Thursday, 13 December, 2018 5:22 PM

**To:** SG AXA Insurance SM AXA SGP - Motor Survey <[motor\\_survey@axa.com.sg](mailto:motor_survey@axa.com.sg)>

**Cc:** [ongbobo@moval.com.sg](mailto:ongbobo@moval.com.sg); 'Suann' <[suann@moval.com.sg](mailto:suann@moval.com.sg)>

**Subject:** TP CLAIMS - SJW1686A AGAINST SHC5156R DOA 25/10/2018 AT STEVENS ROAD

Dear All,

Please assist to assign surveyor and officer in charge for the above mention case.

Thank you.

Best Regards,

Nitha

Claims Officer

Mova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314



**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

### ADDENDUM


**(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:**


Original Report No : \_\_\_\_\_ Vehicle Registration No: SJW 1686A  
Name (as shown in NRIC) : LOW SIEN HUA Kenneth NRIC/FIN/Passport No : S1355484F  
(\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate  
Address : \_\_\_\_\_ Singapore ( )  
Contact (Tel) : \_\_\_\_\_ Mobile No. : 96337874  
Email Address : \_\_\_\_\_  
Date of Accident : 25/10/18 Time of Accident : 2.30pm  
Place of Accident : Stevens Road  
Insurance Company : Etiga

**(B) ADDITIONAL INFORMATION / AMENDMENTS:**

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

I would like to withdraw my 3rd Party claim against  
SHC 1561A  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

  
Policyholder / Driver's Signature  
Date: 26/12/18

  
Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_  
Date: \_\_\_\_\_



 <TP withdraw claim - Submit Survey Report> S8M016KJ  
[ACCIDENT INVOLVING SHC 5156R(OI) & SJW  
1686A(TP) ON 25/10/2018]

Type

 Question

Message

Hi, We refer to the above matter. We were informed by third party repairer that their client had decided to withdraw third party claim, In view of this, we will proceed to close file and submit survey report to your good office soon. Hsiao Tong - 24 Dec 2018

[Reply](#)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18022593/R1pa3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:PETER WONG

Date : 28-12-2018



Code : ASM

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SHC 5156R	Veh. Inspected	SJW 1686A
Policy No.		Coverage (\$)	0.00
Claim No.	S8M016KJ	Excess (\$)	0.00
Assign From		Assign Date	14/12/2018

**2. Vehicle Particulars & Condition**

Make & Model	VOLVO XC60 T5	c.c	1999
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	PNVDZ475BC5333141	Colour	GREY
Odometer	84147	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	235/60 R18	PIRELLI	6 mm
L/H Front Tyre	235/60 R18	PIRELLI	6 mm
R/H Rear Tyre	235/60 R18	PIRELLI	6 mm
L/H Rear Tyre	235/60 R18	PIRELLI	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

**5. General Information**

Accident Date	25/10/2018	Inspection Date	21/12/2018
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 1686A**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	CTR RR BUMPER REINF (CONSISTENT) (WCP)	* CHECK	1,380.00	-
1	L/R INN BUMPER BRKT (CONSISTENT) (WCP)	* CHECK	85.00	-
1	L/R OUT BUMPER BRKT (CONSISTENT) (WCP)	* CHECK	90.00	-
1	L/R PARK SYS SENSOR (CONSISTENT) (WCP)	NOT WORKING	185.00	185.00
1	R/R INN BUMPER BRKT (CONSISTENT) (WCP)	* CHECK	85.00	-
1	R/R OUT BUMPER BRKT (CONSISTENT) (WCP)	* CHECK	90.00	-
1	REAR HEAT SHIELD (CONSISTENT) (WCP)	BENT	550.00	550.00
1	REAR SILENCER (CONSISTENT) (WCP)	* CHECK	905.00	-
1	REAR SPOILER (CONSISTENT) (WCP)	SCRATCHED	455.00	455.00
1	RR BUMPER CLAMP KIT (CONSISTENT) (WCP)	* CHECK	120.00	-
1	RR BUMPER CTR COVER (CONSISTENT) (WCP)	SCRATCHED	225.00	225.00
	COST PLUS 15% (PARTS SUPPLIED BY WORKSHOP)		625.50	212.25
			4,795.50	1,627.25
<b>LABOUR</b>				
	PANEL/MECHANICAL		216.00	216.00
	PAINTWORK		216.00	216.00
	MATERIAL COSTS		101.32	101.32
			533.32	533.32
<b>GRAND TOTAL</b>			<b>5,328.82</b>	<b>2,160.57</b>
<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$3,168.25 NETT)</b>				<b>2,160.57</b>

Report Ref No. CC4/ASM18022593/R1pa3q2

**MOHAMMED RASUL BIN MOHD YUNUS**

Automotive Assessor

**HO LEONG CHUAN**

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

## Service Request Details

Claim	58M016KJ				
Reference	CCA/ASHM18022592/PTpa3q2				
Loss Date	25 October 2018				
Request Date	14 December 2018				
Due Date					
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)				
Type of Loss	Third Party Vehicle Damage				
Services	Pending verification - Direct Settlement				


```

graph TD
    A[Approve Invoice] --> B[Wait for Approve Invoice]
    B --> C{Is Invoice Approved?}
    C -- No --> A
    C -- Yes --> D[Send Invoice]
  
```

Vehicle Information	
Incident Vehicle Registration #	SJW1586A
Make	TPVO VOLVO
Model	XC60-2.0 TS (A)
Service Address	
...	

Primary Contact/Insured

Claim Handler  
WANG Peter  
peter.wang@aol.com.sg

Additional Instruction Library		NON-REPORTED				
Messages	Invitation	History	Documents	Assessment	Methods	Notes
<div>Document Type<div>Document SubType</div><div><div></div><div></div></div></div> <div>+ Upload Documents</div>						
NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED		
 LKKInvoice1 (2).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE (TD (TP)	28 December 2018)		

