

22/03/2002

ASS. REC. BY:

REF:

CS3/MSH18022595/B cher

Special Instruction:

Surveyor:

Mr Lim

ASSIGNMENT (Office)

Malina

From (Person):

Pauline Tham

of

MSH

Date/Time:

17.12.2018 358pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SME 1945L

Insured:

SLE 9176Z

at Workshop m/s

Apex Motoring

Tel:

9169 0825

of

25 Kaki Bukit Rd 4 # 01-55 C Synergy

Policy No:

210008590MY

Claim No:

578863

Sum Insured:

Excess:

Make of Veh:

D.O.A.

12.12.2018

(Client's Record)

18.12.2018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:


Date/Time:

17.12.2018 408pm

Person Contacted:

Ms. Lim

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SME 1945L - X
	SLE 9176Z - X
	Repair range 4K - 5K 6 days repair
	 8/1/2019

REF:

ASSIGNMENT

From:

Date:

18/12/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SME 1945L

at Workshop m/s

APEX Motoring

of 25 Kaki Bukit Rd 4, 01-55

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SME 1945 L

Yr Regn:

2018 / Sep 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA Prius

C.C

1798

Colour:

GREY

A/C:

Insured / Std / NI / NA

Sp. Reading

15766

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZVW506138499

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65/15

R:

195/65/15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

18/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

2

Survey Fee:

120

Transportation:

) \$ + RS.) SI

) Photos

) Others

TOTAL

130

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

PRC

Lump Sum / I.B.I: (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Dec 2018		17 Dec 2018 15:58 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	SARATHA D/O SAMMANDHAM, ID: NA			[Created by insurer]					
Main Claimant:	ASIA EXPRESS CAR RENTAL PTE LTD, Co. Reg. No.: 201116882D								
Vehicle Reg. No.:	SME1945L	Date of Loss:	12/12/2018 00:00 - :59 [2 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 578863	Policy/Cover Note No.:	29000859QMY (Comprehensive) Coverage: 05/08/2018 - 04/08/2019						
Vehicle Reg. No. (Insured):	SLE9176Z	Policy No. (Claimant):							
Repairer:	Apex Motoring () 25 Kaki Bukit Road 4, #01-55 Synergy @ KB, 417800 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/12/2018]								
Driver/Custodian (Insured):	KARTHIGESAN S/O GOVINDASAMY (), NRIC: S7120544D								
Adj Asg. Remarks:	on WP. Third Party Pre-Repair Survey. TP reject our list & we nominated LKK to be SJE, vehicle at workshop : 25 Kaki Bukit Rd 4 #01-55 Synergy@KB S'pore 417800 Insured non-reporting. Contact : Miss Lim @ 9169 0825								
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
View All Compose Case Mail									
ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6882D
Vehicle Details	
Vehicle No.:	SME1945L
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8S CVT
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	2ZR2A92597
Chassis No.:	ZVW506138499
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$25,805.00
Original Registration Date:	21 Sep 2018
First Registration Date:	21 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$18,127.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Sep 2028
PARF Rebate Amount:	\$13,595.00
Intended COE Rebate Details	
COE Expiry Date:	20 Sep 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$31,801.00
COE Rebate Amount:	\$30,855.00
Total Rebate Amount:	\$44,450.00

The information contained herein is correct as at 07 Jan 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/12/2018 14:31
Date Of Accident	12/12/2018 18:00
Exact Location Of Accident	CTE TOWARDS BALESTIER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME1945L
Insured/Policyholder	
Name Of Registered Owner	ASIA EXPRESS CAR RENTAL PTE LTD
Co Reg No	201116882D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91372711
Alternative Phone No	OFFICE-91372711

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	HIRER USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5089067751-01
Cover Note Number	

Driver

Name of Driver	LOW CHOON MIN, EDDIE
NRIC No	S8813894E
Date Of Birth	24/04/1988
Occupation	OUTDOOR
Date Of Driving Pass	11/06/2009
Driving Experience	9 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91372711
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	APT BLK 514 SERANGOON NORTH AVENUE 4 #04-278
Postcode	550514
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLE9176Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KARTHIGESAN S/O GOVINDASAMY
NRIC/Passport Number	S7120544D
Contact Number	86610144
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

(a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")

(b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

(e) the information so collected under (d) above may be shared / disclosed:

- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders.


Date & Time: 13/12/18
11:10 am

(If driver is not the policyholder)
Date & Time: 12/12/18
12:10 am

Name: _____
NRIC/FIN No.: _____

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 12/12/2018 at 6pm - I was travelling along CTE.

Traffic was heavy but moving in tandem. At one point, I checked on my left and see no oncoming vehicle. I decided to switch my lane from 2nd to 3rd lane. Upon completing my change of lane, I noticed another vehicle, SLE 4562J, on my left (4th lane) coming into my lane. I stopped momentarily to give way to him, this is when I felt an impact to the rear of my vehicle. I put on my handbrake, gear to 'neutral' and came down to check. That was when I discovered that SLE 91762 collided into the rear of my vehicle.

DECLARATION

(We declare the foregoing particulars are true in every respect)

Policyholder's Signature

Date & Time: 12/12/18

11:10am

REPORTING CENTRE



Driver's Signature

(If driver is not the policyholder)

Date & Time: 12/12/18

11:10am

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:






































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Dec 2018		17 Dec 2018 15:58 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SARATHA D/O SAMMANDHAM, ID: NA								
Main Claimant:	ASIA EXPRESS CAR RENTAL PTE LTD, Co. Reg. No.: 201116882D								
Vehicle Reg. No.:	SME1945L	Date of Loss:	12/12/2018 00:00 - :59 [2 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 578863	Policy/Cover Note No.:	29000859QMY (Comprehensive) Coverage: 05/08/2018 - 04/08/2019						
Vehicle Reg. No. (Insured):	SLE9176Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Apex Motoring () 25 Kaki Bukit Road 4, #01-55 Synergy @ KB, 417800 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Imm.Advice due 18/12/2018]								
Driver/Custodian (Insured):	KARTHIGESAN S/O GOVINDASAMY (), NRIC: S7120544D								
Adj Asg. Remarks:	on WP. Third Party Pre-Repair Survey. TP reject our list & we nominated LKK to be SJE, vehicle at workshop : 25 Kaki Bukit Rd 4 #01-55 Synergy@KB S'pore 417800 Insured non-reporting. Contact : Miss Lim @ 9169 0825								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SME1945L (578863)**
[SLE9176Z]
TP
ASIA EXPRESS CAR RENTAL PTE LTD
Dec 12 2018 12:00AM
[SARATHA D/O SAMMANDHAM]
Apex Motoring

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/01/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
2	03/01/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
3	03/01/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
4	03/01/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
5	03/01/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
6	03/01/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
7	03/01/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
8	03/01/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
9	03/01/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
10	03/01/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
11	03/01/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
12	03/01/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
13	03/01/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
14	03/01/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
15	03/01/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
16	03/01/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
17	03/01/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
18	03/01/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
19	03/01/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
20	03/01/19 09:56	General View	 Load JPG	<input checked="" type="checkbox"/>
21	03/01/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
22	03/01/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
23	03/01/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
24	03/01/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
25	03/01/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
26	03/01/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
27	03/01/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
28	03/01/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
29	03/01/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
30	03/01/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
31	03/01/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
32	03/01/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
33	03/01/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
34	03/01/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
35	03/01/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
36	03/01/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
37	03/01/19 10:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	03/01/19 10:01	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
39	03/01/19 10:01	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
40	03/01/19 10:01	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
41	03/01/19 10:01	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
42	03/01/19 10:01	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
43	03/01/19 10:01	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
44	03/01/19 10:01	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
45	03/01/19 10:01	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
46	03/01/19 10:01	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
47	03/01/19 10:01	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
48	03/01/19 10:01	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
49	03/01/19 10:01	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
50	03/01/19 10:01	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
51	03/01/19 10:01	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
52	03/01/19 10:01	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
53	03/01/19 10:43	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
54	03/01/19 10:43	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
55	03/01/19 10:43	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
56	03/01/19 10:43	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
57	03/01/19 10:43	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
58	03/01/19 10:43	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
59	03/01/19 10:43	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
60	03/01/19 10:43	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
61	03/01/19 10:43	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
62	03/01/19 10:43	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
63	03/01/19 10:43	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
64	03/01/19 10:43	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
65	03/01/19 10:43	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/12/18 18:44	TP PRI	Load PDF	
2	17/12/18 08:57	TP ACCDT REPORT	Load PDF	
3	17/12/18 09:23	TP REJECT SJE & WE NOMINATED LKK	Load PDF	
4	19/12/18 13:31	TP REQUEST FOR RE-SURVEY	Load PDF	
5	27/12/18 08:52	TP WORKSHOP REQUESTING FOR RE-SURVEY	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18022595/BCBE2

Date: 09/01/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29000859QMY

Claimant Vehicle No : SME1945L

Insured Vehicle No : SLE9176Z

Date of Loss: 12/12/2018

Nature of Claim: TP

Claim No: 578863

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SME1945L

Make & Model: TOYOTA PRIUS HYBRID, 1.8 S CVT (A)

Engine No: 2ZR2A92597

Reg. Date: 21/09/2018 (Man. Year: 2018)

Chassis No: ZVW506138499

Colour: Grey

Odometer: 15766 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Dunlop 5 mm

Rear Left Side: Dunlop 5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 17/12/2018

Date Inspected: 18/12/2018 Inspected At:

Apex Motoring
25 Kaki Bukit Road 4, #01-55 Synergy @
KB
Singapore 417800

Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jan 2019)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME1945L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >