

000000

INS CASE OWNER

CC AXA1802

LKK
IDAC

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A:

Nature of Accident:

(VA: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

Insured Liability: %

TP GIA REPORT: YES / NO

Final ? Yes / No



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup):

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO: B 28, Ass. Lia:

Repair Cost:

SS

1312.85

3 VEH C.C. 01 END

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

3w.u (3w x 3 days)

Loss of Income (LOI):

SS

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search

SS

2.w

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

1614.85

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

1614.85

Name 1:

K him thin Auto Ple utel

GIA.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

REF: ASM(CAxA)

ASSIGNMENT

From:

Date: 24/12/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKS 9597E

at Workshop m/s

K. Kim Hin

of:

160 Sin Ming Drive # 02-20

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

After 12pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

882k

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

02 days

Res: Yes or No

Lum Sum:

1.811 %

3 Val: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKS 9597E

n Regn:

05 15

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Camry

CC:

1998

Colour:

M. P. White

A/C:

Insured / Std / NI / NA

Sp. Reading:

36639

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR053DK5100101055

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal:

7

mm

R/Bal:

7

mm

L/Bal:

7

mm

L/Bal:

7

mm

D.O.A:

11/12/18

D.O.I:

24/12/18

Survey held at:

Des. of Damages: Frt / Rear / Q/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/12 File para to Customer

PR # 1226.96 Cred # 2061.24/6381.

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

1. S + RS. \$

2. Photo

3. Other

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format:

Lump Sum / L.B.I: (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18022601/hb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 17-12-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFS 1802A	Veh. Inspected	SKS 9597E	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	17/12/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/12/2018	Inspection Date		
Survey held at	K.KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

K.KIM HIN AUTO PTE LTD
160 Sin Ming Drive
#02-20 Sin Ming AutoCity
Singapore 575722

Claim Reference:
Assessment Number: KKHA0070
Version: K.KIMHIN/2
Date Calculated: 30/03/2019 03:46

Full Report - V1
Registration: SKS9597E
Printed: 30/03/2019 11:47

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	SANDRA KHONG	Date of Incident:	11/12/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA

Claim Reference:		Estimated Repair Time:
Policy Number:		Quote Due Date:
Other Reference:		Actual Repair Days:
Third Party:	True	Parts Ordered Date:
Insured Amount:		Hire Car Start:
Under Warranty:		Hire Car End:
Warranty Expired:		Vehicle Collected:

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Camry
Sub Model:	BASE MODEL
Model Sheet Number:	YA7 01
Registration:	SKS9597E
Registration Month:	May
Registration Year:	2015
VIN Number:	MR053DK5100101055
Manufacture Year:	2015
Odometer:	Not Known
Colour:	
Engine Number:	6ARP016445
Fuel Level:	%

Model Specs

FROM 06/2015	BLIND SPOT MIRROR
REARVIEW CAMERA	RR PARK DIST CONTROL
PARTS ORIGIN JAPAN	REAR SPOILER
PREPARE OFF VEHICLE	THREE COAT PEARL

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	24/12/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		

K.KIM HIN AUTO PTE LTD
160 Sin Ming Drive
#02-20 Sin Ming AutoCity
Singapore 575722

Claim Reference:
Assessment Number: KKHA0070
Version: K.KIMHIN/1
Date Calculated: 24/12/2018 03:41

Full Report - V1
Registration: SKS9597E
Printed: 24/12/2018 11:41

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	SANDRA KHONG	Date of Incident:	11/12/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:	True	Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle	Model Specs
Manufacturer: TOYOTA	FROM 06/2015
Model: Camry	REARVIEW CAMERA
Sub Model: BASE MODEL	PARTS ORIGIN JAPAN
Model Sheet Number: YA7 01	PREPARE OFF VEHICLE
Registration: SKS9597E	BLIND SPOT MIRROR
Registration Month: May	RR PARK DIST CONTROL
Registration Year: 2015	REAR SPOILER
VIN Number: MR053DK5100101055	THREE COAT PEARL
Manufacture Year: 2015	
Odometer: Not Known	
Colour:	
Engine Number: 6ARP016445	
Fuel Level: %	

Not Notified
1-131
Resurvey By repair
2 days

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on
	Inspection:
Brakes Pedal Travel:	Date of Inspection: 24/12/2018
Place of Inspection:	
Pre-Accident Damage:	

Tyres Condition:
Tread Depth LHF:
Tread Depth LHR:
Damage Areas:

Tread Depth RHF:
Tread Depth RHR:
Direction of Impact:

LKH Auto Consultants hence notify

- Repairer of the following:
- Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

K.KIM HIN AUTO PTE LTD

Claim Reference:
Assessment Number: KKHA0070
Version: K.KIMHIN/1
Date Calculated: 24/12/2018 03:41

Full Report - V1
Registration: SKS9597E
Printed: 24/12/2018 11:41

2587	REAR CTR LWR SPOILERNEW PART PAINT K1R	5.0
2671	L/R INN PARKING SENSNEW PART PAINT K1R	3.0
2672	R/R INN PARKING SENSNEW PART PAINT K1R	3.0
2673	L/R OUT PARKING SENSNEW PART PAINT K1R	3.0
2674	R/R OUT PARKING SENSNEW PART PAINT K1R	3.0
2675	L/R INN SENSOR COVERNEW PART PAINT K1R	3.0
2676	R/R INN SENSOR COVERNEW PART PAINT K1R	3.0
2677	L/R OUT SENSOR COVERNEW PART PAINT K1R	3.0
2678	R/R OUT SENSOR COVERNEW PART PAINT K1R	3.0
2711	REAR PANEL REPAIR PAINTING >50%	17.0
2931	BOOTLID REPAIR PAINTING >50%	28.0
2584	REAR BUMPER SURFACE PAINT PLAST. ADD/WORK FOR MULTI-COAT PAINT *	10.0
2588	REAR CTR LWR SPOILERSURFACE PAINT PLAST. ADD/WORK FOR MULTI-COAT PAINT *	4.0
2712	REAR PANEL SURFACE PAINT ADD/WORK FOR MULTI-COAT PAINT *	5.0
2934	BOOTLID SURFACE PAINT ADD/WORK FOR MULTI-COAT PAINT *	8.0

LABOUR COST - PAINT

TIME(PAINT)	120.0
Preparation Main Work Plastic	5.0
Preparation Main Work Metal	25.0
Preparation Work Multi Layer Paint	5.0
Total Work Units (10WU/HR)	155.0
Total Paintwork Labour	15.5HRS

\$697.50

MATERIAL COST - PAINT

New Part Painting - Plastic K1R	\$97.40
Material-Constant Main Work Metal	\$28.60
Surface-/Blend Paint	\$30.70
Surface Paint Plastic	\$49.59
Repair Painting	\$58.86
Material-Const Main Work Plastic	\$9.00
Total Excluding Pearlescent Uplift	\$283.45
Pearlescent Uplift @ 0.0%	\$0.00
Total Paint Material Cost	\$283.45

Cost Price



PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
2583	1	REAR BUMPER	52159 0X908	Buc/nd	0%	280.00* ✓
2587	1	REAR CTR LWR SPOILER	52169 06100		0%	Sm 160.00* X
2591	2	CLIP FASTENING	75392 35220		0%	My 15.00* ✓
2619	1	L/R BUMPER BRACKET	52576 06150		0%	SVC 50.00* ✓
2620	1	R/R BUMPER BRACKET	52575 06150		0%	SVC 50.00* ✓
2640	1	REAR BUMPER SUPPORT	52023 06130		0%	R 130.00* ✓
2651	4	CLIP FASTENING	52161 02030		0%	My 15.00* ✓
2671	1	L/R INN PARKING SENS	89341 33210C0		0%	Sm 185.00* X
2672	1	R/R INN PARKING SENS	89341 33210C0		0%	Sm 185.00* X

Price Valid: 01/06/2015

Claim Reference:
 Assessment Number: KKHA0070
 Version: K.KIMHIN/2
 Date Calculated: 30/03/2019 03:46

Full Report - V1
 Registration: SKS9597E
 Printed: 30/03/2019 11:47



Addresses

Cost Summary

Total Labour	\$571.50
Total Paint/Material	\$256.96
Total Parts	\$356.50
Total of Additional Costs	\$42.00
Excess:	TBA
Grand Total Exc GST:	\$1,226.96
7 % GST:	\$85.89
Grand Total Inc GST:	\$1,312.85

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
 Price/Dent = \$0.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
B410	R + R REAR BUMPER	7.0	31.50
B420)	RENEW REAR BUMPER (REMOVED)	1.0	4.50
NO NUMBER	ADD/WORK FOR PARKING AID SENSOR DRILLING	1.0	4.50
B410)	R + R REAR BUMPER CARRIER	1.0	4.50
NO NUMBER	R + R REAR PARKING AID SENSOR/S	2.0	9.00

LABOUR COST

Total Work Units	12.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	1.2HRS	\$54.00
Paint Labour	11.5HRS	\$517.50
Total Labour	12.7HRS	\$571.50

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- PREPARE OFF VEHICLE		
	- THREE COAT PEARL		
2583	REAR BUMPER NEW PART PAINT K1R	15.0	
2584	REAR BUMPER SURFACE PAINT PLAST.	10.0	
	ADD/WORK FOR MULTI-COAT PAINT *		
2587	REAR CTR LWR SPOILERSURFACE PAINT PLAST.	5.0	
2588	REAR CTR LWR SPOILERSURFACE PAINT PLAST.	4.0	
	ADD/WORK FOR MULTI-COAT PAINT *		
2640	REAR BUMPER SUPPORT SURFACE PAINT	4.0	

K.KIM HIN AUTO PTE LTD

Claim Reference:
Assessment Number: KKHA0070
Version: K.KIMHIN/2
Date Calculated: 30/03/2019 03:46

Full Report - V1
Registration: SKS9597E
Printed: 30/03/2019 11:47

2671	L/R INN PARKING SENSSURFACE PAINT PLAST.	3.0
2672	R/R INN PARKING SENSSURFACE PAINT PLAST.	3.0
2673	L/R OUT PARKING SENSSURFACE PAINT PLAST.	3.0
2674	R/R OUT PARKING SENSSURFACE PAINT PLAST.	3.0
2675	L/R INN SENSOR COVER SURFACE PAINT PLAST.	3.0
2676	R/R INN SENSOR COVER SURFACE PAINT PLAST.	3.0
2677	L/R OUT SENSOR COVER SURFACE PAINT PLAST.	3.0
2678	R/R OUT SENSOR COVER SURFACE PAINT PLAST.	3.0
2711	REAR PANEL SURFACE PAINT	6.0
2712	REAR PANEL SURFACE PAINT	5.0
	ADD/WORK FOR MULTI-COAT PAINT	
	*	
2931	BOOTLID SURFACE PAINT	9.0
2934	BOOTLID SURFACE PAINT	8.0
	ADD/WORK FOR MULTI-COAT PAINT	
	*	

LABOUR COST - PAINT

TIME(PAINT)	90.0	
Preparation Main Work Plastic	15.0	
Preparation Comp. Work Metal	5.0	
Preparation Work Multi Layer Paint	5.0	
Total Work Units (10WU/HR)	115.0	
Total Paintwork Labour	11.5HRS	\$517.50

MATERIAL COST - PAINT

New Part Painting - Plastic K1R	\$78.72
Surface-/Blend Paint	\$67.81
Surface Paint Plastic	\$63.53
Material-Const Main Work Plastic	\$28.60
Material-Const Comp. Work Metal	\$9.00
Total Excluding Pearlescent Uplift	\$256.96
Pearlescent Uplift @ 0.0%	\$0.00
Total Paint Material Cost	\$256.96

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
2583	1	REAR BUMPER	52159 0X908		0%	280.00*
2591	2	CLIP FASTENING	75392 35220		0%	15.00*
2651	4	CLIP FASTENING	52161 02030		0%	15.00*
f: OEM Parts			Sub Total			\$310.00
g: Original			Mark Up From Cost	(15 %)		\$46.50
h: Secondhand			Sundry Parts	(Fixed)		\$0.00
p: Parallel			Total Parts			\$356.50
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEE	0%	\$42.00
SPECIALIST		
Total Extras		\$42.00

Final Calculation

Total Parts	\$356.50
Labour	
Total Panel/Mechanical	\$54.00

K.KIM HIN AUTO PTE LTD**Claim Reference:****Assessment Number: KKHA0070****Version: K.KIMHIN/2****Date Calculated: 30/03/2019 03:46****Full Report - V1****Registration: SKS9597E****Printed: 30/03/2019 11:47**

Total Paintwork	\$517.50	
Total Labour		\$571.50
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$42.00	
Total of Additional Costs		\$42.00
Total Paint/Material Costs		\$256.96
Grand Total Excludes GST		\$1,226.96
GST @ 7 %		\$85.89
Grand Total Includes GST		\$1,312.85

Assessment Notes

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	6900T
Vehicle Details	
Vehicle No.:	SKS9597E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	13 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.0 AUTO
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	6ARP016445
Chassis No.:	MR053DK5100101055
Maximum Power Output:	123.0 kW (164 bhp)
Open Market Value:	\$27,591.00
Original Registration Date:	18 May 2015
First Registration Date:	18 May 2015
Transfer Count:	0
Actual ARF Paid:	\$30,628.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 May 2025
PARF Rebate Amount:	\$22,971.00
Intended COE Rebate Details	
COE Expiry Date:	17 May 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$77,600.00
COE Rebate Amount:	\$49,876.00
Total Rebate Amount:	\$72,847.00

The information contained herein is correct as at 13 Dec 2018

OK



<TP - Mandate IA> - S8M016KF [ACCIDENT INVOLVING SFS 1802A(OI) / SKS 9597E(TP) / OTHERS ON 11/12/2018]

Type

Question

Message

Liability: 100%. 3 vehicles chain collision whereby OI was 2nd car. Under MCF, we have to settle the claim submitted by the car in front of OI. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$1,620.30(if claim LOU) - \$1,801.80(if claim LOR). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 01 July 2019

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563564 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 01/07/2019

Survey Details:

Date of loss	11.12.2018
Date of appointment	15.12.2018
Date of survey	24.12.2018
Location of survey	K.KIM HIN AUTOMOTIVE PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SKS9597E
Make and Model	Toyota Camry (1998cc)
Date of registration	18.05.2015
Excess	
Market Value/ Book Value	\$ 82,000.00 (est)
Parf/COE Rebate	\$ 72,847.00 (est)
Nett Value/ ERV	\$ 9,153.00 (est)

Repair details:

Initial Estimate	\$ 3,288.20
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 356.50
Check items (estimate)	NIL
Labour	\$ 870.46
Supplementary	NIL
Total	\$ 1,226.96
Lump Sum(if applicable)	-

Number of days for repair	<u>2</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (665) 62563561 FAX : (665) 62564315

Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 1,312.85	\$ 1,312.85
Loss of use (3days x \$100.00)	\$ 300.00	NIL
Loss of rental (w/GST)(3days x \$150.00)	NIL	\$ 481.50
Loss of income	NIL	NIL
LTA/GIA search fees	\$ 7.45	\$ 7.45
Others (Audatex Fee)	NIL	NIL
Proposed Total	\$ 1,620.30	\$ 1,801.80



Re:RE: <TP - Mandate IA> - S8M016KF [ACCIDENT INVOLVING SFS 1802A(OI) / SKS 9597E(TP) / OTHERS ON 11/12/2018]

Type

🔔 Question

Message

PLS PROCEED DS QUANTUM AS PROPOSED

Reply

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 7 August 2019 8:05 AM
To: service@ k kim hin (service@kkimhin.com.sg); Margaret KKH
Cc: Admin A
Subject: <Request for LOD & Docs> Your Ref: SKS9597E *Our Ref: CC4/ASM18022601/Kpb3 [ACCIDENT INVOLVING SFS 1802A(AXA) & SKS 9597E ON 11/12/2018]

Your Ref: **SKS9597E**
Our Ref: CC4/ASM18022601/Kpb3

Without Prejudice

Dear Sirs/Mdm,

ACCIDENT INVOLVING SFS 1802A(AXA) & SKS 9597E ON 11/12/2018

We refer to the above matter.

For COR, recommended amount at **P/P \$1,226.96(before GST)** with **02 repair days**.

****Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us [LKK] for our necessary action.**

Please note that all the finalisation subject to insurer approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From: margaret@kkimhin.com.sg
Sent: Wednesday, 16 October 2019 11:50 AM
To: Hsiao Tong (LKKAuto); claims@kkimhin.com.sg
Cc: Admin A
Subject: RE: <Request for LOD & Docs> Your Ref: SKS9597E *Our Ref: CC4/ASM18022601/Kpb3 [ACCIDENT INVOLVING SFS 1802A(AXA) & SKS 9597E ON 11/12/2018]

Our Ref: 180822/12

Hi Hsiao Tong

Reference to your offer dated 16 October 2019.

We confirm acceptance of your offer of settlement at **\$1,614.85**. Please arrange PB and payment to be made payable to K. Kim Hin Auto Pte Ltd.

Rgds

Margaret
K. Kim Hin Auto Pte Ltd.

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Wednesday, October 16, 2019 8:54 AM
To: service@k kim hin (service@kkimhin.com.sg) <service@kkimhin.com.sg>; Margaret KKH <margaret@kkimhin.com.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: <Request for LOD & Docs> Your Ref: SKS9597E *Our Ref: CC4/ASM18022601/Kpb3 [ACCIDENT INVOLVING SFS 1802A(AXA) & SKS 9597E ON 11/12/2018]

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 1,312.85
2. Loss of Use (3days x \$100.00)	\$ 300.00
3. LTA/GIA Search Fee	\$ 2.00
Total	\$ 1,614.85

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Wednesday, 7 August 2019 8:05 AM

To: service@k kim hin (service@kkimhin.com.sg) <service@kkimhin.com.sg>; Margaret KKH
<margaret@kkimhin.com.sg>

Cc: Admin A <admin-a@lkkauto.com>

Subject: <Request for LOD & Docs> Your Ref: SKS9597E *Our Ref: CC4/ASM18022601/Kpb3 [ACCIDENT INVOLVING SFS 1802A(AXA) & SKS 9597E ON 11/12/2018]

Your Ref: **SKS9597E**

Without Prejudice

Our Ref: CC4/ASM18022601/Kpb3

Dear Sirs/Mdm,

ACCIDENT INVOLVING SFS 1802A(AXA) & SKS 9597E ON 11/12/2018

We refer to the above matter.

For COR, recommended amount at **P/P \$1,226.96(before GST)** with **02 repair days**.

**Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Please note that all the finalisation subject to insurer approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

◀ Service Request Details

Claim

S8M016KF

Reference

None 

Loss Date

11 December 2018

Request Date

14 December 2018

Due Date

21 December 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

17-12-2018 @ 1030am
Shuman veh not in

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKS9597E

Make

TPVD TOYOTA

Service Address

...

Primary Contact/Insured

TAN SEOK PING
52 CHU YEN STREET, 669845, Singapore

KKYEOMS@SINGNET.COM.SG

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions
NON-REPORTED

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

TYPE



SENT

15/12/18 10:07 PM

FROM

CHAN Kian Chuan

SUBJECT

DS

BODY

DOC SHARED. PLS PROCEED FOR DS WITH QUANTUM TO BE

...



TYPE



SENT

14/12/18 9:13 AM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

BODY

Kindly provide us the workshop detail.



Catherine Chong (LKK Auto)

From: service@kkinhin.com.sg
Sent: Thursday, 13 December, 2018 7:50 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: sandrakhong@gmail.com; admin1@kkinhin.com.sg
Subject: Accident Involving SKS9597E and SFS 1802 A on 11/12/2018
Attachments: GIAreport.PDF

Categories: Shailendra

Dear Claims Officer

Good day to you.

Enclosed our client GIA report SKS 9597 E who was hit by your insured SFS 1802 A on 11 Dec 2018 (Chain Collision).

Vehicle is not in yet.

Please kindly assign a surveyor and officer for this case. Greatly appreciates.

Thanks & Regards
Sandra
6452 7018
K. Kim Hin Auto Pte Ltd

Your Ref : SFS1802A
Our Ref : 180822/12

11.12.2018

Miss Choi SunYoung

Correspondence Address :

c/o M/s K. Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20 Sin Ming AutoCity
Singapore 575722

E-mail : claims@kkimhin.com.sg

Date : 11.09.2019

AXA Insurance Pte Ltd
Motor Claims Dept.
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Dear Sir/Madam

**ACCIDENT INVOLVING SKS9597E AND SFS1802A ALONG NEAR ARC ON
ALEXANDRA ROAD ON 11.12.2018.**

I am the owner of the m/vehicle SKS9597E which was involved
in the above accident.

My vehicle sustained damages as a result of the said accident and
I am now claiming against you for the followings:-

1. Costs of repairs	\$ 1,312.85
2. Loss of use of vehicle at \$ 120.00 per day for 03 day(s)	\$ 360.00
3. Police documents/Search fees	\$ 2.00
4. Surveyor report fee	\$
Total:					\$ 1,674.85 =====

Please advise whether you are prepared to settle my claim as
outlined above. As I have yet to settle my repair bill with my
repairers, I hereby authorise my repairers and/or their
representatives to negotiate/compromise settlement of above claim
on my behalf.

Looking forward to hear from you soon.

Yours faithfully,



encl.



AUTO PTE LTD

TAX CLAIM INVOICE

金興(龔)汽車私人有限公司

NO: 123103

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Accident Date : 11-Dec-2018

Date : 11-Sep-2019

Our Ref : 180822 / ANGIE

PAGE : 1

AXA INSURANCE PRIVATE LIMITED
8 SHENTON WAY
#24-01 AXA TOWER
Singapore 068811

FINAL REPAIR BILL FOR TOYOTA CAMRY 2.0 AUTO (2015) SKS9597E ✓
=====

1 pc rear bumper		280.00 c	
2 pcs clip fastening	@ S\$ 7.50	15.00 c	
4 pcs clip fastening	@ S\$ 3.75	15.00 c	

		310.00	
	Add 15% :	46.50	
		-----	356.50
1 pc audatex fee			42.00 sn
To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.			828.46
To remove and refit reverse sensor assy.			
To putty and respray on affected portions.			

	1,226.96
Add 7% GST :	85.89

Total :	S\$ 1,312.85
	=====

Singapore Dollars One Thousand Three Hundred
and Twelve and Cents Eighty Five Only

金興(龔)汽車私人有限公司
K. KIM HIN AUTO PTE LTD

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Friday, 3 May 2019 1:55 PM
To: carolinetan33@hotmail.com
Subject: ACCIDENT INVOLVING SFS1802A AND SKS9597E ALONG ALEXANDRA ROAD TOWARDS PASIR PANJANG ROAD ON 11/12/2018

Dear Ms. **TAN SEOK PING**,

OUR REF : CC4/ASM18022601/Khb3
YOUR REF : SFS1802A
ACCIDENT INVOLVING SFS1802A AND SKS9597E ALONG ALEXANDRA ROAD TOWARDS PASIR PANJANG ROAD ON 11/12/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Singapore Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s K KIM HIN AUTO PTE LTD, acting on behalf of the owner of SKS9597E against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had was involved in a 3 vehicle chain collision and your vehicle was the second vehicle. Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being pending for final allocation of liability in settlement by our principal.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to khanchna@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Authorization Letter for the Driver to drive the vehicle
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at khanchna@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Letter of Authorization

To Whom It May Concern

Accident on 11th December 2018 involving SKS9597E and SFS1802A


Along Near ARC on Alexandra Road

I/We Choi SunYoung NRIC NO. G3156900T of
c/o 30 Pasir Panjang Road #17-31/32 Mapletree Business City S(117440)

owner of Motor Vehicle Registration No. SKS9597E insured by
QBE INSURANCE (SINGAPORE) PTE LTD under Policy No. 8-V0010565-MVA-

do hereby authorize M/s K. Kim Hin Auto Pte Ltd as my/our
representative with full authority to write, negotiate and settle claim for damages on my/our
behalf against the owner and /or driver of Motor Vehicle Regn No. SFS1802A
in regard to the above mentioned accident

I /We also consent to the agreed settlement sum be made in favour of my/our representative,
M/s K. Kim Hin Auto Pte Ltd and the said
payment be forwarded to them to be construed as full and final discharge of my/our claim.


Owner's Signature & Company Stamp

11.09.2019

Date



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SFS 1802A	(Insd veh)	Model: TOYOTA CAMRY 2.0 AUTO
	SKS 9597E	(TP veh)	
Date of Accident/ Time:	11/12/2018		

Repair Estimate	: \$	3,518.57	
Final Repair Cost (WITH GST)	: \$	1,312.85	
Loss of Use	: \$	300.00	3 days at \$100.00 per day
Rental (if any)	: \$	—	days at \$ per day
LTA / GIA Search Fee	: \$	2.00	
Others	: \$		
Final Settlement Sum	: \$	1,614.85	

Payee Name : K KIM HIN AUTO PTE LTD

Is Third Party Workshop GIA Registered? ☒ YES | ☐ NO (Kindly indicate below)

A)	For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/No BOLA Scenario No: 28
	BOLA Liability: 100 (%)	Assessed Liability (*): 0 (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		
Remarks:		

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and/or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident

 Signature of workshop representative / Workshop stamp Name of Representative: EWEK TO YONG Date: 17-10-2019	 Signature of Witness / Workshop stamp (if applicable) Name of Witness: HANAGARET Date: 17-10-2019
 Signature of AXA's surveyor/representative Name of AXA's surveyor / Representative: Date:	

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

SFS 9597E

Third Party Insurer Enquiry

Our Ref No: GR-18-192983

Date of Request: 13/12/2018

Your Ref No: Online Purchase

K Kim Hin Auto Pte Ltd
160 Sin Ming Drive #02-20
Sin Ming AutoCity
Singapore 575722

Dear Sir/Madam,

Enquiry Date 13/12/2018
Enquiry By Sandra Khong Yee Teng
TP Vehicle No. SFS1802A
Accident Date 11/12/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SFS1802A	AXA Insurance Pte Ltd	16/08/2018-15/08/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-192983

Date of Request: 13/12/2018

Your Ref No: Online Purchase

K Kim Hin Auto Pte Ltd
160 Sin Ming Drive #02-20
Sin Ming AutoCity
Singapore 575722

Dear Sir/Madam,

Enquiry Date 13/12/2018
Enquiry By Sandra Khong Yee Teng
TP Vehicle No. SFS1802A
Accident Date 11/12/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:


☒ GIRO ☐ Cash ☐ Cheque

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18022601/Kpb3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN			Date : 29-10-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFS 1802A	Veh. Inspected	SKS 9597E	
Policy No.	GA384589/1	Coverage (\$)	0.00	
Claim No.	S8M016KF	Excess (\$)	0.00	
Assign From		Assign Date	17/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	MR053DK5100101055	Colour	METALLIC PEARL WHITE	
Odometer	36639	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	BRIDGESTONE	7 mm	
L/H Front Tyre	215/60 R16	BRIDGESTONE	7 mm	
R/H Rear Tyre	215/60 R16	BRIDGESTONE	7 mm	
L/H Rear Tyre	215/60 R16	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/12/2018	Inspection Date	24/12/2018	
Survey held at	K.KIM HIN AUTO PTE LTD 160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 9597E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (WCP) (CONSISTENT)	BUCKLED / DENTED	280.00	280.00
1	REAR CTR LWR SPOILER (WCP) (CONSISTENT)	SERVICEABLE	160.00	-
2	CLIP FASTENING (WCP) (CONSISTENT)	NECESSARY	15.00	15.00
1	L/R BUMPER BRACKET (WCP) (CONSISTENT)	SERVICEABLE	50.00	-
1	R/R BUMPER BRACKET (WCP) (CONSISTENT)	SERVICEABLE	50.00	-
1	REAR BUMPER SUPPORT (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	130.00	-
4	CLIP FASTENING (WCP) (CONSISTENT)	NECESSARY	15.00	15.00
1	L/R INN PARKING SENS (WCP) (CONSISTENT)	SERVICEABLE	185.00	-
1	R/R INN PARKING SENS (WCP) (CONSISTENT)	SERVICEABLE	185.00	-
1	L/R OUT PARKING SENS (WCP) (CONSISTENT)	SERVICEABLE	185.00	-
1	R/R OUT PARKING SENS (WCP) (CONSISTENT)	SERVICEABLE	185.00	-
1	L/R INN SENSOR COVER(WCP) (CONSISTENT)	SERVICEABLE	20.00	-
1	R/R INN SENSOR COVER(WCP) (CONSISTENT)	SERVICEABLE	20.00	-
1	L/R OUT SENSOR COVER (WCP) (CONSISTENT)	SERVICEABLE	20.00	-
1	R/R OUT SENSOR COVER (WCP) (CONSISTENT)	SERVICEABLE	20.00	-
1	MANUFACTURER BADGE (WCP) (CONSISTENT)	NOT NECESSARY	32.00	-
1	EQUIPMENT BADGE (WCP) (CONSISTENT)	NOT NECESSARY	30.00	-
1	BADGE MODEL (WCP) (CONSISTENT)	NOT NECESSARY	33.00	-
1	'D-45' EMBLEM (WCP) (CONSISTENT)	NOT NECESSARY	30.00	-
	COST PLUS 15%		246.75	46.50
			1,891.75	356.50
SPECIAL NETT ITEMS				
1	AUDATEX FEE (SN)(CONSISTENT)	NECESSARY	42.00	42.00
			42.00	42.00
LABOUR				
	PANEL/MECHANICAL INCLUSIVE OF THE REPAIR OF REAR BUMPER SUPPORT.		373.50	54.00
	PAINTWORK.		697.50	517.50

Report Ref No. CC4/ASM18022601/Kpb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PAINT/MATERIAL COSTS.		283.45	256.96
			1,354.45	828.46
	GRAND TOTAL		3,288.20	1,226.96
	RECOMMENDED COST OF REPAIRS			1,226.96

Report Ref No. CC4/ASM18022601/Kpb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

<< Service Request Details

Claim	SALM016KF	Vehicle Information	
Reference	CC4/ASM18022601/Kpb3q2	Incident Vehicle Registration #	SKSW597E
Loss Date	11 December 2018	Make	TMVD TOYOTA
Report Date	14 Dec 2018 8:42:25 AM	Model	CAMRY 2.0 (A)
Request Date	29 July 2019	Service Address	
Due Date		...	
Vendor Name	LUK AUTO CONSULTANTS PTE LTD (TP)	Primary Contact/Insured	
Type of Loss	Third Party Vehicle Damage		TAN SEOK PING 52 CHU YEN STREET, 669845, Singapore KKYEOMSG@SINGNET.COM.SG
Services	Pending verification - Direct Settlement	Claim Handler	
			CHAN Kian Chuan 68805444 kianchuan.chan@saxa.com.sg

Actions

Next Step

Wait for Approve Invoice

Add Invoice















Additional InstructionsNON-REPORTED

3 MessagesInvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merlimon	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1 (3).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
 LKKInspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
 LKKAdjustment1a (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
 GIA_SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
 PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
 AUTHOBISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
 LETTER TO Cl.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
 TP_ESTIMATE_MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	1 July 2019
 LKK Resurvey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	1 July 2019
 TP-Mandate (A dt 010719).pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	1 July 2019
 PARF_CODE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	1 July 2019
 Audition Report (KCS9597E).pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	1 July 2019
 LKK Survey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	1 July 2019
 EMAIL.mig	Letters and Correspondence	Workshop	RATAN BHOSALE (ragal)	17 December 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 FBI FROM WORKSHOP WITH TP CIA 5K39597E.mig	Form / Claim Documents	Others	KUMAR Shalindra	14 December 2018