| 15/5d010   | toel   | GC 4, Gal 180  | 72633,   | fe3sv LKK:  |  |                                   |
|--|--|--|--|---|--|-----------------------------------|
| Surveyor   | Tenufikh   | DOI: ASSIGN  | MENT   | Pohky<br>Date/Time: 17  | 12/18  | ( ( + 4 de 10 + 1 ) 10 de 14 + 14 |
|  | en se voe  | 6.4  | 1.77   | Registered in Merimen:  | -  |                                   |
| Pre-assign / CCU   | C 6 6 6  |  | Claim No.  |   |  | 3                                 |
| Name of Insured  | : LAKK AAS   | li Itan  | Policy No.   |   |  |                                   |
| Insured Tel No.  |  | IP:  | Make / Model   |   |  |                                   |
| Excess Sec II :S\$  Is driver the owner  |  | 81.C1121   | Place of Acciden   | :: Apmipae  | 79 W   | 1p7_                              |
| If NO, Driver Nan  | 1.60   | Vature of Accident :   |  | ()  | 76.0   |                                   |
| Driver Tel 1   |  | (V/L:(YES)/NO)   | OI GIA REPORT<br>Insured Liability   | T: (ES/NO; TP GIA REP<br>: % Final?   |  | 0                                 |
| Sm 6 590   | y_ →   | >  |  |   |  |                                   |
| INSRS: WSP: Tel: Liability: RMKS:  | WASP: Tel: Liability RMKS:   |  | INSRS:<br>WSP:<br>Tel:<br>Liability;<br>RMKS:  | WS Tel  |  |                                   |
| Data Time  | SWG 51104, X -   |  |  |   |  |                                   |
| MIX  | 1  | the reserve Charles  | The state of the s | STAGE   | DATE / F   | 'IC                               |
| ( hor)   | 1649711 - CC3 [P   | 4 120200 61 (001212  |  | Non-Reporting ltr (1st):<br>Non-Reporting ltr (2nd):  |  |                                   |
| OF IC  | -(cd/h   | CITO MAJOHNI 1936  | is will adulate  | Non-Reporting ltr (Final);  |  |                                   |
|  | 10 1 VI  | 1  |  | Notification ltr (if non-pickup):   |  | - 777                             |
|  | TP Video testinge  | 1 U Muc / Ea   |  | Call OI:  | 0.1  | _                                 |
| 21/10/201  | 1 Spoke to 01, (me)-   | I out dest defeat  |  | Documentation Check List:   |  | ist                               |
| 55554541591  |  | 1 13   |  | Notification ltr (if non-pickup)  |  |                                   |
|  | ALC: N   | 11 11 11 11 11 11 11 11  |  | After call itr to OI:   | V  |                                   |
|  | were ALD will be   | attilled this even lat   |  | Authorisation To Act:   | V  |                                   |
|  |  |  |  | Release Voucher:  | 7  |                                   |
|  |  |  |  | Final Repair Bill:<br>Car Rental Invoice:   | V  |                                   |
| 10   |  |  |  | Fowing Invoice  |  |                                   |
|  |  |  |  | LTA/GIA:  |  | -                                 |
|  |  |  |  | Medical Bill:   | W  |                                   |
|  |  |  |  | PIR:  | -  | - 2                               |
|  |  |  |  | Mandate/Reject Instruction:   | 1.7  | -                                 |
|  | 100  | _/   |  | LOD   |  |                                   |
| DDET TATALL DAY  | the beter part photo   |  |  | Payment Breakdown Form:   |  |                                   |
| PRELIMINARY ADVICE   | Date/Time: 7th (1-1-2-2)   | Sent By:   |  | Post-Repair Photos:   |  |                                   |
| FINALIZATION   | P. III III   | )  |  | Others:   |  |                                   |
| Repair Cost:   | Date/Time:   | Confirm with:  |  | Confirm by:   |  |                                   |
| FINAL SETTLEMENT   | \$\$ 5,670.43 (5   | days) Reduction: 53.02   | %  | Email   | Call   |                                   |
| Final Liability:   | The second secon | Confirm with Hily  |  | Email Call  |  | 9                                 |
| Repair Cost: (u/h5t)   | % (M) (Agreed / A  | Assessed) BOLA S/N No. :   | 5  | If NO or B 28, Ass. Lia:  |  |                                   |
| Loss of Rental (LOR):  | SS 5,425.36  | dena   |  | M Asa +   | Inut: 1  |                                   |
| Loss of Use (LOU):   | S\$ (30.00 (\$ 90.00x 7  | days)<br>days)   |  | u= inpose c   | Horfe the  |                                   |
| Loss of Income (LOI):  | SS - (\$ x   | days)  |  | 70-101  | SEWIT.   |                                   |
| LOR only LOU only  | The second secon | R+LOI Tick only on   | e1   | 201   | . 0  |                                   |
| GIA/LTA Search   | S\$ 2.00   | Tank only on   |  | 58(01   | 17   |                                   |
| Medical:   | S\$ -  | 72   |  | 1) Claim status: Normal/Reje  | ot/Deixes Care   |                                   |
| Disbursement;  | S\$ -  | (e.g. Tow/ Independe   |  | Claim status: Normal/Reje     Report Format:  | cornvate Settle  | 0                                 |
| Legal Cost   | S\$  | The state of the s |  |   | 00.710   |                                   |
| Total:   |  | Global Sum S\$:  | a Altinoa — olle —   | 7.20  | VV-I/V   |                                   |
| FINAL PAYMENT  | Date/Time:   | Confirm with:  |  | Email Catt  | normino con a series de la constitución de la const |                                   |
| Payee 1:   |  | Name 1: Jolkswayen   | Centre Singer  |   |  |                                   |
| Payee 2: (Strike if N.A.) Payee 3: (Strike if N.A.)  |  | Neme 2:  |  |   |  |                                   |
| The state of the s | S\$  | Name 3:  | to an extension of the second  | Water Committee of the |  |                                   |

Alexandra Road 159934 Singapore

VGS Singapore

Phone No. Fax No.

+65 6305 7299 +65 6474 3643

E-Mail

service@vw.com.sg

VAT Registration No. M20098505-2

199101494Z

## Service Quote

Customer No.

CV028369

Quote No.

SER/QUO/1802136

QuoteDate Salesperson

12/12/18 Grace Sng

Page

\* EMSTOMER INFORMED ALIGNMENT OUT AFTER ACCIDENT. \*

Model Description

THIS IS NOT AN OFFICIAL TAX INVOICE

Make Volkswagen Passeng Passat 1.8 TSI Comfortline

VGS Singapore, 247, 159934 Singapore

296A BUKIT BATOK STREET 22

WANG HAOMING

Singapore, 651296

#31-60

Singapore

License No. SMG590Y

VIN

WVWZZZ3CZKE019294

**Engine Code** Labor Type

Mileage 17

Initial Registration

30/11/18 Engine No. CJS 298031

Service Advisor Kong Charmaine Sales Advisor Grace Sng

Model Code 3G24JZ

|   | No.                 | Description                | Qty. | UoM                | Unit Price | ,      | Amount     |
|---|---------------------|----------------------------|------|--------------------|------------|--------|------------|
| p | B&P ALEX LABOUR     | LABOUR                     |      | V 1914 4 5 5 5 5 5 |            | 1680   | ALTO TANKS |
| P | B&P ALEX PAINT      |                            | 4    |                    |            | 1100 3 | ,360.00    |
| D |                     | SPRAY PAINT                | 4    | Labor              |            | 3      | ,200.00    |
|   | B&P WHEEL ALIGNMENT | B&P WHEEL ALIGNMENT -NETT  | 1    |                    |            |        | 360.00     |
| Р | B&P DIAG            | PROGRAMMING & CALIBRATION  | 1    | Time Un            |            |        | 480.00     |
| - |                     | COMPULSORY TO DO AFTER AC  |      |                    |            |        |            |
| P | B&P MECH            | CHECK WIRE HARNESS, ECU, S | 1    | Time Un            |            |        | 280.00     |
|   |                     | Nett                       |      |                    |            |        |            |
|   |                     | Sum Labor                  |      |                    |            | 7      | ,680.00    |
| P | 3G0805912Q          | WHEEL HOUSE RH             | 1    | Pieces             |            | ľ      | 84.70      |
| P | 3G0805970F          | WHEEL HOUS RH              | 1    | Pieces             |            |        | (108.14    |
| P | 3G0807050           | BUMPER BRACKET RH          | 1    | Pieces             |            |        | 2 45.91    |
| P | 3G0807178           | BUMPER GUIDE RH            | 1    | Pieces             |            |        | 79.69      |
| P | 3G0807217K GRU      | FRT BUMPER COVER           | 1    | Pieces             |            | F.     | .445.73    |
| P | 3G0821022A          | RHF FENDER                 | 1    | Pieces             |            |        | 670.43     |
|   |                     | Predecessor 3G0821022      |      | 1 10003            |            | Der    | 070.43     |
| P | 3G0853245 2ZZ       | CHROME MOLDING CENTER      | 1    | Pieces             |            | 03     | 230.02     |
| Р | 3G0853253 2ZZ       | CHROME MOLDING LH          | 1    | Pieces             |            | 7      | 117.97     |
| P | 3G0853254 2ZZ       | CHROME MOLDING RH          | 1    | Pieces             |            |        | 105.02     |
| P | 3G0998493           | SENSOR BRACKET             | 1    | Pieces             |            | my ?   | 70.01      |
| P | D 180KU2A1          | 2KADHESIVE                 | 1    | Pieces             |            | ) 1    | 89.84      |
| P | D 822150A1          | BONDAGENT                  |      | Pieces             |            | ( 7    | 64.27      |
|   |                     |                            |      |                    |            | ſ,     |            |
|   |                     |                            |      | Sum carri          | ed forward | 10.    | 791.73     |

VGS Singapore, 247, 159934 Singapore

WANG HAOMING 296A BUKIT BATOK STREET 22 #31-60 Singapore, 651296 Singapore

VGS Singapore

Alexandra Road 159934 Singapore

Phone No.

+65 6305 7299

Fax No.

+65 6474 3643

E-Mail

service@vw.com.sq

VAT Registration No. M20098505-2

Tax No.

1991014947

Service Quote

Customer No.

CV028369

Quote No.

SER/QUO/1802136

QuoteDate

12/12/18

Salesperson

Grace Sng

Page

THIS IS NOT AN OFFICIAL TAX INVOICE

Service Advisor

Kong Charmaine

Make

Volkswagen Passeng

License No.

Engine Code

SMG590Y

Model Description

Passat 1.8 TSI Comfortline

WVWZZZ3CZKE019294

Labor Type

Mileage

Initial Registration

30/11/18

Engine No. CJS 298031 Sales Advisor

Grace Sng

Model Code 3G24JZ

Continued

10,791.73

Sum Item

3,111.73

Sum Labor

Sum Item

7,680,00

3,111.73

Total

SGD

10.791.73

10,791.73

7% GST Total SGD Incl. GST

755.42 11,547.15

Explanations

P = Proportionately Charged

Payment Terms

No Credit

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Payments to:

- BBN: - Acc.-No ..:



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref:

TBA

Our ref:

CC4/EQI18022633/T1fa3

Date:

24/12/2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

#### PRELIMINARY ADVICE OF VEHICLE NO.

**SMG 590Y** 

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 19/12/2018 at the premises of M/s Volkswagen Centre Singapore - Alexandra have the following to report:-

| Workshop Estimate Amount      | : S\$ | 10,791.73 |
|-------------------------------|-------|-----------|
| Revised Estimate Amount       | : S\$ | 5,070.43  |
| "Check" Items Amount          | : S\$ | 995.57    |
| Total (Including Check Items) | : S\$ | 6,066.00  |
| Market Value                  | : S\$ |           |
| LTA Reimbursement Value       | : S\$ | 4         |
| Nett Value                    | : S\$ | -         |

Description of Damage:

The vehicle sustained damages at the

Front O/S Portion

rear nearside

Comments/Present Status:

Damages Consistent

Estimated normal period for repairs:

5.0 days

Yours faithfully,

MOHD. TAUFIKH

Licensed Appraiser

#### Nivitha (LKK Auto)

From:

Shu Pei (LKKAuto) <shupei@lkkauto.com>

Sent:

Monday, 17 December 2018 9:37 AM

To:

assignments

Subject:

FW: PRS FOR SMG590Y (EQ: SGG9711C)

Attachments:

14122018134822-0001.pdf

9-52am@17/12/18 Chemeine UNI

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: <a href="mailto:shupel@lkkauto.com">shupel@lkkauto.com</a> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | \$(408933)

From: Joel Goh <joel.goh@eqinsurance.com.sg> Sent: Monday, 17 December 2018 9:36 AM

To: Kong, Charmaine (VWG Singapore) < charmaine.kong@vw.com.sg>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: PRS FOR SMG590Y (EQ: SGG9711C)

#### Without Prejudice

Dear Charmaine

Thank you for your attachments.

We welcome direct settlement for this accident and will assign LKK to handle this matter.

Dear LKK

Please assist on the following DS.

Best Regards,

Joel Goh

Executive | Claims



#### **EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190 www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: Kong, Charmaine (VWG Singapore) [mailto:charmaine.kong@vw.com.sg]
Sent: Friday, December 14, 2018 5:58 PM
To: Joel Goh

1.7


Subject: RE: PRS FOR SMG590Y (EQ: SGG9711C)

Dear Joel,

Clearer Screenshots FYI...







#### Thanks.

Best Regards,

Charmaine Kong Insurance Service Advisor Aftersales

Volkswagen Group Singapore Pte Ltd 247 Alexandra Road Singapore 159934


Direct line: +65 6305 7176

Main Line: +65 6305 7299

Main Fax: +65 6474 3643

charmaine.kong@vw.com.sg

http://www.vw.com.sg



From: Kong, Charmaine (VWG Singapore) Sent: Friday, 14 December, 2018 4:32 PM

To: 'Joel Goh'

Subject: RE: PRS FOR SMG590Y (EQ: SGG9711C)

Dear Joel,

Scene video ( rear view ) for your perusal. Please revert on liability.


Thanks.

Best Regards,

Charmaine Kong Insurance Service Advisor Aftersales

Volkswagen Group Singapore Pte Ltd 247 Alexandra Road Singapore 159934

Direct line: +65 6305 7176 Main Line: +65 6305 7299 Main Fax: +65 6474 3643



From: Joel Goh [mailto:joel.goh@eqinsurance.com.sg]

Sent: Friday, 14 December, 2018 1:58 PM
To: Kong, Charmaine (VWG Singapore)
Subject: PRS FOR SMG590Y (EQ: SGG9711C)

#### Without Prejudice

Dear Charmaine

We refer to your attached fax. Kindly assist to forward your client's video footage in order for us to review on liability.

Best Regards,

#### Joel Goh

Executive | Claims



#### **EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190 www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

#### Mei Kwan (LKKAuto)

From:

Joel Goh <joel.goh@eqinsurance.com.sg>

Sent:

Tuesday, 18 December, 2018 9:29 AM

To:

Mei Kwan (LKKAuto)

Cc:

Admin A; assignments; CS A Team; Poh Kin (LKKAuto)

Subject:

RE: PRS FOR SMG590Y (EQ: SGG9711C) \*\*\* LKK REF: CC4/EQI18022633/fa3

Attachments:

SGG9711C (12.12.18).pdf; SMG590Y.PDF

Categories:

**HMK** 

Dear Mei Kwan

Attached accident reports for your attention.

Best Regards,

Joel Goh

Executive | Claims



#### **EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190 www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]

Sent: Monday, December 17, 2018 8:03 PM

To: Joel Goh

Cc: Admin A; assignments; CS A Team; Poh Kin (LKKAuto)

Subject: RE: PRS FOR SMG590Y (EQ: SGG9711C) \*\*\* LKK REF: CC4/EQI18022633/fa3

'WITHOUT PREJUDICE' SAVE AS TO COSTS

EQI ref: TBA

LKK REF: CC4/EQI18022633/fa3

Dear Sir / Madam,

We refer to the above matter.


Kindly let us have a copy of insured's accident report for our necessary action.

Please take note that the case handler in-charge is Poh Kin and he can be contacted at DID: 6841 2132.

To check availability of the case handler, you may contact the undersigned.

#### **EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190 www.eqinsurance.com.sg





Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: Kong, Charmaine (VWG Singapore) [mailto:charmaine.kong@vw.com.sg]

Sent: Friday, December 14, 2018 5:58 PM

To: Joel Goh

Subject: RE: PRS FOR SMG590Y (EQ: SGG9711C)

Dear Joel,

Clearer Screenshots FYI...


Thanks.

Best Regards,

Charmaine Kong Insurance Service Advisor Aftersales

Volkswagen Group Singapore Pte Ltd 247 Alexandra Road Singapore 159934

Direct line: +65 6305 7176
Main Line: +65 6305 7299
Main Fax: +65 6474 3643
charmaine.kong@vw.com.sg
http://www.vw.com.sg




From: Kong, Charmaine (VWG Singapore) Sent: Friday, 14 December, 2018 4:32 PM

To: 'Joel Goh'

Subject: RE: PRS FOR SMG590Y (EQ: SGG9711C)

EQ Insurance Company Limited 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190 www.eqinsurance.com.sg

www.avg.com





| Privileged/Con | fidential information may be contained in this message. If you are not the intended recipient, please no |
|----------------|--|
|                |  |
|                | This email has been checked for viruses by AVG antivirus software.                                       |

From:

Wong, Meiy (VWG Singapore) <meiy.wong@vw.com.sg>

Sent:

Monday, 28 January 2019 1:16 PM

To:

Poh Kin (LKKAuto)

Cc:

Cheong, Pearlyn (VWG Singapore); Foo, John (VWG Singapore); Kong, Charmaine

(VWG Singapore); Admin A

Subject:

RE: RTA involving vehicle nos. SGG 9711C and SMG 590Y on 12/12/2018

Dear Poh Kin,

Offer accepted. Please forward us DV, if any, and kindly process payment.

Thanks and Best Regards,

Meiy Insurance Service Advisor Aftersales


Volkswagen Group Singapore Pte Ltd 247 Alexandra Road Singapore 159934

Main Line: +65 6305 7299

Direct line: +65 6305 7216

Main Fax: +65 6474 3643

meiy.wong@vw.com.sg http://www.vw.com.sg



It's not e-mail, if you print it. Think Blue.

From: Poh Kin (LKKAuto) [mailto:pohkin@lkkauto.com]

Sent: Monday, January 28, 2019 1:04 PM

To: Wong, Meiy (VWG Singapore)

Cc: Cheong, Pearlyn (VWG Singapore); Foo, John (VWG Singapore); Kong, Charmaine (VWG Singapore); Admin A

Subject: RE: RTA involving vehicle nos. SGG 9711C and SMG 590Y on 12/12/2018

Importance: High

**'WITHOUT PREJUDICE'** SAVE AS TO COSTS

From:

Poh Kin (LKKAuto)

Sent:

Monday, 28 January 2019 1:04 PM

To:

Wong, Meiy (VWG Singapore)

Cc:

Cheong, Pearlyn (VWG Singapore); Foo, John (VWG Singapore); Kong, Charmaine

(VWG Singapore); Admin A

Subject:

RE: RTA involving vehicle nos. SGG 9711C and SMG 590Y on 12/12/2018

Importance:

High

#### **'WITHOUT PREJUDICE'** SAVE AS TO COSTS

Our Ref:

CC4/EQI18022633/T1fa3

Your Ref:

SMG 590Y

Dear Meiy,

We refer to above matter.

Purely towards an amicable settlement and without admission of liability to our Insured's part, we revise offer settlement as below:

| 1. Cost of Repair (w/gst)        | \$\$ 5,425.36       |
|----------------------------------|---------------------|
| 2. Loss of Use (\$90.00 x 7days) | \$\$ 630.00         |
| 3. GIA search fee                | <u>S\$ 2.00</u>     |
|                                  | <u>\$\$6,057.36</u> |

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Pava Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Save the Earth Print only when necessary

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not

From:

Wong, Meiy (VWG Singapore) <meiy.wong@vw.com.sg>

Sent:

Monday, 28 January 2019 12:56 PM

To:

Poh Kin (LKKAuto)

Cc:

Cheong, Pearlyn (VWG Singapore); Foo, John (VWG Singapore); Kong, Charmaine

(VWG Singapore); Admin A

Subject:

RE: RTA involving vehicle nos. SGG 9711C and SMG 590Y on 12/12/2018

Categories:

clear

Dear Poh Kin,

Thanks your offer ,please re-consider LOU from \$80 to \$100 per days at least based on benchmark rate settlement \$6127.36, Thanks.

Thanks and Best Regards,

Insurance Service Advisor

Aftersales

Volkswagen Group Singapore Pte Ltd 247 Alexandra Road Singapore 159934

Direct line: +65 6305 7216


Main Line: +65 6305 7299

Main Fax:

+65 6474 3643

meiy.wong@vw.com.sg

http://www.vw.com.sg



It's not e-mail, if you print it. Think Blue.

From: Poh Kin (LKKAuto) [mailto:pohkin@lkkauto.com]

Sent: Monday, January 28, 2019 11:05 AM

To: Wong, Meiy (VWG Singapore); Ong, Germaine (VWG Singapore)

Cc: Cheong, Pearlyn (VWG Singapore); Foo, John (VWG Singapore); Kong, Charmaine (VWG Singapore); Admin A

Subject: RTA involving vehicle nos. SGG 9711C and SMG 590Y on 12/12/2018

Importance: High

'WITHOUT PREJUDICE'

From:

Poh Kin (LKKAuto)

Sent:

Monday, 28 January 2019 11:05 AM

To:

'Wong, Meiy (VWG Singapore)'; Ong, Germaine (VWG Singapore)

Cc:

Cheong, Pearlyn (VWG Singapore); Foo, John (VWG Singapore); Kong, Charmaine

(VWG Singapore); Admin A

Subject:

RTA involving vehicle nos. SGG 9711C and SMG 590Y on 12/12/2018

Importance:

High

#### 'WITHOUT PREJUDICE' SAVE AS TO COSTS

Our Ref:

CC4/EQI18022633/T1fa3

Your Ref:

**SMG 590Y** 

Dear Sir/Madam,

We refer to above matter and your letter of demand.

Towards an amicable settlement and without admission of liability to our Insured's part, we offer settlement as below:

| 1. Cost of Repair (w/gst)        | \$\$ 5,425.36    |
|----------------------------------|------------------|
| 2. Loss of Use (\$80.00 x 7days) | S\$ 560.00       |
| 3. GIA search fee                | <u>\$\$</u> 2.00 |
|                                  | \$\$5,987.36     |

Kindly confirm acceptance on this matter.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LIKK Save the Earth Print only when necessary.

From:

Poh Kin (LKKAuto)

Sent:

Wednesday, 9 January 2019 2:00 PM

To:

Ong, Germaine (VWG Singapore; Taufikh (LKKAuto)

Cc:

Cheong, Pearlyn (VWG Singapore; Wong, Meiy (VWG Singapore; Foo, John (VWG

Singapore; Kong, Charmaine (VWG Singapore; Admin A

Subject:

RE: SMG590Y - FINALISE

Importance:

High

#### 'WITHOUT PREJUDICE' SAVE AS TO COSTS

Our Ref:

CC4/EQI18022633/T1fa3

Your Ref:

**SMG 590Y** 

Dear Germaine.

We refer to the above matter.

For COR, our surveyor had recommended amount at P/P \$5,070.43 (before GST) with 5 repair days.

Please note that: All finalisation is subject to our Principal insurer's approval.

In the meantime, kindly furnish us a copy of the before paint photo for our file record.

\*\*\* Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

# Volkswagen Centre Singapore



Biz Reg. No. 53103069E GST No. M20098505-2

# DISCHARGE VOUCHER

| I / We         | WANG HAD      | MNA           | (Passport No.                   | 583766985        | ) the        |
|----------------|---------------|---------------|---------------------------------|------------------|--------------|
| owner of vehi  | icle number _ | 5mh 5904      | hereby a                        | ccept from       |              |
|                |               | (Insur        | ance Company)                   | the sum of       |              |
|                | _(total repai | r cost) in fu | ll and final settle             | ment for the cos | t of repairs |
| arising from   | the loss dama | ige of prope  | rty as a result of              | the accident inv | olving       |
| SMG Squ4       | _&            | 5669711       | along No                        | D LANDS          |              |
| on             |               |               |                                 |                  |              |
| The lost of us |               |               | our behalf. rental receipts) to | o be payable to  |              |
|                | Dated this    | on02/01       | Z01 [7] (I                      | DD/MM/YYYY)      |              |
|                | 1             |               | —. Д                            |                  |              |
|                | f owner / Con |               |                                 |                  |              |
| Name ,:        | Wong )        | 100 mm        | 1                               |                  |              |
| NRIC Nox:      | 283           | 1 10          | 6                               |                  |              |
| Date ∧:        | 1/0           | 2 20 []       |                                 |                  |              |



### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|  |  | Affiliated to Federation Interna                 | itionale Des Experts En Autom | nobile      |
|--|--|--|-------------------------------|-------------|
| EQ INSURANC                              | CE COM   | PANY LTD   | Ref : CC4/EQI18022            | 633/T1fa3s2 |
| 5 MAXWELL R<br>#17-00 TOWE<br>MND COMPLE | R BLOCK  | K<br>APORE 069110                                | Date: 29-01-2019              |             |
|  | al Alek  | Policy Particula                                 | rs :- THIRD PARTY CLA         | IM          |
| Insured                                  | Veh.   | SGG 9711C  | Veh. Inspected                | SMG 590Y    |
| Policy N                                 | lo.  | DMPPHQ18-003030                                  | Coverage (\$)                 | 0.00        |
| Claim N                                  |  |  | Excess (\$)                   | 0.00        |
| Assign                                   | The state of the s | JOEL   | Assign Date                   | 17/12/2018  |
| 2.                                       |  | Vehicle Pa                                       | rticulars & Condition         |             |
| Make &                                   | Model  | VOLKSWAGEN PASSAT                                | c.c                           | 1798        |
| Engine                                   | No.  | HIDDEN   | Year of Reg.                  | 2018        |
| Chassis                                  | No.  | WVWZZZ3CZKE019294                                | Colour                        | BLUE        |
| Odomet                                   | er   | 1381   | Steering                      | IN ORDER    |
| Brakes                                   |  | IN ORDER   | Modification                  | SPORTS RIM  |
| General                                  |  | GOOD   |                               |             |
| 3.                                       | No. 12   | Cond   | ditions of Tyres              |             |
|  |  | Size   | Make                          | Balance     |
| R/H Fro                                  | nt Tyre  | 215/55R17  | PIRELLI                       | 6 mm        |
| L/H Froi                                 | nt Tyre  | 215/55R17  | PIRELLI                       | 6 mm        |
| R/H Rea                                  | r Tyre   | 215/55R17  | PIRELLI                       | 6 mm        |
| L/H Rea                                  | r Tyre   | 215/55R17  | PIRELLI                       | 6 mm        |
| 4.                                       | 1840   | Descrip  | ption of Damages              |             |
| THE VEH                                  | IICLE SU   | STAINED DAMAGES AT THE F                         | FRONT O/S PORTION.            |             |
| DAMAGE                                   | S SEE D  | ETAILS.  |                               |             |
| 5.                                       | 1000   | Gene   | eral Information              |             |
| Acciden                                  | nt Date  | 12/12/2018                                       | Inspection Date               | 19/12/2018  |
| Survey                                   | held at  | VOLKSWAGEN CENTRE SIN                            | NGAPORE                       |             |
|  |  | 247 ALEXANDRA ROAD<br>SINGAPORE 159934           |                               |             |
| 5a.                                      |  |  | Remarks                       |             |
|  |  | ON WAS CONDUCTED ON A"VICE TO YOUR INSTRUCTIONS. |                               |             |
| 5b.                                      | Market 1   | Estima   | ate Days of Repair            |             |
| TESTIMAT                                 | TED NOR  | MAL PERIOD FOR REPAIR:                           | 5 Working Da                  | vs          |



#### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

#### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 590Y

| Qty | Description of Parts                                 | Condition               | Estimate By<br>Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-------------------------|-------------------------------|-------------------|
|     | REPLACEMENT OF PARTS                                 |                         |                               |                   |
| 1   | WHEEL HOUSE RH (SN)                                  | NOT NECESSARY           | 84.70                         | -                 |
| 1   | WHEEL HOUS RH (SN)                                   | NOT NECESSARY           | 108.14                        |                   |
| -1  | BUMPER BRACKET RH (SN)                               | NOT NECESSARY           | 45.91                         |                   |
| 1   | BUMPER GUIDE RH (SN)                                 | NOT NECESSARY           | 79.69                         |                   |
| 1   | FRT BUMPER COVER (SN)                                | TO REPAIR SEE<br>LABOUR | 1,445.73                      |                   |
| 1   | RHF FENDER (SN)                                      | BENT                    | 670.43                        | 670.43            |
| 1   | CHROME MOLDING CENTER (SN)                           | NOT NECESSARY           | 230.02                        | -                 |
| 1   | CHROME MOLDING LH (SN)                               | NOT NECESSARY           | 117.97                        | -                 |
| 1   | CHROME MOLDING RH (SN)                               | NOT NECESSARY           | 105.02                        | -                 |
| 1   | SENSOR BRACKET (SN)                                  | NOT NECESSARY           | 70.01                         |                   |
| 1   | 2KADHESIVE (SN)                                      | NOT NECESSARY           | 89.84                         |                   |
| 1   | BONDAGENT (SN)                                       | NOT NECESSARY           | 64.27                         |                   |
|     |  | 1                       | 3,111.73                      | 670.43            |
|     | LABOUR   |                         |                               |                   |
|     | LABOUR. INCLUSIVE OF THE REPAIR OF FRT BUMPER COVER. |                         | 3,360.00                      | 1,680.00          |
|     | SPRAY PAINT  |                         | 3,200.00                      | 1,600.00          |
|     | B&P WHEEL ALIGNMENT.                                 |                         | 360.00                        | 360.00            |
|     | PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC: |                         | 480.00                        | 480.00            |
|     | CHECK WIRE HARNESS, ECU, S.                          | 1                       | 280.00                        | 280.00            |
|     |  |                         | 7,680.00                      | 4,400.00          |
|     | GRAND TOTAL  |                         | 10,791.73                     | 5,070.43          |

| RECOMMENDED COST OF REPAIRS | 5,070.43 |
|-----------------------------|----------|
|-----------------------------|----------|

Report Ref No. CC4/EQI18022633/T1fa3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

HO LEONG CHUAN

**Automotive Assessor** 

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.