

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315





TD Ref:	NS/INC180226	554/K1ths2
10 .te	140/1140 100220	70-1/TC1032
RE Date:	31-12-2018	
Code:	INC4	
1. Policy Particulars :- THIRD PARTY CLAIM		
Veh. Ir	nspected	SHC 7301A
Cover	age (\$)	0.00
Exces	s (\$)	0.00
Assigi	n Date	17/12/2018
2. Vehicle Particulars & Condition		
c.c		1685
Year o	of Reg.	2016
Colou	r	YELLOW
Steeri	ng	IN ORDER
Modifi	cation	STANDARD ALLOY RIM
3. Conditions of Tyres		
Make		Balance
CAMPE	EON	7 mm
4. Description of Damages		
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.		
5. General Information		
Inspec	ction Date	17/12/2018
COMFORTDELGRO ENGINEERING PTE LTD		
59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks		
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair		
	Code: ars:-THIR Veh. II Cover Exces Assign articulars & c.c Year of Colou Steerii Modifi aditions of Make CAMPE C	Code: INC4 ars:-THIRD PARTY CLAIM Veh. Inspected Coverage (\$) Excess (\$) Assign Date articulars & Condition c.c Year of Reg. Colour Steering Modification ditions of Tyres Make CAMPEON CA

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: