

ASS. REC. BY:

REF:

CS3 / ALH18022673 / Gcb

Special Instruction:

Surveyor:

merman

ASSIGNMENT (Office)

From (Person):

Chin Lee Yng

of

ALI

Date/Time: 18/12/2018 3:07pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJU 1159R

Insured:

SJK 7484P

at Workshop m/s

Green Star.

Tel:

6546 3092

of

Blk 3011 Bedok North Ave 4 #01-2004

Policy No:

2100103184

Claim No:

703579949136

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16.12.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time:

18/12/2018 3:46pm

Person Contacted:

June

Vehicle IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	SJU 1159R - X
	SJK 7484P - NA/ALH16006315/13
	After repair: 21/12/2018

D.O.A.: 06042016

PRS

Signature

REF: ALG

16878

(-2019)

## ASSIGNMENT

From: Date: 19-12-2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJU 1159R

at Workshop m/s Green Star

of 3011 Bedok North Ave 4 #01-2004

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$18K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SJU 1159R

Yr Regn:

18 Nov 2009

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mit Lancer 1.5 c.c. 1499

Colour:

Silver grey A/C Insured / Std / NI / NA

Sp. Reading:

122186

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JMY SRCY 2AA U000317

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225 / 45 R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

19-12-18

Survey held at

w/s

4:50pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + RS. SI

) Photos

) Others

TOTAL

Report Format :

DAR

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$


☐

Tech. Invs (\$

☐

Weekend (\$

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJK7484P AND SJU1159R ON 16/12/2018

From: Chin, Lee-Ying  
To: assignments, admin-a@lkkauto.com  
Cc: Fong, Andy-SY  
Sent: Tuesday, 18 December, 2018 3:07:42 PM  
Attachments:  tmpA0AD.TIF

---

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



883 North Bridge Road  
#11-03 Southbank  
Singapore 198785  
T: 6292 5838  
F: 6292 5938  
(UEN No. 201333127N)  
(GST Reg No. 201333127N)

Our Ref : CY.SJU1159R.18.GSSP(HW).wp(Lh)

Your Ref : Your insured vehicle **SJK 7484P**

18 December 2018

**LOH YEOW LIANG BENJAMIN**  
c/o The Motor Claims Department  
**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way #07-16  
Singapore 079120

By Fax No: 6835 7416

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SJU 1159R & SJK 7484P ON 16.12.2018 @ 13:00HRS ALONG PARKWAY PARADE 80 MARINE PARADE ROAD MSCP**

We are instructed by THONG JIUNN YUAN to notify you of a road traffic accident on 16.12.2018 @ 13:00hrs at Parkway Parade 80 Marine Parade Rd MSCP involving our client's vehicle registration number SJU 1159R and vehicle registration number SJK 7484P driven by you at the material time. A copy of the Singapore accident statement is enclosed.

As the result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

**C. Yogarajah LLC**  
Enc

cc: M/s Green Star Spray Painting  
Block 3011 Bedok North Ave 4  
#01 - 2004 Bedok Industrial Park E  
Singapore 489977  
Janice / Jane (Tel #: 6546 3092 / Fax #: 6545 2066)  
Email: sales@greenstarsp.com

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/12/2018 12:36
Date Of Accident	16/12/2018 13:00
Exact Location Of Accident	PARKWAY PARADE 80 MARINE PARADE ROAD 449269 MSCP
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJU1159R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	THONG JIUNN YUAN
NRIC No	S7511687Z
Email Address	THONGJY@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-98776510
Alternative Phone No	OFFICE-98776510
<b>Vehicle Particulars</b>	
Manufacturer	MITSUBISHI
Model	LANCER EX 1.5 SPORTS 1499CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10706626
Cover Note Number	

### Driver

Name of Driver	THONG JIUNN YUAN
NRIC No	S7511687Z
Date Of Birth	14/04/1975
Occupation	INDOOR
Date Of Driving Pass	01/02/2002
Driving Experience	16 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98776510
Fax Number	
Contact Number	OFFICE-98776510
Email Address	THONGJY@HOTMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON THE DATE AND TIME MENTIONED, I WAS DRIVING ALONG THE SAID LOCATION, AND WHILST GIVING WAY TO A VEHICLE IN FRONT WHICH WAS REVERSING TO PARK, MY VEHICLE WHICH WAS STATIONARY WAS HIT FROM THE REAR BY VEHICLE B. NO BODY WAS INJURED... STATEMENT QS READ TO ME AND I ACKNOWLEDGED IT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	UPLOAD INTO FILEZILLA
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJK7484P
Vehicle Make/Model/Colour	TOYOTA WISH BLUE
Details Of Properties	N.A
Vehicle Category	PRIVATE CAR
Name of Driver	LOH YEOW LIANG BENJAMIN
NRIC/Passport Number	S7112652H
Contact Number	96943025
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

# Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
  - (a) I understand, acknowledge, agree and consent that:
    - (i) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
      - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
      - (ii) investigating the accident and/or my claims;
      - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
      - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
      - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
    - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
    - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS  
REPORTING OFFICER  
Hashim Kamari

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre  
Personnel 17/12/18

### Sketch Plan





ACCIDENT STATEMENT (2000 characters)

ON THE DATE AND TIME MENTIONED, I WAS DRIVING ALONG THE SAID LOCATION, AND WHILST GIVING WAY TO A VEHICLE IN FRONT WHICH WAS REVERSING TO PARK, MY VEHICLE WHICH WAS STATIONARY WAS HIT FROM THE REAR BY VEHICLE B. NO BODY WAS INJURED... STATEMENT QS READ TO ME AND I ACKNOWLEDGED IT.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
HASHIM BIN KAMARI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

17 December 2018 at 11:18 AM

Date/Time:

17 December 2018 at 11:18 AM



## &gt; Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1687Z
Vehicle Details	
Vehicle No.:	SJU1159R
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Dec 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.5 MIVEC SPORTS AT ABS D/AB
Primary Colour:	Grey
Manufacturing Year:	2009
Engine No.:	4A910126018
Chassis No.:	JMYSRCY2AAU000317
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$18,600.00
Original Registration Date:	18 Nov 2009
First Registration Date:	18 Nov 2009
Transfer Count:	0
Actual ARF Paid:	\$18,600.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Nov 2019
PARF Rebate Amount:	\$9,300.00
Intended COE Rebate Details	
COE Expiry Date:	17 Nov 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$16,747.00
COE Rebate Amount:	\$1,524.00
<b>Total Rebate Amount:</b>	<b>\$10,824.00</b>

The information contained herein is correct as at 20 Dec 2018

OK

Condition (CON)  
 (01) Bent (2) Dented (3) Disoriented (4) Cracked (5) Cut (6) Scratched  
 (07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary  
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

# MOTORCAR (Rear)

ACTION (AC)  
 (1) Replace (✓) (2) Repair (X) (3) Check (0)  
 (4) Not Consistent (NC)

Aug 2005

## Rear Portion

Vehicle No: SJU-1159R

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector LH	BR	✓	
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DM	✓	
1159	993327	Rear End Panel	DB	✓	
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	993116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

26/12/2018

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Dec 2018 <a href="#">Edit Reg</a>		18 Dec 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Loh Yeow Liang Benjamin, ID: S7112652H		
Main Claimant:	THONG JIUNN YUAN, ID: S7511687Z		
Vehicle Reg. No.:	SJU1159R	Date of Loss:	16/12/2018 13:00 - :59 [108 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 7035799491SG	Policy/Cover Note No.:	2100103184 (Comprehensive)
Vehicle Reg. No. (Insured):	SJK7484P	Policy No. (Claimant):	
		Excess:	
Repairer:	GREEN STAR SPRAY PAINTING (HQ) BLK 3011 BEDOK NORTH AVENUE 4 #01-2004 BEDOK INDUSTRIAL PARK E, 489977 Bedok - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 02/01/2019]		
Claimant's Solicitor:	C YOGARAJAH LLC - Tel: 62925838		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG\_SG (26/12/2018): Request for TP GIA Report

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date    Priority    Type    Task Group    Subject    Handler    Assigned By    Completed On    Created On    Done?

No results.



## Claim Documents

**\*SJU1159R (7035799491SG)**  
**[SJK7484P]**  
**TP**  
**THONG JIUNN YUAN**  
**Dec 16 2018 1:00PM**  
**[Loh Yeow Liang Benjamin]**  
**GREEN STAR SPRAY PAINTING**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

**View**
[View in Browser](#)

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	26/12/18 12:06	<b>Accident Statement</b> From: OD - Reg, No: SJK7484P, Claimant: LOH YEOW LIANG BENJAMIN		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
2	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
3	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
4	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
5	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
6	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
7	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
8	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
9	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
10	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
11	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
12	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
13	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
14	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
15	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
16	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
17	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
18	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
19	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
20	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
21	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
22	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
23	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
24	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
25	24/12/18 14:54	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
26	24/12/18 14:54	<b>Photo After Spray</b>		Load JPG	<input checked="" type="checkbox"/>
27	24/12/18 14:54	<b>Photo After Spray</b>		Load JPG	<input checked="" type="checkbox"/>
28	24/12/18 14:54	<b>Photo After Spray</b>		Load JPG	<input checked="" type="checkbox"/>
29	24/12/18 14:54	<b>Photo After Spray</b>		Load JPG	<input checked="" type="checkbox"/>
30	24/12/18 14:54	<b>Photo After Spray</b>		Load JPG	<input checked="" type="checkbox"/>
31	24/12/18 14:54	<b>Photo After Spray</b>		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
32	24/12/18 14:54	Photo After Spray	Load JPG	✓
33	24/12/18 14:54	Photo After Spray	Load JPG	✓
34	24/12/18 14:54	Photo After Spray	Load JPG	✓
35	24/12/18 14:54	Photo After Spray	Load JPG	✓
36	24/12/18 14:54	Photo After Spray	Load JPG	✓
37	24/12/18 14:54	Photo After Spray	Load JPG	✓
38	24/12/18 14:54	Photo After Spray	Load JPG	✓
39	24/12/18 14:54	Photo After Spray	Load JPG	✓
40	24/12/18 14:54	Photo After Spray	Load JPG	✓
41	24/12/18 14:54	Photo After Spray	Load JPG	✓
42	24/12/18 14:54	Photo After Spray	Load JPG	✓
43	24/12/18 14:54	Photo After Spray	Load JPG	✓

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18022672/GCBS2

Date: 04/01/2019

## REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100103184
Claimant Vehicle No :	SJU1159R	Insured Vehicle No :	SJK7484P
Date of Loss:	16/12/2018	Nature of Claim:	TP
		Claim No:	7035799491SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SJU1159R		
Make & Model:	MITSUBISHI LANCER, 1.5 (A)	Engine No:	4A910126018
Reg. Date:	18/11/2009 (Man. Year: 2009)	Chassis No:	JMYSRCY2AAU000317
Colour:	Grey	Odometer:	122186 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	225/45R18	Rear Tyre Size:	225/45R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment:	18/12/2018	GREEN STAR SPRAY PAINTING (HQ) BLK 3011 BEDOK NORTH AVENUE 4 #01-2004 BEDOK INDUSTRIAL PARK E Singapore 489977
Date Inspected:	19/12/2018 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	*Check	0.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT	*Check	0.00 F	*- F
5	1		*REAR BUMPER REFLECTOR LH	Broken	0.00 F	*- F
6	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
7	1		*REAR END PANEL	Repair	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	*Check	0.00 F	*- F
9	1		*REAR LH TAILLAMP	*Check	0.00 F	*- F
10	1		*REAR RH TAILLAMP	*Check	0.00 F	*- F
11	1		*TAILGATE LOCK	*Check	0.00 F	*- F
F=Franchise part.						
				<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >