

27/03/2002

ASS. REC. BY:

REF:

CS/SMO18022674 / Evb21

Special Instruction:

SURVEYOR:

MURIMAN

ASSIGNMENT (Office)

From (Person):

Shawn Ngo

of

SMO

Date/Time:

18/12/18 2330pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLX 3709B

Insured:

SKJ 1859A

Volvo S60 T4

at Workshop m/s

Motorcarz

Tel:

6841 5383

of

53 Ubi Ave 1 #01-19

Policy No:

DIBMT PYD1003712

Claim No:

CMD1805569

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15.12.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS w/p

17.12.2018

H.O.D. Endorsement:

Date/Time:

18/12/18 3:08pm

Person Contacted:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLX 3709B - NA / 210080 22674 / K4
	SKJ 1859A - X
21/12/18	Send preli revised via meriman
24/12/18	Mr Koh finalise amount L/S 16,000.00
26/12/18	Amend finalise amount 4,350 with Mr Koh (Red 10,650.70, 769)

PR9.

REF: SMO

ASSIGNMENT

From: Date: 19/12/2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: 82X 3709B

at Workshop n/s: Motorcarz

of 53 Ubi Ave 1 # 01-19

Insured

Policy No.

Claims: No

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
XX	X

Bal. or Market Value:

IDAC Accident Rpt. Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: 8 LX 3709B Yr Regn: 01/06/2009

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Land Rover Free lander

C.C. 3192

Colour: Black

A/C Insured / Std / NI / NA

Sp Reading: 117930

T/Radio: Insured / Std / NI / NA

Eng/No:

C/Nr: SAL FA23A 78H 095 430

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 235/60R18

R: 235/60R18

BS / DUN / EXNOVA / ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mm

R/Bal. 4 mm

L/Bal. 4 mm

L/Bal. 4 mm

D.O.A.

D.O.I. 20.12.2018

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV - 26,000

PV - 21,147

NV - 4853

RECEIVED 20 DEC 2018

Repair - SK - 6K

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 26/12 - typist

Report Format: merimen

Lump Sum / I.B.F. (\$) 3400/-

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee

Transportation

) \$ + R5.00 St

) Photos

) Others

TOTAL

350

10

360

[Signature]
26/12/2018

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Dec 2018		18 Dec 2018 14:33 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

TEO CATHAY (ZHANG GUOTAI), ID: S7830232A, Tel: +6598241412, Email: cathayteo@gmail.com

Main Claimant:

SHANE LEE, ID: S1703516I

Vehicle Reg. No.:

SLX3709B

Claim Type:

TP / CMTD1805569

Vehicle Reg. No. (Insured):

SKJ1859A

Repairer:

Motoricarz Garage (HQ) 53 UBI AVENUE 1, #01-19 PAYA UBI INDUSTRIAL PARK, 408934 Paya Lebar - Tel: 68415383

Handling Insurer:

Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by NGO SAU WEI SHAWN - 6329 5202]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/12/2018]

Driver/Custodian (Insured):

TEO CATHAY (ZHANG GUOTAI) (40 / Male), NRIC: S7830232A, Tel: +6598241412

Date of Loss:

15/12/2018 21:00 - :59

Policy/Cover Note No.:

D18MTPV01003712 (Comprehensive)

Policy No. (Claimant):

Excess:

[Created by insurer]

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompso Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: NGO SAU WEI SHAWN

Date: 21 Dec 2018

Preliminary Advice

Insured Vehicle No	: SKJ1859A		
TP Vehicle No	: SLX3709B	Accident Date	: 15/12/2018
Make	: LAND ROVER FREELANDER 2	Assignment Date	: 18/12/2018
Date of Inspection	: 20/12/2018	Est. Duration of Repair	: 3.00
Inspection At	: MOTORICARZ GARAGE (HQ) 53 UBI AVENUE 1, #01-19 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,050.70
Revised Amount	:S\$	7,807.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,807.20

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : The above survey was conducted on a 'Without Prejudice' basis.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3516I
Vehicle Details	
Vehicle No.:	SLX3709B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	20 Dec 2018
Vehicle Make:	LAND ROVER
Vehicle Model:	FREELANDER 2 I6 AUTO HSE
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	B6324515020822500
Chassis No.:	SALFA23A78H095430
Maximum Power Output:	171.0 kW (229 bhp)
Open Market Value:	\$41,643.00
Original Registration Date:	01 Jun 2009
First Registration Date:	01 Jun 2009
Transfer Count:	3
Actual ARF Paid:	\$41,643.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 May 2019
PARF Rebate Amount:	\$20,821.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$7,326.00
COE Rebate Amount:	\$326.00
Total Rebate Amount:	\$21,147.00

The information contained herein is correct as at 20 Dec 2018

OK

CHEAPEST CAR INSURANCE RENEWAL



Choice of
\$0 excess

Option of any
workshop

GET A CHEAPER QUOTE NOW

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Coe Renewal Toyota Altis 1.6A



2.88%p.a Lowest Interest@GV
Cars Financing \$1800
Downpayment Monthly From
\$568
GV Credit Pte Ltd [StarAd](#)



**VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND**



HOTLINE: 6741 9997

[view our cars](#)
[Browse by Category](#)
[Sort by Date Posted](#)
[20 results/page](#)

2 vehicles

Land Rover Freelander

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Land Rover Freelander		Any	Any	2010	Any	Any	Any	Available
	Land Rover Freelander 2 3.2A HSE		\$37,800	\$11,840 /yr	31-May-2010	3,192 cc	146,000 km	SUV	Available
Beautiful Red Freelander 2 3.2 HSE. Spacious Interior And Flawless Exterior. Silky Smooth 6 Speed Auto Transmission Emitting 229 Bhp. Parked Strictly In Sheltered Car Parks. Call Now For Any Enquiry...									
Posted: 24-Nov-2018 Tags: 2010 Land Rover Freelander, 2010 land rover freelancer, Land Rover Freelander, land rover freelancer, Land Rover, Freelander, freelancer, Used Land Rover									
	Land Rover Freelander 2 Diesel 2.2A		\$37,838	\$13,010 /yr	18-Mar-2010	2,179 cc	90,000 km	SUV	Available
Fuel Type: Diesel (Euro 4 Engine and Below)									
Very Well Taken Care By Owner, Beautiful Condition, Low Mileage. Serious Offers Will Be Considered, High Trade In Welcome! 100% In House Loan Available.GST Included. Call Now!									
Posted: 26-Oct-2018 Tags: 2010 Land Rover Freelander, 2010 land rover freelancer, Land Rover Freelander, land rover freelancer, Land Rover, Freelander, freelancer, Used Land Rover									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rate: insurance. Find buy used Land Rover Freelander, Land Rover Freelander Singapore, used Land Rover Freelander Singapore, used Land Rover Freelander, used vehicles Singapore or ever used Land Rover Freelander Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car la and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, comm vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

[Compare](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	17/12/2018 14:15
Date Of Accident	15/12/2018 21:15
Exact Location Of Accident	CHOA CHU KANG AVE1(BLK817,KEATHONGLINKMSCP/SOLACRES
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLX3709B
Insured/Policyholder	
Name Of Registered Owner	SHANE LEE
NRIC No	S1703516I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81000881
Alternative Phone No	OTHERS-81000881
Vehicle Particulars	
Manufacturer	LAND ROVER
Model	FREELANDER 2 I6 AUTO HSE
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5100713287
Cover Note Number	
Driver	
Name of Driver	SHANE LEE
NRIC No	S1703516I
Date Of Birth	31/10/1965
Occupation	OUTDOOR
Date Of Driving Pass	09/03/2009
Driving Experience	9 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81000881
Fax Number	
Contact Number	OTHERS-81000881
E-Mail Address	NOEMAIL

Address	BLK 438 ANG MO KIO AVENUE 10 #02-1331
Postcode	560438
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : HA THI MY HIEN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CHOA CHU KANG NPC
Police Station Address	ROAD: 20 CHOA CHU KANG ST 52 #01-02 , POSTCODE: 689286 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE POLICE REPORT : T/20181216/2114

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKJ1859A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TEO CATHAY
NRIC/Passport Number	S7830232A
Contact Number	98241412
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name SHANE LEE

Approximate Age

Injuries Sustain NECK PAIN

Injured person in which vehicle? SLX3709B

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Person's Signature
Name:
NRIC/Fin No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Pls Refer to the Police Report
T/20181216/2114

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature] 17/12/2018

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Police Report



**SINGAPORE
POLICE FORCE**



T/20181216/2114

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

1 of 4

Report No. T/20181216/2114

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/12/2018 21:48		Vide Report No.:		Station Diary No. 116	
Informant's Particulars					
Name of Informant SHANE LEE			Address: APT BLK 438 ANG MO KIO AVENUE 10 #02-1331 SINGAPORE 560438		
ID Type / ID No NRIC NO / S17035161			Contact No.: Home/Office Mobile 81000881		
Nationality SINGAPORE CITIZEN			Email:		
Sex Male	Age 53	Date of Birth 31/10/1965	Type of Informant Driver		
Race Chinese			Language:		Institution / School Name:
Occupation: CONSTRUCTION			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident	Non-Injury	Drink Drive: No	Date/Time of Accident: 15/12/2018 21:15	Type of Location
Location: Along Road 1 CHOA CHU KANG AVENUE 1 small road in between Blk 817 Keat Hong Link MSCP and Sol Acres				
Weather Drizzling		Road Surface Wet		Road Speed Limit
Traffic Flow:		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKJ1859A	Car				Slightly Damaged	0
SLX3709B	Car	LAND ROVER	FREELAND ER	Black	Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police Report



**SINGAPORE
POLICE FORCE**



T/20181215/2114

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

2 of 4

Report No: T/20181215/2114

CONTINUATION OF REPORT

Driver			
Name	TEO CATHAY		ID No. S7830232A
Related Vehicle	SKJ1859A (Car)		Contact No. 98241412
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL
Driver			
Name	SHANE LEE		ID No. S1703516I
Related Vehicle	SLX3709B (Car)		Contact No. 81000881
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL
Passenger			
Name	HA THI MY HIEN		ID No. S8365221G
Related Vehicle	SLX3709B (Car)		Contact No. 88777012
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL

Brief Details.

On 15/12/2018 at about 2115hrs, my car bearing SLX3709B was parked at the road in between Blk 817 Keat Hong Link and a condominium, Sol Acres. My wife and I was having a discussion in the car when a car bearing SKJ1859A came reversing and collided onto my vehicle. The collision was quite an impact.

After our car had collided, I got down from my car to speak to the driver. The driver namely, TEO CATHAY, S7830232A, Tel:98241412 came down to check on us. He informed that he is not injured and do not need any ambulance.

My vehicle suffered damages on the rear where the bumper's inner layer is protruding out on the left side and the left rear light is broken. The car reverse guiding system is faulty. My rear left tyre is not smooth while driving. I will be sending my car for servicing to check for other damages. The other party's vehicle

Police Report



**SINGAPORE
POLICE FORCE**



T/20181216/2114

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

3 of 4

Report No. T/20181216/2114

CONTINUATION OF REPORT

suffered damages on the rear left bumper and the bonnet is protruding out.

We exchanged particulars and we will be claiming insurances on other own.

I did not suffer any injuries. However, I feel that my back sore and my wife feels giddy from the impact. I have not yet to see a doctor, but I have booked an appointment for myself and my wife on 17/12/2018 to have a check-up.

I am lodging this report for record purposes and for insurance claims.

Police Report



SINGAPORE
POLICE FORCE



T/20181216/2114

Police Station Of Origin
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

4 of 4

Report No. T/20181216/2114

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference

Signature Of Officer Recording The Report:

J/

Sgt 2 FELICIA GOH MIN EN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Signature Of Informant:

Date/Time:

16/12/2018 21:48

Classification Of Case:

Authentication Stamp

N6P168

Motoricarz Garage

53 Ubi Avenue 1#01-19 Paya Ubi Industrial Park Singapore 408934
Tel: 6844 4290 Fax: 6841 6043 Email: carzingarage@gmail.com
Kaman Koh: 9769 9299
Register No.: 53188526K

Estimate

Vehicle: SLX3709B
Make & Model: LAND ROVER

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

No	DESCRIPTION	Qty	Amount (\$)
PARTS REPLACEMENT -LIST ITEMS			
1	REAR BUMPER DO	1PCS	1,940.00
2	REAR TAILLAMP @\$580.00 BR-LH, RH-NN	2PCS	1,160.00
3	REAR BUMPER REFLECTOR @\$65.00 D-LH, RH-NN	2PCS	130.00
4	REAR REVERSE SENSOR @\$190.00 BR Swift	2PCS	380.00
5	REAR BUMPER RETAINER @\$82.00 BR	2PCS	164.00
6	REAR END PANEL UPPER INNER X NN	1PCS	1,650.00
7	REAR END PANEL LOWER OUTER Repu	1PCS	1,258.00
8	REAR BUMPER TOP GARNISH TN	1PCS	156.00
9	REAR BUMPER REINFORCEMENT Repu	1PCS	1,280.00
10	REAR BOOT H R	1PCS	3,560.00
11	REAR BOOT MOULDING BR	1PCS	265.00
	LESS 10%		12,323.00 (1,232.30)
	Sub-Total cost for parts		11,090.70
PARTS REPLACEMENT-SPECIAL NETT ITEMS			
1	BUMPER CLIP ALK	6SET	30.00
	Sub-Total		30.00
LABOUR AND MISC CHARGES			
1	TO REMOVE,REFIX REAR WINDSCREEN		150.00
2	TO REMOVE , REFIX REVERSE SENSOR		80.00
3	TO CHECK REAR WIRING		50.00
4	TO SPRAY UNDERCOATING		150.00
5	TO SPRAY PAINTIG ACCIDENT AREAS		450.00
6	TO PANEL BEAT,REPAIR AND REFIX		450.00
	Sub-Total		2,930.00
	Grand Total		14,050.70

P- 3146.20

L- 1150

4,296.20

20/12/18 Steve
3 Days
L/S

21/12/18

L/S- 3,436.96 = 3400.00

...CLAIM SUBFOLDER...(Pending for Survey Report)





































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Dec 2018		18 Dec 2018 14:33 Edit Adj Rpt	S\$3,400.00 Edit Estimates	S\$3,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TEO CATHAY (ZHANG GUOTAI) , ID: S7830232A, Tel: +6598241412, Email: cathayteo@gmail.com								
Main Claimant:	SHANE LEE , ID: S17035161								
Vehicle Reg. No.:	SLX3709B	Date of Loss:	15/12/2018 21:00 - :59 [114 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1805569	Policy/Cover Note No.:	D18MTPV01003712 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKJ1859A	Policy No. (Claimant):							
		Excess:							
Repairer:	Motoricarz Garage (HQ) 53 UBI AVENUE 1, #01-19 PAYA UBI INDUSTRIAL PARK, 408934 Paya Lebar - Tel: 68415383								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by NGO SAU WEI SHAWN - 6329 5202]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 28/12/2018]								
Driver/Custodian (Insured):	TEO CATHAY (ZHANG GUOTAI) (40 / Male), NRIC: S7830232A, Tel: +6598241412								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLX3709B (CMTD1805569)
[SKJ1859A]
TP
SHANE LEE
Dec 15 2018 9:00PM
[TEO CATHAY (ZHANG GUOTAI)]
Motoricarz Garage

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	18/12/18 14:32	Accident Statement From: SC - Reg. No: SKJ1859A, Claimant: TEO CATHAY (ZHANG GUOTAI)	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/12/18 09:43	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/12/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
2	26/12/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
3	26/12/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
4	26/12/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
5	26/12/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
6	26/12/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
7	26/12/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
8	26/12/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
9	26/12/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
10	26/12/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
11	26/12/18 13:53	General View	Load JPG	<input checked="" type="checkbox"/>
12	26/12/18 13:53	General View	Load JPG	<input checked="" type="checkbox"/>
13	26/12/18 13:53	General View	Load JPG	<input checked="" type="checkbox"/>
14	26/12/18 13:53	General View	Load JPG	<input checked="" type="checkbox"/>
15	26/12/18 13:53	General View	Load JPG	<input checked="" type="checkbox"/>
16	26/12/18 13:53	General View	Load JPG	<input checked="" type="checkbox"/>
17	26/12/18 13:53	General View	Load JPG	<input checked="" type="checkbox"/>
18	26/12/18 13:53	General View	Load JPG	<input checked="" type="checkbox"/>
19	26/12/18 13:53	General View	Load JPG	<input checked="" type="checkbox"/>
20	26/12/18 13:53	General View	Load JPG	<input checked="" type="checkbox"/>
21	26/12/18 13:53	General View	Load JPG	<input checked="" type="checkbox"/>
22	26/12/18 13:53	General View	Load JPG	<input checked="" type="checkbox"/>
23	26/12/18 13:53	General View	Load JPG	<input checked="" type="checkbox"/>
24	26/12/18 13:53	General View	Load JPG	<input checked="" type="checkbox"/>
25	26/12/18 13:53	General View	Load JPG	<input checked="" type="checkbox"/>
26	26/12/18 13:53	General View	Load JPG	<input checked="" type="checkbox"/>
27	26/12/18 13:53	General View	Load JPG	<input checked="" type="checkbox"/>
28	26/12/18 13:53	General View	Load JPG	<input checked="" type="checkbox"/>
29	26/12/18 13:53	General View	Load JPG	<input checked="" type="checkbox"/>
30	26/12/18 13:53	General View	Load JPG	<input checked="" type="checkbox"/>
31	26/12/18 13:53	General View	Load JPG	<input checked="" type="checkbox"/>
32	26/12/18 13:53	General View	Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
34	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
35	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
36	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
37	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
38	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
39	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
40	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
41	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
42	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
43	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
44	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
45	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
46	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
47	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
48	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
49	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
50	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
51	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
52	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
53	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
54	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
55	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
56	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
57	26/12/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
58	26/12/18 13:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	26/12/18 13:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	26/12/18 13:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	26/12/18 13:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	26/12/18 13:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	26/12/18 13:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	26/12/18 13:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	26/12/18 13:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	26/12/18 13:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	26/12/18 13:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18022674/EVBE2

Date: 27/12/2018

REFERENCE

Handling Insurer: Sompoo Insurance Singapore Pte. Ltd. Policy No: D18MTPV01003712

Claimant Vehicle No: SLX3709B Insured Vehicle No: SKJ1859A

Date of Loss: 15/12/2018 Nature of Claim: TP Claim No: CMTD1805569

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX3709B**
 Make & Model: LAND ROVER FREELANDER 2, 3.2 i6 HSE (A) Engine No: B6324S15020822500
 Reg. Date: 01/06/2009 (Man. Year: 2008) Chassis No: SALFA23A78H095430
 Colour: Black Odometer: 117930 km
 Engine Capacity: 3192 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18
 Front Left Side: Goodyear 4 mm Rear Left Side: Goodyear 4 mm
 Front Right Side: Goodyear 4 mm Rear Right Side: Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,120.70	3,146.20	7,974.50	71.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,930.00	1,150.00	1,780.00	60.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,050.70	4,296.20	9,754.50	69.42
Approved Total (Overridden) (S\$)		3,400.00		
Nett Amount (S\$)	14,050.70	3,400.00	10,650.70	75.80

INSPECTION

Date of Assignment: 18/12/2018

Date Inspected: 20/12/2018 Inspected At:

Motoricarz Garage (HQ)
 53 UBI AVENUE 1, #01-19 PAYA UBI
 INDUSTRIAL PARK
 Singapore 408934

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Dec 2018)
Parts:	M1-SUV	LAND ROVER FREELANDER 2 3.2 i6 HSE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX3709B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,940.00 FL	*1,940.00 FL
2	1		*REAR TAILLAMP	N/S Broken / O/S Not Necessary	1,160.00 FL	*580.00 FL
3	1		*REAR BUMPER REFLECTOR	N/S Broken / O/S Not Necessary	130.00 FL	*65.00 FL
4	1		*REAR REVERSE SENSOR (4PCS)	Shorted-2pcs only	760.00 FL	*380.00 FL
5	1		*REAR BUMPER RETAINER (2PCS)	Broken-1pc only	164.00 FL	*82.00 FL
6	1		*REAR END PANEL UPPER INNER	Not Necessary	1,650.00 FL	*- FL
7	1		*REAR END PANEL LOWER OUTER	Repair	1,258.00 FL	*- FL
8	1		*REAR BUMPER TOP GARNISH	Torn	156.00 FL	*156.00 FL
9	1		*REAR BUMPER REINFORCEMENT	Repair	1,280.00 FL	*- FL
10	1		*REAR BOOT	Repair	3,560.00 FL	*- FL
11	1		*REAR BOOT MOULDING	Broken	265.00 FL	*265.00 FL
12	1		*SET BUMPER CLIP (6 SET)	Necessary	30.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,353.00	3,493.00
- List Item Discount on L Items 10.00/10.00% (S\$)	1,232.30	346.80
Total Parts (S\$)	11,120.70	3,146.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, REFIX REAR WINDSCREEN	New	150.00	100.00
2	TO REMOVE, REFIX REVERSE SENSOR	New	80.00	50.00
3	TO CHECK REAR WIRING	New	50.00	50.00
4	TO SPRAY UNDERCOATING	New	150.00	50.00
5	TO SPRAY PAINTING ACCIDENT AREAS	New	1,100.00	450.00
6	TO PANEL BEAT, REPAIR AND REFIX	New	1,400.00	450.00
Gross Labour Cost (\$\$)			2,930.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >