

ASS. REC. BY:

REF: C93/SPF18022678 / RVB521

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Frankie Thay of SPF Date/Time: 18/22018 2.26pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLF 909E Insured: Ym 41708

at Workshop m/s Miracle Works Tel:

of 48 Toh Guan Rd East #04-126

Policy No: Claim No: AEMD/105/009/2018/172

Sum Insured: Excess:

Make of Veh: D.O.A. 14/12/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS Wp. 07-01-2019 @ after 12pm H.O.D. Endorsement:

Date/Time: 18/22018 2.40pm Person Contacted: Nicole Vehicle IN / OUT

Date/Time	Action/Instruction (x) Estimate
	SLF 909E - X
	Ym 41708 - X
16/1/19	Submit LS \$ 1650, 3 days upper range \$2K - \$3K

Form

REF: SPF

07045.

ASSIGNMENT

From: Date: 07/01/2019

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLF 909E
at Workshop m/s: Miracle Works
of: 48 Joh Guen Rd East

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

After 12pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLF 909E Yt Regn: 2015 / 86P

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz C250 AMG C.C 1991

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 29575 T/Radio: Insured / Std / NI / NA

Eng/No:

Ct/No: W00 2050452 R0 58 523

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Order / Jammed / Leaked / Burnt or

Brake: ☒ Order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre-Size: F: 225/40 ZR19

R: 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 14/12/18 D.O.I. 07/01/19 1.51pm

Survey held at: Miracle works

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/D

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 17 JAN 2019

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 3

1) Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: 1

2) 16/1- typist

Add Fee: ☐ : Site Insp (\$)

Survey Fee:

Transportation

\$ * RS. SI

Photos

Others

Report Format :

Lump Sum / I.B.I. (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

TOTAL

Catherine Chong (LKK Auto)

From: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>
Sent: Tuesday, 18 December, 2018 2:26 PM
To: Catherine Chong; assignments
Cc: Olivia Lau (LKKAuto)
Subject: RE : Pre-repair Inspection for SLF909E

Your reference: SLF909E

Our reference : AEMD/105/009/2018/172

Catherine ,

Please conduct a Pre-Repair Inspection for the vehicle SLF909E at M/s Miracle Works Pte Ltd, 48 Toh Guan East, #04-126 Enterprise Hub, Singapore 608586.

Please contact M/s Nicole mobile phone 82045858/96472568/64683096 for appointment.

Thanks.

Frankie Thay (Mr)
Safe Driving Manager
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4841 | FAX: (65) 6478 4848



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/12/2018 13:15
Date Of Accident	14/12/2018 19:30
Exact Location Of Accident	BLK 921 OPEN SPACE CARPARK JURONG WEST ST 92
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF909E
Insured/Policyholder	
Name Of Registered Owner	TAN KIAN WAI
NRIC No	S8270704B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90618558
Alternative Phone No	OFFICE-90618558

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C250 CGI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5105345145
Cover Note Number	

Driver

Name of Driver	TAN KIAN WAI
NRIC No	S8270704B
Date Of Birth	20/05/1980
Occupation	OUTDOOR
Date Of Driving Pass	03/08/2007
Driving Experience	11 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90618558
Fax Number	
Contact Number	OFFICE-90618558
EMail Address	NOEMAIL

Address	192 WESTWOOD AVENUE #10-25 WESTWOOD RESIDENCES
Postcode	648151
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	NANYANG N.P.C
Police Station Address	ROAD: 2 JURONG WEST AVE 5 , POSTCODE: 649482 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7929999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER POLICE REPORT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	CANNOT BE UPLOADED
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YM4170B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	RIZAL
NRIC/Passport Number	
Contact Number	90092864
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

17 DEC 2018

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

NG WING KIN JAMES
S7927881E


Sketch Plan #2 Pg. 1

SKETCH PLAN

Blk 921 Open Space Carpark
Jing Joo St 92

(A): SLF909E

(B): YM4170B




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to Police Report

Police Report No: T/2018 214/-2145

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
(Date & Time)
17 DEC 2018

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: NG WING KIN JAMES
S7927881E

Sketch Plan #3 Pg. 1



POLICE FORCE



T/20181214/2145

Police Station Of Origin:
Nanyang N.P.C.
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929998

Report No: T/20181214/2145

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/12/2018 21:37	Vide Report No.: J/20181214/0106	Station Diary No: 165
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: TAN KIAN WAI	Address: 192 WESTWOOD AVENUE #10-25 SINGAPORE 648151
ID Type / ID No.: NRIC NO / S8270704B	Contact No.: Home/Office: Mobile: 90618556
Nationality: SINGAPORE CITIZEN	Email:
Sex: Male Age: 36 Date of Birth: 20/05/1982	Type of Informant: Driver
Race: Chinese	Language: Institution / School Name:
Occupation: Building and construction project manager	Driving Licence Information: Class: Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 14/12/2018 19:30	Type of Location: Car Park
Location: Along Road 1 JURONG WEST STREET 92 <u>Blk 921 Open Space Carpark</u>				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLF909E	Car	MERCEDES BENZ	C250 AMG LINE (R18 LED)	White	Slightly Damaged	0
YM4170B	Van					0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------

Sketch Plan #4 Pg. 1



SINGAPORE
POLICE FORCE



T/20181214/2145

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No. 1800-7929999

2018

Report No. T/20181214/2145

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLF909E	NTUC Income Insurance Co-Operative Limited	5105345145	13/11/2018	12/11/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	TAN KIAN WAI		ID No.	S8270704B
Related Vehicle	SLF909E (Car)		Contact No	90618558
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL
Driver				
Name	RIZAL		ID No.	NIL
Related Vehicle	YM4170B (Van)		Contact No	90092864
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL

Brief Details.

On 14/12/2018 at 1950hrs, I received a call from Rizal, who informed that he had collided onto my car, SLF909E, while parking his vehicle. Subsequently, I went down to assess the damages. The driver told me that at about 1910hrs, while parking his vehicle, the front left portion of his vehicle scraped onto the front portion of my vehicle causing the number plate to fall off. I also observed some scratches on the middle of the front bumper.

Traffic Police then attended to me and advised to make a police report. The in-car camera recorded the video of the accident.

Sketch Plan #5 Pg. 1



POLICE FORCE



T/20181214/2145

Police Station Of Origin:
Nanyang N.P.C.
2 Jurong West Avenue 5 SINGAPORE
849482
Tel No. 1800-7829999

2 of 3

Report No. T/20181214/2145

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan.

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J / Staff Sgt R VIKNESH	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 14/12/2018 21:37
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No. 65476151	Classification Of Case:
Authentication Stamp: NP166 	

Condition (CON)
 (0) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched (07) Deformed
 (08) Shifted (09) Buckled (10) Broken (11) Necessary (12) Missing (13) Torn
 (14) Unconfirmed (15) Not Working

MOTOR CAR (Fr)

ACTION (AC)
 (1) Replace (✓) (2) Repair (X) (3) Check (?)
 (4) Not Consistent (NC)

Aug 2005

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Fr Number Plate	SN	✓	35
1002	991887	Fr Number Plate Base	SN	✓	85
1003	991889	Fr Number Plate Garnish			
1004	991300	Fr Bumper	✓		1485
1005	992341	Fr Bumper Clips	✓		48
1006	991325	Fr Bumper Bracket			
1007	991462	Fr Bumper Side Retainer			
1008	991433	Fr Bumper Reinforcement			
1009	991318	Fr Bumper Beam			
1010	991468	Fr Bumper Sponge			
1011	991427	Fr Bumper Protector			
1012	991420	Fr Bumper Pad			
1013	991363	Fr Bumper Grille			
1014	991301	Fr Bumper Moulding			
1015	991407	Fr Bumper Lower Spoiler			
1016	991438	Fr Bumper Sensor			
1017	995100	Fr LH Bumper Fog Lamp Cover			
1018	991355	Fr RH Bumper Fog Lamp Cover			
1019	995079	Fr LH Bumper Fog Lamp			
1020	995080	Fr RH Bumper Fog Lamp			
1021	991793	Fr Grille			
1022	991328	Fr Grille Emblem			
1023	991799	Fr Grille Chrome Moulding			
1024	991222	Fr Apron Panel			
1025	992013	Fr Support Panel			
1026	992025	Fr Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Fr Brace Panel			
1029	995153	Fr LH Headlamp Assy			
1030	991821	Fr RH Headlamp Assy			
1031	995088	Fr LH Side Lamp			
1032	995089	Fr RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Fr Exhaust Manifold			
1064	991713	Fr Exhaust Manifold Cover			
1065	991054	Fr Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

Vehicle No:

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Fr LH Chassis Member			
1093	991520	Fr RH Chassis Member			
1094	990728	Fr Vertical Cross Member			
1095	991863	Fr Lower Cross Member			
1096	995070	Fr LH Fender			
1097	995072	Fr LH Fender Inner Panel			
1098	995147	Fr LH Fender Lamp			
1099	995148	Fr LH Fender Protector			
1100	991740	Fr LH Fender Inner Shield			
1101	995179	Fr LH Mudflap			
1102	995170	Fr LH Wheel Rim			
1103	994025	Fr LH Rim Cover			
1104	995065	Fr LH Tyre			
1105	995071	Fr RH Fender			
1106	991739	Fr RH Fender Inner Panel			
1107	991744	Fr RH Fender Lamp			
1108	991752	Fr RH Fender Protector			
1109	991740	Fr RH Fender Inner Shield			
1110	991884	Fr RH Mudflap			
1111	992087	Fr RH Wheel Rim			
1112	994025	Fr RH Rim Cover			
1113	995065	Fr RH Tyre			
1114	992093	Fr Windscreen Glass			
1115	992117	Fr Windscreen Rubber			
1116	992108	Fr Windscreen Moulding			
1117	992098	Fr Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Fr Wiper Arm			
1121	992142	Fr Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Fr Driver Seat			
1133	991922	Fr RH Seat Belt Assy			
1134	991899	Fr Passenger Seat			
1135	995182	Fr LH Seat Belt Assy			
1136	990247	Sticker			

No of Items:

Accessories:

1) Replace accident damage parts - 290
 2) Spray paint damage parts - 250
 3) Remove 8 re fit bond reverse sensor - 60

ORIGINAL COPY (1k-2K)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGINEERING & MGT DIVISION
ACCIDENT CLAIM SECTION (SPORE POLICE
FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD
POLICE ACADEMY SINGAPORE 298333
ATTN: FRANKIE THAY

Ref: CS3/SPF18022678/R1vbs2

Date: 18-01-2019



Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	YM 4170B	Veh. Inspected	SLF 909E
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/172	Excess (\$)	0.00
Assign From	FRANKIE THAY	Assign Date	18/12/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C250 AMG	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD2050452R058523	Colour	WHITE
Odometer	29575 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40ZR19	MICHELIN	6 mm
L/H Front Tyre	225/40ZR19	MICHELIN	6 mm
R/H Rear Tyre	225/40ZR19	MICHELIN	6 mm
L/H Rear Tyre	225/40ZR19	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/12/2018	Inspect Date / Time	07/01/2019 (01:51 PM)
Survey held at	MIRACLE WORKZ PTE LTD 48 TOH GUAN ROAD EAST #04-126 ENTERPRISE HUB SINGAPORE 608586		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SLF 909E

Qty	Description of Parts	Condition	Recommended (\$)
REPLACEMENT OF PARTS			
1	FRT BUMPER	SCRATCHED	1,485.00
8	FRT BUMPER CLIPS @ \$6.00	NECESSARY	48.00
	LESS 10% DISCOUNT		-153.30
			1,379.70
SPECIAL NETT ITEMS			
1	FRT NUMBER PLATE (SN)	CRACKED	35.00
1	FRT NUMBER PLATE BASE (SN)	DEFORMED	85.00
			120.00
LABOUR			
	REPLACE ACCIDENT DAMAGE PART.		250.00
	SPRAY PAINTING DAMAGE PARTS.		250.00
	REMOVE & REFIT FRONT REVERSE SENSOR.		60.00
			560.00
GRAND TOTAL			2,059.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,650.00

Report Ref No. CS3/SPF18022678/R1vbs2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.