

INS CASE OWNER: Richard | CC 6/15/18 / AXA1802 1689, F1&639 | LOC: 10/12/18
 Surveyor: Kalvin | DOI: 18/12/18 | Date / Time: 10/12/18
 Registered in Meritum: _____

Pre-assign / CCU / FTE

Insured Vehicle No: 876 645H | Claim No: 88m016RA (8847)
 Name of Insured: HE HUEL KHIM | Policy No: _____
 Insured Tel No: _____ | HP: _____ | Make / Model: _____
 Excess Sec II (SS): _____ | D.O.A: 14/12/18 | Place of Accident: _____
 Is driver the owner? (YES) / NO | Nature of Accident: _____
 If NO, Driver Name / Age: _____ | OI GIA REPORT: (YES) / NO | TP GIA REPORT: (YES) / NO
 Driver Tel No: _____ | (V/L) (YES) / NO | Insured Liability: _____ % | Final? Yes / No

876 645H

INSRS: premier | WSP: _____ | Tel: _____ | Liability: _____ | RMKS: _____
 INSRS: _____ | WSP: _____ | Tel: _____ | Liability: _____ | RMKS: _____
 INSRS: _____ | WSP: _____ | Tel: _____ | Liability: _____ | RMKS: _____
 INSRS: _____ | WSP: _____ | Tel: _____ | Liability: _____ | RMKS: _____

Date/Time	STAGE	DATE / PIC
	Non-Reporting In (1st)	
	Non-Reporting In (2nd)	
	Non-Reporting In (Final)	
	Notification In (if non-pickup)	
	Call CR	
	After call In to CR	<u>7 9/7/19</u>
	Documentation Check List: Handler	Typist
	Notification In (if non-pickup)	☒
	After call In to CR	☒
	Authorization To Act	☒
	Release Voucher	☒
	Final Repair Bill	☒
	Car Rental Invoice	☒
	Towing Invoice	☒
	LTA / GIA	☒
	Medical Bill	☒
	PIR	☒
	Mandate/Reject Instruction	☒
	LOD	☒
	Payment Breakdown Form	☒
	Post-Repair Photos	☒
	Others	☒

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____ Confirm by: _____

FINALIZATION Date/Time: 18/12/18 Confirm with: Shatwan Email: ☒ Call: ☒

FINAL SETTLEMENT Date/Time: 18/12/18 Confirm with: Shatwan Email: ☒ Call: ☒
 Final Liability: % 100 (Agreed / Assessed) BOA S/N No: 8
 Repair Cost: (W/ST) \$ 2193.50
 Loss of Rental (LOR): \$ 513.60 (5 days) X \$102.72
 Loss of Use (LOU): \$ - (5 days)
 Loss of Income (LOI): \$ 700.00 (5 days) X \$102.72
 LOR only ☒ LOU only ☒ LOR + LOU ☒ [Tick only one]
 GLA/TA Search: \$ 2.00
 Medical: \$ -
 Disbursement: \$ - (e.g. Tow/Independent)
 Legal Cost: \$ -
 Total: \$ 2409.10 Global Sum \$ 2409.10
 1) Claim status: Not Settled
 2) Report Form: TP
 3) Survey fee: \$3701-

FINAL PAYMENT Date/Time: 18/12/18 Confirm with: Shatwan Email: ☒ Call: ☒
 Payee 1: \$ 2409.10 Name 1: Premier Automotive Services Pte Ltd
 Payee 2 (Strike if N.A.): \$ - Name 2: _____
 Payee 3 (Strike if N.A.): \$ - Name 3: _____

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

17-Dec-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6821 Y

1 pc	Front o/s door <i>dot</i>	\$	761.00
1 pc	Rear o/s door <i>X rep</i>	\$	791.00
2 pcs	Rear o/s door hinges @ \$34.00 <i>X m</i>	\$	68.00
1 pc	o/s rocker panel garnish <i>m</i>	\$	286.00
1 pc	Rear o/s wheel cover <i>X m</i>	\$	116.00

\$ 2,022.00

Less 10%

\$ 202.20

\$ 1,819.80

S/NETT

1 set	o/s rocker panel garnish clips <i>acc</i>	\$	38.00
1 set	o/s door stickers <i>m</i>	\$	100.00
1 pc	Rear o/s fender sticker <i>acc</i>	\$	60.00

Sundry *m*

To check wheel alignment

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs

To dismantle / refit inner components of the front o/s door & rear o/s door into new shell door

\$ 50.00 *20*

\$ 80.00 *X m*

\$ 180.00 *X m*

\$ 300.00 *50*

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear o/s fender, rear bumper etc

\$ 400
750.00

To putty and spray painting on front o/s door, rear o/s door, o/s rocker panel garnish, rear o/s fender, rear bumper

\$ 900
1,000.00

To apply rustproofing on the repaired and replaced panels.

\$ 150.00 *50*

\$ 4,527.80

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

2 2/1/19
total 45 \$2250 / 3 hrs

17/12/18 1620 L
3 hrs
45
After Repair

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

17-Dec-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6821 Y

1 pc	Front o/s door ✓	\$	761.00
1 pc	Rear o/s door <i>X 750</i>	\$	791.00
2 pcs	Rear o/s door hinges @ \$34.00 X	\$	68.00
1 pc	o/s rocker panel garnish ✓	\$	286.00
1 pc	Rear o/s wheel cover X	\$	116.00

\$ 2,022.00

Less 10%

\$ 202.20

\$ 1,819.80

S/NETT

1 set	o/s rocker panel garnish clips ✓	\$	38.00
1 set	o/s door stickers ✓	\$	100.00
1 pc	Rear o/s fender sticker ✓	\$	60.00
	Sundry	\$	50.00 <i>20</i>
	To check wheel alignment	\$	80.00 X
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs	\$	180.00 X
	To dismantle / refit inner components of the front o/s door & rear o/s door into new shell door <i>front o/s</i>	\$	300.00 <i>50</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear o/s fender, rear bumper etc	\$	400.00 <i>750.00</i>
	To putty and spray painting on front o/s door, rear o/s door, o/s rocker panel garnish, rear o/s fender, rear bumper	\$	900.00 <i>1,000.00</i>
	To apply rustproofing on the repaired and replaced panels.	\$	150.00 <i>50</i>
		\$	4,527.80

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Ka Hei
17/12/18 1620h
300
45
Atta Reporp

Text size + -

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H
Owner ID Type: Company
Owner Name: PREMIER TAXIS PTE. LTD.
Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
Mailing Address: -
Birth Date: -

Vehicle Particulars

Vehicle No.: SHC6821Y
Previous Vehicle No.: -
Effective Date of Ownership: 03 Aug 2015
Original Regn Date: 03 Aug 2015
Registration Date: 03 Aug 2015
Year of Manufacture: 2014
Vehicle Type: Public Transport Taxi (Motor Car)
Vehicle Scheme: Taxi (Company)
Vehicle Attachment 1: Air-Con (Taxi)
Vehicle Attachment 2: -
Vehicle Attachment 3: -
Vehicle Make: KIA
Vehicle Model: OPTIMA 1.7(A) DIESEL
Primary Colour: Silver
Secondary Colour: -
Passenger Capacity: 4
Chassis No.: KNAGM414MF5564123
Engine No.: D4FDGH901634
Engine Capacity/Power Rating: 1685 cc / -
Maximum Power Output: 100.0 kW (134 bhp)
Propellant: Diesel
Max Unladen Weight: 1584 kg
Maximum Laden Weight: 2050 kg
Open Market Value: \$21,050.00
PARF Eligibility: Yes
PARF Eligibility Expiry Date: 02 Aug 2023
Minimum PARF Benefit: \$12,882.00
No. of Transfers: 0
IU Label No.: 1050529692
COE No.: 2015080301002835W
COE Expiry Date: 02 Aug 2023
COE Category: A - Car (up to 1600cc & 97kW (130bhp))
COE Registration Category: A - Car (up to 1600cc & 97kW (130bhp))

PREMIER TAXIS PTE LTD

23 CHANGI SOUTH AVE 2 #03-02

SINGAPORE 486443

TEL: 65446676, 65446689 FAX: 62141511

Our Ref: SHC 6821 Y

WITHOUT PREJUDICE

Date: 17 Dec 2018

Attn: The Motor Claims Department

(BY EMAIL ONLY)

AXA Insurance Pte Ltd

No.8 Shenton Way

#27-01

Singapore 068811

ACCIDENT INVOLVING SHC6821Y & SJL645H ALONG SOUTH BRIDGE ROAD ON 14.12.18

We are the registered owner of vehicle number of SHC6821Y which was involved on the above mentioned accident between SJL645H.

Investigation reveals that the motor vehicle number SJL645H was insured with you at the material time of the said accident.

As a result of the accident was caused solely and completely by the negligence of your insured vehicle number SJL645H. Therefore, we are holding you liable for the repair costs and other consequential loss which was sustained by us.

Kindly arrange your representative to survey our vehicle at 23 Changi South Avenue 2, #01-02, Singapore 486443 within two (2) days from the date hereof as to avoid further LOR/I incur. We enclosed hereby the GIA report of SHC6821Y for your kind attention.

Failing which, we have no alternative but to proceed with the necessary repairs and the bill will be forward to you for reimbursement.

Yours Faithfully,



PREMIER TAXIS PTE LTD



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 09/07/2019

Survey Details:

Date of loss	14-Dec-18
Date of appointment	17-Dec-18
Date of survey	17-Dec-18
Location of survey	PREMIER AUTOMOTIVE SERVICES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHC 6821Y
Make and Model	KIA OPTIMA 1.7D
Date of registration	3/8/2015
Excess	
Market Value	\$0
Parf Rebate	\$0
Nett Loss	\$0

Repair details:

Initial Estimate	\$ 4,527.80
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 1,160.30
Check items (estimate)	\$ -
Labour	\$ 1,400.00
Total	\$ 2,560.30
Lump Sum(if applicable)	\$ 2,050.00

Number of days for repair	3
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

3 RECOMMENDED REPAIR DAYS + 1 WEEKEND + 2PRS = 7 DAYS

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 2,193.50	W/GST
Loss of use	\$ -	
Loss of rental	\$ 719.04	7days x \$102.72
Loss of income	\$ 280.00	7days x \$40
LTA search fees	\$ 2.00	
Others	\$ -	
Proposed Total	\$ 3,194.54	

 <MANDATE IA> - S8M016VA {ACCIDENT INVOLVING
SJL 645H (OI) & SHC 6821Y (TP) ON 14/12/2018 }

Type

 Question

Message

LAIBILITY: 100% OI TURNING OUT TO MAIN ROAD BOLA S8 - INFORMED OI ABOUT TP CLAIM & NCD
ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$3194.54 (CLAIMING LOR).
MANDATE IA HAD BEEN UPLOADED IN SMARTCLAIMS. KINDLY LET US HAVE YOUR
APPROVAL/INSTRUCTION. THANKS - CECILIA 09/07/2019

[Reply](#)



Re:<MANDATE IA> - S8M016VA {ACCIDENT INVOLVING SJL 645H (OI) & SHC 6821Y (TP) ON 14/12/2018 }

Type

🔔 Question

Message

Hi, pls proceed as per mandate. TY.

Reply

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-194038
Date of Request: 17/12/2018

Your Ref No: Online Purchase

Premier Automotive Services Pte Ltd
23 Changi South Ave 2
#01-02
Singapore 486443

Dear Sir/Madam,

Enquiry Date 17/12/2018
Enquiry By GOH WEE DEK
TP Vehicle No. SJL645H
Accident Date 14/12/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJL645H	AXA Insurance Pte Ltd	22/09/2018-21/09/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-194038
Date of Request: 17/12/2018

Your Ref No: Online Purchase

Premier Automotive Services Pte Ltd
23 Changi South Ave 2
#01-02
Singapore 486443

Dear Sir/Madam,

Enquiry Date 17/12/2018
Enquiry By GOH WEE DEK
TP Vehicle No. SJL645H
Accident Date 14/12/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVE 2 #01-02
SINGAPORE 486443
TEL:65446671 FAX:62141511
CO. REG:200707743D GST REG:200707743D

Our Ref: SHC6821Y/GS

WITHOUT PREJUDICE

11th January 2019

(By Email Only)

Attn: The Motor Claims Department

AXA Insurance Pte Ltd
No.8 Shenton Way
#27-01
Singapore 068811

Dear Sir/Madam

ACCIDENT INVOLVING SHC6821Y & SJL645H ALONG SOUTH BRIDGE ROAD ON 14.12.18

We have been authorized by Premier Taxis Pte Ltd, the owner of Taxi vehicle number: SHC6821Y, to claim against the party/parties responsible for the damages arising from the above-mentioned accident.

Our records show that you are the insurers of vehicle number: SJL645H at the material time of the accident with the driver of our client's vehicle, Mr Brandon Peng Chee Hong

As a result of the accident caused by your Insured Driver's negligent driving and/or management of your insured's Vehicle Number: SJL645H, our client's vehicle was damaged and we have been put to loss and damage as follows:

(1) Cost of repair	\$ 2193.50 (Incl. GST)
(2) Loss of Rental - 13Days @\$102.72per day	\$ 1335.36
(3) Loss of Income – 13Days @\$100.00per day	\$ 1300.00
(4) GIA Search Fee	\$ 2.00
	<u>\$ 4830.86</u>

A copy of each of the following supporting documents is enclosed:

- (1) Final Repair Bill, GIA report & sketch plan of SHC6821Y
- (2) Driver's I/C and Driving Licence
- (3) Vehicle Registration card, Certificate of Insurance
- (4) Check In/Out Voucher, GIA search & Scene video



PREMIER AUTOMOTIVE SERVICES PTE LTD
OFFICE: 23 Changi South Avenue 2 #01-02 S(486443)
TEL: 65436676 / 65436689 FAX: 62141511
CO. REG NO.: 200707743D GST. REG. NO.: 200707743D

PREMIER TAXIS PTE LTD
23 CHANGI SOUTH AVENUE 2 #03-02
SINGAPORE 486443

TAX INVOICE

DATE 11-Jan-2019
PAGE 1 OF 1

ITEM	Description	QTY	U.PRICE	AMOUNT
	FINAL REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6821 Y			\$ 2,050.00
TOTAL LUMP SUM REPAIR COSTS AS RECOMMENDED BY SURVEYOR				\$ 2,050.00
GST @ 7%				\$ 143.50
GRAND TOTAL				\$ 2,193.50



for Premier Automotive Services Pte Ltd

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18022689/K1gb3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD ANG			Date : 12-12-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJL 645H	Veh. Inspected	SHC 6821Y	
Policy No.	GA401077/1	Coverage (\$)	0.00	
Claim No.	S8M016VA	Excess (\$)	0.00	
Assign From		Assign Date	17/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5594123	Colour	SILVER	
Odometer	396159	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	ACHILLES	7 mm	
L/H Front Tyre	205/65 R16	ACHILLES	7 mm	
R/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
L/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/12/2018	Inspection Date	17/12/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6821Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT O/S DOOR (CONSISTENT)	DENTED	761.00	761.00
1	REAR O/S DOOR (CONSISTENT)	TO REPAIR SEE LABOUR	791.00	-
2	REAR O/S DOOR HINGES @\$34.00 (CONSISTENT)	SERVICEABLE	68.00	-
1	O/S ROCKER PANEL GARNISH (CONSISTENT)	CRACKED	286.00	286.00
1	REAR O/S WHEEL COVER (CONSISTENT)	SERVICEABLE	116.00	-
	LESS 10% DISCOUNT		-202.20	-104.70
			1,819.80	942.30
SPECIAL NETT ITEMS				
1	SET O/S ROCKER PANEL GARNISH CLIPS (SN) (CONSISTENT)	NECESSARY	38.00	38.00
1	SET O/S DOOR STICKERS (SN) (CONSISTENT)	NECESSARY	100.00	100.00
1	REAR O/S FENDER STICKER (SN) (CONSISTENT)	NECESSARY	60.00	60.00
1	SUNDRY (SN) (CONSISTENT)	NECESSARY	50.00	20.00
			248.00	218.00
LABOUR				
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO DISMANTLE /REFIT INNER COMPONENTS OF THE FRONT O/S DOOR & REAR O/S DOOR INTO NEW SHELL DOOR.		300.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE REAR O/S FENDER ,REAR BUMPER ETC.INCLUSIVE OF THE REPAIR OF REAR O/S DOOR .		750.00	400.00
	TO PUTTY AND SPRAY PAINTING ON FRONT O/S DOOR ,REAR O/S DOOR ,O/S ROCKER PANEL GARNISH ,REAR O/S FENDER ,REAR BUMPER .		1,000.00	900.00
	TO APPLY RUSTPOORING ON THE REPAIRED AND REPLACED PANELS.		150.00	50.00
			2,460.00	1,400.00

Report Ref No. CC4/ASM18022689/K1gb3q2



GRAND TOTAL		4,527.80	2,560.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,050.00

Report Ref No. CC4/ASM18022689/K1gb3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

⏪ Service Request Details

Claim	SBM016VA
Reference	CC4/ASM18022689/K1gb0u2 
Loss Date	14 December 2018
Report Date	17 Dec 2018 2:59:01 PM
Request Date	17 December 2018

Due Date

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss
Third Party Vehicle Damage

Services
Pending verification - Direct Settlement

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	SHC6821Y
Make	TPYD
Model	TBC
Service Address	

...

Primary Contact/Insured

HE HUEI KHHM (XU HUIQIN)
BLK B2B LORONG 4 TOA PAYOH, #03-496,
312082, Singapore

CHINSURANCE@OUTLOOK.COM

Claim Handler

ANG Richard

richard.angba@axa.com.sg

Additional Instructions

NON REPORTED

Messages Invoices History Documents Assessment Metrics Notes

Document Type Document SubType

 Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Accident Statement	Reports & Statement		Merimen	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UNLOADED
LKKInvoice1 (4).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	18 December 2019
RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 December 2019
RENTAL MILEAGE.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 December 2019
LKKInspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 December 2019
LKKAdjustment1a (3).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 December 2019
GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 December 2019
PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	18 December 2019
AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	18 December 2019
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	18 December 2019
LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	9 July 2019
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	9 July 2019
HANDATE IA DO 09072019.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	9 July 2019
LOG AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	9 July 2019
TP EST LIST MARKED.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	9 July 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UNLOADED
 SHC6821Y - Same video (convert-video-online.mpg)	Evidence	Videos	LXX AUTO CONSULTANTS PTE LTD (TP)	9 July 2019
 PRI EMAIL RECEIVED FROM WORKSHOP.png	Letters and Correspondence	Workshop	RATAN BHOSALE (Priyati)	17 December 2018