

22/03/2002

ASS. REC. BY:

REF:

CS3 / ALH18022694 / C1Cben

Special Instruction:

Surveyor

Melvin

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

ALH

Date/Time:

18/12/2018 1009am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMT 8168 G

Insured:

SDJ 378 K

at Workshop m/s

Khek Joo Motor

Tel:

9616 6658

of

9004 Tampines St 93 #01-94

Policy No:

2100391244

Claim No:

249735890286

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time:

18/12/2018 1047am

Person Contacted:

Mr. Ng

Vehicle IN / OUT

Date/Time	Action/Instruction (x) Estimate
	SMT 8168 G - X
	SDJ 378 K - X
	After repair: 24/12/2018

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING YOUR INSURED VEHICLE SDJ378K AND SMG8168G ON 15/12/2018

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: Tuesday, 18 December, 2018 10:09:24 AM
Attachments:  tupFF69.tif

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors Commissioner For Oaths Notary Public

UEN NO : 201523418E

(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16
MANHATTAN HOUSE
SINGAPORE 169876
TEL : (65) 6532 2455
FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: lhling@tcmg.com.sg;mdmling@tcmg.com.sg

Our Ref : TCMG/SMG8168G/1218//KJM

Your Ref : SDJ 378 K

17 December 2018

BY FAX NO. 6835-7416 ONLY

M/s AIG Asla Pacific Insurance Pte Ltd
78 Shenton Way#07-16
AIG Building
Singapore 079120

Attn: Motor Claims Department

Dear Sirs,

PRE-REPAIR INSPECTION NOTICE

We act for **Leong Hoong Wai (Liang HongWei)**, the owner and/or driver of motor vehicle no. **SMG 8168 G**, which was involved in an accident along Stevens Road towards PIE on 15 December 2018 at 17:00 hours.

We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. **SDJ 378 K** for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s Khek Joo Motor, (9004, Tampines Street 93 #01-94, Singapore 528838 – Mr Ng Wee Khiang @ 9616 6658).

If we do not hear from you within the next **two (2) working days**, we shall deem that you have waived the requirement for the pre-repair inspection.

Yours faithfully,

**MR LING LEONG HUI**

cc. M/s Khek Joo Motor
(Yref: SMG8168G)

BY FAX NO. 6785 4258 ONLY

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3594F
Vehicle Details	
Vehicle No.:	SMG8168G
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Dec 2018
Vehicle Make:	SUBARU
Vehicle Model:	SUBARU FORESTER 2.0XT
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	FA20J865620
Chassis No.:	JF1SJGK85EG035471
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$17,870.00
Original Registration Date:	30 May 2015
First Registration Date:	30 May 2015
Transfer Count:	1
Actual ARF Paid:	\$17,870.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 May 2025
PARF Rebate Amount:	\$13,402.00
Intended COE Rebate Details	
COE Expiry Date:	29 May 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$75,002.00
COE Rebate Amount:	\$48,085.00
Total Rebate Amount:	\$61,487.00

The information contained herein is correct as at 31 Dec 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/12/2018 13:28
Date Of Accident	15/12/2018 17:00
Exact Location Of Accident	ALONG STEVEN ROAD TWDS PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMG8168G
Insured/Policyholder	
Name Of Registered Owner	LEONG HOONG WAI (LIANG HONGWEI)
NRIC No	S8033594F
Email Address	LEONG80@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93865862
Alternative Phone No	OTHERS-93865862

Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER-2.0 X (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5104200003
Cover Note Number	

Driver

Name of Driver	LEONG HOONG WAI (LIANG HONGWEI)
NRIC No	S8033594F
Date Of Birth	29/10/1980
Occupation	INDOOR
Date Of Driving Pass	21/08/2003
Driving Experience	15 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93865862
Fax Number	
Contact Number	OTHERS-93865862
EMail Address	LEONG80@GMAIL.COM

Address	BLK230B TAMPINES STREET 24 #04-35
Postcode	525230
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NIKI YIU GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER SKETCH PLAN ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	NOT AVAILABLE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDJ378K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KONG WEI CHANG
NRIC/Passport Number	S7831547D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: 17/12/18



SKETCH PLAN



Steven Road

A - SMG8168G

B - SDJ378K

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Dear officer:
I like to report an accident that happened on 15 Dec 2018 along Steven Rd.
I was travelling @ about 50km/hr along Stevens Rd when the van in front of me jam brake. I managed to stop in time to avoid the accident with the van in front but was rear ended by vehicle number SDJ378K.
We exchanged details and agreed to settle via insurance and to claim his insurance.
My Vehicle number: SMG8168G
NRIC: 88033594/F
LEONG HOON WAI,
Vehicle that rear ended my car: SDJ378K
NRIC: 87831547 D
NAME: KONG WEI CHAN CHANG.
<input type="checkbox"/> claim OD / TP at Falcon-Air <input type="checkbox"/> claim OD / TP Own W/shop <input type="checkbox"/> Reporting Only

DECLARATION

I/We declare the foregoing particulars are true in every respect.

 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:


17/12/18

Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



(01) Bent (2) Denied (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

ACTION 16C
(1) Replace (✓) (2) Repair (X) (3) Check (✓)
(4) Not Consistent (NC)

Aug 2005

Rear Portion

Vehicle No:

SMG-8168G

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover	DD	✓	
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	DD	✓	
1149	993045	Rear Bumper Reinforcement	DD	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler	CUT	✓	
1158	994023	Reverse Sensor	RR	✓	
1159	993327	Rear End Panel	DD	R	
1160	993339	Rear End Panel Top Garnish	DD	R	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	DD	R	
1182	991328	Tailgate Emblem	NEC	✓	5
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock	BT	✓	
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

Done by Steve.

26/2/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Dec 2018 Edit Reg		18 Dec 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case



















Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	KONG HOE LEONG (KUANG HAOLIN) , ID: S1022697Z								
Main Claimant:	-								
Vehicle Reg. No.:	SMG8168G	Date of Loss:	15/12/2018 00:00 - :59 [42 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2497358902SG	Policy/Cover Note No.:	2100391244 (Comprehensive)						
Vehicle Reg. No. (Insured):	SDJ378K	Policy No. (Claimant):							
		Excess:							
Repairer:	Khek Joo Motor Workshop (HQ) BLK 9004 TAMPINES STREET 93 #01-94, 528838 Tampines - Tel: 67854258								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 02/01/2019]								
Claimant's Solicitor:	TOMMY CHOO, MARK GO LLC - Tel: 65322455								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (26/12/2018): Request for TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMG8168G (2497358902SG)**
[SDJ378K]
TP

-
Dec 15 2018 12:00AM
[KONG HOE LEONG (KUANG HAOLIN)]
Khek Joo Motor Workshop

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser <input type="button" value="v"/>	
Assessment Reports			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		
1	26/12/18 11:17	Accident Statement From: SC - Reg. No: SDJ378K, Claimant: KONG HOE LEONG		Load HTM <input type="button" value="Print"/>
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
2	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
3	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
4	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
5	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
6	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
7	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
8	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
9	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
10	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
11	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
12	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
13	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
14	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
15	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
16	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
17	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
18	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
19	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
20	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
21	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
22	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
23	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
24	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
25	24/12/18 14:20	General View		Load JPG <input checked="" type="checkbox"/>
26	31/12/18 08:55	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
27	31/12/18 08:55	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
28	31/12/18 08:55	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
29	31/12/18 08:55	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
30	31/12/18 08:55	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
31	31/12/18 08:55	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
32	31/12/18 08:55	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
33	31/12/18 08:55	Photo After Spray		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	31/12/18 08:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
35	31/12/18 08:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
36	31/12/18 08:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
37	31/12/18 08:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
38	31/12/18 08:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	31/12/18 08:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	31/12/18 08:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	31/12/18 08:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	31/12/18 08:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	31/12/18 08:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	31/12/18 08:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	31/12/18 08:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	31/12/18 08:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	31/12/18 08:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	31/12/18 08:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	31/12/18 08:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	31/12/18 08:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	31/12/18 08:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18022694/GCBE2

Date: 08/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100391244
Claimant Vehicle No : SMG8168G **Insured Vehicle No :** SDJ378K
 Date of Loss: 15/12/2018 Nature of Claim: TP Claim No: 2497358902SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMG8168G**
 Make & Model: SUBARU FORESTER, 2.0 XT (A) Engine No: FA20J865620
 Reg. Date: 30/05/2015 (Man. Year: 2014) Chassis No: JF1SJGK85EG035471
 Colour: Black Odometer: 53478 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18
 Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm
 Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 18/12/2018
 Date Inspected: 19/12/2018 Inspected At: Khek Joo Motor Workshop (HQ)
 BLK 9004 TAMPINES STREET 93 #01-94
 Singapore 528838
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER TOW COVER	Dented	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	2		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
6	1		*REAR BUMPER SPONGE	* Check	0.00 F	*- F
7	2		*REAR BUMPER REFLECTOR	* Check	0.00 F	*- F
8	1		*REAR BUMPER LOWER SPOILER	Cut	0.00 F	*- F
9	2		*REVERSE SENSOR	Broken	0.00 F	*- F
10	1		*REAR END PANEL	Repair	0.00 F	*- F
11	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
12	1		*REAR LH TAILLAMP	* Check	0.00 F	*- F
13	1		*REAR RH TAILLAMP	* Check	0.00 F	*- F
14	1		*TAILGATE	Repair	0.00 F	*- F
15	5		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
16	1		*TAILGATE LOCK	Bent	0.00 F	*- F
17	1		*TAILGATE RUBBER	* Check	0.00 F	*- F
18	2		*REAR EXHAUST CHROME PIPE	* Check	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >