

12/03/2012

ASS. REC. BY:

REF: CS / ATG18022697 / Unbsz

Special Instruction:

Survivor:

ASSIGNMENT (Office)

Maimin.

From (Person):

Syuzairdin

of

ALH

Date/Time: 18122018 1:15pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBM 7784H

Insured:

SIV 7751X

at Workshop m/s

Siang Hai Motor

Tel:

6555 7272

of

Blk 7 Kaki Bukit Ave 6 #02-03

Policy No:

1800071829

Claim No:

52027270059

Sum Insured:

Excess:

Make of Veh:

D.O.A. 13-12-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS w/p

H.O.D. Endorsement:

Date/Time:

18122018 1:40pm

Person Contacted:

Ah Huat

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	FBM 7784H - X
	SIV 7751X - NA/INC15013104/d2

DDA: 030315

Surround

REF: A76

ASSIGNMENT

From:

Date: 18/12/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBM 7784H

at Workshop m/s

Siong Hai

of

Blk 1 Kaki Bukit Ave 6 # 02-03

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

11k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBM 7784H

Yr Regn:

3 18

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha Jupiter c.c. 114

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

42939

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MH3UE1120JJ168964

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

70-90-17

R:

80-90-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Dunlop

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

13/2/18

mm

L/Bal.

18/12/18

mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

all, o/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27A 7048

1/1/19

L/S \$3000 conf. with AH insur. (Red 3900.50, 560)

RECEIVED 03 JAN 2019

Date/Time: File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

250

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Report Format :

merimen

Lump Sum / I.B.I. (\$

3000p

20

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Dec 2018 Edit Reg		19 Dec 2018 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Ng Jeffrey Boon Heng, ID: S7536877A		
Main Claimant:	AMV PTE. LTD., Co. Reg. No.: 201505825Z		
Vehicle Reg. No.:	FBM7784H	Date of Loss:	13/12/2018 17:00 - :59
Claim Type:	TP / 5202727200SG	Policy/Cover Note No.:	1800071829
Vehicle Reg. No. (Insured):	SGV7751X	Policy No. (Claimant):	
		Excess:	
Repairer:	Siong Hai Motor & Trading (HQ) NO 1 KAKI BUKIT AVE 6, #02-03 AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 31/12/2018]		
Claimant's Solicitor:	HIN TAT AUGUSTINE & PARTNERS - Tel: 65330212		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (20/12/2018): No OI GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

- Pre repair inspection request - FBM7784H VS SGV7751X (OI) DOA: 13/12/2018

From: Azlan, Syazairdina

To: admin-a@lkkauto.com; assignments@lkkauto.com

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinrul; Chan, Yoke Shi; Kaur, Baljit

Sent: Tuesday, 18 December, 2018 1:15:19 PM

Hi,

Please refer to the enclosed request from **Hin Tat Augustine & Partners**.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks and regards,

Syaza Irdina Azlan

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

From: anil@htapartners.com.sg [mailto:anil@htapartners.com.sg]

Sent: Tuesday, December 18, 2018 12:25 PM

To: Azlan, Syazairdina

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinrul; Chan, Yoke Shi; Kaur, Baljit; anil@htapartners.com.sg

Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGV7751X AND FBM7784H ON 13/12/2018

WITHOUT PREJUDICE

URGENT

Dear Sir

We refer to your email of even date.

Our client is agreeable to appoint Mr Marcus Chua, LKK Auto Consultants Pte Ltd as the single joint expert to carry out the pre-repair survey for FBM 7784H.

Please make the necessary arrangements with the contact person. The details are as follows :

Venue : **Siong Hai Motor & Trading**
1 Kaki Bukit Avenue 6
#02-03 Autobay
Singapore 417883

Contact Person : **Mr Ah Huat (H/P : 6555 7272)**

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our client's right to claim for compensation for loss of use for your current request for re-survey.

Best regards,

Ruby Ong

Secretary

M/s Hin Tat Augustine & Partners

20 Upper Circular Road

#02-10/12 The Riverwalk

Singapore 058416

Tel : **6533 0212 ext 278**

Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

From: Azlan, Syazairdina

Sent: Tue, 18 Dec 2018 01:07:03 +0000

To: anil@htapartners.com.sg

Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Hor, Yinrul, Chan, Yoke Shi, Kaur, Baljit

Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGV7751X AND FBM7784H ON 13/12/2018

Without Prejudice

Your Reference : TCL.GCN.ro.50516.18.shm
Our Reference : SGV7751X

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Abu Kassim, Noor Mariesa

Sent: Monday, December 17, 2018 4:44 PM

To: Azlan, Syazairdina

Subject: FW: NOTICE OF ACCIDENT & PRE-REPAIR SURVEY - YOUR REF: SGV7751X & OUR REF: TCL.GCN.ro.50516.18.shm - ACCIDENT INVOLVING FBM7784H & SGV7751X ON 13/12/18

Importance: High

From: Anil Kumar [mailto:anil@htapartners.com.sg]

Sent: Monday, December 17, 2018 4:43 PM

To: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene; Abu Kassim, Noor Mariesa

Cc: Ruby Ong

Subject: NOTICE OF ACCIDENT & PRE-REPAIR SURVEY - YOUR REF: SGV7751X & OUR REF: TCL.GCN.ro.50516.18.shm - ACCIDENT INVOLVING FBM7784H & SGV7751X ON 13/12/18

Importance: High

Dear Sir,

ACCIDENT INVOLVING FBM7784H & SGV7751X ALONG / AT SIGLAP ROAD ELITE PARK AVENUE (JUNCTION OF ROAD 1 AND 2) ON 13/12/18 @ TIME: 17:30 HRS

We are instructed to notify you of the above-mentioned road traffic accident which involves our client's vehicle registration number **FBM7784H** and vehicle registration number **SGV7751X** driven by your insured at the material time.

As a result of the accident, our client's motorcycle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,

Anil (Secretary)
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext.256
Direct Fax: 63383536
Fax : 6533 0313

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/12/2018 18:21
Date Of Accident	13/12/2018 17:30
Exact Location Of Accident	SIGLAP ROAD ELITE PARK AVENUE(JUNC OF RD 1 & RD 2)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBM7784H
Insured/Policyholder	
Name Of Registered Owner	AMV PTE. LTD.
Co Reg No	201505825Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98583956

Vehicle Particulars

Manufacturer	YAMAHA
Model	JUPITER 115 Z1

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5099364749
Cover Note Number	

Driver

Name of Driver	AMROSE ARULSELVAM
Passport No/FIN	G7842265W
Date Of Birth	02/05/1985
Occupation	OUTDOOR
Date Of Driving Pass	21/11/2011
Driving Experience	7 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90384045
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	1 BEDOK SOUTH AVENUE #05-919
Postcode	460001
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No.T/20181217/2036

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGV7751X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	AMROSE ARULSELVAM
Approximate Age	33
Injuries Sustain	
Injured person in which vehicle?	FBM7784H
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	YES
Address	1 BEDOK SOUTH AVENUE #05-919
Postcode	460001

Accident Sketch Plan Pg. 1

GP/PS/2011/Rev 2.0/04/2014

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

17 DEC 2018
IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Singapore 415933
Reporting Centre Person's Signature
Name: Tel: 67416697
Fax: 67492305
NRIC/FIN No: Email: vackb@sinonet.com.sg

Accident Sketch Plan Pg. 1

Siglap Road		A-FBM7784H
	↑	B-SGU7751X
Elite Park Ave		
	↑	
←	↑	
↑	↑	
↑	↑	

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

* Refer to police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

SIAPMC SketchPlanForm_V3

Driver's Signature

(if driver is not the policyholder)

Date & Time:

17 DEC 2018

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No:

Initial: Vackb@singnet.com.sg

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20181217/2036

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20181217/2036

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/12/2018 11:31		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: AMROSE ARULSELVAM			Address: 1 BEDOK SOUTH AVENUE 1 #05-919 SINGAPORE 460001		
ID Type / ID No.: FIN NO / G7842265W			Contact No.: Home/Office: Mobile: 90384045		
Nationality:			Email:		
Sex: Male	Age: 33	Date of Birth: 02/05/1985	Type of Informant: Rider		
Race:			Language:		Institution / School Name:
Occupation: Motorcycle delivery man			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 13/12/2018 17:30	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 SIGLAP ROAD ELITE PARK AVENUE				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBM7784H	Motorcycle					0
SGV7751X	Car					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20181217/2036

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20181217/2036

CONTINUATION OF REPORT

Rider			
Name	AMROSE ARULSELVAM	ID No.	G7842265W
Related Vehicle	FBM7784H (Motorcycle)	Contact No.	90384045
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	13/12/2018	Date Discharge	13/12/2018
No. of Days granted Medical Leave	04	Degree of Injury	NIL
Driver			
Name	JEFFREY NG BOON HENG	ID No.	S7536877A
Related Vehicle	SGV7751X (Car)	Contact No.	-
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTIONED TIME,DATE AND LOCATION.

I WAS RIDING ALONG SIGLAP ROAD. ON THE LEFT OF 2 LANES. I WAS APPROACHING THE JUNCTION, THE CAR MENTIONED ABOVE WAS ON MY RIGHT. I WAS RIGHT BESIDE THE CAR. AT THE JUNCTION, THE CAR SUDDENLY MADE A LEFT TURN AND HIT ONTO THE RIGHT SIDE OF MY MOTORCYCLE. I DO NOT KNOW WHETHER THE CAR SIGNALLED BECAUSE I WAS DIRECTLY BESIDE HIM. I WAS INJURED AS A RESULT OF THIS ACCIDENT. I TOOK PHOTOS AND EXCHANGED PARTICULARS. AFTERWARDS, I WAS CONVEYED TO CHANGI GENERAL HOSPITAL.



**SINGAPORE
POLICE FORCE**



T/20181217/2036

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20181217/2036

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: TP / KHALED AMR HASSAN MOHSEN 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 17/12/2018 11:31
Officer In Charge Of Case: TP / GIT / Staff Sgt MOHAMED SUFIAN BIN SUDIN Contact No.: 65476367	Classification Of Case: <div data-bbox="853 1825 1396 2045" data-label="Form">  <p>SINGAPORE POLICE FORCE</p> <p>Signature: </p> </div>

Authentication Stamp
NP168

Date of Accident : 13/12/18 Accident Time: 17:30 (24-HR-Format)
Accident Place : Siglap Road Elite Park Avenue (Junction of Road 1 And 2)
Vehicle. No. (Car Plate No.) : FBW 7784H Make/Model: _____
Insurance Company : NTUC Policy No: 5099364749
Owner or Company Name /IC No. : AMV PTE LTD 2015058252
Owner or Company Contact No. : _____ Owner's Hp 98583956 Company Tel _____
DRIVER'S Name / IC No. : Amrose Arulselvam G7842265W
DRIVER'S Date Of Birth : 02/05/1985 DRIVER'S License Pass Date 21/11/2011
Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling Employee Others: _____
DRIVER'S Address : 1 Bedok South Ave 1, #05-919 Singapore 460001
DRIVER'S Contact No./ Alt No. : 1) _____ 2) 90384045
DRIVER'S Occupation : INDOOR OUTDOOR (e.g. working inside or outside office)
Email Address : _____
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type : Reporting Only Claim Other Party Claim Own Insurance
Number of Passengers (Including Driver): 01
Was there any video Captured by car camera: YES \ NO
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
Any Injury (If YES, Pls state): _____

Other Party Driver's Particular (if any)

Vehicle. No: <u>SGV 7751X</u>	Vehicle. No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: <u>Jeffrey Ng Boon Heng</u>	Name Driver: _____
IC No. Driver/Contact: <u>57536877A</u>	IC No. Driver/Contact: _____

*** NEW - Passenger's name & gender:**

* There was no passenger in my vehicle at the time of the accident.



SINGAPORE POLICE FORCE



T/20181217/2036

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20181217/2036

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/12/2018 11:31	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars			
Name of Informant: AMROSE ARULSELVAM		Address: 1 BEDOK SOUTH AVENUE 1 #05-919 SINGAPORE 460001	
ID Type / ID No.: FIN NO / G7842265W		Contact No.: Home/Office: Mobile: 90384045	
Nationality:		Email:	
Sex: Male	Age: 33	Date of Birth: 02/05/1985	Type of Informant: Rider
Race:		Language:	Institution / School Name:
Occupation: Motorcycle delivery man		Driving Licence Information: Class: 2B,3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 13/12/2018 17:30	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 SIGLAP ROAD ELITE PARK AVENUE				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBM7784H	Motorcycle					0
SGV7751X	Car					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20181217/2036

3 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20181217/2036

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

TP /

KHALED AMR HASSAN MOHSEN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Staff Sgt MOHAMED SUFIAN BIN SUDIN

Contact No.: 65476367

Signature Of Informant:

Date/Time:

17/12/2018 11:31

Classification Of Case:



**SINGAPORE
POLICE FORCE**

Signature: _____

Authentication Stamp

NP168

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5825Z
Vehicle Details	
Vehicle No.:	FBM7784H
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Dec 2018
Vehicle Make:	YAMAHA
Vehicle Model:	JUPITER 115 Z1
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	E3R5E0178381
Chassis No.:	MH3UE1120JJ168964
Maximum Power Output:	-
Open Market Value:	\$1,459.00
Original Registration Date:	28 Mar 2018
First Registration Date:	28 Mar 2018
Transfer Count:	1
Actual ARF Paid:	\$219.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Mar 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$7,602.00
COE Rebate Amount:	\$7,048.00
Total Rebate Amount:	\$7,048.00

The information contained herein is correct as at 19 Dec 2018

OK

Bike model

Yamaha Jupiter

Type

Any

Price From

Any

Price To

Any

Class

Any

MORE SEARCH OPTIONS ▼

Q SEARCH

VIEW ALL (/LISTING/USEDBIKES/LISTING/)

Q SEARCH ▼

Yamaha Jupiter MX150 (/listing/usedbike/yamaha-yamaha-jupiter-mx150/10581/)



(/listing/usedbike/yamaha-yamaha-jupiter-mx150/10581/)

SGD\$7800

Reg : 15/07/2016

Type: Cubs

150cc

1 lady owner. Low mileage. Showroom condition.

Posted on : 05/12/2018

★ PAID AD

★ DEALER AD

■ COMPARE

DETAILS > (/LISTING/USEDBIKE/YAMAHA-YAMAHA-JUPITER-MX150/10581/)

Yamaha Jupiter MX135 (/listing/usedbike/yamaha-yamaha-jupiter-mx135/9011/)

2:08

4G



Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5099364749

Cover : Third Party

1. Index mark and Registration Number of Vehicle
Chassis Number

: ~~To Be Advised~~ FBM7784H
: MH3UE1120JJ168964

2. Name of Policyholder

: AMV PTE. LTD.

3. Effective Date of Insurance

: ~~27 Mar 2018~~ 28 Mar 2018

4. Expiry Date of Insurance

: ~~26 Mar 2019~~ 27 Mar 2019

5. Persons or Classes of Persons entitled to drive#

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

(a) Use for hire or reward.

(b) Use for racing, pace-making, reliability trial or speed-testing.

(c) Use for the carriage of goods (other than samples) in connection with any trade or business.

(d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: N/A
INSURE WITH COE	: N/A
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: SPEEDWAY MOTOR PTE LTD
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : SININS AGENCY PTE. LTD. (00000615123)

Date of Issue : 27 Mar 2018 14:00 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

EMPLOYMENT PASS
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer:
AMY PTE. LTD.

Name:
AMROSE ARULSELVAM

Occupation:
CHAUFFEUR, PRIVATE MOTOR CAR

FIN:
G7842265W

Date of Application:
15-12-2017

Date of Issue:
25-01-2018

Date of Expiry:
25-01-2020

L8587641

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **G7842265W**

Name:
AMROSE ARULSELVAM

Birth Date: **02 May 1985**

Issue Date: **02 Nov 2016**

Valid Till: **20/11/2021**

002625050F

VISIT PASS
Immigration Regulations

Name:
AMROSE ARULSELVAM

Date of Birth: **02-05-1985** Sex: **M** Nationality: **INDIAN**

FIN: **G7842265W** Date of Issue: **25-01-2018** Date of Expiry: **25-01-2020**

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

		EFFECTIVE DATE
C	Class 2B	Motorcycles <= 200 CC
C	Class 3	Motor cars <= 3000 kg with <= 7 passengers, exclusive of the driver; and motor tractors/vehicles <= 2500 kg
3		21 Nov 2011
C		21 Nov 2011

G7842265W **S / No. 9000255314**

NP 428A

License No: G7842265W

SIONG HAI MOTOR & TRADING

No. 1 Kaki Bukit Avenue 6, #02-03 (Autobay), Singapore 417883

TEL: 6555 7272

H/P: 9336 5311 (Ah Huat)

not follow
2/1/18
4/5 @ 3000
18/12/18
4 day.

Vehicle number: FBM7784H

Vehicle Made & Model: YAMAHA JUPITER 115

Qty	List Items		Amount \$
1	Headlamp	cm	195.00 ✓
1	Headlamp top fairing	n	105.00 X
1	Headlamp bracket	n	85.00 X
1	Handle bar	but	120.00 ✓
2	Handle grips @ 32	11	64.00 X
2	Handle bar balancers @ 28	o/s scr	56.00 1/2 C
1	Meter	11	450.00 X
1	Meter cover	11	123.00 X
2	Mirrors - L/R @ 65	o/s 3w	130.00 1/2 C
1	Centre fairing	cur/cm	165.00 ✓
2	Left & Right side fairings @ 165	o/s cur	330.00 1/2 C
2	Left & Right side lamps @ 85	11	170.00 X
1	Brake level	scr	45.00 ✓
1	Brake disc	scr	130.00 X
1	Front fender	cur	95.00 ✓
2	Front fork assys - L/R @ 450	scr/cm	900.00 ✓
1	Front fork under bracket	but	185.00 ✓
1	Front sport wheel	but	225.00 ✓
1	Front sport wheel shaft	scr	35.00 ✓
1	Front footrest stay	but	155.00 ✓
2	Front footrest rubbers - L/R @ 32	o/s 10.00	64.00 1/2 C
1	Brake pedal	cur	95.00 ✓
1	Cushion <i>seaf</i>	n	155.00 X
1	Cushion lower cover - CTR	cm	130.00 ✓
1	Exhaust muffler	n	350.00 X
1	Exhaust muffler cover - FRT	scr	85.00 ✓
1	Exhaust muffler cover - Rear	scr	120.00 ✓
1	Rear footrest - RH	cur	45.00 ✓
1	Rear footrest bracket - RH	scr	85.00 X
1	Rear mudguard	11	58.00 X
1	Rear Taillamp	11	120.00 X

Vehicle Make & Model: YAMAHA JUPITER 115

	CUY 155.00	
Sub-total	5,225.00	
Less 10%	522.50	3040
Total List	4,702.50	2736

1	Rear no. plate	300	20.00	10
1	Rear box	600	250.00	✓
1	Rear box bracket	300	80.00	✓
1	Front tyre	300	150.00	X
1 set	Body sticker	200	280.00	120
Total Special Nett			780.00	

Transportation charges	50.00	35
To check front & rear electrical wiring	50.00	17 x
To remove, refix & realign front fork	120.00	17 x
To straighten, repair & realign chassis frame member	350.00	17 x
To respray painting and etc	400.00	250
Panel beating, cut, weld remove & replacing above parts	450.00	300
Total Labour	1,420.00	378

At

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main:	19 Dec 2018 Edit Reg		18 Dec 2018 00:00 Edit Adj Rpt	S\$3,000.00 Edit Estimates	S\$3,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Ng Jeffrey Boon Heng , ID: S7536877A		
Main Claimant:	AMV PTE. LTD. , Co. Reg. No.: 201505825Z		
Vehicle Reg. No.:	FBM7784H	Date of Loss:	13/12/2018 17:00 - :59 [8 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 5202727200SG	Policy/Cover Note No.:	1800071829
Vehicle Reg. No. (Insured):	SGV7751X	Policy No. (Claimant):	
		Excess:	
Repairer:	Siong Hai Motor & Trading (HQ) NO 1 KAKI BUKIT AVE 6, #02-03 AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 31/12/2018]		
Claimant's Solicitor:	HIN TAT AUGUSTINE & PARTNERS - Tel: 65330212		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (20/12/2018): No OI GIA Report

ALL ASSOCIATED TASKS










































[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)








































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBM7784H (5202727200SG)**
[SGV7751X]
TP
AMV PTE. LTD.
Dec 13 2018 5:00PM
[Ng Jeffrey Boon Heng]
Siong Hai Motor & Trading

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser ▼		
Photos/Images															3 per page ▼			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print		
1	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
2	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
3	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
4	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
5	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
6	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
7	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
8	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
9	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
10	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
11	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
12	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
13	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
14	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
15	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
16	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
17	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
18	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
19	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
20	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
21	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
22	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
23	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
24	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
25	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
26	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
27	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
28	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
29	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
30	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
31	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
32	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
33	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
34	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		
35	03/01/19 08:56		General View													Load JPG		<input checked="" type="checkbox"/>		

Photos/Images			3 per page ▼	☑
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	03/01/19 08:56	General View	 Load JPG	☑
37	03/01/19 08:56	General View	 Load JPG	☑
38	03/01/19 08:56	General View	 Load JPG	☑
39	03/01/19 08:56	General View	 Load JPG	☑
40	03/01/19 08:56	General View	 Load JPG	☑
41	03/01/19 08:56	General View	 Load JPG	☑
42	03/01/19 08:56	General View	 Load JPG	☑
43	03/01/19 08:56	General View	 Load JPG	☑
44	03/01/19 08:56	General View	 Load JPG	☑
45	03/01/19 08:56	General View	 Load JPG	☑
46	03/01/19 08:56	General View	 Load JPG	☑
47	03/01/19 08:56	General View	 Load JPG	☑
48	03/01/19 08:56	General View	 Load JPG	☑
49	03/01/19 08:56	General View	 Load JPG	☑
50	03/01/19 08:56	General View	 Load JPG	☑
51	03/01/19 08:56	General View	 Load JPG	☑
52	03/01/19 08:56	General View	 Load JPG	☑
53	03/01/19 08:56	General View	 Load JPG	☑
54	03/01/19 08:56	General View	 Load JPG	☑
55	03/01/19 08:56	General View	 Load JPG	☑
56	03/01/19 08:56	General View	 Load JPG	☑
57	03/01/19 08:56	General View	 Load JPG	☑
58	03/01/19 08:56	General View	 Load JPG	☑
59	03/01/19 08:56	General View	 Load JPG	☑
60	03/01/19 08:56	General View	 Load JPG	☑
61	03/01/19 08:56	General View	 Load JPG	☑
62	03/01/19 08:56	General View	 Load JPG	☑
63	03/01/19 08:56	General View	 Load JPG	☑
64	03/01/19 08:56	General View	 Load JPG	☑
65	03/01/19 08:56	General View	 Load JPG	☑
66	03/01/19 08:56	General View	 Load JPG	☑
67	03/01/19 08:56	General View	 Load JPG	☑
68	03/01/19 08:56	General View	 Load JPG	☑
69	03/01/19 08:56	General View	 Load JPG	☑
70	03/01/19 08:56	General View	 Load JPG	☑
71	03/01/19 08:56	General View	 Load JPG	☑
72	03/01/19 08:56	General View	 Load JPG	☑
73	03/01/19 08:57	Reinspection Photo	 Load JPG	☑
74	03/01/19 08:57	Reinspection Photo	 Load JPG	☑
75	03/01/19 08:57	Reinspection Photo	 Load JPG	☑
76	03/01/19 08:57	Reinspection Photo	 Load JPG	☑
77	03/01/19 08:57	Reinspection Photo	 Load JPG	☑
78	03/01/19 08:57	Reinspection Photo	 Load JPG	☑
79	03/01/19 08:57	Reinspection Photo	 Load JPG	☑
80	03/01/19 08:57	Reinspection Photo	 Load JPG	☑
81	03/01/19 08:57	Reinspection Photo	 Load JPG	☑
82	03/01/19 08:57	Reinspection Photo	 Load JPG	☑
83	03/01/19 08:57	Reinspection Photo	Load JPG	☑

Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	03/01/19 08:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	03/01/19 08:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
131	03/01/19 08:57	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

Reset Save Print

There are no document checklists configured.

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18022697/UVBS2

Date: 04/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800071829
 Claimant Vehicle No: FBM7784H Insured Vehicle No: SGV7751X
 Date of Loss: 13/12/2018 Nature of Claim: TP Claim No: 5202727200SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBM7784H
 Make & Model: YAMAHA JUPITER 115 Z1, 114cc Engine No: E3R5E0178381
 Reg. Date: 28/03/2018 (Man. Year: 2018) Chassis No: MH3UE1120JJ168964
 Colour: Blue Odometer: 42939 km
 Engine Capacity: 114 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70-90-17 Rear Tyre Size: 80-90-17
 Front Left Side: Duro 6 mm Rear Left Side: Duro 6 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,482.50	3,196.00	2,286.50	41.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,420.00	585.00	835.00	58.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,902.50	3,781.00	3,121.50	45.22
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	6,902.50	3,000.00	3,902.50	56.54

INSPECTION

Date of Assignment: 18/12/2018
 Date Inspected: 18/12/2018 Inspected At: Siong Hai Motor & Trading (HQ)
 NO 1 KAKI BUKIT AVE 6, #02-03 AUTOBAY @ KAKI BUKIT
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP	Cracked	195.00 FL	*195.00 FL
2	1		*HEADLAMP TOP FAIRING	Repair	105.00 FL	*- FL
3	1		*HEADLAMP BRACKET	Repair	85.00 FL	*- FL
4	1		*HANDLE BAR	Bent	120.00 FL	*120.00 FL
5	2		*HANDLE GRIPS	Not Necessary	64.00 FL	*- FL
6	1		*HANDLE BAR BALANCERS	O/s Scratched	56.00 FL	*28.00 FL
7	1		*METER	Not Necessary	450.00 FL	*- FL
8	1		*METER COVER	Not Necessary	123.00 FL	*- FL
9	1		*MIRRORS - L/R	O/s Broken	130.00 FL	*65.00 FL
10	1		*CENTRE FAIRING	Cut / Cracked	165.00 FL	*165.00 FL
11	1		*LEFT & RIGHT SIDE FAIRINGS	O/s Cut	330.00 FL	*165.00 FL
12	2		*LEFT & RIGHT SIDE LAMPS	Not Necessary	170.00 FL	*- FL
13	1		*BRAKE LEVEL	Scratched	45.00 FL	*45.00 FL
14	1		*BRAKE DISC	Serviceable	130.00 FL	*- FL
15	1		*FRONT FENDER	Cut	95.00 FL	*95.00 FL
16	2		*FRONT FORK ASSYS - L/R	Bent / Twisted	900.00 FL	*900.00 FL
17	1		*FRONT FORK UNDER BRACKET	Bent	185.00 FL	*185.00 FL
18	1		*FRONT SPORT WHEEL	Bent	225.00 FL	*225.00 FL
19	1		*FRONT SPORT WHEEL SHAFT	Necessary	35.00 FL	*35.00 FL
20	1		*FRONT FOOTREST STAY	Bent	155.00 FL	*155.00 FL
21	1		*FRONT FOOTREST RUBBERS - L/R	O/s Torn	64.00 FL	*32.00 FL
22	1		*BRAKE PEDAL	Cut	95.00 FL	*95.00 FL
23	1		*CUSHION SEAT	Repair	155.00 FL	*- FL
24	1		*CUSHION LOWER COVER - CTR	Cracked	130.00 FL	*130.00 FL
25	1		*EXHAUST MUFFLER	Repair	350.00 FL	*- FL
26	1		*EXHAUST MUFFLER COVER - FRT	Scratched	85.00 FL	*85.00 FL
27	1		*EXHAUST MUFFLER COVER - REAR	Scratched	120.00 FL	*120.00 FL
28	1		*REAR FOOTREST - RH	Cut	45.00 FL	*45.00 FL
29	1		*REAR FOOTREST BRACKET - RH	Serviceable	85.00 FL	*- FL
30	1		*REAR MUDGUARD	Not Necessary	58.00 FL	*- FL
31	1		*REAR TAILLAMP	Not Necessary	120.00 FL	*- FL
32	1		*TAILBOARD - RH	Cut	155.00 FL	*155.00 FL
33	1		*REAR NO. PLATE	Bent	20.00 FS	*10.00 FS
34	1		*REAR BOX	Cut	250.00 FS	*250.00 FS
35	1		*REAR BOX BRACKET	Bent	80.00 FS	*80.00 FS
36	1		*FRONT TYRE	Serviceable	150.00 FS	*- FS
37	1		*SET BODY STICKER	Necessary	280.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,005.00	3,500.00
- List Item Discount on L Items 10.00/10.00% (\$)	522.50	304.00
Total Parts (\$)	5,482.50	3,196.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORTATION CHARGES.	New	50.00	35.00
2	TO CHECK FRONT & REAR ELECTRICAL WIRING.	New	50.00	0.00
3	TO REMOVE, REFIX & REALIGN FRONT FORK.	New	120.00	0.00
4	TO STRAIGHTEN, REPAIR & REALIGN CHASSIS FRAME MEMBER.	New	350.00	0.00
5	TO RESPRAY PAINTING AND ETC.	New	400.00	250.00
6	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS.	New	450.00	300.00
Gross Labour Cost (S\$)			1,420.00	585.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >