

INS. CASE OWNER:

CCU/LPC1802

LKK:

IDAC:

Surveyor:

DOI:

Date / Time :

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

Name of Insured :

Insured Tel No. :

Excess Sec II : \$

Is driver the owner?

(YES / NO)

Nature of Accident :

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No

SLJ 71897



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	☐
	After call ltr to OI:	☐
	Authorisation To Act:	☐
	Release Voucher:	☐
	Final Repair Bill:	☐
	Car Rental Invoice:	☐
	Towing Invoice:	☐
	LTA / GIA :	☐
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☐
	LOD:	☐
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐
PRELIMINARY ADVICE Date/Time: Sent By:		
FINALIZATION Date/Time: Confirm with: Confirm by:		
Repair Cost:	\$	(days) Reduction: % Email ☐ Call ☐
FINAL SETTLEMENT Date/Time: Confirm with: Email ☐ Call ☐		
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :
Repair Cost:	\$	
Loss of Rental (LOR):	\$	(days)
Loss of Use (LOU):	\$	(\$ x days)
Loss of Income (LOI):	\$	(\$ x days)
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LO ☐		[Tick only one]
GIA/LTA Search	\$	
Medical:	\$	
Disbursement:	\$	(e.g. Tow/ Independent)
Legal Cost	\$	
Total:	\$	Global Sum \$:
FINAL PAYMENT Date/Time: Confirm with: Email ☐ Call ☐		
Payee 1:	\$	Name 1:
Payee 2: (Strike if N.A.)	\$	Name 2:
Payee 3: (Strike if N.A.)	\$	Name 3:

Surveyor

Tang

REF:

LPC

ASSIGNMENT

SLJ7189Z

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLJ7189Z

Yr Regn:

2016, Dec.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3.

C.C.

1496

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp.Reading

126277

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JM 65N 22AS40132506

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

18/12/18

Survey held at

Pegasus Market

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

) S + RS. St

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL