



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18022721/Kpa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:PETER

Date : 17-04-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GV 9307H	Veh. Inspected	GBE 6778A
Policy No.	GA299879	Coverage (\$)	0.00
Claim No.	S8M016Z9	Excess (\$)	0.00
Assign From		Assign Date	18/12/2018

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV200 (M)	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	VSKYBAM20Z0120787	Colour	METALLIC GREY
Odometer	83722	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/70 R14	HAIDA	9 mm
L/H Front Tyre	185/70 R14	HAIDA	9 mm
R/H Rear Tyre	185/70 R14	HAIDA	9 mm
L/H Rear Tyre	185/70 R14	HAIDA	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	17/12/2018	Inspection Date	21/12/2018
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------