

SS. REC. BY:

REF:

CS/FCL18022727 / As b²

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

CWS

Joanne Yong

of

FCL

Date/Time:

18/12/2018 536pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH 9134D

Insured:

SHA 7867U

at Workshop m/s

Cycle & Carriage

Tel:

of

330 Ubi Road 3

Policy No:

Claim No:

D18008890MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12.12.2018

CA / REV / REP. / REV 24 HRS 'Wp'

20.12.2018 @ 2pm

H.O.D. Endorsement:

Date/Time:

18.12.2018 538pm

Person Contacted:

Mars

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLH 9134D - X

SHA 7867U - CS/FCL17033455 / Agbn2

DIA: 06122017

21/12/18

@ 17:40 p.m. revised PA to Joanne Yong via email.

27/09/19

@ 15:43 pm check with Mars her, owner has not yet sent in the vehicle for repair.