

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The mere act of acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GAA Reports Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the acceptance of this report by the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or processed by my insurer (collectively the "Personal Information") and disclose and/or transfer such Personal Information to all insurers who have insured vehicle(s) involved in the accident (all insurers who have insured vehicle(s) involved in the accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Ministry of Transport, the Ministry of Police and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions as responding to any enquiries by me;
(iv) processing my claims (including the making of compensation, settlements, interest, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages) and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
(b) all insurer(s) who have insured vehicle(s) involved in the accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may not be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (Must be not the policyholder) / Date & Time

VERIFIED BY AJAX MARS
REPORTING OFFICER
THOMAS NG CHIN CHUN

Witnessed by Reporting Centre
Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I WAS DRIVING ALONG LOWER DELTA RD TOWARDS TELOK BLANGAH AREA AND I WAS DRIVING AT THE SECOND LANE. WHEN IM ABOUT TO REACH THE CROSS JUNCTION BETWEEN BUKIT PURMEI AND TELOK BLANGAH, TRAFFIC LIGHT SHOWS RED SO I SLOW DOWN AND STOP MY VEHICLE STATIONARY. AFTER FEW SECOND, SUDDENLY I FELT A BIG IMPACT FROM REAR SO I DECIDED TO CAME DOWN AND CHECK. VEHICLE B COLLIDED ONTO MY REAR PORTION AND THE DRIVER TOLD ME HE WAS TEXTING WITH HIS PHONE AND FORGET TO APPLIED HAND BRAKED. WE TOOK PHOTO ON THE SPOT AND EXCHANGED PARTICULRAS. NO INJURIES INVOLVED. PLEASE REFER TO THE VIDEO FOOTAGE.

Taxi Voucher No.:

Are you claiming your own insurance policy for the repair of your vehicle?


No, Claim 3rd party

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
NG CHIN CHUN

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

1 March 2018 at 11:33 AM

Date/Time

1 March 2018 at 11:33 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/03/2018 08:27
Date Of Accident	28/02/2018 16:30
Exact Location Of Accident	LOWER DELTA ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC8182A
-----------------------------	---------

Insured/Policyholder

Name Of Registered Owner	KHIM SEAH ENTERPRISE PTE LTD
Co Reg No	200206061K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67582468

Vehicle Particulars

Manufacturer	ISUZU
Model	LT134P-7.8 D (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	NO
--	----

If No, Please state action to be taken	REPORTING ONLY
--	----------------

Vehicle Category	BUS
------------------	-----

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P0902358
Cover Note Number	

Driver

Name of Driver	LIU ZHONG BAO
Passport No/FIN	G5032289R
Date Of Birth	18/06/1965
Occupation	OUTDOOR
Date Of Driving Pass	01/10/2010
Driving Experience	7 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82872333
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	C/O WAVE 9 @ 71 WOODLANDS INDUSTRIAL PARK E9 #06-08
Postcode	757048
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLB2514T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

Toward:
Terak Blangsan Way

Lower Delta Road.


$$A = P \cup P \cap A$$

B: SLB-25/4T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving my bus 'A' (PC81P3A) along the 3rd lane of Lower Delta Road intend to turn right to Belok Blangah way.

As I was waiting for the traffic light, I did not notice that my bus slightly moved forward and touched into the rear portion of vehicle 'B' (SUBSIST)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Page 9 Three

Driver's Signature _____

doi:10.1017/S0022292412001766

Reporting Centre Personnel's Signature

© 2004 Blackwell Publishing Ltd *Journal of Internal Medicine* 255: 105–112

Accident Photo



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 1 of 1

PRE-REPAIR INSPECTION REPORT			
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811 ATTN: RUTH CHUA		Ref: CS3/ASM18004105/Sa3s2 Date: 03-05-2018 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	PC 8182A	Veh. Inspected	SLB 2514T
Policy No.	P0902358	Coverage (\$)	0.00
Claim No.	S8M009VS	Excess (\$)	0.00
Assign From		Assign Date	02/03/2018
2. Vehicle Particulars & Condition			
Make & Model	NISSAN NOTE	c.c	1198
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JN1TBAE12Z0982402	Colour	GREY
Odometer	29174 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/65R15	CONTINENTAL	6 mm
L/H Front Tyre	185/65R15	CONTINENTAL	6 mm
R/H Rear Tyre	185/65R15	CONTINENTAL	6 mm
L/H Rear Tyre	185/65R15	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information			
Accident Date	26/02/2018	Inspect Date / Time	05/03/2018 (09:35 AM)
Survey held at	HAN CAR REPAIRS BLK 1001 #01-49 BUKIT MERAH LANE 3 ALEXANDRA VILLAGE SINGAPORE 159718		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/ASM18004105/Sa3s2

Inspected By

YEANG WAI KEEN

Automotive Assessor

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.



THNG HENG GUAN
31 ALEXANDRA ROAD #03-02
159967

Attention : THE OWNER
Contact : 9685 3063

Tax Invoice : TP000280

Date : 20/09/2018
Vehicle Num. : SLB 2514 T
Make/Model : NISSAN NOTE 1.2-2016
Chassis/Eng# : JN1TBAE12Z0982402/HR12173528B
Accident Date : 28/02/2018
Claim No. :
Reference :
Policy No. :

	Amount S\$
LUMP SUM REPAIRS	6,800.00



for HAN CAR REPAIRS

E. & O.E.	Total S\$:	6,800.00
	GST @ 7% S\$:	476.00
	Amount Due S\$:	7,276.00
		=====



TAX INVOICE

GST REG. NO.: 200106276D

INVOICE TC
THNG HENG GUAN 31 ALEXANDRA ROAD #03-02 SINGAPORE 159967

DATE	INVOICE NO.
28-Mar-2018	A 37470

		VHA NO.	DUE DATE	VEH. NO.
		A 37470	28-Mar-2018	SLT 7942 M
DESCRIPTION	NO. OF DAYS	RATE	AMOUNT	
RENTAL FROM 14 MARCH 2018 TO 27 MARCH 2018 YOUR REF: SLB 2514 T	13	140.187	1,822.43	
GST @ 7%			\$127.57	
TOTAL			\$1,950.00	

All cheques must be made payable to BKW Rent A Car Pte Ltd.
Please write the vehicle and invoice number on the reserve.

BKW Rent-A-Car Pte Ltd
120 Lower Delta Road #02-15 Cendex Centre (S) 169208 Tel: 6738 7777 Fax: 6738 6666
ACRA No: 20C106276D GST Reg. No: 20-0106276-D Website: www.bkw.sg
A subsidiary of BKW Automobile Pte Ltd



bizSAFE



BKW RENT A CAR PTE LTD

120 Lower Delta Road #02-15 Condex Centre Singapore 169208 Tel: 6738 7777 Fax: 6738 6666

ACRA No. 20-0106276-D GST Reg. No. 20-0106276-D

24 HOURS HELPLINE: 6223 1122

VHA No. **A 37470**

HAL CAR


VEHICLE HIRING AGREEMENT

HIRER'S PARTICULARS

Name (as in I/C): Mr. Heng Heng
NRIC/Passport No: 12 Date of Birth: 24-2-1958
Address: 31 Age: 56
Name & Address of Employer: _____
Occupation: _____ Driving Exp: _____
Driving Licence No: _____ Passed Date: _____
D/L Type: Local/Int'l/Other: _____
Tel(C): _____ (R): _____ HP: 4145 2443

DRIVER'S PARTICULARS

Name (as in I/C): _____
NRIC/Passport No: _____ Date of Birth: _____
Address: _____ Age: _____
Occupation: _____ Driving Exp: _____ Yrs: _____
Driving Licence No: _____ Passed / Expiry Date: _____
D/L Type: Local/Int'l/Other: _____ Contact No: _____



I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have been given by BKW Rent A Car Pte Ltd in connection with this agreement is true.

IMPORTANT

- The hirer and the authorized driver must be over 23 years of age and under 70 years of age and be hold valid driving licenses and have a minimum 3 years experience. Failure to observe stipulation will result in the hirer/the Authorized Driver being liable for all costs.
- All vehicles are supplied with petrol and should returned with petrol level likewise. A service charge of \$5 on top of a petrol surcharge is payable by the hirer should he fail to return the vehicle at the appropriate petrol level.
- No refund for early return of vehicle. The hirer shall be liable for additional charges for any late return at the rate shown per hour per day inclusive of CDW and/or PAI where applicable. Any returns after our operation hours will be charged as a full day rental.
- Use of the vehicle for illegal purpose (For instance: in connection with theft, drug peddling or trafficking, smuggling), is strictly prohibited.
- Vehicle strictly for Singapore use only and may not be driven out of Singapore without prior written consent of BKW Rent A Car Pte Ltd. The hirer is liable for a penalty fee of \$200 in addition to the appropriate insurance top up in the case of non-disclosure of Malaysia usage.
- The hirer and/or driver shall be responsible for all damages or losses however caused, all traffic violations, fines and penalties imposed on the vehicle for whatever reason in respect of or in connection with its use or operation. The hirer and/or driver shall be responsible for all claims, damages, losses, increased insurance premium, non-waiver excess and cost expense (including

Hirer's Own Vehicle No: _____ Replace Veh No: _____
Loan Vehicle No: SIT 7942M VR No: _____
Make & Model: FIAT PUNTRA Auto/Manual Group: _____
CHARGES
Daily 13 day @ \$ 150 Per day: 1950
Weekly/Monthly week @ \$ _____ Per week/Monthly _____
Others _____
CDW/PAI @ \$ _____ Per day/Monthly _____
Delivery/Collection Svc _____
GST _____
OR No: _____ (A) SUB-TOTAL: 1950
Perpet Level: OUT E IN 1/2 3/4 1
Surcharge IN _____
First _____ km FREE per day GST _____
Excess mileage is chargeable at _____ cents per km TOTAL CHARGES: _____

Security Deposit: \$ _____ Bank: _____

CASH/NETS/VISA/MC/AMEX/CHQ No: _____

Expiry Date: _____ Card ID No: _____

Name as in Card: _____

NON-WAIVER EXCESS (Added to GST): 20

ACCESSORIES CHECK

- ☐ Data Cards ☐ Camera Systems ☐ Hub Cap ☐ Radio / CD Cartridge
☐ Jack ☐ Tyre Opener ☐ Petrol Cap ☐ Spare Tyre

Hirer's Signature: _____ Additional Driver's Signature: _____

SINGAPORE Use Only

- The hirer agrees that a puncture tyre directly causes loss of vehicle key or other accessories belonging to him/her does not constitute an accident. In the event the owner's 24-Hour Emergency Service is called upon to respond to such occurrence, the hirer shall bear the cost of such response at \$50.00 per trip.
- In case of accident, the hirer shall report to rental office immediately. An accident report must be made within 24 hours. Failure to comply, the hirer will have to borne all liability from all parties claim. Full excess amount have to be paid immediately in the event of an accident.
- The hirer agrees to ensure that the vehicle is always kept in a safe condition and to ensure that the vehicle is always kept in a safe condition and to ensure that the vehicle is always kept in a safe condition.
- All customers' data will be kept strictly confidential and is only used for the purpose of completing the sales transactions and other related matters.
- I understand and agree to the personal data collection statement stated on the Terms and Conditions Page.

Date Out	Time Out	Mileage	Check By	Remarks
14/1/18	18:00	716		
Return Of Vehicle: The Hirer/Driver is Required To Sign In The Column "Signature Of Hirer/Driver" Failing Which The Day And Time Inserted Below Shall Be Deemed To Be The Day And Time The Vehicle Is Returned To BKW Rent A Car Pte Ltd And The Same Shall Be Accepted As Conclusive Evidence Of The Same And Shall Not Be Challenged Or Questioned On Any Account Whatsoever. And I had cleared my belonging items from the rental vehicle (cash card, parking coupons, etc)				
Date In	Time In	Mileage	Check By	Remarks
24/1/18	08:39	719	NIK	716/11/2/110

Hirer's/Driver Signature

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Billing Name & Address
Thng Heng Guan
31 Alexandra Road
#03-02
Singapore 159967

Invoice No 03-18022/DY

Date 14 Sep 2018

Vehicle No : SLB 2514 T

Model : Nissan Note

Item	Descriptions	Amount S\$
1	Date of inspection : <u>14 Mar 2018</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Purchase of films, develop negatives - Storage of negatives - Submission of photographs <u>152</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 752.00</u>
	SDLS : SEVEN HUNDRED AND FIFTY-TWO ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Pal's Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O. E

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference : TP / 03-18022/DY / 2018
Date of Report : 14 Sep 2018

Thng Heng Guan
31 Alexandra Road
#03-02
Singapore 159967

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 28 Feb 2018

As per your instruction dated 14 Mar 2018 with regard to the above matter. We have carried out a physical inspection on the said vehicle SLB 2514 T. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SLB 2514 T
Model : Nissan Note
Year / Capacity : 2016/1198
Chassis No : JN1TBAE12Z0982402
Engine No : HR12173528B
Mileage : 29555
Colour : Silver

2. TYRES CONDITION

			<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT	O/S	:	185/65 R15	Continental	6.00 mm	Sport
REAR	O/S	:	185/65 R15	Continental	6.00 mm	Sport
FRONT	N/S	:	185/65 R15	Continental	6.00 mm	Sport
REAR	N/S	:	185/65 R15	Continental	6.00 mm	Sport

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Han Car Repairs
Blk 1001 Bukit Merah Lane 3
#01-49 Alexandra Village
Singapore 159718

5. Estimated normal period of repair : 13 working days and including lead time to complete.
6. Enclosed number of photograph : 152 copies.
7. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
8. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SLB 2514 T
Report No: TP/ 03-18022/DY / 2018

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Rear tailgate	Damage	\$ 1177.80	\$ 1177.80 DD ✓
1	Rear tailgate inner board	Damage	\$ 131.80	\$ 131.80 NNX
1	Rear tailgate outer handle	Damage	\$ 255.20	\$ 255.20 DD ✓
1	Rear end panel	Damage	\$ 619.70	\$ 619.70 DD ✓
1	Rear bumper	Damage	\$ 1085.10	\$ 662.87 1085.10 DD ✓
2	Rear fenders	Repair	\$ 1578.20	\$
2	Rear fender inner garnishes	Damage	\$ 796.80	\$ 796.80 NNX
			\$ 5644.60	\$ 4066.40
	Discount	30.0%	\$ 1693.38	\$ 1219.92
			\$ 3951.22	\$ 2846.48
<u>Nett Items</u>				
1	Rear tailgate lock	Damage	\$ 117.30	\$ 117.30 BT
1	Rear tailgate lock striker	Damage	\$ 31.18	\$ 31.18
1	Rear tailgate rubber	Necessary	\$ 65.50	\$ 65.50 DD NNX
1	Rear tailgate logo	Necessary	\$ 52.50	\$ 45.60 52.50 } NEC ✓
1	Rear tailgate 'NOTE' emblem	Necessary	\$ 64.60	\$ 64.60
1	Rear tailgate inner handle	Damage	\$ 36.20	\$ 36.20 NNX
1	Rear end panel inner garnish	Damage	\$ 63.90	\$ 63.90 DL ✓
2	Rear taillamps	Damage	\$ 1168.80	\$ 1168.80 NNX
2	Rear taillamp panels	Damage	\$ 172.84	\$ 172.84 NNX
2	Rear bumper side retainers @ 25.20	Necessary	\$ 100.80	\$ 50.40 100.80 NEC ✓
2	Rear bumper brackets	Damage	\$ 62.46	\$ 62.46 NNX
1	Rear bumper inner sponge	Damage	\$ 82.10	\$ 82.10 NNX
1	Rear smart sensor	Damage	\$ 106.20	\$ 106.20 NNX
1	Rear exhaust silencer	Damage	\$ 461.80	\$ 461.80
2	Rear exhaust silencer mountings	Necessary	\$ 36.20	\$ 36.20 } NNX
1	Rear wiper motor	Damage	\$ 421.30	\$ 421.30
2	Rear windscreen side garnishes	Damage	\$ 63.90	\$ 63.90 NNX
1	Rear spare tyre top cover	Damage	\$ 171.10	\$ 171.10 NNX
			\$ 3278.68	\$ 3278.68
	Discount	10.0%	\$ 327.87	\$ 327.87
			\$ 2950.81	\$ 2950.81
<u>Special Nett Items</u>				
1	Rear windscreen seal	Necessary	\$ 80.00	\$ 80.00 50
1	Rear windscreen sealant	Necessary	\$ 60.00	\$ 40.00 60.00 ✓
1	Rear reverse sensor (1 set)	Damage	\$ 280.00	\$ 200.00 280.00
			\$ 420.00	\$ 420.00
Spare Parts Total			\$ 7322.03	\$ 6217.29

Vehicle No: SLB 2514 T
Report No: TP/ 03-18022/DY / 2018


LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 7322.03	\$ 6217.29
1	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 50.00	\$ 40.00
2	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 220.00	\$ 140.00 <i>60</i>
3	To remove and refit rear bumper sensor.	\$ 150.00	\$ 60.00 80.00
4	To remove and refit rear windscreen glass.	\$ 200.00	\$ 120.00
5	To remove and refit, straighten and re-adjust exhaust pipe and replace rear exhaust silencer and mountings.	\$ 150.00	\$ 80.00 <i>NNX</i>
6	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1000.00	\$ 880.00 <i>700</i>
7	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1000.00	\$ 880.00 <i>600.00 + 280</i>
8	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 150.00	\$ 60.00 <i>90.00</i>
Total		\$ 10242.03	\$ 8527.29

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 6800.00

SDLS: SIX THOUSAND EIGHT HUNDRED ONLY


Qualified Appraiser

Repaid days 5

TGrim

him

26/12/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 2514T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAILGATE	DENTED	1,177.80	1,177.80
1	REAR TAILGATE INNER BOARD	NOT NECESSARY	131.80	-
1	REAR TAILGATE OUTER HANDLE	DENTED	255.20	255.20
1	REAR END PANEL	DENTED	619.70	619.70
1	REAR BUMPER	DENTED	1,085.10	662.87
2	REAR FENDERS	TO REPAIR SEE LABOUR	1,578.20	-
2	REAR FENDER INNER GARNISHES	NOT NECESSARY	796.80	-
	LESS 30% DISCOUNT		-1,693.38	-814.67
			3,951.22	1,900.90
<u>NETT ITEMS</u>				
1	REAR TAILGATE LOCK (N)	BENT	117.30	117.30
1	REAR TAILGATE LOCK STRIKER (N)	NOT NECESSARY	31.18	-
1	REAR TAILGATE RUBBER (N)	DENTED	65.50	65.50
1	REAR TAILGATE LOGO (N)	NECESSARY	52.50	45.60
1	REAR TAILGATE 'NOTE' EMBLEM (N)	NECESSARY	64.60	64.60
1	REAR TAILGATE INNER HANDLE (N)	NOT NECESSARY	36.20	-
1	REAR END PANEL INNER GARNISH (N)	DISLODGE	63.90	63.90
2	REAR TAILLAMPS (N)	NOT NECESSARY	1,168.80	-
2	REAR TAILLAMP PANELS (N)	NOT NECESSARY	172.84	-
2	REAR BUMPER SIDE RETAINERS	NECESSARY	100.80	50.40
2	REAR BUMPER BRACKETS (N)	NOT NECESSARY	62.46	-
1	REAR BUMPER INNER SPONGE (N)	NOT NECESSARY	82.10	-
1	REAR SMART SENSOR (N)	NOT NECESSARY	106.20	-
1	REAR EXHAUST SILENCER (N)	NOT NECESSARY	461.80	-
2	REAR EXHAUST SILENCER MOUNTINGS (N)	NOT NECESSARY	36.20	-
1	REAR WIPER MOTOR (N)	NOT NECESSARY	421.30	-
2	REAR WINDSCREEN SIDE GARISHES (N)	NOT NECESSARY	63.90	-
1	REAR SPARE TYRE TOP COVER (N)	NOT NECESSARY	171.10	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-327.87	-40.73
			2,950.81	366.57
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEAL (SN)	NECESSARY	80.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
1	SET REAR REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
			420.00	290.00
	<u>LABOUR</u>			
	TO REMOVE AND REFIT REAR ELECTRICAL WIRING, REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING.		50.00	40.00
	TO REMOVE AND REFIT INNER TRIMS, INNER GARNISHES, TO FACILITATE THE REPAIRS.		220.00	60.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		150.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		200.00	120.00
	TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REPLACE REAR EXHAUST SILENCER AND MOUNTINGS.	NOT NECESSARY	150.00	-
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF REAR FENDERS.		1,000.00	700.00
	TO SPRAY PAINT ON THE REPLACED AND REAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		1,000.00	800.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		150.00	60.00
			-	-
			-	-
			-	-
			2,920.00	1,840.00
	GRAND TOTAL		10,242.03	4,397.47

Report Ref No. CS3/ASM18004105/Bpa3s2-1



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,500.00
---	--	--	----------

Report Ref No. CS3/ASM18004105/Bpa3s2-1

LIM TEOW GUAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.