



Your Ref: S8M009VS

Date: 1<sup>st</sup> February 2019

Our Ref: CS3/ASM18004105/Bpa3s2-1

**M/s AXA Insurance Pte Ltd**

8 Shenton Way #24-01

AXA Tower

Singapore 068811

Attn: Johnny Yong

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLB 2514T  
INSURED VEHICLE: PC 8182A ACCIDENT DATE: 28/02/2018**

We thank you for your instruction on 22/03/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLB 2514T from M/s PAL's Appraiser Pte Ltd.
- b) Final Repair Bill of SLB 2514T from M/s Han Car Repairs.
- c) Singapore Accident Statement of Vehicles SLB 2514T and PC 8182A.
- d) Colour damaged vehicle photographs of SLB 2514T.

Pre-Repair Inspection Date : 05/03/2018 at M/s Han Car Repairs, Blk 1001 #01-49 Bukit Merah Lane 3 Alexandra Village Singapore 159718.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLB 2514T
Make & Model	: Nissan Note
Year of Registration	: 2016
Chassis Number	: JN1TBAE12Z0982402
Engine Capacity	: 1198 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.