

ASS. REC. BY:

REF:

CS3/MSG18022741/Bcd3<sup>2</sup>

Special Instruction:

Surveyor:

Yehmen

Mr Lim

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSIG

Date/Time:

19/12/18 @ 9.33am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIF 4971Y

Insured:

FBG 8792J

at Workshop m/s

Team Auto pro

Tel:

9674 6635

of

8 Kaki Bukit Ave 4 # 06-21 premier

Policy No:

MSD/VMT/17-988136-WTT

Claim No:

MSC/V/18-001612

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 01/12/2018

CA / REV / REP. / REV 24 HRS

Cup

H.O.D. Endorsement:

Date/Time: 9.51am @ 19/12/18

Person Contacted:

Frederick

Vehicle IN/OUT

Date/Time	Action/Instruction ( X ) Estimate
	SIF 4971Y - X
	FBG 8792J - X
	Dismantle: 20/12/2018
	After repair: 27/12/2018

REF: MSIG

PRS

## ASSIGNMENT

From:

Date: 19/12/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLF 4971Y

at Workshop m/s

Team Autopro

of

No 8 kaki Bukit Ave 4 #06-21

Insured:

Premier

Policy No

Claims No

Sum Insured

Excess:

(Client's Record)

Make of Veh:

Frederick 9674 6635

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS <sup>1up</sup>

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No

SLF 4971Y

Yt Regn

2F/1/2010

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Lexus IS250

G.C. 2500

Colour

WHITE

A/C

Insured / Std / NI / NA

Sp. Reading

125479

T/Radio: Insured / Std / NI / NA

Eng/No:

4GR0628855

C/N:

JTHFR252702509872

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/45R17

R: 225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC7 OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

4/2/15

D.O.I.

19/12/18

Survey held at

Team Autopro

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range 700/2 - 800/2

*[Signature]*  
27/12/2018

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) \$ + RS. SI

) Photos

) Others

) :

TOTAL

Report Format :

PRQ

Lump Sum / I.B.I: (\$)

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: Weekend (\$)

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	17 Dec 2018		19 Dec 2018 09:33 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ALISTAR ENTERPRISE, Co. Reg. No.: 53224828K		
Main Claimant:	CHEN JIA, ID: S8373041B		
Vehicle Reg. No.:	SLF4971Y	Date of Loss:	01/12/2018 19:00 - :59 [103 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-001612	Policy/Cover Note No.:	MSD/VMT/17-988136-WTT (Third Party Only) Coverage: 22/12/2017 - 21/12/2018
Vehicle Reg. No. (Insured):	FBG8792J	Policy No. (Claimant):	
		Excess:	
Repairer:	Team Autopro Pte Ltd (KAKI BUKIT) No.8 Kaki Bukit Avenue 4, #06-21 Premier@ Kaki Bukit (Gate 2), 415875 Kaki Bukit - Tel: 90927279		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/12/2018]		
Driver/Custodian (Insured):	NOR ASY'ARI BIN YUSOFF (24 / Male), NRIC: S9349185H, Tel: +6581822124		
Adj. Remarks:	on WP, SJE : DISAGREED / LIABILITY IN DISPUTE Please appoint LKK AUTO CONSULTANTS to conduct the survey . Kindly contact MR ALAN KOH @ 9092 7279 or MR FREDERICK LIM @ 9674 6635 to arrange for survey .		

### ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	04/12/2018 13:08
Date Of Accident	01/12/2018 19:30
Exact Location Of Accident	KOON SENG ROAD TURNING INTO TEMBELING ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF4971Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHEN JIA
NRIC No	S8373041B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96191568
Alternative Phone No	OTHERS-96191568

### Vehicle Particulars

Manufacturer	TOYOTA
Model	LEXUS IS250C AUTO STD
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA126983/1
Cover Note Number	

### Driver

Name of Driver	ZHU YING
NRIC No	S8274048A
Date Of Birth	25/01/1982
Occupation	INDOOR
Date Of Driving Pass	08/04/2015
Driving Experience	3 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96191568
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address 631 SENJA ROAD #12-224 SPORE 670631

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured SPOUSE

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : CHEN JIA

GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBG8792J

Vehicle Make/Model/Colour YAMAHA YBR 125 MANUAL

Details Of Properties

Vehicle Category MOTORCYCLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: S. G. K. A. S.  
NRIC/FIN No.: S70801720

# Sketch Plan #2

## SKETCH PLAN



Koon Seng Road Turning  
into Tembeling Road

Vehicle A : SLF4971Y

Vehicle B :

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle A was turning right  
into Tembeling Road. Suddenly vehicle B hit onto my vehicle  
left portion.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: S. S. S. S.  
NRIC/FIN No.: 5204017713



[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	3041B
<b>Vehicle Details</b>	
Vehicle No.:	SLF4971Y
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS IS250C AUTO STD
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	4GR0628855
Chassis No.:	JTHFK252702509872
Maximum Power Output:	153.0 kW (205 bhp)
Open Market Value:	\$53,007.00
Original Registration Date:	26 Apr 2010
First Registration Date:	26 Apr 2010
Transfer Count:	1
Actual ARF Paid:	\$53,007.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Apr 2020
PARF Rebate Amount:	\$29,153.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	25 Apr 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$40,001.00
COE Rebate Amount:	\$5,389.00
<b>Total Rebate Amount:</b>	<b>\$34,542.00</b>

The information contained herein is correct as at 20 Dec 2018

OK





**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

18 Mths Old BMW X3 SDrive20i, 1 Owner, 13000Kml



Fully PML Maintained, PML 3  
Years/200,000Km Warranty, 5  
Years Free Servicing!  
Auto Zoom Enterprise StarAd

**PRIME MOTOR & LEASING**  
(CHENG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES)  
With over 200 units of vehicles  
to choose from, ranging from  
all European to Japanese Makes.

Browse by Category ▼

Sort by Date Posted ▼

100 results/page ▼

2 vehicles

Lexus IS250C

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	Lexus IS250C		Any	Any	2010	Any	Any	Any	All
	Lexus IS250C		\$45,800	\$17,140 /yr	05-Feb-2010	2,500 cc	91,000 km	Sports	Available
Bidded Carplate Number, Cheap Depreciation With Rare Convertible Unit, Elegant Colour And Perfect Paint Condition. Smooth Engine And Transmission, Accident Free. Well Maintained Without Accident. Very...									
Prem Roy Motoring									
Posted: 15-Dec-2018 Tags: 2010 Lexus IS250C, 2010 Lexus IS250C, Lexus IS250C, Lexus IS250C, Lexus IS250C, IS250C, Used Lexus									
	Lexus IS250C		-	N.A	10-Feb-2010	2,500 cc	-	Sports	SOLD
Rare Convertible Model And Colour! (Original Deep Purple, Very Beautiful Esp Under The Sun). Excellent Condition! Enjoy The Cool Wind Blowing Through You At Night After Rain, Yet Surprise By The Quiet...									
Car Empire Automobiles Pte Ltd									
Posted: 03-Dec-2018 Tags: 2010 Lexus IS250C, 2010 Lexus IS250C, Lexus IS250C, Lexus IS250C, Lexus IS250C, IS250C, Used Lexus									

Save this search criteria, to get email alerts whenever a match is found.

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
For old advertisements, view Expired ads									
									100 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Lexus, Lexus Singapore, used Lexus Singapore, used Lexus, used vehicles Singapore or even buy used Lexus Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)  
©2004-2018 sgCarMart. All rights reserved.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Dec 2018		19 Dec 2018 09:33	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>ALISTAR ENTERPRISE</b> , Co. Reg. No.: 53224828K								
Main Claimant:	<b>CHEN JIA</b> , ID: S8373041B								
Vehicle Reg. No.:	<b>SLF4971Y</b>	Date of Loss:	01/12/2018 19:00 - :59 [103 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / MSC/V/18-001612</b>	Policy/Cover Note No.:	MSD/VMT/17-988136-WTT (Third Party Only) Coverage: 22/12/2017 - 21/12/2018						
Vehicle Reg. No. (Insured):	<b>FBG8792J</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Team Autopro Pte Ltd (KAKI BUKIT)</b> No.8 Kaki Bukit Avenue 4, #06-21 Premier@ Kaki Bukit (Gate 2), 415875 Kaki Bukit - Tel: 90927279								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Irene Tan Gek Ing</b> - 6594 2541]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Lim Teow Guan</b> ] ... [Imm.Advice due 20/12/2018]								
Driver/Custodian (Insured):	NOR ASY'ARI BIN YUSOFF (24 / Male), NRIC: S9349185H, Tel: +6581822124								
Adj Asg. Remarks:	on WP. SJE : DISAGREED / LIABILITY IN DISPUTE Please appoint LKK AUTO CONSULTANTS to conduct the survey . Kindly contact MR ALAN KOH @ 9092 7279 or MR FREDERICK LIM @ 9674 6635 to arrange for survey .								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




















## Claim Documents

\*SLF4971Y (MSC/V/18-001612)  
[FBG8792J]  
TP  
CHEN JIA  
Dec 1 2018 7:00PM  
[ALISTAR ENTERPRISE]  
Team Autopro Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
2	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
3	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
4	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
5	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
6	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
7	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
8	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
9	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
10	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
11	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
12	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
13	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
14	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
15	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
16	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
17	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
18	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
19	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
20	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
21	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
22	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
23	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
24	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
25	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
26	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
27	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
28	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
29	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
30	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
31	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
32	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
33	26/12/18 19:19	General View	 Load JPG	<input checked="" type="checkbox"/>
34	26/12/18 19:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	26/12/18 19:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	26/12/18 19:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
37	26/12/18 19:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
38	26/12/18 19:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
39	26/12/18 19:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
40	26/12/18 19:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
41	26/12/18 19:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
42	26/12/18 19:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
43	26/12/18 19:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
44	26/12/18 19:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
45	26/12/18 19:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
46	26/12/18 19:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
47	26/12/18 19:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
48	26/12/18 19:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
49	26/12/18 19:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
50	26/12/18 19:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
51	26/12/18 19:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
52	26/12/18 19:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
53	26/12/18 19:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
54	31/12/18 11:10	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
55	31/12/18 11:10	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
56	31/12/18 11:10	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
57	31/12/18 11:10	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
58	31/12/18 11:10	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
59	31/12/18 11:10	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
60	31/12/18 11:10	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
61	31/12/18 11:10	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	18/12/18 11:38	TPD SLF4971Y GIA REPORT	Load PDF	
2	18/12/18 11:43	TPD SLF4971Y - PRI	Load PDF	
3	18/12/18 11:45	Reject email to TP Lawyer & appoint LKK AUTO	Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18022741/BCD3S2  
Date: 02/01/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VT/17-988136-WTT

Claimant Vehicle No: SLF4971Y Insured Vehicle No: FBG8792J

Date of Loss: 01/12/2018 Nature of Claim: TP Claim No: MSC/V/18-001612

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLF4971Y

Make & Model: TOYOTA LEXUS, 2.5 IS250 (A) Engine No: 4GR0628855

Reg. Date: 26/04/2010 (Man. Year: 2010) Chassis No: JTHFK252702509872

Colour: White Odometer: 125479 km

Engine Capacity: 2500 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 19/12/2018

Date Inspected: 19/12/2018 Inspected At: Team Autopro Pte Ltd (KAKI BUKIT)  
No.8 Kaki Bukit Avenue 4, #06-21 Premier@ Kaki Bukit  
(Gate 2)  
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 - \$8,000.00



REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Jan 2019)
Parts:	143	TOYOTA LEXUS 2.5 IS250 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF4971Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >