

ASS. REC. BY:

REF

CS3/MSG18022743/Jcd3e2

Special Instruction:

Surveyor: Alfred Lee
Menimen Amelia

ASSIGNMENT (Office)

From (Person): Pauline Thiam

of

MSIG

Date/Time: 19/12/18 @ 9:31 am

Estimated Cost

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XD 5419M

Insured: XD 8666x

at Workshop m/s

Shingda Group.

Tel: 9621 1398

of

10 kmnji Crescent

Policy No: 28729953MKC

Claim No: 579238

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 15/12/2018

CA / REV / REP. / REV 24 HRS *lup*

H.O.D. Endorsement:

Date/Time: 9:46am @ 19/12/18

Person Contacted:

Mr. Mok

Vehicle IN/OUT[illegible]

REF: MSIG

Payable Here Jie

PRS

Pls call Mr. Mok once reach

ASSIGNMENT

From: Date: 19/12/18

Estimated Cost:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: XD 5419M
at Workshop m/s Shingda Group
of 10 Kranji Crescent

Insured:

Policy No.


Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Mr. Mok @ 96211398

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: XD 5419M Yr Regn: 27 Jan 2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

☒ Truck / Trailer or

Make: Mitsubishi

C.C. 12882

Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 154983

T/Radio: Insured / Std / NI / NA

Eng/No: -

C/No: FV51JJ A00767

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Order / Jammed / Leaked / Burnt orBrake: ☒ Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / ☒ STD / Rim or

Tyre Size: F: 295/80 R22.5

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or AUFINE

Front

Rear

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 15/12/18

D.O.I. 19/12/18

Survey held at


Shingda Group

Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range: \$1,000 - \$1,500
2 days

24/12/2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: -

Survey Fee:

Transportation

) \$ + RS. \$

) Photos

) Others

TOTAL

120

10

130

Report Format: PRS

Lump Sum / I.B.I. (\$))

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Dec 2018		19 Dec 2018 09:31 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SINGLAND HEAVY MACHINERY & CONSTRUCTION PTE LTD, Co. Reg. No.: 200302202M			
Main Claimant:	SHINGDA EQUIPMENT LEASING PTE LTD, Co. Reg. No.: 201723619M			
Vehicle Reg. No.:	XD5419M	Date of Loss:	15/12/2018 00:00 - :59 [82 Months and 18 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 579238	Policy/Cover Note No.:	28729953MKC Coverage: 01/06/2018 - 31/05/2019	
Vehicle Reg. No. (Insured):	XD8666X	Policy No. (Claimant):		
		Excess:		
Repairer:	Shingda Group (HQ) 10 Kranji Crescent, 728660 Kranji - Tel: 9621 1398			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/12/2018]			
Adj Asg. Remarks:	on WP. Liability unclear. Non Reporting. TP disagree with our SJE list. Proceed to appoint LKK Auto Consultants as the SJE. Contact Person: Mr Mok / 9621 1398.			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3619M
Vehicle Details	
Vehicle No.:	XD5419M
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Dec 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	FV51JJD4RDEA
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	6M70447151
Chassis No.:	FV51JJA00767
Maximum Power Output:	-
Open Market Value:	\$103,571.00
Original Registration Date:	27 Jan 2012
First Registration Date:	27 Jan 2012
Transfer Count:	1
Actual ARF Paid:	\$5,179.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jan 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$39,589.00
COE Rebate Amount:	\$12,270.00
Total Rebate Amount:	\$12,270.00

The information contained herein is correct as at 20 Dec 2018

OK

2018 3:37 PM FAX

0002/0005

MH110101820 / Hua Hong Pte Ltd - Sungei Kadut
 ENTRY DATE & TIME: 17/12/2018 10:11
 SUBMITTED BY: Yvonne Teh Yi Zhuang

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/12/2018 10:11
Date Of Accident	15/12/2018 17:10
Exact Location Of Accident	AT WOODLANDS AVE 4 (CHUAN LIM'S SITE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD5419M
Insured/Policyholder	
Name Of Registered Owner	SHINGDA EQUIPMENT LEASING PTE. LTD.
Co Reg No	201723619M
Email Address	CYNTHIA.SING@SHINGDA.COM
Mobile Phone No	
Alternative Phone No	OFFICE-63688936
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	FV51JJD4RDEA
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2018-V0103407-VCV
Cover Note Number	
Driver	
Name of Driver	GANESAN SURESH
Passport No/FIN	G7009111P
Date Of Birth	29/05/1975
Occupation	OUTDOOR
Date Of Driving Pass	19/03/2013
Driving Experience	5 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82907441
Fax Number	
Contact Number	

Address NIL
 Postcode
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

AS PER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XD8666X
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NPIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Yvonne Toh
NRFQFIN No.:

Accident Sketch Plan Pg. 1

SKETCH PLAN



A > XD 3419 M

B > XD 8886 X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident Date & Time: 15 Dec 2018, 17.09

Accident Location: At Woodlands Ave 4 (Chun Lim's Site)

I was at the above-mentioned location. My vehicle was stationary while queuing up to enter site. However, as the steel plate by the corner of the road was broken, veh B moved further and then made a reverse without checking the distance between his vehicle and mine. Veh B then hit my vehicle LH side's corner frame and corner.

☐ Reporting Only ☐ Own Damage ☐ Third Party ☒ Claim at other workshop (OCTP)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

REPORTING NOTE:

Reported from a vehicle involved in the accident that you are not a member of the Reporting Centre. Please contact the Reporting Centre for more information.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

Yvonne Toh

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Dec 2018		19 Dec 2018 09:31 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SINGLAND HEAVY MACHINERY & CONSTRUCTION PTE LTD, Co. Reg. No.: 200302202M		
Main Claimant:	SHINGDA EQUIPMENT LEASING PTE LTD, Co. Reg. No.: 201723619M		
Vehicle Reg. No.:	XD5419M	Date of Loss:	15/12/2018 00:00 - :59 [82 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 579238	Policy/Cover Note No.:	28729953MKC Coverage: 01/06/2018 - 31/05/2019
Vehicle Reg. No. (Insured):	XD8666X	Policy No. (Claimant):	
		Excess:	
Repairer:	Shingda Group (HQ) 10 Kranji Crescent, 728660 Kranji - Tel: 9621 1398		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Imm.Advice due 20/12/2018]		
Adj Asg. Remarks:	on WP. Liability unclear. Non Reporting. TP disagree with our SJE list. Proceed to appoint LKK Auto Consultants as the SJE. Contact Person: Mr Mok / 9621 1398.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***XD5419M (579238)**
[XD8666X]
TP
SHINGDA EQUIPMENT LEASING PTE LTD
Dec 15 2018 12:00AM
[SINGLAND HEAVY MACHINERY & CONSTRUCTION PTE LTD]
Shingda Group

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/12/18 09:13	General View	Load JPG	<input checked="" type="checkbox"/>
2	20/12/18 09:13	General View	Load JPG	<input checked="" type="checkbox"/>
3	20/12/18 09:13	General View	Load JPG	<input checked="" type="checkbox"/>
4	20/12/18 09:13	General View	Load JPG	<input checked="" type="checkbox"/>
5	20/12/18 09:13	General View	Load JPG	<input checked="" type="checkbox"/>
6	20/12/18 09:13	General View	Load JPG	<input checked="" type="checkbox"/>
7	20/12/18 09:13	General View	Load JPG	<input checked="" type="checkbox"/>
8	20/12/18 09:13	General View	Load JPG	<input checked="" type="checkbox"/>
9	20/12/18 09:13	General View	Load JPG	<input checked="" type="checkbox"/>
10	20/12/18 09:13	General View	Load JPG	<input checked="" type="checkbox"/>
11	20/12/18 09:13	General View	Load JPG	<input checked="" type="checkbox"/>
12	20/12/18 09:13	General View	Load JPG	<input checked="" type="checkbox"/>
13	20/12/18 09:13	General View	Load JPG	<input checked="" type="checkbox"/>
14	20/12/18 09:13	General View	Load JPG	<input checked="" type="checkbox"/>
15	20/12/18 09:13	General View	Load JPG	<input checked="" type="checkbox"/>
16	28/12/18 09:46	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
17	28/12/18 09:46	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
18	28/12/18 09:46	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
19	28/12/18 09:46	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
20	28/12/18 09:46	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	18/12/18 16:02	PRI, TP GIA Rpt	Load PDF	
2	18/12/18 16:04	Email to TP our SJE list	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18022743/JCD3E2

Date: 28/12/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28729953MKC

Claimant Vehicle No : XD5419M

Insured Vehicle No : XD8666X

Date of Loss: 15/12/2018

Nature of Claim: TP

Claim No: 579238

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD5419M

Make & Model: MITSUBISHI FV51JJD4RDEA, 12.9 D (M)

Reg. Date: 27/01/2012 (Man. Year: 2011)

Colour: White

Engine Capacity: 12882 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 6M70447151

Chassis No: FV51JJA00767

Odometer: 154983 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5

Front Left Side: AUFINE 8 mm

Rear Left Side: AUFINE 8 mm

Front Right Side: AUFINE 8 mm

Rear Right Side: AUFINE 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/12/2018

Date Inspected: 19/12/2018

Inspected At:

Shingda Group (HQ)
10 Kranji Crescent
Singapore 728660

Estimated Period of Repair: 2.0 days

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000.00 -\$1,500.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 28 Dec 2018)

Parts: N/A MITSUBISHI FV51JJD4RDEA 12.9 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for XD5419M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >