


REF: CS3/LPC18011517/Ggd3-1<sup>m2</sup>  
 ASS. REC. BY: Guo Guang  
 Surveyor: Ong li li  
 From (Person): LPC Date/Time: 19/12/2018  
 Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD /  TP / WS / TP RES / OD RES / EVA / INV / MV / CS  
 To Inspect Vehicle No: SKR 6292J Insured: SKE 4047H  
 at Workshop no: Motor Intel Tel: 8838 3318  
 of: 13 Kaki Bukit Road 4 # 01-20  
 Policy No: \_\_\_\_\_ Claim No: 18/18/18/VP05/020692  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A: 20/06/2018  
 (Client's Record) 26/06/2018  
 CA / REV / REP. / REV 24 HRS lup I.O.D. Endorsement: \_\_\_\_\_  
 Date/Time: 25/6/18 Person Contacted: wilson Vehicle:  IN  OUT

Date/Time	Action/Instruction (X) Estimate
	SKR 6292J - X
	SKE 4047H - X
07/8/18 @ 2145	Wilson checked with Wilson, the AJAX already surveyed on 27/6 & 26/6/18
09/5/18 @	Submit PAs.
04/1/19	Submit VS to 8400, 4 days (Red to 5300, 39%)

  
 3/1/2019

RECEIVED 04 JAN 2019



## Nivitha (LKK Auto)

---


**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Wednesday, 19 December 2018 11:05 AM  
**To:** Nivitha (LKK Auto); sales@mia.com.sg; assignments@lkkauto.com  
**Cc:** MT\_Claim\_SG; sur@lkkauto.com  
**Subject:** RE: OUR REF : VS SKR6292J (MIA) PRE-REPAIR INSPECTION - YOUR REF: SKE 4047 H; Clm Ref: 18/18/18/VP05/020692  
**Attachments:** 20692 TPD SR 1.pdf

Hi Nivitha/Catherine

Please see attached for TP survey report (part 1) and let us have your surveyor's review and report.

I will be sending part 2 to you in a separate email.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



---

**From:** Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]  
**Sent:** Monday, 25 June, 2018 4:13 PM  
**To:** ONG LI LI; sales@mia.com.sg; assignments@lkkauto.com  
**Cc:** MT\_Claim\_SG; sur@lkkauto.com  
**Subject:** RE: OUR REF : VS SKR6292J (MIA) PRE-REPAIR INSPECTION - YOUR REF: SKE 4047 H; Clm Ref: 18/18/18/VP05/020692

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** ONG LI LI [mailto:llong@lonpac.com]  
**Sent:** Monday, 25 June 2018 3:37 PM  
**To:** [sales@mia.com.sg](mailto:sales@mia.com.sg); [assignments@lkkauto.com](mailto:assignments@lkkauto.com); 'SUR' ([sur@lkkauto.com](mailto:sur@lkkauto.com)) <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>  
**Subject:** RE: OUR REF : VS SKR6292J (MIA) PRE-REPAIR INSPECTION - YOUR REF: SKE 4047 H; Clm Ref: 18/18/18/VP05/020692

Without Prejudice  
Save as to Costs

Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick <input type="checkbox"/>
1	Kalvin Ang	<input type="checkbox"/>
2	Xing Guo Qiang	<input type="checkbox"/>
3	Mohamad Taufikh	<input type="checkbox"/>
4	Bryan Ang	<input type="checkbox"/>
5	Adrian Ling	<input type="checkbox"/>
6	Mohammed Rasul	<input type="checkbox"/>
7	Marcus Chua	<input type="checkbox"/>
8	Kenneth Kong	<input type="checkbox"/>
9	Muhammad Nazril Bin Abdullah	<input type="checkbox"/>
10	Sathya Sai Kathirrasen	<input type="checkbox"/>

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Dear Catherine,

Please refer to the attached and follow up to arrange PRI.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

---

**From:** CHEW BENG KEE

**Sent:** Monday, 25 June, 2018 3:32 PM

**To:** MT\_Claim\_SG

**Subject:** FW: OUR REF : VS SKR6292J (MIA) PRE-REPAIR INSPECTION - YOUR REF: SKE 4047 H; Clm Ref: 18/18/18/VP05/020692

Hi Li Li, pls assist to arrange the PRI. TQ.

Best Regards

Chew Beng Kee  
Head of Claims | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6250 7388 Ext. 246 | Fax: (65) 6296 2706

---

**From:** Sales MIA [<mailto:sales@mia.com.sg>]  
**Sent:** Monday, June 25, 2018 3:06 PM  
**To:** CHEW BENG KEE  
**Subject:** OUR REF : VS SKR6292J (MIA) PRE-REPAIR INSPECTION - YOUR REF: SKE 4047 H

Without Prejudice

Dear Sir / Mdm ,

We refer to the above matter.

Please find enclosed documents for your necessary action.

Kindly assist to arrange the Pre-Repair Survey as per attachment details.

Thks & Regards  
Tinie  
Motor Intel Automo Pte Ltd

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/06/2018 12:19
Date Of Accident	20/06/2018 19:20
Exact Location Of Accident	PIE(CHANGI) BEFORE EXIT 26B
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR6292J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	AARON LEE XUAN ANG
NRIC No	S8938712D
Email Address	AARONLXA@LIVE.COM
Mobile Phone No	(LOCAL) +65-88770007
Alternative Phone No	OTHERS-88770007

### Vehicle Particulars

Manufacturer	VOLVO
Model	S80-1.6 D 2 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	S118V07075/VPE
Cover Note Number	

### Driver

Name of Driver	AARON LEE XUAN ANG
NRIC No	S8938712D
Date Of Birth	25/10/1989
Occupation	INDOOR
Date Of Driving Pass	22/06/2009
Driving Experience	8 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88770007
Fax Number	
Contact Number	OTHERS-88770007
Email Address	AARONLXA@LIVE.COM

Address BLK 16A SIMEI LANE #07-12  
 Postcode 520116  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident CHAIN COLLISION  
 Weather Conditions AFTER RAIN  
 Road Surface WET

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident 3  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER TO BELOW STATEMENT/SKETCH PLAN

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLK1788D  
 Vehicle Make/Model/Colour BMW  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number SKE4047H  
 Vehicle Make/Model/Colour CHEVROLET

Details Of Properties

Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name AARON LEE XUAN ANG  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SKR6292J  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance?  
Address 167A SIMEI LANE #07-12  
Postcode 52116

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ["GIA"] may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquires by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

X   
Policyholder's Signature  
Date & Time:


X   
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

IBAC KAKI BUKIT (VAC)  
23 KAKI BUKIT AVE 4  
Reporting Centre Personal Signature  
Name: Tel: 67416697  
NRIC/FIN No. Fax: 67492305  
Email: vacbh@singnet.com.sg

21 JUN 2018

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2<sup>nd</sup> Jun 2018 around 4:20pm, I was travelling along PIE towards changez before exit 26B. Car B slowed down and stop and I followed to stop behind car B. Suddenly, car C hit my the rear portion of my vehicle. Car C forced me to hit car B.

DECLARATION

(We declare the foregoing particulars are true in every respect.

x *Heo*  
 Policyholder's Signature  
 Date & Time:

x *Heo*  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 21 JUN 2018

IBAC KAKI BUKIT (PAC)  
 23 KAKI BUKIT AVE 4  
 Singapore 415933  
 Tel: 67416697  
 Fax: 67492305  
 Reporting Centre Person's Signature  
 Name: *Kanup: yockk...*  
 NRIC/FIN No.:

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/06/2018 12:52
Date Of Accident	20/06/2018 18:40
Exact Location Of Accident	PIE TWD CHANGI BEFORE UPPER BUKIT TIMAH RD EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKE4047H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHEW MAY LEE
NRIC No	S1760538J
Email Address	DIANA.CHEWML@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96314408
Alternative Phone No	OFFICE-92952845

### Vehicle Particulars

Manufacturer	CHEVROLET
Model	CRUZE-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z18VP05017461
Cover Note Number	

### Driver

Name of Driver	SEAN KOH YONG CAI
NRIC No	S9014743I
Date Of Birth	02/05/1990
Occupation	INDOOR
Date Of Driving Pass	18/02/2013
Driving Experience	5 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92952845
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address BLK 651B JURONG WEST ST 61 #12-354 (642651)  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured CHILDREN  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident CHAIN COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance?  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER TO SKETCH PLANS

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SKR6292J  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number SLK1788D  
 Vehicle Make/Model/Colour



**REPUBLIC OF SINGAPORE DRIVING LICENCE**

S90147431

SEAN KOH YONG CAI

Date of Birth: 02 May 1990  
 Issue Date: 18 Feb 2013

002152462J




**SINGAPORE ARMED FORCES IDENTITY CARD**

Name: SEAN KOH YONG CAI

NRIC No: S90147431



This card is the property of the Singapore Armed Forces. Any person finding this card is requested to forward it without delay to Central Manpower Base or any Police Station.

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES!**

EFFECTIVE DATE: 18 Feb 2013

**Class 3A** Motor cars without clutch pedals (Auto) <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles without clutch pedals <= 2600kg

NP 428A

Licence No: S90147431



GENERAL CATEGORY: 00000000000000000000

00000000128963

NRIC No/Colour: S90147431/ PINK

Race: CHINESE

Date Of Birth: 02/05/1990

Blood Group: A (+)

Country Of Birth: SINGAPORE

Sex: M

Religion: BUDDHISM

Address: B1K 651B JURONG WEST STREET 61 #12-354 SINGAPORE 642651



Accident Photo



Accident Photo



Accident Photo





# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

## VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0470618

Date of Report : 28/08/2018

To : Mr Aaron Lee Xuan Ang  
C/o. 13 Kaki Bukit Road 4  
#01-20 Bartley Biz Centre  
Singapore 417807

Date of Assignment : 21/06/2018  
Report requested by : Mr Aaron Lee Xuan Ang  
Date of Accident : 20/06/2018  
Date of Inspection : 21/06/2018  
Claim No. : Third Party Claim  
Policy No. : -

### **PARTICULARS OF DAMAGED VEHICLE**

Vehicle Registration No. : SKR6292J  
Make & Model : Volvo S80 (A) T5  
Date of Registration : 26/02/2015  
Colour : Met. Grey

Engine Capacity (cc) : 1969cc  
Mileage (km) : 61041km  
Chassis / Frame No. : YV1AS40CDF1189242  
Engine No. : B4204T111128090

### **TYRE CONDITION**

Front LH : 6 mm	Front RH : 6 mm
Make : Michelin	Make : Michelin
Rear LH : 6 mm	Rear RH : 6 mm
Make : Michelin	Make : Michelin

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

### **PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)**

General Bodywork : Good  
Paintwork : Good  
Handbrake : Serviceable  
Footbrake : Serviceable  
Steering : Serviceable  
Apparent Engine Modification : Nil

### **PLACE OF REPAIRER OFFICE/WORKSHOP**

Location : M/s. Motor Intel Automo Pte. Ltd.  
13, Kaki Bukit Road 4, #01-20, Bartley Biz Centre, Singapore 417807

### **ASSESSMENT**

Repairer's Estimate : \$ 20,940.70  
Revised Amount : \$ 17,147.60  
Less Excess : \$ -  
Recommended Reserve : \$ 13,700.00 (Lump Sum)

Estimated Normal Period of Repairs : 14 Working Days

*Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.*



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(52989D)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

Vehicle No : SKR6292J

Report No. : PAS/TP/0470618

## GENERAL REMARKS

WITHOUT PREJUDICE

### THE ASSIGNMENT

The survey was conducted at M/s. Motor Intel Automo Pte. Ltd., 13, Kaki Bukit Road 4, #01-20, Bartley Biz Centre, Singapore 417807.

(Subsequent inspections have been conducted)

### POINT OF IMPACT

At the front and rear portions.

### DAMAGES

The bonnet, front support panel, front bumper, LHF fender, LH headlamp, front grilles, boot lid, rear bumper, rear end panel, rear floor panel, LHR chassis member, LHR fender, rear exhaust silencer, LH taillamps, etc.

*Other parts were also found damaged. (See schedule for details)*

### ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$17,147.60.

### CONCLUSION


The repairer has agreed to undertake the repairs at a lump sum of SGD \$13,700.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,  
Prominent Appraiser Services Pte Ltd

  
Andrew How  
Automobile Appraiser  
MSAAA  
Licensed Appraiser



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)  
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SKR6292J

Report No. : PAS/TP/0470618

## APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition		Repairer's Estimate (\$\$)	Our Assessment (\$\$)
1	1 pc	Headlamp LH	Cracked/Defaced		\$ 1,352.00	\$ 1,352.00 ✓
2	1 pc	Frt grille	Dented/Cracked		\$ 650.00	\$ 650.00 ✓
3	1 pc	Frt bumper	Dented/Deformed		\$ 1,924.00	\$ 1,924.00 ✓
4	1 pc	Frt bumper grille	Cracked		\$ 273.00	\$ 273.00 ✓
5	1 pc	Frt bumper fog lamp LH	Cracked		\$ 675.00	\$ 675.00 ✓
6	1 pc	Frt bumper fog lamp grille LH	Dented/Loop Broken		\$ 201.00	\$ 201.00 ✓
7	1 pc	Frt bumper absorber	Dented/Cracked		\$ 239.00	\$ 239.00 ✓
8	1 pc	Frt bumper rail	Refit		\$ 958.00	\$ - x n n
9	8 pcs	Frt bumper clip	Necessary	\$ 3.00	\$ 24.00	\$ 24.00 ✓
10	2 pcs	Frt bumper guide R/L	Necessary	\$ 41.00	\$ 82.00	\$ 82.00 ✓
11	2 pcs	Frt bumper bracket R/L	LH Dented/Cracked	\$ 33.00	\$ 66.00	\$ 33.00 ✓
12	1 pc	Frt support panel assy	Dented/Repair		\$ 893.00	\$ - x R
13	1 pc	Boot lid	Dented/Distorted		\$ 1,611.00	\$ 1,611.00 x R
14	1 pc	Boot lid emblem (Volvo)	Necessary		\$ 86.00	\$ 86.00 ✓
15	1 pc	Boot lid emblem (S80)	Necessary		\$ 78.00	\$ 78.00 ✓
16	1 pc	Boot lid emblem (T5)	Necessary		\$ 65.00	\$ 65.00 ✓
17	1 pc	Boot lid lock	Damaged		\$ 287.00	\$ 287.00 ✓
18	1 pc	Taillamp LH	Cracked		\$ 586.00	\$ 586.00 ✓
19	1 pc	Rr bumper	Dented		\$ 2,029.00	\$ 2,029.00 ✓ 1309.33
20	1 pc	Rr bumper skirt	Dented		\$ 438.00	\$ 438.00 ✓ 390.8
21	4 pcs	Rr bumper reverse sensor	Dented/Damaged	\$ 248.00	\$ 992.00	\$ 744.00 ✓ 496
22	8 pcs	Rr bumper clip	Necessary	\$ 3.00	\$ 24.00	\$ 24.00 ✓
23	2 pcs	Rr bumper side guide R/L	Necessary	\$ 58.00	\$ 116.00	\$ 116.00 ✓
24	2 pcs	Rr bumper side bracket R/L	LH Dented/Cracked	\$ 33.00	\$ 66.00	\$ 33.00 ✓
25	1 pc	Rr bumper absorber	Dented/Cracked		\$ 104.00	\$ 104.00 ✓
26	1 pc	Rr bumper rail	Dented		\$ 944.00	\$ 944.00 ✓
27	1 pc	Rr end panel	Dented/Distorted		\$ 702.00	\$ 702.00 x R
28	1 pc	Rr end panel garnish	Refit		\$ 294.00	\$ - x n n
29	1 pc	Rr exhaust silencer LH	Dented/Bent		\$ 964.00	\$ 964.00 x ADR
30	1 pc	Bonnet	Dented/Repair			(Refer labour no. 3 & 4)
31	1 pc	Frt support panel assy	Dented/Repair			(Refer labour no. 2, 3 & 4)
32	1 pc	Rr fender LH	Dented/Repair			(Refer labour no. 11 & 12)
33	1 pc	Rr floor panel	Dented/Repair			(Refer labour no. 11 & 12)
					\$ 16,723.00	\$ 14,264.00
Less Discount : 10%					\$ 1,672.30	\$ 1,426.40
List Parts Sub-Total :					\$ 15,050.70	\$ 12,837.60
1	1 set	Frt no.plate (w/bracket)	Dented/Cracked	S/N	\$ 50.00	\$ 50.00 ✓ 40
Special Nett Sub-Total :					\$ 50.00	\$ 50.00
<b>Parts Total :</b>					<b>\$ 15,100.70</b>	<b>\$ 12,887.60</b>



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)  
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SKR6292J

Report No. : PAS/TP/0470618

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To check front electrical system and calibrate/focus headlamp.	\$ 60.00	\$ 50.00 /30
2	To remove, reinstall radiator, a/c condenser and pipings for necessary repairs. (Include pressure test cooling system and vacuum, recharge a/c gas)	\$ 200.00	\$ 180.00 X 11
3	To straighten, repair, realign on front affected area and replace damaged parts.	\$ 1,000.00	\$ 550.00 300/
4	To spray painting, blending on front affected and adjacent area.	\$ 1,000.00	\$ 700.00 400/
5	To check rear electrical wiring system.	\$ 80.00	\$ 50.00 /30
6	To transfer boot component parts to new boot.	\$ 120.00	\$ 100.00 111X
7	To remove and reinstall rear interior trims, garnishes, etc. for necessary repairs.	\$ 120.00	\$ 120.00 60
8	To remove and reinstall LHR undercarriage parts for remove exhaust system.	\$ 200.00	\$ 180.00 X
9	To straighten, repair, realign center exhaust pipe and replace exhaust silencer.	\$ 180.00	\$ 120.00 111X
10	To remove, replace and reinstall rear reverse sensors & reset control unit.	\$ 200.00	\$ 180.00 50/
11	To straighten, repair, realign on rear affected area and replace damaged parts.	\$ 1,200.00	\$ 770.00 500/
12	To spray painting, blending on rear affected and adjacent area.	\$ 1,400.00	\$ 1,200.00 700/
13	To spray anti-rust coating on new and affected panels.	\$ 80.00	\$ 60.00 30/
<b>Labour Total :</b>		<u>\$ 5,840.00</u>	<u>\$ 4,260.00</u>
<b>Total (Parts &amp; Labour) :</b>		<u>\$ 20,940.70</u>	<u>\$ 17,147.60</u>

9 days

### For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 13,700.00

Under normal circumstances, the repairs should be completed within a reasonable period of **14 Working Days.** (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

136 Photographs were taken at the time of inspection.

**N.B:** By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

*Note: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CS3/LPC18011511/Gqd3n2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 07-01-2019	
		Code : LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SKE 4047H	Veh. Inspected	SKR 6292J
Policy No.	Z18VP05017461	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020692	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	19/12/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	VOLVO S80 T5 2.0	c.c	1969
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	YV1AS40CDF1189242	Colour	GREY
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	235/40 ZR18	MICHELIN	6 mm
L/H Front Tyre	235/40 ZR18	MICHELIN	6 mm
R/H Rear Tyre	235/40 ZR18	MICHELIN	6 mm
L/H Rear Tyre	235/40 ZR18	MICHELIN	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	20/06/2018	Inspection Date	26/06/2018
Survey held at	MOTOR INTEL AUTOMO PTE LTD 13 KAKI BUKIT ROAD 4 @ BARTLEY BIZ CENTRE #01-20 SINGAPORE 147807		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>9 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 6292J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	HEADLAMP LH	CRACKED / DEFACED	1,352.00	1,352.00
1	FRT GRILLE	DENTED / CRACKED	650.00	650.00
1	FRT BUMPER	DENTED / DEFORMED	1,924.00	1,924.00
1	FRT BUMPER GRILLE	CRACKED	273.00	273.00
1	FRT BUMPER FOG LAMP LH	NOT NECESSARY	675.00	-
1	FRT BUMPER FOG LAMP GRILLE LH	DENTED / LOOP BROKEN	201.00	201.00
1	FRT BUMPER ABSORBER	DENTED / CRACKED	239.00	239.00
1	FRT BUMPER RAIL	NOT NECESSARY	958.00	-
8	FRT BUMPER CLIP @\$3000	NECESSARY	24.00	24.00
2	FRT BUMPER GUIDE R/L @\$41.00	NECESSARY	82.00	82.00
2	FRT BUMPER BRACKET R/L @\$33.00	N/S DENTED / CRACKED	66.00	33.00
1	FRT SUPPORT PANEL ASSY	TO REPAIR SEE LABOUR	893.00	-
1	BOOT LID	TO REPAIR SEE LABOUR	1,611.00	-
1	BOOT LID EMBLEM (VOLVO)	NECESSARY	86.00	86.00
1	BOOT LID EMBLEM (S80)	NECESSARY	78.00	78.00
1	BOOT LID EMBLEM (T5)	NECESSARY	65.00	65.00
1	BOOT LID LOCK	DAMAGED	287.00	287.00
1	TAILLAMP LH	CRACKED	586.00	586.00
1	RR BUMPER	DENTED	2,029.00	1,309.32
1	RR BUMPER SKIRT	DENTED	438.00	390.87
4	RR BUMPER REVERSE SENSOR @\$248.00	DENTED / DAMAGED (2 PCS ONLY)	992.00	496.00
8	RR BUMPER CLIP @\$3.00	NECESSARY	24.00	24.00
2	RR BUMPER SIDE GUIDE R/L @\$58.00	NECESSARY	116.00	116.00
2	RR BUMPER SIDE BRACKET R/L @\$33.00	N/S DENTED / CRACKED	66.00	33.00

Report Ref No. CS3/LPC18011511/Gqd3n2-1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RR BUMPER ABSORBER	DENTED / CRACKED	104.00	104.00
1	RR BUMPER RAIL	DENTED	944.00	944.00
1	RR END PANEL	TO REPAIR SEE LABOUR	702.00	-
1	RR END PANEL GARNISH	NOT NECESSARY	294.00	-
1	RR EXHAUST SILENCER LH	TO REPAIR SEE LABOUR	964.00	-
1	BONNET (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRT SUPPORT PANEL ASSY (NPA)	TO REPAIR SEE LABOUR	-	-
1	RR FENDER LH (NPA)	TO REPAIR SEE LABOUR	-	-
1	RR FLOOR PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-1,672.30	-929.72
			15,050.70	8,367.47
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRT NO PLATE (W/BRACKET)(SN)	DENTED / CRACKED	50.00	40.00
			50.00	40.00
	<b><u>LABOUR</u></b>			
	TO CHECK FRONT ELECTRICAL SYSTEM AND CALIBRATE/FOCUS HEADLAMP.		60.00	30.00
	TO REMOVE,REINSTALL RADIATOR,A/C CONDENSER AND PIPINGS FOR NECESSARY REPAIRS.(INCLUDE PRESSURE TEST COOLING SYSTEM AND VACUUM,RECHARGE A/C GAS).	NOT NECESSARY	200.00	-
	TO STRAIGHTEN,REPAIR,REALIGN ON FRONT AFFECTED AREA AND REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF FRT SUPPORT PANEL ASSY.		1,000.00	300.00
	TO SPRAY PAINTING,BLENDING ON FRONT AFFECTED AND ADJACENT AREA.		1,000.00	400.00
	TO CHECK REAR ELECTRICAL WIRING SYSTEM.		80.00	30.00
	TO TRANSFER BOOT COMPONENT PARTS TO NEW BOOT.	NOT NECESSARY	120.00	-

Report Ref No. CS3/LPC18011511/Gqd3n2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS,GARNISHES,ETC FOR NECESSARY REPAIRS.		120.00	60.00
	TO REMOVE AND REINSTALL LHR UNDERCARRIAGE PARTS FOR REMOVE EXHAUST SYSTEM.	NOT NECESSARY	200.00	-
	TO STRAIGHTEN,REPAIR,REALIGN CENTER EXHAUST PIPE AND REPLACE EXHAUST SILENCER.	NOT NECESSARY	180.00	-
	TO REMOVE,REPLACE AND REINSTALL REAR REVERSE SENSORS & RESET CONTROL UNIT.		200.00	50.00
	TO STRAIGHTEN,REPAIR,REALIGN ON REAR AFFECTED AREA AND REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF BOOT LID,RR END PANEL,RR EXHAUST SILENCER LH,BONNET,RR FENDER LH AND RR FLOOR PANEL.		1,200.00	500.00
	TO SPRAY PAINTING,BLENDING ON REAR AFFECTED AND ADJACENT AREA.		1,400.00	700.00
	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.		80.00	30.00
			5,840.00	2,100.00
	<b>GRAND TOTAL</b>		<b>20,940.70</b>	<b>10,507.47</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>8,400.00</b>

Report Ref No. CS3/LPC18011511/Gqd3n2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.