

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo

FOOD, LINE



Tel : 6858 5360

Fax: 6858 5359

Email: foodline@pacific.net.sg



Enquire Vehicle & Owner Information (Vehicle No. YN2056G As At 18 Nov 2018 / 10:30:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: GTW.ACC.12T193.18

Current Owner Details

Owner ID Type: Company
Owner ID: 200900424W
Owner Name: FOOD LINE PTE LTD
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 8A
Registered Street Name: ADMIRALTY STREET
Registered Unit No.: # 01 - 03
Registered Building Name: FOOD XCHANGE @ ADMIRALTY
Registered Postal Code: 757437

Current Vehicle Details

Vehicle No.: YN2056G
Make Description/Model: MITSUBISHI / FE83BE6SRDEA
Insurance Company Name: AXA INSURANCE PTE LTD

BIZ CHECK

COMPANY NAME: FOOD LINE PTE. LTD.
 REGISTRATION NO.: 200900424W

SINGAPORE
COMMERCIAL
CREDIT BUREAU

REQUEST DATE	REQUEST NO.	CLIENT'S A/C REF.	REMARKS
18/12/2018 11:49:21	ONL180854038	GTW.ACC.12T193.18	

**ACCOUNTING AND CORPORATE REGULATORY
 AUTHORITY BUSINESS PROFILE INFORMATION**

ACRA
 ACCOUNTING AND CORPORATE
 REGULATORY AUTHORITY

REGISTRY

REGISTRATION DATE	08/01/2009
NAME EFFECTIVE DATE	08/01/2009
COUNTRY OF INCORPORATION	SINGAPORE
COMPANY TYPE	EXEMPT PRIVATE COMPANY LIMITED BY SHARES
REGISTERED ADDRESS	8A ADMIRALTY STREET, 01 - 03 FOOD XCHANGE @ ADMIRALTY 757437 SINGAPORE
CHANGE ADDRESS DATE	28/03/2013
COMPANY STATUS	LIVE COMPANY
STATUS EFFECTIVE DATE	08/01/2009
REGISTERED ACTIVITIES	1. 10109 - PROCESSING AND PRESERVING OF MEAT AND MEAT PRODUCTS N.E.C. (COLDSTORE WITH CUTTING, PROCESSING & PACKING FACILITIES) 2. 46900 - WHOLESALE TRADE OF A VARIETY OF GOODS WITHOUT A DOMINANT PRODUCT (-)
AUDITOR	FIDES PAC
AUDITOR APPOINTMENT DATE	04/09/2018
ACCOUNT DATE	31/12/2017
DATE OF LAST AR	03/08/2018
DATE OF LAST AGM	30/06/2018

CHANGE OF COMPANY NAME

PREVIOUS NAME	EFFECTIVE DATE
Nil	

CAPITAL

CAPITAL CATEGORY	CURRENCY	CAPITAL AMOUNT	NO. OF SHARES
ISSUED ,ORDINARY	SINGAPORE, DOLLARS	150,000.00	150,000
PAID-UP ,ORDINARY	SINGAPORE, DOLLARS	150,000.00	NA

OFFICER(S)/ OWNER(S)

OFFICER NAME/ ADDRESS/ CHANGE ADDRESS DATE	IDENTITY NO. / PA REG. NO.	POSITION	APPOINTMENT DATE	NATIONALITY
SER LIP JING 538 UPPER CROSS STREET	S0821712B	SECRETARY	08/01/2009	SINGAPORE CITIZEN

2. Officer in Charge of Investigation/ Traffic Police Investigation Result

NIL

A copy each of the following supporting documents is enclosed:

1. Our client's GIA Report;
2. GIA Report of motor vehicle YN 2056G;
3. Land Transport Authority of motor vehicle YN 2056G;
4. ACRA search of Food Line Pte Ltd;
5. A DVD containing the video footages of the accident;
6. Repair Bill from M1 Motoring;
7. Survey Report from Prudent Adjustors Services.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer. Please note that you or your insurer should send to us an acknowledgment of receipt of this letter within 14 days of your receipt of this letter.

Should you fail to acknowledge receipt of this letter within 14 days, our client can commence court proceedings against you without further notice to you or your insurer.

Please also note that if you have a counterclaim against our client arising out of the accident, you or your insurer are required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully

Goh Teck Wee

Enc.

Cc **AXA Insurance Singapore Pte Ltd**
8 Shenton Way
#27-01 AXA Tower
Singapore 068811
Attention: Motor Claims Department

AR Registered Post

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 0841B

Vehicle Details

Vehicle No.: FBM1340U
Vehicle to be Exported: Yes
Intended Deregistration Date: 21 Dec 2018
Vehicle Make: YAMAHA
Vehicle Model: JUPITER MX (HC)
Primary Colour: Red
Manufacturing Year: 2013
Engine No.: 50C564723
Chassis No.: MH350C003DK564682
Maximum Power Output: -
Open Market Value: \$1,802.00
Original Registration Date: 17 Jun 2013
First Registration Date: 17 Jun 2013
Transfer Count: 3
Actual ARF Paid: \$271.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 16 Jun 2023
COE Category: D - Motorcycle
COE Period(Years): 10
QP Paid: \$1,701.00
COE Rebate Amount: \$763.00
Total Rebate Amount: \$763.00

The information contained herein is correct as at 21 Dec 2018


OK

ad



REPORT ERROR > (/LISTING/LISTING/ERROR/USEDBIKE/10605/)

+ ADD TO SHORTLIST



© SHARE (WHATSAPP://SEND?TEXT=HTTPS://SGBIKEMART.COM.SG/LISTING/USEDBIKE/YAMAHA-YAMAHA-JUPITER-MX135/10605/)

Yamaha Jupiter MX135

Listing Type	Paid Ad
Brand	Yamaha (/listing/usedbike/brand/yamaha/)
Model	Yamaha Jupiter MX135 (/listing/usedbike/model/yamaha-jupiter-mx135/)
Engine Capacity	134cc
Classification	2B
Registration Date	22/07/2013
COE Expiry Date	21/07/2023 (4 years 7 months left)
Mileage	-
No. of owners	-
Type of Vehicle	Cubs (/listing/usedbikes/listing/?bike_type=3)

Price: SGD\$5300

DETAILS

Yamaha Jupiter MX135. COE till July 2023. Good condition. One of the original and still one of the best. Loan available, welcome trade in. Come visit us at Sin Boon Motor. Interested buyers are welcome to negotiate.



GOH JP & WONG LLC

advocates & solicitors
commissioner for oaths

GOH TECK WEE

WONG TZE ROY

WONG FUNG KWAI

SOON WEI SONG

133 New Bridge Road #16-09 Chinatown Point Singapore 059413
Tel: 6538 5868 Fax: 6538 4898 (Not for service of Court documents) Email: mail@gohjpwong.com
Goh JP & Wong LLC is a law corporation with limited liability. GST/UEN: 201406078M

YOUR REF:

OUR REF:

GTW.ACC.12T193.18.wk

WHEN REPLYING, PLEASE QUOTE OUR REFERENCE NO

DATE:

18th December 2018

Food Line Pte Ltd

8A Admiralty Street

#01-03 Food Xchange@Admiralty

Singapore 757437

Dear Sirs

NOTIFICATION OF ACCIDENT

SUBJECT MATTER: TRAFFIC ACCIDENT INVOLVING FBM 1340U & YN 2056G ON 18.11.2018 AT CARPARK OF SINGAPORE INSTITUTE OF TECHNOLOGY

We act for Tan Li Ye in the above matter.

We are instructed to notify you of the above accident on 18th November 2018 at about 10.30 am at carpark of Singapore Institute of Technology involving our client's motorcycle FBM 1340U and motorlorry YN 2056G driven by your servant and/or agent at the material time. A copy of the traffic police report filed is enclosed.

As a result of the accident, our client's motorcycle FBM 1340U has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days (excluding Saturdays, Sundays and Public Holidays) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair inspection of the vehicle or whether you or your insurer waive the pre-repair inspection. If we do not receive any reply from you within the stipulated timeline our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Goh Teck Wee

Enc.

Cc **AXA Insurance Singapore Pte Ltd**
Attention: Motor Claims Department
By email: motor.doc@axa.com.sg
motor.survey@axa.com.sg

Cc **M1 Motoring**
Fax No. 6743 7556
Please do not proceed with repairs until further notice.

Nivitha (LKK Auto)

From: Xin Yi <xinyi@seahong.com.sg>
Sent: Thursday, 21 February 2019 11:02 AM
To: 'Admin-D (LKKAuto)'; 'Admin A'
Cc: 'Chee Kiong'; samson@seahong.com.sg; amanda@seahong.com.sg; sharon@seahong.com.sg
Subject: FBM 1340U [Our file ref: 19.26438 PD-O]
Attachments: YN2056G - INSD GIA Report.PDF; FBM1340U - TP GIA Report.PDF; LOD.pdf

Dear Nivita,

CLAIMANT :	TAN LI YE
VEHICLE NUMBER :	FBM 1340U
ALLEGED ACCIDENT DATE :	18.11.18
AXA VEHICLE NUMBER :	YN 2056G

We act for AXA Insurance Pte Ltd for the above matter.

We understand that you were engaged to survey the claimant's vehicle.

The claimant has issued their LOD and their surveyor's report is attached. A copy is enclosed.

Please let us hear from you on the following: -

- a. If you have conducted post-repair inspection already, please let us have your survey report urgently.
- b. If you have not conducted post-repair inspection, please arrange for inspection with the claimant's solicitor and let us have your survey report in due course.

May we hear from you on the above soonest.

Thanks & Best Regards

Heng Xinyi

(Secretary to Mr Tan Chee Kiong)

Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

Tel: 6536 5369

Fax: 6536 5811

This message is intended for the recipient named above. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to this message and then delete it from your system. Do not read, copy, use or circulate this communication. Thank you.

Disclaimer: Internet communications are not secure. While every reasonable effort has been made to ensure that this communication has not been tampered with, Seah Ong & Partners LLP cannot be responsible for alterations made to the contents of this message without its express consent. If you wish to receive a hard copy of this message for comparison or should you require any other form of confirmation of the contents of this message, please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the company shall be understood as neither given nor endorsed by Seah Ong & Partners LLP.

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192
SINGAPORE (510607)
BUSINESS REGN. No. 53193457L
Hp 96699986

INVOICE

Mr. Tan Li Ye
C/o Goh JP & Wong Advocates & Solicitors
133 New Bridge Road # 16-09
Chinatown Point
Singapore 059413

Invoice No : PA/19010014/G
Our Ref : PA/FBM1340/1218/tpw
Date : 10 January 2019

Claim Type	Third Party	Date of Accident	: 18 November 2018
Vehicle No.	FBM 1340 U	Date of Inspection	: 21 December 2018
No	Description		Amount (S\$)
1	Survey fees inclusive of Transportation and Photographs (37) copies		\$367.00
		Total	\$367.00
Singapore Dollar: Three Hundred And Sixty Seven Only			
All payments made payable to : Prudent Adjustors Services			


Prudent Adjustors Services

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192

SINGAPORE 510607

BUSINESS REGN. No. 53193457L

HP 96699986

VEHICLE DAMAGE INSPECTION REPORT

Mr. Tan Li Ye
C/o Goh JP & Wong Advocates & Solicitors
133 New Bridge Road # 16-09
Chinatown Point
Singapore 059413

Our Ref : PA/FBM1340/1218/tpw
Date : 10 January 2019

REFERENCES

Claim Type	: Third Party	Date of Accident	: 18 November 2018
Vehicle No.	: FBM 1340 U	Date of Assignment	: 21 December 2018
Make	: Yamaha	Date of Inspection	: 21 December 2018
Model	: Jupiter MX (HC)	Date of Re-inspn	: Nil
Reg. Date	: 17 June 2013	Chassis No	: Blocked MH350C0030K5646P2
Color	: Red	Engine No	: 50C564723
Odometer	: 4627 km		

TYRE CONDITION

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	Dunlop	80/80-17	6mm
Rear	Dunlop	90/80-17	8mm

GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at front and right side portion.
Please refer to photographs and assessment of repairs for details
Enclosed (37) photographs depicting damage

INSPECTION AND ADJUSTMENT

Original Quotation : \$ 4,807.42 Revised Assessment \$3,200.00 Lump sum

Survey conducted at: M 1 Motoring (Changi)

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately Six (6) days to complete.

This survey was conducted on a "WITHOUT PREJUDICE" basis.

Note:

The workshop has agreed to undertake the repair on a lump sum basis, and or the use of ex-stock Reconditioned parts whichever is possible

PRUDENT ADJUSTORS SERVICES

Vehicle No: **FBM 1340 U**

Our ref: PA/FBM1340/1218/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

S/N	Description Material	Qty	Condition	Original Quotation	Revised Quotation
1	Handle bar front cover <i>X repair</i>	1 pc	Grazed	152.00	152.00
2	Handle bar rear cover	1 pc	Usable	112.50	~
3	Handle bar <i>X not damage</i>	1 pc	Bent	102.90	102.90 <i>X</i>
4	Handle bar bracket @ \$46.80/- <i>X not damage</i>	2 pcs	Distorted	93.60	93.60 <i>X</i>
5	Handle balancer	1 set	Grazed	40.00	40.00
6	Mirror	1 set	Grazed	112.00	112.00
7	Head lamp <i>X not damage</i>	1 pc	Hdr cracked	175.00	175.00 <i>X</i>
8	Headlamp bracket <i>X not damage</i>	1 pc	Bent	77.00	77.00 <i>X</i>
9	Front cowling	1 pc	Cracked	216.00	216.00
10	Front signal RH	1 pc	Grazed	63.00	63.00
11	Front mudguard <i>X repair</i>	1 pc	Cut	78.00	78.00 <i>X</i>
12	Side fairing RH	1 pc	Grazed	165.20	165.20
13	Side fairing panel	1 pc	Usable	87.00	~
14	Front foot rest bar	1 pc	Bent	80.60	80.60
15	Front foot rest rubber	1 pc	Cut	16.00	16.00
16	Brake pedal	1 pc	Bent	58.00	58.00
17	Exhaust protector (Front) <i>X not damage</i>	1 pc	Grazed	85.00	85.00 <i>X</i>
18	Muffler protector chrome	1 pc	Scratch	120.00	120.00
19	Exhaust assy <i>X repair</i>	1 pc	Dented	630.00	630.00 <i>X</i>
				2,463.80	2,264.30
List price less 10%				246.38	226.43
				2,217.42	2,037.87
<u>Add special nett item</u>					
20	Front fork oil seal <i>X nny</i>	2 pcs	Necessary	140.00	70.00 <i>X</i>
21	Front fork oil <i>X nny</i>	3 lits	Necessary	60.00	30.00 <i>X</i>
22	Steering cone & bearing <i>X nny</i>	1 set	Necessary	160.00	80.00 <i>X</i>
23	Body sticker	1 set	Necessary	150.00	120.00
24	Rear box	1 pc	Grazed	450.00	350.00 <i>150</i>
25	Rear box rack with base <i>X repair</i>	1 pc	Bent	180.00	150.00
				1,140.00	800.00

PRUDENT ADJUSTORS SERVICES

Vehicle No: **FBM 1340 U**

Our ref: PA/FBM1340/1218/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

<u>Labour charge</u>		
Front fork align	400.00	300.00 /100
Steering stem Align	200.00	150.00 /50
Body chassis align	450.00	380.00 X
Dismantle & replace damage parts	400.00	350.00 /250
	<hr/>	<hr/>
	1,450.00	1,180.00
Total parts & labour concluded	<u>4,807.42</u>	<u>4,017.87</u>
Lump sum repair adjustment		<u>3,200.00</u>

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to be



Prudent Adjustors Services
Bok Jee Tan

4/5 1150 / 3 Pgs

Claim: SM0173K

Reference: CS3/ASM18022761/K1td3s2 

Loss Date: November 18, 2018

Report Date: Dec 19, 2018 8:42:09 AM

Request Date: December 19, 2018

Due Date: December 19, 2019

Vendor Name: LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss: Third Party Vehicle Damage

Services: Pre-Repair Survey

Actions

Next Step: Finish the work

Complete Work More ▾

Vehicle Information

Incident Vehicle Registration #: FBM1340U

Make: TPVD

Model: UNKNOWN

Service Address:

...

Primary Contact/Insured

FOOD LINE PTE LTD
 8A ADMIRALTY STREET, #01-03 FOOD XCHANGE
 @ADMIRALTY, 757437, Singapore
 63380083
 JEUNESSE@VIRTUALINVEST.BIZ

Claim Handler

TAN Wancong
 tan.wancong@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type: Document SubType:

 Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 CO LEGAL.msg	Legal	Others	KUMAR Shailendra	December 21, 2018
 REPLY FROM SOLICITOR.msg	Legal	Others	KUMAR Shailendra	December 19, 2018

Claim	SBM0175K
Reference	CS3/ASM18022761/K11e3s2
Loss Date	November 18, 2018
Report Date	Dec 19, 2018 8:42:09 AM
Request Date	December 19, 2018
Due Date	December 19, 2019
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TPP)
Type of Loss	Third Party Vehicle Damage
Services	Pre-Repair Survey

Actions

Next Stop: Finish the work

Completed Work:

Vehicle Information

Incident Vehicle Registration #	FBM1340U
Make	TPVD
Model	UNKNOWN
Service Address	

Primary Contact/Insured

FOOD LINE PTE LTD
 8A ADMIRALTY STREET, #01-03 FOOD XCHANGE @ADMIRALTY, 757437, Singapore
 63380083
 JEUNESSE@VIRTUALINVEST.BIZ

Claim Handler

TAN Wancong
 tan.wancong@axa.com.sg

Additional Instructions

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	5/16/19 3:07 PM	1150	1150	Open	<input type="button" value="Share"/>	<input type="button" value="Clone"/>
KUMAR Shalendra	12/19/18 11:32 AM	1453.72	1453.72	Open	<input type="button" value="Share"/>	<input type="button" value="Clone"/>

Vehicle & Driver Details

Vehicle Registration#	FBM1340U	Purchase Date	mm/dd/yyyy																																																												
Registration State	SINGAPORE	Registration Date *	06/17/2013																																																												
Mileage	4627	Age of Vehicle	5																																																												
<table border="1"> <thead> <tr> <th>CATEGORY</th> <th>POLICY INFORMATION</th> <th>ASSESSMENT INFORMATION</th> </tr> </thead> <tbody> <tr> <td>Manufacturing Year</td> <td></td> <td>2013</td> </tr> <tr> <td>Make</td> <td>TPVD</td> <td>YAMAHA</td> </tr> <tr> <td>Model</td> <td>UNKNOWN</td> <td>JUPITER MX (HC)</td> </tr> <tr> <td>Type</td> <td></td> <td></td> </tr> <tr> <td>Type of Paint</td> <td></td> <td></td> </tr> <tr> <td>Chassis No</td> <td></td> <td>MH350C003DK564682</td> </tr> <tr> <td>Engine No</td> <td></td> <td>50C564723</td> </tr> <tr> <td>Engine Capacity</td> <td></td> <td>134 cc</td> </tr> <tr> <td>Sum Insured</td> <td></td> <td>0</td> </tr> </tbody> </table>		CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	Manufacturing Year		2013	Make	TPVD	YAMAHA	Model	UNKNOWN	JUPITER MX (HC)	Type			Type of Paint			Chassis No		MH350C003DK564682	Engine No		50C564723	Engine Capacity		134 cc	Sum Insured		0	<table border="1"> <thead> <tr> <th>CATEGORY</th> <th>FNOL INFORMATION</th> <th>POST SURVEY INFORMATION</th> </tr> </thead> <tbody> <tr> <td>Driver Name</td> <td>TAN LI YE</td> <td></td> </tr> <tr> <td>Date of Birth</td> <td></td> <td>mm/dd/yyyy</td> </tr> <tr> <td>Age</td> <td>0</td> <td></td> </tr> <tr> <td>Occupation</td> <td>Unknown</td> <td></td> </tr> <tr> <td>Education Qualification</td> <td>Other</td> <td></td> </tr> <tr> <td>Driving Experience</td> <td>0</td> <td></td> </tr> <tr> <td>Driver License #</td> <td></td> <td></td> </tr> <tr> <td>License Type</td> <td></td> <td></td> </tr> <tr> <td>License Issue Date</td> <td></td> <td>mm/dd/yyyy</td> </tr> </tbody> </table>		CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION	Driver Name	TAN LI YE		Date of Birth		mm/dd/yyyy	Age	0		Occupation	Unknown		Education Qualification	Other		Driving Experience	0		Driver License #			License Type			License Issue Date		mm/dd/yyyy
CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION																																																													
Manufacturing Year		2013																																																													
Make	TPVD	YAMAHA																																																													
Model	UNKNOWN	JUPITER MX (HC)																																																													
Type																																																															
Type of Paint																																																															
Chassis No		MH350C003DK564682																																																													
Engine No		50C564723																																																													
Engine Capacity		134 cc																																																													
Sum Insured		0																																																													
CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION																																																													
Driver Name	TAN LI YE																																																														
Date of Birth		mm/dd/yyyy																																																													
Age	0																																																														
Occupation	Unknown																																																														
Education Qualification	Other																																																														
Driving Experience	0																																																														
Driver License #																																																															
License Type																																																															
License Issue Date		mm/dd/yyyy																																																													

Detailed Assessment

Inspection Date * 03/22/2019

Total Loss Yes No

Towing Charges 0

Voluntary Excess 0

Compulsory Excess 0

Young/Inexperienced/Unarmed Driver Excess 0

Other Excess

Condition of Vehicle at time of survey

General condition Fair

Steering (Serviceable) Yes No

Footbrake (Serviceable) Yes No

Handbrake (Serviceable) Yes No

Engine Modification Yes No

Pre-accident condition Good

Tyre Condition

Spare wheel

Rear Tyre Size 90/80-17

Rear left side DUNLOP 8mm

Rear right side

Age of Tyres

Front Tyre Size 80/80-17

Front left side DUNLOP 6mm

Front right side

Parts

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./BITTS	DISC COUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	1	1			HANDLE BAR FRONT COVER			Repair	0		10		0	Reviewing	
	2	1			HANDLE BAR REAR COVER			Serviceable	0		10		0	Reviewing	
	3	1			HANDLE BAR			Serviceable	0		10		0	Reviewing	
	4	2			HANDLE BAR BRACKET			Serviceable	0		10		0	Reviewing	
	5	1			SET HANDLE BALANCER			Grazed	40		10		36	Reviewing	
	6	1			SET MIRROR			Grazed	112		10		100.8	Reviewing	
	7	1			HEAD LAMP			Serviceable	0		10		0	Reviewing	
	8	1			HEADLAMP BRACKET			Serviceable	0		10		0	Reviewing	
	9	1			FRONT COWLING			Cracked	216		10		194.4	Reviewing	
	10	1			FRONT SIGNAL RH			Grazed	63		10		56.7	Reviewing	
	11	1			FRONT MUDDGUARD			Repair	0		10		0	Reviewing	

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR	Reviewing		3	
	2	FRONT FORK OIL SEAL	Reviewing	0	NOT NECESSARY	
	3	LITS FRONT FORK OIL	Reviewing	0	NOT NECESSARY	
	4	SET STEERING CONE & BEARING	Reviewing	0	NOT NECESSARY	
	5	SET BODY STICKER	Reviewing	120	NECESSARY	
	6	REAR BOX	Reviewing	150	GRAZED	
	7	REAR BOX RACK WITH BASE	Reviewing	0	REPAIR	

Claim Amount \$1,453.72 Claim Amount \$1,453.72

CATEGORY ESTIMATE REVISED AMOUNT

Spare Parts \$783.72 \$783.72

Labour \$400.00 \$400.00

Miscellaneous \$270.00 \$270.00

Submit for Review

SERVICE REQUESTS MESSAGES CLAIMS

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Buttons: Add, Approve, Deny, Submit All

EDIT SR NO NAME ACTION AMOUNT COMMENT REMOVE

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	FINAL LUMP SUM	Reviewing	1150		