

PRS

ASSIGNMENT

From: 1st East Centre
Date: 20/12/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBE 21382

at Workshop m/s

of 10 kaki Bukit Rd 2 #01-24

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

(up)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: FBE 21382 Yr Regn: 11/1/2010

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA 600RR c.c 599

Colour: RED A/C: Insured / Std / NI / NA

Sp. Reading: 76765 T/Radio: Insured / Std / NI / NA

Eng/No: PG40E2060728

C/No: JH2PC40A78M108083

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70/2R17

R: 180/55/2R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 2/12/18 D.O.I. 20/12/18 1.14pm

Survey held at Moto Plex

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV 1300 / \$4,500

27/12/2018

TGM

24/12/18

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ Site Insp (\$)

) S + RS. SI

☐ Interview (\$)

) Photos

☐ Tech. Invs (\$)

) Others

☐ Weekend (\$)

) ..

Report Format: PRS

Lump Sum / I.B.I: (\$)

TOTAL