

ASS. REC. BY:

REF:

CS3/SM018022816/ELd3/2

Special Instruction:

Surveyor

Meimien

ASSIGNMENT (Office)

From (Person): Ngo sau weichawon

of

8MO

Date/Time: 19/12/18 @ 4.49pm

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBJ 187T

Insured:

SGN 3308L

at Workshop m/s

Wee Hoe Auto

Tel:

6858 0019

of

19 Kim chuen Terrace

Policy No:

D18MTpv01018953

Claim No:

CMTD1805578

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 15/12/2018

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

018am @ 20/12/18

Person Contacted:

Kiat

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	GBJ 187T-X
	SGN 3308L-X:
	Dismantle: 2/1/2019.

PRS
Steve

REF: SMO

ASSIGNMENT

From: Date: 02/01/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBJ 187 T
at Workshop m/s Wee Hoe

of

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GBJ 187 T Yr Regn: 23/11/2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace G.C. 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 4018 T/Radio: Insured / Std / NI / NA

Eng/No:

C/N: JTFHT02 P000246235

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or Steel Rim

Tyre Size: F: 195R15C

R: 195R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 15/12/2018 D.O.I. 2/1/2019

Survey held at IDAC LKK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Page SK-GK 6 Days app.

2/1/2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S+RS, SI

) Photos

) Others

Report Format: PRG

Lump Sum / I.B.I: (\$

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

TOTAL

170

10

60

100

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Dec 2018		19 Dec 2018 16:49 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	ANG ENG TECK, ID: S7504645F, Tel: +6590037575, Email: NOEMAIL		
Main Claimant:	MENG CHENG TRANSPORT & SERVICES, Co. Reg. No.: 53378329A		
Vehicle Reg. No.:	GBJ187T	Date of Loss:	15/12/2018 16:00 - :59
Claim Type:	TP / CMTD1805578	Policy/Cover Note No.:	D18MTPV01018953 (Third Party Only)
Vehicle Reg. No. (Insured):	SGN3308L	Policy No. (Claimant):	
		Excess:	
Repairer:	Wee Hoe Auto Service (HQ) 19 Kim Chuan Terrace, Singapore 537041, 537041 Kaki Bukit - Tel: 68580019		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by NGO SAU WEI SHAWN - 6329 5202]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/12/2018]		
Driver/Custodian (Insured):	ANG ENG TECK (43 / Male), NRIC: S7504645F, Tel: +6590037575		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Thursday, 20 December 2018 9:46 AM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: ct-admin@visionlawllc.com; Ngo, Sau Wei Shawn; Ye, Yong Kang Melvin; Henry, Irene James
Subject: CMTD1805578/NSW - SUV(LKK)/ SGN3308L & GBJ187T ACC ON 15.12.18
Attachments: 1492_001.pdf

Our Reference : CMTD1805578/NSW

Dear LKK AUTO,

Please make arrangement to conduct the survey for GBJ187T on a without Prejudice Basis and any admission of liability basis.

Please submit with your report via Merimen upon completion of survey.

The repairer is as follows:

WEE HOE AUTO SERVICE
19 KIM CHUAN TERRACE
SINGAPORE 537041

TEL: 68580019 (KIAT)

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom

disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: ct-admin@visionlawllc.com [mailto:ct-admin@visionlawllc.com]

Sent: Thursday, December 20, 2018 9:28 AM

To: Claims - Motor Survey

Subject: Attached Image

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

Company Registration No. 200721148H

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
SEGA PARAM
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
JANICE HAN JIA LIN
TAN YINGXIAN, SELWYN
CHEONG YUNHUI, CLARISSA
EDISON TAM CHYI EU

 **Head Office:**
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Branch:
490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

HEAD OFFICE:

TEL : 65342811 (Hunting)
FAX : 65356802 (General)

 E-MAIL: annatan@visionlawllc.com

BRANCH

TEL : 63580703
FAX : 63580448(conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - Please reply to **HEAD OFFICE** for this matter

OUR REF: AKN-atv-INS-W30-GBJ187T-2018 - [please reply to: annatan@visionlawllc.com](mailto:annatan@visionlawllc.com)
YOUR REF: SGN 3308 L

20 December 2018

SOMPO INSURANCE COMPANY LTD

50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623
Attn: Motor Claims Department

BY FAX 6221 3147 & EMAIL

motorsurvey@sompo.com.sg

Dear Sirs

NAME OF CLAIMANT: MENG CHENG TRANSPORT & SERVICES

VEHICLE NUMBER: GBJ 187 T

YOUR INSURED VEHICLE NUMBER: SGN 3308 L

ACCIDENT ALONG BOON LAY DRIVE ON 15 DECEMBER 2018 AT ABOUT 1700HOURS

We refer to your email dated 19 December 2018 wherein there is no agreement to the appointment of Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at :

WEE HOE AUTO SERVICE
19 KIM CHUAN TERRACE
SINGAPORE 537041
TEL: 6858-0019 (KIAT)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

(Head Office)

cc. **GBJ 187 T** - By fax 6858-0195 only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature) :

Date & Time of Inspection :

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 8329A

Vehicle Details

Vehicle No.: GBJ187T

Vehicle to be Exported: No

Intended Deregistration Date: 02 Jan 2019

Vehicle Make: TOYOTA

Vehicle Model: HIACE VAN TURBO 5DR MT

Primary Colour: Silver

Manufacturing Year: 2018

Engine No.: 1KD2830965

Chassis No.: JTFHT02P000246235

Maximum Power Output: -

Open Market Value: \$28,136.00

Original Registration Date: 23 Nov 2018

First Registration Date: 23 Nov 2018

Transfer Count: 0

Actual ARF Paid: \$1,407.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 22 Nov 2028

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$23,840.00

COE Rebate Amount: \$23,575.00

Total Rebate Amount: \$23,575.00

The information contained herein is correct as at 02 Jan 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/12/2018 15:58
Date Of Accident	15/12/2018 17:00
Exact Location Of Accident	BOON LAY DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBJ187T
Insured/Policyholder	
Name Of Registered Owner	MENG CHENG TRANSPORT & SERVICES
Co Reg No	53378329A
Email Address	JRSIR1984@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90088701
Alternative Phone No	OFFICE-90088701

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE VAN
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5100224794-01
Cover Note Number	

Driver

Name of Driver	QUEK KAI YUNG
NRIC No	S8403244A
Date Of Birth	06/09/1984
Occupation	OUTDOOR
Date Of Driving Pass	11/06/2012
Driving Experience	6 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90955634
Fax Number	
Contact Number	
EMail Address	JRSIR1984@GMAIL.COM

Address	BLK 16 MARSILING LANE #11-183
Postcode	730016
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TURNING LEFT AND STOPPED HALFWAY WHILE WAITING FOR THE PEDESTRIANS TO CROSS. SUDDENLY, A VEHICLE FROM BEHIND KNOCKED INTO THE REAR PORTION OF MY VEHICLE. (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGN3308L
Vehicle Make/Model/Colour	HONDA CIVIC
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ANG ENG TECK
NRIC/Passport Number	S7504645F
Contact Number	82257575
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Company Stamp



Policyholder's Signature

Date & Time:

19 DEC 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)

Reporting Centre


Name: **23 Kaki Bukit Ave 4**

TEL: **Singapore 415933**

TEL: **67416697** Fax: **67492305**

Email: **vackb@singnet.com.sg**

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I w

Refer

Statement

Company Stamp

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4

Reporting Centre Personnel
Name: Singapore 415933
Tel: 67416697 Fax: 67492305
NRIC/Fin No:
Email: vackb@singnet.com.sg

19 DEC 2018



MENG CHENG TRANSPORT & SERVICES

BLK 531A, UPP CROSS STREET, #04-113, HONG LIM COMPLEX, SINGAPORE 031531

TEL : 65 9239 5379 (Rui Fen) / 65 9008 8701 (Stephen)

ROC NO: 53378929A

RENTAL AGREEMENT

MCT - 18/0301

Name: <u>V/S Forwarders</u>		NRIC / ROC: <u>53378929A</u>
Address: <u>240 Pasir Ris St 2 #04-45 (510240)</u>		
Contact Hp: <u>82275498</u>	Office:	Email/Fax:

Name: <u>Ouek Kai Yung (Gao Jiarong)</u>		NRIC / Permit: <u>58403244A</u>
Address: <u>16 Marsiling Lane (H) 90955634</u>		
Driving Experience: <u>5 years</u>	License No: <u>0020 T6498K</u>	D.O.B: <u>17 Sep 1984</u>

Vehicle No: <u>G8J 187 T</u>		Make & Model: <u>Toyota Hiace Euro 5</u>
Rental Period: <u>2 year</u>	Charges: <u>\$1550</u>	Deposit: <u>600</u>
Date Out: <u>29/11/18</u>	Time: <u>12.20pm</u>	Mileage: <u></u> Fuel Level: <u></u>

*INTEREST OF LATE PAYMENT 1.5% PER MONTH

IMPORTANT NOTES: Restricted to Singapore use only.

No refund will be given for fuel left in vehicle. 2000 27.55
1500 27.55
 Hirer is liable to pay first Insurance Excess \$1500 in any accident plus lost of earnings while damaged vehicle is under repair.

Hirer is liable for all Parking Fines and Traffic Violations.

Driver must be above 23 years with minimum 2 years driving experience.

Vehicles return during office hours only. No services on Public Holidays and Sundays.

I/WE DECLARE THAT THE ABOVE PARTICULARS ARE TRUE AND CORRECT IN EVERY ASPECT AND
 I/WE HAVE READ AND UNDERSTOOD THE TERMS AND CONDITIONS OF THIS RENTAL AGREEMENT AND
 AGREE.




Company's Stamp / Hirer's Signature & Date

8 8403244A

A

NO
 damage
 Brand
 new

INDICATE:
 D - DENTS
 S - SCRATCHES
 A - ACCIDENT



Checked By:	Deposit Refund:		
Remarks:			
Date Out:	Time:	Mileage:	Fuel Level:

Signature of Hirer / Driver

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Dec 2018		19 Dec 2018 16:49 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

ANG ENG TECK, ID: S7504645F, Tel: +6590037575, Email: NOEMAIL

Main Claimant:

MENG CHENG TRANSPORT & SERVICES, Co. Reg. No.: 53378329A

Vehicle Reg. No.:

GBJ187T

Claim Type:

TP / CMTD1805578

Vehicle Reg. No. (Insured):

SGN3308L

Repairer:

Wee Hoe Auto Service (HQ) 19 Kim Chuan Terrace, Singapore 537041, 537041 Kaki Bukit - Tel: 68580019

Handling Insurer:

Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by NGO SAU WEI SHAWN - 6329 5202]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 31/12/2018]

Driver/Custodian (Insured):

ANG ENG TECK (43 / Male), NRIC: S7504645F, Tel: +6590037575

Date of Loss:

15/12/2018 16:00 - :59
[22 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

D18MTPV01018953 (Third Party Only)

Policy No. (Claimant):

Excess:

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBJ187T (CMTD1805578)**
[SGN3308L]



































TP

















































MENG CHENG TRANSPORT & SERVICES

Dec 15 2018 4:00PM

[ANG ENG TECK]

Wee Hoe Auto Service

Upload Documents			Upload Photos		Compose New Letter		View <div>View in Browser</div>	
Assessment Reports							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)					Thumbnail	Print
1	19/12/18 16:50	Accident Statement From: SC - Reg. No: SGN3308L, Claimant: ANG ENG TECK					 Load HTM	
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print
1	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
2	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
3	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
4	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
5	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
6	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
7	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
8	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
9	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
10	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
11	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
12	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
13	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
14	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
15	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
16	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
17	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
18	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
19	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
20	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
21	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
22	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
23	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
24	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
25	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
26	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
27	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
28	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
29	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
30	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
31	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
32	02/01/19 10:49	General View					 Load JPG	<input checked="" type="checkbox"/>
33	03/01/19 15:03	Photographs of Damaged Parts					 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
34	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	03/01/19 15:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	19/12/18 15:40	Third Party E-filed GIA report(M)	 Load PDF	
2	19/12/18 16:49	Pre-Repair Survey - ASSIGN LKK	 Load PDF	
3	20/12/18 13:00	LTR FROM VISION LAW LLC VIA FAX DT 20.12.18	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO18022816/ECD3E2

Date: 08/01/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTPV01018953

Claimant Vehicle No : GBJ187T

Insured Vehicle No : SGN3308L

Date of Loss: 15/12/2018

Nature of Claim: TP

Claim No: CMTD1805578

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBJ187T

Make & Model: TOYOTA HIACE, 2.0 (M)

Engine No: 1KD2830965

Reg. Date: 23/11/2018 (Man. Year: 2018)

Chassis No: JTFHT02P000246235

Colour: Silver

Odometer: 4018 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 195 R15C

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/12/2018

Date Inspected: 02/01/2019 Inspected At:

Wee Hoe Auto Service (HQ)
19 Kim Chuan Terrace, Singapore 537041
Singapore 537041

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 08 Jan 2019)

Parts: N/A TOYOTA HIACE 2.0 (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBJ187T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >