

XRL

REF: ALG

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Vin's Motor

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: \$40k - 42k

IDAC Accident Rpt. Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKP 3071K Yr Regn: 14 Jul 2011

Type: M.Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 318i c.c. 1995

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 122304 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAPF720 20F.G 90110

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R16

R: 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 20-12-18

Survey held at w/s 9:30 AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Int N/S, R/O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	repair limit \$4500 - \$6500

Date/Time, File Pass to? : Preli. Report : Final Report

Days Of Repair: _____

1) Date/Time, File Return to?

Resurvey No. of Trip: _____

2) _____

Add Fee: Site Insp (\$) Interview (\$) Tech. Invs (\$) Weekend (\$)

Survey Fee:	
Transportation:	
_____ S + RS _____ SI	
Photos	
Others	
TOTAL	

Report Format : _____

Lump Sum / I.B.I: (\$ _____)