

INS. CASE OWNER: BONNIE | CC 4/AIG1802 | LKK: 28/4/18 | IDAC: 6/10/18

Surveyor: XGQ | DOI: ASSIGNMENT 20/12/18 | Date/Time: 19/1/18
 Registered in Merimen: 20/12/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SLE 6110 Y
 Name of Insured : LHA SHEWETH
 Insured Tel No. : _____ HP: _____
 Excess Sec II : \$\$ _____ D.O.A. : 15/1/18
 Is driver the owner? (YES / NO) (NO) Nature of Accident : _____
 If NO, Driver Name / Age : LHA SHU 44 W JIMIE
 Driver Tel No. : _____ (VL: YES / NO) _____

Claim No. : 3789 5415859
 Policy No. : 150006185
 Make / Model : MAZDA
 Place of Accident : SECURITY ST - PARKER'S LANDS
 OI GIA REPORT: YES / NO : (YES) TP GIA REPORT: YES / NO : (YES)
 Insured Liability : 0 Final ? Yes / No : _____

SEP 2018



INSRS: _____
 WSP: Vin Automotive
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____

Date/Time	STAGE	DATE / PIC
<u>26/1/18</u>	<u>SEP 2018 - 7</u>	<u>SLE 6110 Y - W</u>
<u>20/1</u>	<u>OI HIT PARKED TP</u>	
<u>25-1-19 @ 208</u>	<u>called - NO AWS.</u>	
<u>17/5/19</u>	<u>Called OI to inform TP claim</u>	
<u>15/09/19</u>	<u>TP LOD IN BY MAIL</u>	
<u>01/10/19</u>	<u>TP ACCEPTED OFFER.</u>	
	<u>ALL DOCS IN ORDER.</u>	

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: LS \$5 6,000.00 (6 days) Reduction: 02 % Email Call

FINAL SETTLEMENT Date/Time: 01/10/19 Confirm with: RAYMOND Email Call

Final Liability: 0 (A / Assessed) BOLA S/N No.: NIL If NO or B 28, Ass. Lia: _____

Repair Cost: (w/acc) \$5 6,420.00 **COLD HIT PARKED TP)**

Loss of Rental (LOR): \$5 1,080.00 (9 days) X 120.00 **COPY SENT**

Loss of Use (LOU): \$5 - (5 x days)

Loss of Income (LOI): \$5 - (5 x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: \$5 2.00

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/Independent)

Legal Cost: \$5 -

Total: \$5 7,502.00 Global Sum \$5: -

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: \$5 7,502.00 Name 1: VIN'S MOTOR PTB LTD

Payee 2: (Strike if N.A.) \$5 - Name 2: _____

Payee 3: (Strike if N.A.) \$5 - Name 3: _____

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s Vin's Motor
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: \$42k - 42k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Veh No: SKP 3071K Yr Regn 14 Jul 2011
 Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: BMW 318i c.c. 1995
 Colour: Black A/C: Insured / Std / NI / NA
 Sp Reading: 122304 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WBAPF720 20F-G 90110
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Brim / STD A/Rim or _____
 Tyre Size: F: 205/55 R16
 R: 17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front R/Bal: 6 mm Rear R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A. _____ D.O.I. 20-12-18
 Survey held at: w/s 9:30 AM
 Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or
Frnt N/S, Rt O/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	repair limit \$4500 - \$6500
	Lg \$6,000.00 (CRD: 99.78134/62%)
	MV: \$42,000.00 (est)
	LHA: \$35,423.00 (est)
	nett: \$6,577.00 (est)

Date/Time. File Pass to? : Prel. Report
 : Final Report
 Days Of Repair: _____
 Resurvey No. of Trip: _____
 Survey Fee: _____
 Transportation: _____
 Add Fee: Site Insp (\$ _____)) \$ + RS \$
 Interview (\$ _____)) Photos
 Tech Invs (\$ _____)) Others
 Weekend (\$ _____))
 Report Format : _____
 Lump Sum / I.B.I: (\$ _____)
 TOTAL _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/AIG18022843/jb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 20-12-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLZ 6110Y	Veh. Inspected	SKP 3071K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	20/12/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/12/2018	Inspection Date	
Survey held at	VIN'S MOTOR PTE LTD 160 SIN MING DRIVE #03-03 SIN MING AUTO CITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Vin's

AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/122018/3721

Accident date : 15/12/2018

Your Ref : SLZ6110Y

Invoice No.:

Date : 19/12/2018

MOTOR CLAIM DEPARTMENT

AIG ASIA PACIFIC INSURANCE PTE LTD

AIG Building

78 Shenton Way #07-16

Singapore 079120

ESTIMATE COST OF REPAIRS TO BMW 318I SKP3071K

1	pc	Front bonnet / RT	\$	1,166.55	✓
2	pcs	Front bonnet hinge @ \$81.85 x 2 NN	\$	163.70	✓
1	pc	Front bonnet absorber x	\$	109.45	✓
2	pcs	Front headlamp @ \$980.25 - CRA	\$	1,960.50	✓
2	pcs	Front grille @ \$109.90 1pc - sch sch	\$	219.80	109.9
1	pc	Front bumper - CRA	\$	1,105.15	✓
1	pc	Front bumper towing cover - mis.	\$	45.60	✓
1	pc	Front bumper centre grille x / BR	\$	85.70	?
2	pcs	Front bumper fog lamp @ \$258.15 x - BR	\$	516.30	?
2	pcs	Front bumper fog lamp cover @ \$61.10 x - BR	\$	122.20	?
2	pcs	Front bumper retainer @ \$15.45 - le.	\$	30.90	✓
1	pc	Front bumper reinforcement x - BT	\$	550.30	?
2	pcs	Front bumper bracket @ \$35.15 x NN	\$	70.30	?
1	pc	Front LH fender - BT	\$	648.35	✓
2	pcs	Front LH fender bracket @ \$25.50 x NN	\$	51.00	?
4	pcs	Front LH fender inner fabric @ 112.10 x / CRA	\$	448.40	?
1	pc	Front support panel x - CRA	\$	593.50	?
1	pcs	Front air cond condensor x - BT	\$	979.45	?
		B/F	\$	8,867.15	

Vin's

AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722

T 6453 2121 (4 lines) / 6458 1111 (24 hrs)

F 6459 9795 / 6459 0433

E admin@vinsautogroup.com.sg

W www.vinsautogroup.com.sg

Our Ref TP/122018/3721

Date : 19/12/2018

C/F

\$ 8,867.15

1	pcs	Front air cond pipe No 1	X	YNN	\$	247.00	X
1	pcs	Front air cond pipe No 2	X		\$	283.30	X
1	pcs	Front radiator	R	BT	\$	670.80	7
1	pcs	Front radiator fan assy	X	CRA	\$	1,083.75	X
1	pcs	Front radiator air duct	R	CRA	\$	157.20	7
2	pcs	Front safety belt @ \$389.05	LH	- Act . RHD NN	\$	778.10	389.05
1	pc	Front air bag ECU	X	NN	\$	927.15	7
1	pc	Front battery cable	-	Act	\$	293.05	7
					\$	13,307.50	5749.05
Less 5%					\$	(665.38)	
					\$	12,642.13	5461.6

To towing

\$ 120.00 ~~2X~~

To refill air cond gas

\$ 150.00 ~~120~~

To reset air bag system

\$ 250.00 ~~200~~

To repair front damage

\$ ~~800~~ 980.00 ~~600~~

To spray painting

\$ 980.00 ~~800~~

\$ 15,122.13

5,781.31

VIN'S MOTOR PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6 Days.

luxury repair.

After repair photos.

Gno Qiang.

20/12/18.

Vin's

AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/122018/3721
Accident date: 15/12/2018
Your Ref : SLZ6110Y

Tax Invoice :

Date : 21/12/2018

MOTOR CLAIM DEPARTMENT
AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building
78 Shenton Way #07-16
Singapore 079120

SUPPLEMENTARY COST OF REPAIRS TO BMW 318I SKP3071K

1	pc	Front bumper under cover	✓	CRA	\$	412.50
2	pcs	Front support air duct @ \$68.75	✓	CRA	\$	137.50
2	pcs	Front headlamp lower bracket @ \$71.95	✓	CRA	\$	143.90
					\$	693.90
		Less 5 %			\$	(34.70)
					\$	<u>659.21</u>

VIN'S MOTOR PTE LTD



Gen. Owl
21/12/18

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 9528E

Vehicle Details

Vehicle No.: SKP3071K
Vehicle to be Exported: No
Intended Deregistration Date: 20 Dec 2018
Vehicle Make: B.M.W.
Vehicle Model: 318i 2.0 AT D/AB 2WD 4DR
GAS/D SR DRL

Primary Colour: Black
Manufacturing Year: 2011
Engine No.: B536I925N46B20BZ
Chassis No.: WBAPF72020FG90110
Maximum Power Output: 100.0 kW (134 bhp)
Open Market Value: \$31,068.00
Original Registration Date: 14 Jul 2011
First Registration Date: 14 Jul 2011
Transfer Count: 1
Actual ARF Paid: \$31,068.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 13 Jul 2021
PARF Rebate Amount: \$18,640.00

Intended COE Rebate Details

COE Expiry Date: 13 Jul 2021
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$65,490.00
COE Rebate Amount: \$16,783.00
Total Rebate Amount: \$35,423.00

The information contained herein is correct as at 18 Dec 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9528E
Vehicle Details	
Vehicle No.:	SKP3071K
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Dec 2018
Vehicle Make:	B.M.W.
Vehicle Model:	318I 2.0 AT D/AB 2WD 4DR GAS/D SR DRL
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	B536I925N46B20BZ
Chassis No.:	WBAPF72020FG90110
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$31,068.00
Original Registration Date:	14 Jul 2011
First Registration Date:	14 Jul 2011
Transfer Count:	1
Actual ARF Paid:	\$31,068.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jul 2021
PARF Rebate Amount:	\$18,640.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jul 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$65,490.00
COE Rebate Amount:	\$16,783.00
Total Rebate Amount:	\$35,423.00

The information contained herein is correct as at 20 Dec 2018

OK



SKB4859Y

Mercedes-Benz : 204 (C Class 2007-15) : without 4MATIC : Sedan/Wagon Standard Suspension Europe version/USA : 02/2008-
 4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-0°46'	-0°45'	-0°48' -0°05'
10°15'	10°15'	
0°00'	0°00'	0°00' 0°10'
13°50'	13°50'	
13°05'	13°05'	
		-2°12' -1°12'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°56'	-0°56'	-0°48' -0°05'
9°26'	9°26'	
-0°22'	-0°22'	0°00' 0°10'
13°50'	13°50'	
12°54'	12°54'	
		-2°12' -1°12'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0°10'	0°10'	-0°24' 0°24'
0°50'	0°50'	-0°30' 0°30'
0°00'	0°00'	
-0°23'	-0°23'	0°00' 0°20'

Rear : Left

Actual	Before	Specified Range
-1°00'	-1°00'	-1°34' -0°34'
0°16'	0°16'	0°05' 0°19'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-2°18'	-2°19'	-1°34' -0°34'
-0°06'	-0°06'	0°05' 0°19'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
1°18'	1°19'	-0°30' 0°30'
0°10'	0°10'	0°17' 0°31'
0°11'	0°11'	-0°15' 0°15'

▶ **bmw 318i Used Vehicle List (11 vehicles)**

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
BMW 3 Series 318i Sunroof	\$38,800	\$10,420 /yr	16-Mar-2011	1,995 cc	132,000 km	Zenith Motor Pte Ltd	Availab
Set To Sell! 1 Owner, Extremely Well Maintained, With Almost New Run-Flat Tyres! 100% Accident Free, Original Condition With No Touch Up Done! No Repairs Required! Come View To Appreciate Anytime, Bef... Office No. - - Daniel - 96922249 Shawn - 97713161							
BMW 3 Series 318i Sunroof	\$42,800	\$11,510 /yr	28-Apr-2011	1,995 cc	108,000 km	Car Buyers Automotive Pte Ltd	Availab
Monthly Installment At \$1053 x 32Months! Premium Sunroof Model! Responsive And Powerful Engine Paired With Silky Smooth Gearbox Mak This A Unit Not To Miss! Classy Looks, Sporty Drive Makes This An ... Office No. - 68481200 Sean Chia - 81637414 Adrian Tan - 82221375							
BMW 3 Series 318i Sunroof	\$41,800	\$11,020 /yr	29-Apr-2011	1,995 cc	91,000 km	AA Trust Automotive	Availab
AA Trust Certified Quality 1 Owner Vehicle! Extremely Well Maintained By 1 Owner Only! Premium Black Paintwork Coupled With Beige Leath Interior! Quite And Responsive Engine! Smooth Gearbox Transmis... Office No. - 63450381 Willey - 91692071 Clement - 93365036 Ferris - 88185757 Dave - 98500051							
BMW 3 Series 318i Sunroof	\$40,786	\$10,570 /yr	30-Apr-2011	1,995 cc	139,000 km	786 Blitz Automobile LLP	Availab
Well Maintained By Previous Owner. Flexible Loans Schemes Available. Trade In Welcome. Call To Arrange For Viewing Now! Office No. - - Dan - 93259171							
BMW 3 Series 318i Sunroof	\$45,800	\$12,470 /yr	26-May-2011	1,995 cc	171,650 km	GOwheeler Pte Ltd	Availab
Low Down Payment. Low Interest Rate. 1 Year Warranty. Balloon Scheme, In-House Financing Options Available. Buy With A Peace Of Mind 100% Genuine Mileage. Well Maintained. No Chassis/Structural Damag... Office No. - 69311212 Ivan Gan - 81813725 Lawrence Loh - 88083507 Eric Sng - 92971329							
BMW 3 Series 318i Sunroof	\$40,800	\$10,400 /yr	27-May-2011	1,995 cc	-	360 VR Cars	Availab
2 Owners, Well Maintained. Always Park Under Sheltered. Buying At Direct Seller Price With Dealer Loan And Support. Trade In Welcome. Dr Miss! Office No. - 69310005 James Tan - 90700005							
BMW 3 Series 318i Sunroof	\$40,500	\$10,100 /yr	13-Jun-2011	1,995 cc	88,000 km	Des & Co Automobile Pte Ltd	Availab
Another Unique Unit Founded By Us! Genuine Low Mileage Done At 88,000KM Only! Housewife Fetching Kids Is The Main Purpose Of This C Perfect Condition Maintained By Protective Husband, Servicing Jus... Office No. - 62821588 Desmond Tan - 96851355							
BMW 3 Series 318i	\$40,000	\$9,710 /yr	22-Jun-2011	1,995 cc	113,000 km	Car Empire Automobiles Pte Ltd	Availab
Gearbox Overhaul, Major Servicing Done, Beautiful Interior, 90% Loan Available! 2 Meticulous Owners, Car Is In Excellent Condition, Comfortable Drive, Must View To Believe! Accident Free Car. Serious ... Office No. - 69097310 Lucas Lim - 87506761 Samuel - 97222822 Soon - 97379527 Sean - 90120468							
BMW 3 Series 318i Sunroof	\$39,900	\$9,710 /yr	27-Jun-2011	1,995 cc	79,000 km		Availab

Genuine Low Mileage Done At 79,000KM. Well Maintained PML Unit. 1 Meticulous Female Owner Only. No Repair Needed. Viewing By

Appointment Only, Thank You.

Office No. - -

Samantha Lew - 88181116

BMW 3 Series 318i Sunroof \$47,500 \$11,750 /yr 29-Sep-2011 1,995 cc 107,000 km 360 VR Cars Availal

1 Owner, Very Well Maintained PML Unit. Powerful And Responsive Engine. Aircon Just Overhauled. Engine Mounting Just Changed. Classy White, Sporty Drive Makes This An Ideal Car For All Types Of Driver...

Office No. - 69310005

Pauline - 96211963 | James Tan - 90700005

BMW 3 Series 318i Sunroof \$41,800 \$9,730 /yr 30-Sep-2011 1,995 cc 92,000 km Horizon Motoring Availal

Low Depreciation At \$26 Per Day. Beautiful Condition! Mileage Done Only 92,000km, Well Maintain With Prompt Servicing, Accident Free, Go Driving Condition, Beautiful Interior, View To Believe! In Ho...

Office No. - 64755257

Gary - 90092442 | Roy - 97959866 | Stanley - 90391156

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2018 sgCarMart. All rights reserved.

- Pre repair inspection request - SKP3071K VS SLZ6110Y (OI) DOA 15/12/2018

From: Azlan, Syazairina
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Marissa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashwanjeetkaur, Hor, Yinnul, Chan, Yoke Shi, Kaur, Bajji
Sent: Wednesday, 19 December 2018 4:27:10 PM
Attachments: 20181219110816.pdf

Hi,

Please refer to the enclosed request from Vin's Automotive Group.

Claim no : 3789548158SG003
Case Owner : WEI ZHONG BENNIE TAN

If you have any queries/concerns, please let us know
Kindly assist to assign Xing Guo Qiang as Single Joint Expert as requested.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Admin @ VAUG [mailto:admin@vinsautogroup.com.sg]
Sent: Wednesday, December 19, 2018 3:55 PM
To: Azlan, Syazairina
Subject: Re: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLZ6110Y AND SKP3071K ON 15/12/2018

Good afternoon,
Please assign Xing Guo Qiang (LKK Auto) as the surveyor for this case.
Thanks!
Best Regards
Raymond Teo


17-12-2018 @ 3:48pm
Raymond veh in
GR

On Wed, Dec 19, 2018 at 3:31 PM Azlan, Syazairina <Syazairina.Azlan@aig.com> wrote:

This is a secure, encrypted message. To read it, open the attachment.
这是安全加密信息。如要阅读此信息，请开启附件。
이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 열어야 합니다.
Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.
Click here by 2018-12-26 15:31 +08 to read your message. After that, open the attachment.
More info

Disclaimer: This email and its contents are confidential and intended solely for the use of the individual named. If you have received this email in error or simply delete it.
Scanned by PostSecret Encryption, Copyright © 2009-2017 PostSecret, Inc. All rights reserved.

Sin Ming AutoCity
160 Sin Ming Drive
Singapore 575722
Showroom/Office: #03-03
Workshops: #08-08/09
Tel: 64532121 (4 lines)
Fax: 64599795
Website: www.vinsautogroup.com.sg
Email: admin@vinsautogroup.com.sg



** w.e.f 15th May 2017, we have shifted location! **
** w.e.f 20th November 2017, we have changed our email address! **

IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Syazairina Azlan@aiig.com
To: admin@vinsautogroup.com.sg
Cc: Andy-GY.Fong@aiig.com, Lee-Ying.Chin@aiig.com, NurMariasa.AbuKassim@aiig.com, Imran.Ishak@aiig.com, ShengYang.Lim@aiig.com, Aashweenjeetkaur.Mithosingh@aiig.com, Yinnul.Hor@aiig.com, yokeshi.chan@aiig.com, Bai
Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLZ6110Y AND SKP3071K ON 15/12/2018
Date: Wed, 19 Dec 2018 07:31:22 +0000

Without Prejudice

Your Reference : SKP3071K
Our Reference : 3789548158SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Gao Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irina Azlan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: AIG SGP, Claims-Survey
Sent: Wednesday, December 19, 2018 11:36 AM
To: Azlan, Syazairina
Subject: FW: Request For TP Survey SKP3071K ; Yr Insured SLZ6110Y

From: Admin @ VAUG [mailto:admin@vinsautogroup.com.sg]
Sent: Wednesday, December 19, 2018 11:33 AM
To: AIG SGP, Claims-Survey
Subject: Request For TP Survey SKP3071K ; Yr Insured SLZ6110Y

Good morning,

Please help us to arrange for survey ASAP

DOA: 15/12/2018

Location:
Sin Ming Autocity
160 Sin Ming Drive #08-09
Singapore 575722

Please send us a list of surveyor to choose

Please include independent surveyor

Thanks!

Best Regards

Raymond Teo



Sin Ming AutoCity
160 Sin Ming Drive
Singapore 575722
Showroom/Office: #03-03
Workshops: #08-08/09
Tel: 64532121 (4 lines)
Fax: 64599795
Website: www.sinsautogroup.com.sg
Email: admin@sinsautogroup.com.sg

Follow us on :



** w.e.f 15th May 2017, we have shifted location! **

** w.e.f 20th November 2017, we have changed our email address! **



AUTOMOTIVE GROUP

Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
6453 2121 (4 lines) / 6458 1111 (24 hrs)
6459 9795 / 6459 0433
admin@vinsautogroup.com.sg
www.vinsautogroup.com.sg

Our Ref : TP/122018/3721

Your Ref : SLZ6110Y

27-Jun-2019

MOTOR CLAIM DEPARTMENT
AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building
78 Shenton Way #07-16
Singapore 079120

Dear Sir, Mdm,

Accident Involving Vehicles : SKP3071K & SLZ6110Y
Along : 78 ST PATRICK ROAD BASEMENT CARPARK
DOA : 15/12/2018

We are the authorized repair workshop for the owner of motor vehicle no: SKP3071K, which was involved in the captioned accident with your insured vehicle: SLZ6110Y. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

01)	Cost of Repair (inclusive of GST) (COR \$6000.00 + GST \$420.00)	\$	6,420.00
02)	GIA Search fees	\$	2.00
03)	Loss of Rental_ Wait For Surveyor 2 day x \$120/-	\$	240.00
04)	Loss of Rental_Cross 1 Sunday x \$120/-	\$	120.00
05)	Loss of Rental_ 7 days x \$120/-	\$	840.00
		\$	<u>7,622.00</u>


We enclosed herewith the following documents to support the claims:-

- a) Letter of Authorisation / GIA report(s) / Insurance Certificate, etc...
- b) Final Repair Bill
- c) GIA search/ Car Rental Bill & Invoice

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you
Yours faithfully
VIN'S MOTOR PTE LTD



Vincent Khong
(jt)

Please issue Cheque to: Vin's Motor Pte Ltd
Please transfer to: Vin's Motor Pte Ltd
UOB Current Account
A/C No: 451-307-638-4



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/AIG18022843/Gjb3

17 JUNE 2019

CHIA ZHENZHU
54 HAVELOCK ROAD
#30-126
SINGAPORE 161054

Dear Sir/Madam,

ACCIDENT INVOLVING SLZ6110Y AND SKP3071K ON 15/12/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third-Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Jimmy
Case Handler
DID: 6841 2928
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

AUTHORISATION TO ACT

I/We, Lee Chang Kim Par (the Third party claimant") of Blk 78 St. Patrick's Road H04-23 S(424180) (address), owner of SKP3071K (vehicle no.) hereby authorize **VIN'S MOTOR PTE LTD** ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SKP3071K that was damaged pursuant to the accident which occurred on 15/12/18 (date) along 78 St Patrick's Road Basement Car park (location) involving vehicle no's SLZ6110Y ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a Without prejudice and without admission of liability basis insofar as the driver /owner/ insurers of the other vehicle/s is concerned.

Dated this 18th (day) of December (month) 20 19 (year)



Signed by "the third party claimant"
(with company stamp if applicable)



Signed by "the workshop"
(with company stamp)



AUTOMOTIVE GROUP

- Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
- 6453 2121 (4 lines) / 6458 1111 (24 hrs)
- 6459 9795 / 6459 0433
- admin@vinsautogroup.com.sg
- www.vinsautogroup.com.sg

Our Ref : TP/122018/3721
Accident date : 15/12/2018
Your Ref : SLZ6110Y

Invoice No. : VM20194093
Date : 28/6/2019

MOTOR CLAIM DEPARTMENT
AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building
78 Shenton Way #07-16
Singapore 079120

Final Bill To The Vehicle:

Vehicle No. : SKP3071K
Model : BMW 318I

To supply spare parts

To repair front damages

Total amount agreed as at Lump Sum repair	\$ 6,000.00
Add : 7% GST	\$ 420.00
	<u>\$ 6,420.00</u>

VIN'S MOTOR PTE LTD

Please issue Cheque to: Vin's Motor Pte Ltd
Please transfer to: Vin's Motor Pte Ltd
UOB Current Account
A/C No: 451-307-638-4

Vin's

CAR RENTAL PTE LTD

OFFICIAL RECEIPT

160 Sin Ming Drive, Sin Ming AutoCity, #03-03, Singapore 575722.
TEL: 6453 2121 (4 LINES) FAX: 6459 9795
Co. Reg. No.: 201533370W

No: 11137

Received from Lee Chang Kim Par

the sum of Dollars One Thousand Two Hundred Only

being payment of Rental SFV 9111H (21/12/2018 - 31/12/2018)

Date: 31/12/2018

\$ 1200 00
Cash/Cheque No.



VIN'S CAR RENTAL PTE LTD

Vin's

CAR RENTAL PTE LTD

VM

Sin Ming AutoCity, 160 Sin Ming Drive #03-03, Singapore 575722
 Tel: 6453 2421 (4 Lines) Fax: 6459 9795
 Co. Reg. No.: 201533370W

No: 12256
 Date: 21.12.2018

RENTAL AGREEMENT

Vehicle No.	Make/Model	Usage
SKV9111H	TOYOTA CHR 114681D	<input checked="" type="checkbox"/> Self Drive <input type="checkbox"/> Private-Hire

HIRER'S PARTICULARS

Name: LEE CHAMN HIM FAR
 Address: 814 78 ST. PATRICK'S ROAD
 #04-23
 151424180
 Email:
 Telephone (Home):
 (Office):
 (H/P): 9818 9127
 Nric/Passport No.: S7479528E
 Nationality: Singaporean
 Date of Birth: 12.08.1974 Age:
 Driving Licence No.: S7479528E Expires:
 Type: 3 Local/Intl Issued by: TI
 Driving Experience: SINCE 25 NOV 2008
 PDVL No.:


DRIVER'S PARTICULARS (If different from Hirer)

Name:
 Address:
 Email:
 Telephone (Home):
 (Office):
 (H/P):
 NRIC or Passport No.:
 Nationality:
 Date of Birth: Age:
 Driving Licence No.: Expires:
 Type: Local/Intl Issued by:
 Driving Experience:
 PDVL No.:

CHARGES

	\$	cts
10 Day(s) @ \$ 120 /day	1200	00
Week(s) @ \$ / week		
Month(s) @ \$ / month		
Collision Damage Waiver (CDW)		
Malaysia Entry Charges		
Others:		
Total:		
Security Deposit (Cash/Cheque:)		
Grand Total	1200	00
Recipient's Signature:		
Date:		

VEHICLE CONDITION CHECK



I/We declare that the above particulars are true and correct in every respect, and have checked the vehicle and affirm that there are no other defects (if any) besides those listed in the diagram above. I/We have read and understood the terms and conditions of the hire agreement printed overleaf.

Signature of Hirer: [Signature]
 Stamp & Signature of Hirer: _____
 Date: _____

Signature of Driver (if different from Hirer): _____
 Date: _____

SECURITY DEPOSIT REFUND

Security Deposit Refund: _____
 Recipient's Signature: _____
 Date: _____

Date Out: 21.12.2018	Date In: 31/12/18
Time Out: 9.05 AM/PM	Time In: 10:00 AM/PM
Mileage at delivery / pick up:	Mileage on returning:
Fuel level at delivery / pick up: 1/2	Fuel level on returning:

Hire period expires on _____ at _____ If unstated, rental period will be calculated based on a 24 hr timeframe from the time of collection of vehicle.
 Surcharge of fuel will be at \$S _____ per 1/4 tank. There will be no refund for excess fuel upon return of the vehicle.

Remarks: SKP3071K



**GENERAL
INSURANCE
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-194707
Date of Request: 18/12/2018

Your Ref No: Online Purchase

Vin's Motor Pte Ltd
160 Sin Ming Drive, #03-03
Sin Ming AutoCity
Singapore 575722

Dear Sir/Madam,

Enquiry Date: 18/12/2018
Enquiry By: Raymond Teo Yun Loong
TP Vehicle No.: SLZ6110Y
Accident Date: 15/12/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLZ6110Y	AIG Asia Pacific Insurance Pte. Ltd.	11/05/2018-10/05/2020	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-194707

Date of Request: 18/12/2018

Your Ref No: Online Purchase

Vin's Motor Pte Ltd
160 Sin Ming Drive, #03-03
Sin Ming AutoCity
Singapore 575722

Dear Sir/Madam,

Enquiry Date: 18/12/2018
Enquiry By: Raymond Teo Yun Loong
TP Vehicle No.: SLZ6110Y
Accident Date: 15/12/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

 GIRO Cash Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Dec 2018 Edit Reg		19 Dec 2018 00:00 Edit Adj Rpt	S\$6,000.00 Edit Estimates	S\$6,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	CHIA ZHENZHU , ID: S8139140H								
Main Claimant:	LEE CHANG KIM PAR , ID: S7479528E								
Vehicle Reg. No.:	SKP3071K	Date of Loss:	15/12/2018 15:00 - :59 [89 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3789548158SG	Policy/Cover Note No.:	1800060185 (Comprehensive) Coverage: 11/05/2018 - 10/05/2020						
Vehicle Reg. No. (Insured):	SL26110Y	Policy No. (Claimant):	MT/00356448/01						
Excess:									
Repairer:	Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64532121								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Claimant's Insurer:	Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 02/01/2019]								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKP3071K (3789548158SG)
[SLZ6110Y]
TP
LEE CHANG KIM PAR
Dec 15 2018 3:00PM
[CHIA ZHENZHU]
Vin's Motor Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown							Edit		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
2	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
3	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
4	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
5	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
6	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
7	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
8	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
9	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
10	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
11	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
12	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
13	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
14	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
15	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
16	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
17	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
18	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
19	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
20	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
21	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
22	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
23	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
24	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
25	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
26	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
27	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
28	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
29	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
30	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
31	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
32	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
33	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
34	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
35	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
36	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
37	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
38	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
39	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	
40	24/06/19 10:32	General View							Load JPG	<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	24/06/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
42	24/06/19 10:32	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
43	24/06/19 10:32	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
44	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
84	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
85	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
86	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
87	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
88	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
89	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
90	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
91	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
92	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
93	24/06/19 10:33	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
94	24/06/19 10:33	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
95	24/06/19 10:33	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
96	24/06/19 10:33	Dismantled Parts		<input checked="" type="checkbox"/>
97	24/06/19 10:33	Dismantled Parts		<input checked="" type="checkbox"/>
98	24/06/19 10:33	Dismantled Parts		<input checked="" type="checkbox"/>
99	24/06/19 10:33	Dismantled Parts		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/12/18 15:05	EMAIL FROM AIG DD 19122018		<input type="checkbox"/>
2	20/12/18 15:05	TP EST & GIA REPORT		<input type="checkbox"/>
3	31/12/18 08:59	TP ESTIMATE- MARKED		<input type="checkbox"/>
4	17/06/19 16:53	Letter to OI		<input type="checkbox"/>
5	16/10/19 10:19	WORKSHOP INVOICE		<input type="checkbox"/>
6	16/10/19 10:19	AUTHORISATION TO ACT FORM		<input type="checkbox"/>
7	16/10/19 10:19	Release Voucher		<input type="checkbox"/>
8	16/10/19 10:19	RENTAL RECEIPT		<input type="checkbox"/>
9	16/10/19 10:19	LOD		<input type="checkbox"/>
10	16/10/19 10:19	GIA SEARCH		<input type="checkbox"/>

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/12/18 10:36	OI GIA REPORT		<input type="checkbox"/>
2	25/09/19 16:07	Email LKK for case updates		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLZ6110Y (Insd veh)	Model:	BMW 318I 2.0 (A)
	SKP3071K (TP veh)		
Date of Accident:	15/12/2018		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	16,886.02
Final Repair Cost	:	\$	6,420.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	1,080.00 9 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	7,502.00
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)			
A) For Non GIA Registered Workshop: Agreed Liability ___ 100 ___ (%)			
B) For GIA Registered Workshop: BOLA Applicable; Yes/ No BOLA Scenario No: _____			
BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Vin's Motor Pte Ltd	:	\$ 7,502.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

16 Oct
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18022843/GHB3Q2

Date: 16/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800060185
Claimant		
Vehicle No : SKP3071K	Insured Vehicle No :	SLZ6110Y
Date of Loss: 15/12/2018	Nature of Claim: TP	Claim No: 3789548158SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP3071K		
Make & Model:	BMW 318I, 2.0 (A)	Engine No:	B536I925N46B20BZ
Reg. Date:	14/07/2011 (Man. Year: 2011)	Chassis No:	WBAPF72020FG90110
Colour:	Black	Odometer:	122304 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,301.33	11,068.02	2,233.31	16.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,480.00	1,920.00	560.00	22.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,781.33	12,988.02	2,793.31	17.70
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	15,781.33	6,000.00	9,781.33	61.98
+ GST 7.00/7.00% (S\$)	1,104.69	420.00	684.69	61.98
Nett Amount (S\$)	16,886.02	6,420.00	10,466.02	61.98
+ Car Rental (9.0 x S\$120.00/day) (S\$)		1,080.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,502.00		

INSPECTION

Date of Assignment:	19/12/2018	
Date Inspected:	20/12/2018 Inspected At:	Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	6.0 days	

Adjuster: XING GUO QIANG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	1,166.55 FL	*1,166.55 FL
2	2		*FRONT BONNET HINGE	Not Necessary	163.70 FL	*- FL
3	1		*FRONT BONNET ABSORBER	Not Necessary	109.45 FL	*- FL
4	2		*FRONT HEADLAMP	Cracked	1,960.50 FL	*1,960.50 FL
5	2		*FRONT GRILLE	Scratched (1 PCS ONLY)	219.80 FL	*109.90 FL
6	1		*FRONT BUMPER	Cracked	1,105.15 FL	*1,105.15 FL
7	1		*FRONT BUMPER TOWING COVER	Missing	45.60 FL	*45.60 FL
8	1		*FRONT BUMPER CENTRE GRILLE	Broken	85.70 FL	*85.70 FL
9	2		*FRONT BUMPER FOG LAMP	Broken	516.30 FL	*516.30 FL
10	2		*FRONT BUMPER FOG LAMP COVER	Broken	122.20 FL	*122.20 FL
11	2		*FRONT BUMPER RETAINER	Deformed	30.90 FL	*30.90 FL
12	1		*FRONT BUMPER REINFORCEMENT	Bent	550.30 FL	*550.30 FL
13	2		*FRONT BUMPER BRACKET	Not Necessary	70.30 FL	*- FL
14	1		*FRONT LH FENDER	Bent	648.35 FL	*648.35 FL
15	2		*FRONT LH FENDER BRACKET	Not Necessary	51.00 FL	*- FL
16	4		*FRONT LH FENDER INNER FIBRIC	Cracked	448.40 FL	*448.40 FL
17	1		*FRONT SUPPORT PANEL	Cracked	593.50 FL	*593.50 FL
18	1		*FRONT AIR COND CONDENSOR	Bent	979.45 FL	*979.45 FL
19	1		*FRONT AIR COND PIPE NO1	Not Necessary	247.00 FL	*- FL
20	1		*FRONT AIR COND PIPE NO2	Not Necessary	283.30 FL	*- FL
21	1		*FRONT RADIATOR	Bent	670.80 FL	*670.80 FL
22	1		*FRONT RADIATOR FAN ASSY	Cracked	1,083.75 FL	*1,083.75 FL
23	1		*FRONT RADIATOR AIR DUCT	Cracked	157.20 FL	*157.20 FL
24	1		*FRONT SAFETY BELT	N/S Activated/O/SNot Necessary	778.10 FL	*389.05 FL
25	1		*FRONT AIR BAG ECU	Not Necessary	927.15 FL	*- FL
26	1		*FRONT BATTERY CABLE	Activated	293.05 FL	*293.05 FL
27	1		*FRONT BUMPER UNDER COVER	Cracked	412.50 FL	*412.50 FL
28	2		*FRONT SUPPORT AIR DUCT	Cracked	137.50 FL	*137.50 FL
29	2		*FRONT HEADLAMP LOWER BRACKET	Cracked	143.90 FL	*143.90 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	14,001.40	11,650.55
- List Item Discount on L Items 5.00/5.00% (\$)	700.07	582.53
Total Parts (\$)	13,301.33	11,068.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TOWING	New	120.00	0.00
2	TO REFILL AIR COND GAS	New	150.00	120.00
3	TO RESET AIR BAG SYSTEM	New	250.00	200.00
4	TO REPAIR FRONT DAMAGE	New	980.00	800.00
5	TO SPRAY PAINTING	New	980.00	800.00
Gross Labour Cost (S\$)			2,480.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >