

22/03/2003

ASS. REC. BY:

REF:

CS/III18022861/ utd36

Special Instruction:

NEW VOT
MARCUS

MARCUS

ASSIGNMENT (Office)

From (Person):

Gabriel Wee

of

III

Date/Time:

20/12/18 @ 4:06pm

Estimated Cost:

Bill to:

OD/TP/FWS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GP 9590L

Insured:

SH 6263B

at Workshop m/s

Polymath Garage

Tel:

8228 9818

of

1 Kaki Bukit Ave 6 # 02-02

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/12/18

CA / REV / REP. / REV 24 HRS

1 up?

21/12/18 @ after 12pm

H.O.D. Endorsement:

Date/Time:

4:19pm @ 20/12/18

Person Contacted:

Nigel

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	GP 9590L - NA/CTI18022829/24	DOA: 19/12/2018
	SH 6263B - NA/CTI18022829/24	DOA: 19/12/2018

ASSIGNMENT

From: Date: 21/12/2018

Estimated Cost:

OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GP 9590L
at Workshop m/s: Polymath Garage
of 1 kaki Bukit Ave 6 # 02-02

Insured:

Policy No

Claims No

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

After 12pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

15k.

IDAC Accident Report:

Consistent? : Yes or No

G/A / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up! 36547

Vehicle: IN / OUT

Date:

Person Contacted:

29/7/2020

Veh No: GP 9590L Yr Regn: 7 05

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or car

Make: Toyota Dyna C.C. 2988

Colour: S. blue A/C: Insured / Std / NI / NA

Sp. Reading: 4050250 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTFUF34Y603010877

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185R14.

R: 155R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 0/6 mm

L/Bal. 6 mm

L/Bal. 0/6 mm

D.O.A. 19/1/18

D.O.I. 21/1/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/5 H.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

30/12/18 LTA 8829
confirmed k/s @ 2800 with Ngaf
(Red: 4024.87, 58%)

RECEIVED 11 JAN 2019

Date/Time, File Pass to?

☐ : Preli. Report

1) 21/1 Typist

☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

)

TOTAL

Report Format: TP

Lump Sum / I.B.I: (\$) 2300/-

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

290

10

260

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, 20 December 2018 4:06 PM
To: Ruby Ong; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Polymath Garage Pte Ltd; Sundari Nagarajan - III
Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GP9590L [OUR REF. TCL.GCN.RO.50519.18.PG]

Dear Sir / Mdm,

Please conduct a survey on TP vehicle GP9590L and let us have your report urgently.

This claim will be handled by Ms Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

From: Ruby Ong [mailto:ruby@htapartners.com.sg]
Sent: 20 December, 2018 2:51 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: Polymath Garage Pte Ltd <enquiry@polymathgarage.com.sg>
Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GP9590L [OUR REF. TCL.GCN.RO.50519.18.PG]
Importance: High

Your ref: SH 6263B
Our ref: TCL.GCN.ro.50519.18.shm

WITHOUT PREJUDICE

20 December 2018

India International Insurance Pte Ltd
Motor Claims Department
64 Cecil Street
#04-02 IOB Building
Singapore 069428

By Email Only

VERY URGENT

Dear Sirs

CLAIMANT: UNIVERSAL FOOD SUPPLY PTE LTD

ACCIDENT INVOLVING GP 9590L & SH 6263B ALONG EAST COAST PARK SERVICE ROAD ON 19 DECEMBER 2018 @ 1505HRS

We are instructed by Universal Food Supply Pte Ltd to notify you of a road traffic accident on 19 December 2018 at about 1505hrs along East Coast Park Service Road involving our clients' vehicle registration number GP 9590L and vehicle registration number SH 6263B driven by you/your insured at the material time.

As a result of the accident, our clients' vehicle has been damaged. Before our clients proceed to repair the damaged vehicle, our clients propose to appoint Marcus of LKK Auto Consultants Pte Ltd as the single joint expert to carry out the pre-repair survey for GP 9590L.

Please make the necessary arrangements with the contact person. The details are as follows :

Venue : **POLYMATH GARAGE PTE LTD**
1 Kaki Bukit Avenue 6
#02-02 Autobay
Singapore 417883

Contact Person : **Mr Nigel Ong / Mr John Phoon @ 8228 9818**

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our clients' right to claim for compensation for loss of use for your current request for re-survey.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext 278
Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this

message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



Polymath garage

Polymath Garage Pte Ltd
AutoBay@Kaki Bukit, 1 Kaki Bukit Ave 6 #02-02.
Singapore 417883
24 Hour : +65 8228 9818
Phone: +65 6871 8861 | Fax: +65 6871 8814
Email : enquiry@polymathgarage.com.sg

4/5 \$2800/

Not Affected

21/12/2018

Estimated repair checklist

Vehicle Registration No. : GP9590L

Vehicle Make/Model : Toyota/Dyna

Qty List Items

1	Front	bumper
1	Front	door - RH 1218.40
1	Front	door w/strip
1	Front	door seal
1	Front	door glass outer moulding
1	Front	door glass run channel
1	Front	door glass regulator
1	Front	door glass regulator motor
1	Front	door insulation
1	Front	door checker
2	Front	door hinges @ 115
1	Front	headlamp - RH
1	Front	step garnish - RH
1	Front	wheel arch panel - RH
1	Front	door pillar - RH

Amount \$

521.60	—
1,587.50	—
161.20	—
112.60	—
141.20	x
181.90	x
281.95	x
481.95	x
120.30	x
89.95	x
230.00	IPC
704.35	—
312.60	—
561.20	x
711.52	x
Sub-total	6,199.82
Less 25%	1,549.96
Total List	4,649.87

Special Nett Items

1	Front	door R.O.V sticker
---	-------	--------------------

45.00	30
Total Special Nett	45.00

Labour charges

To remove, refix front interior trims to assist repair
To check front electrical wiring
To respray undercoating
To respray painting and etc
Panel beating, cut, weld remove & replacing above parts

120.00	60
50.00	20
80.00	50
800.00	500
1,080.00	120
Total Labour	2,130.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

6,824.87

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	20/12/2018 10:53
Date Of Accident	19/12/2018 15:05
Exact Location Of Accident	EAST COAST PARK SERVICE RD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GP9590L
Insured/Policyholder	
Name Of Registered Owner	M/S UNIVERSAL FOOD SUPPLY PTE LTD
Co Reg No	200503654Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90221646
Alternative Phone No	OFFICE-90221646
Vehicle Particulars	
Manufacturer	TOYOTA
Model	DYNA 150 D
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	DMCVSN3049501803
Cover Note Number	
Driver	
Name of Driver	TAN GIM HWEE
NRIC No	S1509217C
Date Of Birth	16/09/1961
Occupation	OUTDOOR
Date Of Driving Pass	19/05/1980
Driving Experience	38 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97808226
Fax Number	
Contact Number	OFFICE-97808226
EMail Address	NOEMAIL

Address	BLK 773 BEDOK RESERVOIR VIEW #04-127
Postcode	470773
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SH6263B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Accident Sketch Plan

SKETCH PLAN

EAST ROAD TO SERVICE RD AND ENDAVE RD EX 1

ALGONQUIN
IS 5462638



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON THE DATED DATE AND TIME, I WAS TRAVELING ON
EAST ROAD SERVICE ROAD. THE ROAD AHEAD OF ME WAS DOING
ROAD WORK. I STOPPED DUE TO RED LIGHT SIGNAL FROM THE ROAD
WORK WORKERS. AFTER ABOUT 10 TURN GREEN LIGHT AND I
CHECKED CLEAR OF THE OPPOSITE DIRECTION LANE AND I PROCEEDED.
ALL OF A SUDDEN, I SAW VEHICLE "E" APPROACHING FROM
THE LEFT LANE. I IMMEDIATELY STOPPED MY VEHICLE. VEHICLE
"E" WAS TRAVELING IN THE LEFT LANE AND IT WAS TURNING RIGHT
INTO THE RIGHT LANE. I SAW VEHICLE "E" WAS TRAVELING IN THE
LEFT LANE. I IMMEDIATELY STOPPED MY VEHICLE. VEHICLE
"E" WAS TRAVELING IN THE LEFT LANE. I SAW VEHICLE "E" WAS
TRAVELING IN THE LEFT LANE. I IMMEDIATELY STOPPED MY VEHICLE.
VEHICLE "E" WAS TRAVELING IN THE LEFT LANE. I SAW VEHICLE "E"
WAS TRAVELING IN THE LEFT LANE. I IMMEDIATELY STOPPED MY VEHICLE.
VEHICLE "E" WAS TRAVELING IN THE LEFT LANE. I SAW VEHICLE "E"
WAS TRAVELING IN THE LEFT LANE. I IMMEDIATELY STOPPED MY VEHICLE.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

toyota dyna

Price Range

Depreciation

> 10 year(s)

Vehicle Type

[Home](#) » [Used Cars](#) » [Direct Owners](#) » [Toyota Dyna 150 \(COE till 07/2020\)](#)

Resources

[Car Buying](#)
[Car Selling](#)
[Car Ownership](#)
[Car Aftermarket](#)
[On The Move](#)
[Lifestyle](#)

Car Tyres



Toyota Dyna 150 (COE till 07/2020)

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)
[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)
[Report Error](#)
[More Actions](#)
[Share](#)

Car Details

Price	\$20,800	
Depreciation	\$13,410 /yr	?
Reg Date	13-Jul-2005 (1yr 6mths 18days COE left)	
Lifespan	12-Jul-2025	
Manufactured	2005	?
Mileage	-	
Transmission	Manual	
Engine Cap	2,986 cc	
Curb Weight	1,500 kg	?
Fuel type	Diesel	
Features	-	
Accessories	-	
COE	\$26,709	?
OMV	\$23,690	?
ARF	\$1,185	?
Dereg Value	\$8,283 as of today (change)	?
No. of Owners	4	?
Type of Veh	Truck	
Category	COE Car, Direct Owner Sale	
Availability	Available	DIRECT OWNER

[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)

Posted on: 13-Dec-2018 | Last Updated on: 22-Dec-2018

Tags: Toyota Dyna, toyota dyna, 2005 Toyota Dyna, 2005 toyota dyna, Toyota, Dyna, dyna, Used Toyota

Upfront Payment

[» more Financial info](#)
[Compare](#)
Transfer Fee
\$25

?



100% FREE
PAPERWORK
SUPPORT FOR
BOTH BUYER
& SELLER



Seller Information

Contact Person(s) Perum

Contact No. 94236

USEFUL FORMS

[» Indemnity form](#)
[» Receipt](#)
[» Ownership Transfer](#)

Instructions on how to co
consumer deal

Regardless of buying or sell
your paperwork, loans & ins

Useful Services



Afraid of lerr
this car eval

Vehicle E

Find out the

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3654Z
Vehicle Details	
Vehicle No.:	GP9590L
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 D
Primary Colour:	Silver
Manufacturing Year:	2005
Engine No.:	5L56050259
Chassis No.:	JTFUF34Y603010877
Maximum Power Output:	-
Open Market Value:	\$23,690.00
Original Registration Date:	30 Jul 2005
First Registration Date:	30 Jul 2005
Transfer Count:	1
Actual ARF Paid:	\$1,185.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jul 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$26,709.00
COE Rebate Amount:	\$8,529.00
Total Rebate Amount:	\$8,529.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 24 Dec 2018

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

500+ dealers
competed to
buy my car!



- Sell ur Car for More Cash
- Highest Price or Get \$100 Free
- Get Paid Now, Handover Later

SELL YOUR CAR

toyota dyna

Price Range

Depreciation

> 10 year(s)

Vehicle Type



Home » Used Cars » GF Motor Trading Enterprise » Toyota Dyna 150 (COE till 08/2020)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Vehicle Number Plates

BUY & SELL
Your AUSPICIOUS
& UNIQUE Vehicle No.

Do you know? We are Singapore's
BIGGEST PLAYER
with the most vehicle plate numbers for sale?

Click here to see all Auspicious Numbers!

Toyota Dyna 150 (COE till 08/2020)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$24,800	
Depreciation	\$15,290 /yr	?
Reg Date	08-Aug-2005 (1yr 7mths 14days COE left)	
Lifespan	07-Aug-2025	
Manufactured	2005	?
Mileage	-	
Transmission	Manual	
Engine Cap	2,986 cc	
Curb Weight	1,700 kg	?
Fuel type	Diesel	
Features	-	
Accessories	-	
Description	Please Call In Advance Before Viewing. Thanks.	
COE	\$25,292	?
OMV	\$23,690	?
ARF	\$1,185	?
Dereg Value	\$8,204 as of today (change)	?
No. of Owners	3	?
Type of Veh	Truck	
Category	COE Car	
Availability	Available	

Add to Shortlist

Add to Compare

Add a Note

Posted on: 23-Dec-2018 | Last Updated on: 23-Dec-2018

Tags: Toyota Dyna, toyota dyna, 2005 Toyota Dyna, 2005 toyota dyna, Toyota,
Dyna, dyna, Used Toyota



Location

Seller Information

Company	GF Motor Trading Enterprise
	» dealer
	» 9 vehicles
Address	310 The Arcade, Singapore
Location	Eng Aun
Office No	625676

Useful Services



Afraid of len
this car eval

Vehicle E



Find out the
Get a free C
Free Val


Compare

Upfront Payment

» more Financial info

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Jan 2019 12:13 Edit Reg		20 Dec 2018 00:00 Edit Adj Rpt	S\$2,800.00 Edit Estimates	S\$2,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	-								
Vehicle Reg. No.:	GP9590L	Date of Loss:	19/12/2018 00:00 - :59 [160 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SH6263B	Policy No. (Claimant):							
		Excess:							
Repairer:	Polymath Garage Pte Ltd (HQ) 1 KAKI BT AVENUE 6 #02-02 AUTOBAY, 417883 Kaki Bukit - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 02/01/2019]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS 		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									






































Claim Documents

*GP9590L
[SH6263B]
TP
-

Dec 19 2018 12:00AM
[-]
Polymath Garage Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#) ☐

Photos/Images			3 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
2	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
3	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
4	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
5	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
6	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
7	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
8	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
9	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
10	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
11	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
12	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
13	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
14	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
15	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
16	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
17	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
18	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
19	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
20	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
21	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
22	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
23	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
24	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
25	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
26	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
27	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
28	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
29	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
30	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
31	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
32	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
33	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
34	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
35	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
36	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>
37	11/01/19 10:51	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
38	11/01/19 10:51	General View		Load JPG	<input checked="" type="checkbox"/>
39	11/01/19 10:51	General View		Load JPG	<input checked="" type="checkbox"/>
40	11/01/19 10:51	General View		Load JPG	<input checked="" type="checkbox"/>
41	11/01/19 10:51	General View		Load JPG	<input checked="" type="checkbox"/>
42	11/01/19 10:51	General View		Load JPG	<input checked="" type="checkbox"/>
43	11/01/19 10:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
44	11/01/19 10:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
45	11/01/19 10:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
46	11/01/19 10:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
47	11/01/19 10:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	21/12/18 08:45	Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III18022861/UTD3E2

Date: 14/01/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle
No : GP9590L

Insured Vehicle No : SH6263B

Date of Loss: 19/12/2018

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GP9590L

Make & Model: TOYOTA DYNA 150, 3.0 D (M)

Engine No: 5L56050259

Reg. Date: 30/07/2005 (Man. Year: 2005)

Chassis No: JTFUF34Y603010877

Colour: Silver

Odometer: 405050 km

Engine Capacity: 2986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185 R14

Rear Tyre Size: 155 R12 (D)

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6/6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,694.86	2,389.31	2,305.55	49.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,130.00	1,130.00	1,000.00	46.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,824.86	3,519.31	3,305.55	48.43
Approved Total (Overridden) (S\$)		2,800.00		
Nett Amount (S\$)	6,824.86	2,800.00	4,024.86	58.97

INSPECTION

Date of Assignment: 20/12/2018

Date Inspected: 21/12/2018 Inspected At:

Polymath Garage Pte Ltd (HQ)
1 KAKI BT AVENUE 6 #02-02 AUTOBAY
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 14 Jan 2019)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GP9590L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent / Dented	521.60 FL	*521.60 FL
2	1		*FRONT DOOR - RH	Badly Dented	1,587.50 FL	*1,218.40 FL
3	1		*FRONT DOOR W/STRIP	Necessary	161.20 FL	*161.20 FL
4	1		*FRONT DOOR SEAL	Necessary	112.60 FL	*112.60 FL
5	1		*FRONT DOOR GLASS OUTER MOULDING	Not Necessary	141.20 FL	*- FL
6	1		*FRONT DOOR GLASS RUN CHANNEL	Not Necessary	181.90 FL	*- FL
7	1		*FRONT DOOR GLASS REGULATOR	Not Necessary	281.95 FL	*- FL
8	1		*FRONT DOOR GLASS REGULATOR MOTOR	Not Necessary	481.95 FL	*- FL
9	1		*FRONT DOOR INSULATION	Not Necessary	120.30 FL	*- FL
10	1		*FRONT DOOR CHECKER	Not Necessary	89.95 FL	*- FL
11	1		*FRONT DOOR HINGES (2PCS)	Lower Bent	230.00 FL	*115.00 FL
12	1		*FRONT HEADLAMP - RH	Scratched	704.35 FL	*704.35 FL
13	1		*FRONT STEP GARNISH - RH	Cut	312.60 FL	*312.60 FL
14	1		*FRONT WHEEL ARCH PANEL - RH	Repair	561.20 FL	*- FL
15	1		*FRONT DOOR PILLAR - RH	Repair	711.52 FL	*- FL
16	1		*FRONT DOOR R.O.V STICKER	Necessary	45.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,244.82	3,175.75
- List Item Discount on L Items 25.00/25.00% (S\$)	1,549.96	786.44
Total Parts (S\$)	4,694.86	2,389.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, REFIX FRONT INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	60.00
2	TO CHECK FRONT ELECTRICAL WIRING	New	50.00	20.00
3	TO RESPRAY PAINTING AND ETC	New	800.00	500.00
4	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS	New	1,080.00	500.00
5	TO RESPRAY UNDERCOATING	New	80.00	50.00
Gross Labour Cost (S\$)			2,130.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >