

ASS. REC. BY

REP

CS/SMO18022803/Uvd3er

Special Instruction

Sub Vey of
Merimen

Merimen

ASSIGNMENT (Office)

From (Person) Ngo Sau wei Shawn

at SMO

Date/Time: 21/12/18 @ 9:12am

Estimated Cost

Bill to:

(1) TP / WS / TP RES / OD RES / EVA / INV / MV7CS

To Inspect Vehicle No.

SKC 5858M

Insured:

at Workshop n/z

Keh Motor

Tel

90721766

of

15 Ubi Road 4

Policy No. D18MTPV01008162

Claim No.

CMTD1805618

Sum Insured

Excess:

TBA 0 \$800

Make of Veh:

(Client's Record)

~

D.O.A.

20/12/18

CA (1) REP / REP. / REV 24 HRS

H.O.D. Enforcement

Date/Time: 9:25am @ 21/12/18

Person Contacted

Rueben

Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	SKC 5858M - X
21/12/18	Revert via merimen
27/12/18	Recd approved \$ 11,773.32 from Shawn by merimen
27/12/18	Informed Rueben c/A ex 0 by email
27/12/18	Informed Mr Lim / Freez vehicle ex \$ 800

(08/11/13) wef

REF:

ASS. REC. BY: Marcus

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKC5F8FM

at Workshop m/s: Keli nku

of _____

Insured: _____

Policy No. _____

Claims No _____

Sum Insured: _____ Excess: ? \$00

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$99k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 13% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 56512

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKC5F8FM Yr Regn: 16

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or FA

Make: Honda Odyssey CO 2356

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 19310 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/Nr: JHMRC18906C202948

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or all

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / STD A/Rim or

Tyre Size: F: 2.5/55-17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal: 2 mm R/Bal: 2 mm

L/Bal: 2 mm L/Bal: 2 mm

D.O.A: 20/12/18 D.O.I: 21/12/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S H, O/S Body.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

9/1/19 63564318 continued final by #10976.94 with Ruben (Red 2673.88, 2019)

RECEIVED 9 JAN 2019

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

2) 9/1 - typist

Report Format: merimen

Lump Sum / I.B.I: (\$ 10,976.94)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Other

TOTAL

350

10

360

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Dec 2018		21 Dec 2018 09:12 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIM CHAY LUNG CATHERINE, ID: S15144311, Tel: +6596398050, Email: c.goh@firsthiace.com		
Vehicle Reg. No.:	SKC5858M	Date of Loss:	20/12/2018 11:00 - :59
Claim Type:	OD / CMTD1805618	Policy/Cover Note No.:	D18MTPV01008162 (Comprehensive)
		Excess:	
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671		
Handling Insurer:	Sampo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by NGO SAU WEI SHAWN - 6329 5202]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/01/2019]		
Driver/Custodian:	LIM CHAY LUNG CATHERINE (57 / Female), NRIC: S15144311, Tel: +6596398050		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)

[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 27 December 2018 4:51 PM
To: 'Faeaz'; Lim Chou Siong; SUR
Subject: RE: SKC 5858M-DOA: 20/12/2018 (SOMPO INSURANCE OD)

Dear Both,

Please be informed that vehicle excess \$800/-

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 27 December 2018 10:48 AM
To: Faeaz <faeaz@honda.com.sg>; Lim Chou Siong <bdysa2@honda.com.sg>; SUR <sur@lkkauto.com>
Subject: FW: SKC 5858M-DOA: 20/12/2018 (SOMPO INSURANCE OD)

Dear Both,

Kindly take note below email.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 27 December 2018 10:45 AM
To: 'Jeshurueben Rao Thomas' <jeshurueben@honda.com.sg>; SUR <sur@lkkauto.com>
Subject: SKC 5858M-DOA: 20/12/2018 (SOMPO INSURANCE OD)

Dear Rueben,

As instructed by our client , please proceed to repair the insured vehicle **SKC 5858M (Excess \$0-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 27 December 2018 10:48 AM
To: Faeaz; Lim Chou Siong; SUR
Subject: FW: SKC 5858M-DOA: 20/12/2018 (SOMPO INSURANCE OD)

Dear Both,

Kindly take note below email.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 27 December 2018 10:45 AM
To: 'Jeshuruben Rao Thomas' <jeshuruben@honda.com.sg>; SUR <sur@lkkauto.com>
Subject: SKC 5858M-DOA: 20/12/2018 (SOMPO INSURANCE OD)

Dear Rueben,

As instructed by our client , please proceed to repair the insured vehicle **SKC 5858M (Excess S0-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 27 December 2018 10:44 AM
To: 'Jeshurueben Rao Thomas'; SUR
Subject: SKC 5858M-DOA: 20/12/2018 (SOMPO INSURANCE OD)

Dear Rueben,

As instructed by our client , please proceed to repair the insured vehicle **SKC 5858M (Excess S0-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: NGO SAU WEI SHAWN

Date: 21 Dec 2018

Preliminary Advice

Vehicle No	: SKC5858M	Accident Date	: 20/12/2018
Make	: HONDA ODYSSEY	Policy No.	: D18MTPV01008162
Assignment Date	: 21/12/2018	Excess	: S\$0.00
Date of Inspection	: 21/12/2018	Est. Duration of Repair	: 6.00
Inspection At	: KAH MOTOR CO SDN BHD (UBI) 15 UBI ROAD 4 SINGAPORE 408610		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,650.82
Revised Amount	:S\$	10,976.94
Check Items (Estimated)	:S\$	796.38
Total	:S\$	11,773.32

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	99,000.00
COE / PARF Rebate	:S\$	56,512.00
Salvage Value	:S\$	
Margin for Repair	:S\$	42,488.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
 Owner ID: 4431I

Vehicle Details

Vehicle No.: SKC5858M
 Vehicle to be Exported: No
 Intended Deregistration Date: 21 Dec 2018
 Vehicle Make: HONDA
 Vehicle Model: ODYSSEY 2.4 EXV-S CVT SR
 NAVI RES

Primary Colour: Grey
 Manufacturing Year: 2016
 Engine No.: K24W72011313
 Chassis No.: JHMRC1B90GC202948
 Maximum Power Output: 129.0 kW (172 bhp)
 Open Market Value: \$32,399.00
 Original Registration Date: 09 May 2016
 First Registration Date: 09 May 2016
 Transfer Count: 0
 Actual ARF Paid: \$37,359.00 18679

Intended PARF Rebate Details

PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 08 May 2026
 PARF Rebate Amount: \$28,019.00

Intended COE Rebate Details

COE Expiry Date: 08 May 2026
 COE Category: B - Car above 1600cc or 97kW
 (130bhp)
 COE Period(Years): 10
 QP Paid: \$38,610.00
 COE Rebate Amount: \$28,493.00
 Total Rebate Amount: \$56,512.00

The information contained herein is correct as at 21 Dec 2018

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Classic Promo! Best Deal! Fast Selling! Hurry Down Now!



Flexible Loan, Trade In Are
Welcome. 100% Deposit Refund
For Unapproved Loan.
Classic Credit StarAd



PRIME MOTOR

ICHENG YONG CREDIT ENTERPRISES

With over 200 units of vehicle to choose from, ranging from all European to Japanese

[Browse by Category](#)
[« Back \(1 2 \) Next »](#)
[Sort by Date Posted](#)

25 vehicles

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	odyssey		Any	Any	2016	Any	Any	
	Honda	Odyssey 2.4A EXV-S Sunroof	\$99,800	\$11,510 /yr	21-Mar-2016	2,356 cc	63,000 km	
Fully Kah Motor Warranty And Serviced. Most Popular Sporty White! Cheapest In Market! Agent Unit With Sunroof! High Loan And High Available! Call Now For Best Deal!								
Posted: 20-Dec-2018			Tags: 2016 Honda Odyssey, 2016 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda					
	Honda	Odyssey 2.4A EXV-S	\$112,000	\$11,750 /yr	18-Nov-2016	2,356 cc	42,000 km	
Elegant Grey, 7 Seater MPV, With Sunroof, Just Serviced By Agent In Nov 2018, Accident Free, One Owner Only, Low Mileage Done, Will Warranty, Very Well Maintained.								
Prime Motor & Leasing								
Posted: 19-Dec-2018			Tags: 2016 Honda Odyssey, 2016 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda					
	Honda	Odyssey 2.4A EXV-S	\$106,800	\$11,440 /yr	08-Sep-2016	2,356 cc	47,300 km	
\$3,000 Drive Away! Monthly At \$1,790 For 84 Months Full Loan Available! Non-smoker Car! 1 Owner, Well Maintained Condition. 100% Most Popular Full Size 7 Seater In The Market. Call Me N...								
Viking Motor Pte Ltd								
Posted: 16-Dec-2018			Tags: 2016 Honda Odyssey, 2016 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda					
	Honda	Odyssey 2.4A EXV-S	\$99,800	\$11,880 /yr	18-Jan-2016	2,356 cc	68,523 km	
Loan Up To 90%! Full Agent Service And Warranty By Kah Motor. Tip Top Condition And Well Maintained By Previous Owner! In-House Trade In Available! Call Now To Enquire!								
Posted: 16-Dec-2018			Tags: 2016 Honda Odyssey, 2016 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda					
	Odyssey redefines the meaning of space Honda has set its sights on a much bigger slice of the people mover market with the fifth generation of its popular MPV, the Odyssey. Read this article							
	Honda	Odyssey 2.4A EXV-S	\$105,000	\$11,970 /yr	18-Apr-2016	2,356 cc	56,624 km	
5 Year, 5 Years Kah Motor Warranty, Tax Apr'19, Comfy Ottoman Seat, Reliable And Well Equipped Ideal Family MPV, Spacious L Fuel Consumption, Price Negotiable, Trade In Welcome.								

[Compare](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/12/2018 14:19
Date Of Accident	20/12/2018 11:00
Exact Location Of Accident	JALAN SONG KET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC5858M
Insured/Policyholder	
Name Of Registered Owner	LIM CHAY LUNG CATHERINE
NRIC No	S1514431I
Email Address	C.GOH@FIRSTHIACE.COM
Mobile Phone No	(LOCAL) +65-96398050
Alternative Phone No	OTHERS-96398050
Vehicle Particulars	
Manufacturer	HONDA
Model	ODYSSEY 2.4 EXV-S CVT SR NAVI RES
Exact Purpose for which vehicle was being used at time of accident	

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01008162
Cover Note Number	09/05/2018 TO 08/05/2019

Driver

Name of Driver	LIM CHAY LUNG CATHERINE
NRIC No	S1514431I
Date Of Birth	24/09/1961
Occupation	INDOOR
Date Of Driving Pass	06/06/2002
Driving Experience	16 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96398050
Fax Number	
Contact Number	OTHERS-96398050
EMail Address	C.GOH@FIRSTHIACE.COM

Address	22B AROOZOO AVENUE (S) 539834
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : MAID GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

refer with attach.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF8906D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Accident Sketch Plan Pg. 1

Paragraph

Paragraph 2

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

R: 4BF8906D

I was driving my car SKC585BM moving over the hump in the left lane. Upon reaching the junction of Jalan Sungai Ket, there was a lorry GPF2006D who turning to r/h. I swerved out suddenly without giving any signaling & hit onto my car r/h side portion.

Insurance Co. Empire Insurance
Vehicle No. 2K4558H Date of Accident 2/1/12 18
☐ Reporting Only
☐ Own Damage Claim
☐ Third Party Claims
☐ Other Workshop
Kesh Motor

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Name: _____
 Reporting Centre Signature: _____
 NRIC/FIN No.: _____

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : SOMPO INSURANCE SINGAPORE
50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

Registration No : SKC5858M

Chassis No : JHMRC1890GC202948

Model : ODYSSEY2.4 EXV-S 16YM NAVI-RES

Owner's Name : LIM CHAY LUNG CATHERINE

Ins Policy No. :

Date of Accident : 20/12/2018

Document No. : SQT18005439

Date : 20. Dec 2018

Customer No. : WH023

Svc Advisor : RUEBEN THOMAS

Engine No : K24W72011313

Date | Time : 20. Dec 2018 3:20:39 PM


Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	OWN DAMAGE CLAIMS-J/NO: 71876						
	POLICY/CLAIMS NO: D18MTPV01008162						
	OWNER: LIM CHAY LUNG CATHERINE						
	ACC DATE: 20/12/2018						
	SURVEYED BY:						
	DATE:						
	AUTHORIZED ON :						
	REF NO :						
04711-T6A-900ZZ	FACE,FR.BUMPER <i>D.S</i>	1	700.00	25	525.00	36.75	561.75
91505-TM8-003	CLIP,BUMPER <i>ren</i>	14	2.30	25	24.15	1.69	25.84
71198-T6A-003	SPACERL.FR.BUMPER SIDE <i>11</i>	1	11.80	25	8.85	0.62	9.47
71193-T6A-003	SPACERR.FR.BUMPER SIDE <i>CPA</i>	1	11.80	25	8.85	0.62	9.47
71140-T6A-003	BEAMR.FR.BUMPER UPPER <i>11</i>	1	34.90	25	26.17	1.83	28.00
71112-T6A-921ZD	SPOILER ASSYR.FR.SIDE <i>C17</i>	1	94.40	25	70.80	4.96	75.76
71104-T6A-921	GARNISHR.FR.BUMPER <i>gated</i>	1	46.10	25	34.57	2.42	36.99
33100-T6A-Q11	HEADLIGHT ASSYR.WITH LED <i>one</i>	1	2281.90	25	1711.42	119.80	1831.22
76841-T6A-003	TANKWASHER <i>11</i>	1	70.90	25	53.17	3.72	56.89
60210-T6A-300ZZ	FENDER COMPR.FR. <i>D.S</i>	1	548.50	25	411.45	28.80	440.25
72415-T6A-003	MOLDING ASSYR.FR.CORNER <i>34</i>	1	87.70	25	65.77	4.60	70.37
74201-T6A-000	GARNISHR.FR.FENDER <i>11</i>	1	33.10	25	24.82	1.74	26.56
74100-T6A-000	FENDER ASSYR.FR INNER <i>7111</i>	1	120.70	25	90.52	6.34	96.86
74105-T6A-000	ENCLOSURER.FR.FENDER <i>11</i>	1	26.30	25	19.72	1.38	21.10
67010-T6A-000ZZ	PANEL COMPR.FR.DOOR <i>D/S/1</i>	1	895.20	25	671.40	47.00	718.40
67325-T6A-J01	TAPE,R.FR.DOOR SA <i>ren</i>	1	37.30	25	27.97	1.96	29.93
67324-T6A-305ZA	TAPE SETR.FR.DOOR SASH INNER <i>ren</i>	1	38.40	25	28.80	2.02	30.82
76208-T6A-Q03	MIRROR ASSY,R.SET <i>gated</i>	1	1226.40	25	919.80	64.39	984.19
76201-T6A-J01ZD	CAPR.SKULL <i>11</i>	1	66.00	25	49.50	3.47	52.97
67510-T6A-J00ZZ	PANEL COMPR.SLIDE DOOR <i>D/S/1</i>	1	1000.50	25	750.37	52.53	802.90
67821-T6A-305ZA	TAPE SETR.RR.DOOR SASH INNER <i>ren</i>	1	57.10	25	42.82	3.00	45.82
42700-T6A-J81	DISK ALUMINIUM WHEEL 17X7J <i>C17</i>	1	915.00	25	686.25	48.04	734.29



GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : SOMPO INSURANCE SINGAPORE
50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

Registration No : SKC5858M

Chassis No : JHMRC1890GC202948

Model : ODYSSEY2.4 EXV-S 16YM NAVI-RES

Owner's Name : LIM CHAY LUNG CATHERINE

Ins Policy No. :

Date of Accident : 20/12/2018

Document No.	: SQT18005439	Page	2
Date	: 20. Dec 2018		
Customer No.	: WH023		
Svc Advisor	: RUEBEN THOMAS		
Engine No	: K24W72011313		
Date Time	: 20. Dec 2018 3:20:39 PM		
Surveyor Name	:		
Survey Date	:		
Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
44300-T6A-J51	BEARING ASSYFR.HUB 11	1	138.20	25	103.65	7.26	110.91
D-215/55R17SP270	DUNLOP TYRE 507	1	265.00	80% 212	265.00	18.55	283.55
				Sum Item	6620.82	463.49	7,084.31
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	✓	180.00	12.60	192.60
				Sum Ext. Service	180.00	12.60	192.60
BOSUN	SUNDRIES 20	1	50.00	20	50.00	3.50	53.50
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS 80	1	100.00	80	100.00	7.00	107.00
BOMISC1	REMOVE & RENEW RH WING MIRROR ASSY 11	1	320.00	X	320.00	22.40	342.40
BOMISC1	RESET VEHICLE SMART ENTRY SYSTEM (N) 300	1	320.00	300	320.00	22.40	342.40
BKDR12R	REMOVE & TRANSFER ITEMS TO NEW FR R DR. ADJUST ✓	1	350.00	✓	350.00	24.50	374.50
BKDR32R	REMOVE & TRANSFER ITEMS TO NEW RR R SLIDING DR ✓	1	450.00	✓	450.00	31.50	481.50
BMU12R	REMOVE & REPLACE FR R UNDERCARRIAGE PARTS (N) 171 X	1	560.00	171 X	560.00	39.20	599.20
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS. 580	1	1800.00	840	1800.00	126.00	1926.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) 450 X 5.5	1	2900.00	2475	2900.00	203.00	3103.00
				Sum Labor	6850.00	479.50	7,329.50

Survey By _____ mercury UHh
Date & Time _____ 21/12/18
Excess _____ ?
Status _____ Not Allowed
Signature _____ The phl. Bheraparty
6 day.

Total Amount	13,650.82	955.59	14,606.41
Total (Inclusive of GST)			14,606.41

- **Chlorophyll** is the green pigment that captures light energy
- **Photosynthesis** is the process by which plants use light energy to produce glucose and oxygen
- **Glucose** is a simple sugar that plants use for energy
- **Oxygen** is a gas that plants release into the atmosphere
- **Light energy** is the energy that comes from the sun
- **Water** is a liquid that plants use for photosynthesis
- **Carbon dioxide** is a gas that plants use for photosynthesis
- **Stomata** are small openings on the surface of leaves that allow gas exchange
- **Transpiration** is the process by which plants lose water vapor through their stomata
- **Roots** are the part of the plant that absorb water and nutrients from the soil
- **Leaves** are the part of the plant that perform photosynthesis and transpiration
- **Stems** are the part of the plant that support the leaves and roots
- **Flowers** are the part of the plant that produce seeds
- **Fruits** are the part of the plant that contain seeds
- **Seeds** are the part of the plant that can grow into new plants
- **Plants** are living organisms that can grow and reproduce
- **Animals** are living organisms that can move and eat
- **Humans** are animals that can think and use tools
- **Plants and animals** are part of the same ecosystem
- **Plants and animals** interact with each other
- **Plants and animals** depend on each other
- **Plants and animals** are part of the same food chain
- **Plants and animals** are part of the same community
- **Plants and animals** are part of the same environment
- **Plants and animals** are part of the same world
- **Plants and animals** are part of the same universe
- **Plants and animals** are part of the same everything

Printed on 21/12/2018 8:39:52 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line's)

9/1/2019

PAGE 1/2



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651, Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

ATTN: MARCUS CHUA

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

WD: 6 DAYS

Customer: WH023 / SOMPO INSURANCE
 Chassis No: JHMRC1890GC202948
 License No: SKC5858M
 Mileage: 19310
 Engine No: K24W72011313

Document No: SVO18076285
 Printed By: JESHURUEBEN
 Order Date: 21. December 2018
 Order Time: 12:08:51 PM
 Service Advisor: RUEBEN THOMAS

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	incld GST
	OWN DAMAGE CLAIMS-J/NO: 71878						
	POLICY/CLAIMS NO: D18MTPV01008162						
	OWNER: LIM CHAY LUNG CATHERINE						
	ACC DATE: 20/12/2018						
	SURVEYED BY: MARCUS CHUA (LKK)						
	DATE: 21/12/2018						
	AUTHORIZED ON: 22/12/2018						
	REF NO : CMTD1805618						
54206	EXTERNAL LABOUR SALES - INS. EXCESS	-1	800.00		-800.00	-56.00	-856.00
	SUM EXCESS:				-800.00	-56.00	-856.00
04711-T6A-900ZZ	FACE,FR.BUMPER	1	700.00	25	525.00	36.75	561.75
91505-TM8-003	CLIP,BUMPER	14	2.30	25	24.15	1.69	25.84
71193-T6A-003	SPACER,FR.BUMPER SIDE	1	11.80	25	8.85	0.62	9.47
71112-T6A-921ZA	SPOILER ASSY,FR.SIDE	1	94.40	25	70.80	4.96	75.76
71104-T6A-921	GARNISH,FR.BUMPER	1	46.10	25	34.57	2.42	36.99
33100-T6A-Q11	HEADLIGHT ASSY,WITH LED	1	2,281.90	25	1,711.42	119.80	1,831.22
60210-T6A-300ZZ	FENDER COMPR,FR.	1	548.60	25	411.45	28.80	440.25
72415-T6A-003	MOLDING ASSY,FR.CORNER	1	87.70	25	65.77	4.60	70.37
74100-T6A-000	FENDER ASSY,FR INNER	1	120.70	25	90.52	6.34	96.86
67010-T6A-000ZZ	PANEL COMPR,FR.DOOR	1	895.20	25	671.40	47.00	718.40
67325-T6A-J01	TAPE,R,FR.DOOR SA	1	37.30	25	27.97	1.96	29.93
67324-T6A-305ZA	TAPE SET,FR.DOOR SASH INNER	1	38.40	25	28.80	2.02	30.82
76208-T6A-Q03	MIRROR ASSY,R.SET	1	1,226.40	25	919.80	64.39	984.19
67510-T6A-J00ZZ	PANEL COMPR.SLIDE DOOR	1	1,000.50	25	750.37	52.53	802.90
67821-T6A-305ZA	TAPE SET,RR.DOOR SASH INNER	1	57.10	25	42.82	3.00	45.82
42700-T6A-J81	DISK ALUMINIUM WHEEL 17X7J	1	915.00	25	686.25	48.04	734.29
D-215/55R17SP270	DUNLOP TYRE	1	265.00	20	212.00	14.84	226.84
	SUM PARTS:				6,281.94	439.76	6,721.70
BOSUN	0760	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BML01I	EXT-YJ	1	80.00		80.00	5.60	85.60
	INSPECT FR LIGHTING MECHANISMS & FOCUS						
	HEADLIGHTS.(N)						
BOMISC1	EXT-YJ	1	300.00		300.00	21.00	321.00
	RESET VEHICLE SMART ENTRY SYSTEM (N)						
BKDR12R	EXT-YJ	1	350.00		350.00	24.50	374.50
	REMOVE & TRANSFER ITEMS TO NEW FR R DR. ADJUST & ALIGN FR R DR.(N)						
BKDR32R	EXT-YJ	1	450.00		450.00	31.50	481.50
	REMOVE & TRANSFER ITEMS TO NEW RR R SLIDING DR. ADJUST & ALIGN RR R SLIDING DR.(N)						
BKBH01S	EXT-YJ	1	840.00		840.00	58.80	898.80
	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.						
BP06R	EXT-YBH	1	2,475.00		2,475.00	173.25	2,648.25

**HONDA****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

**SERVICE PRE-INVOICE**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WH023 / SOMPO INSURANCE
 Chassis No: JHMRC1890GC202948
 License No: SKC5858M
 Mileage: 19310
 Engine No: K24W72011313

Document No: SVO18076285
 Printed By: JESHURUEBEN
 Order Date: 21. December 2018
 Order Time: 12:08:51 PM
 Service Advisor: RUEBEN THOMAS

SPRAY PAINTING ON REPAIRED OR
 REPLACED AREAS. (6P)

		SUM LABOUR:	4,515.00	316.05	4,831.05
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	12.60	192.60
		SUM EXT SERVICE:	180.00	12.60	192.60
		TOTAL SGD	10,175.94	712.41	10,889.35
Total Payable (SGD)					10,889.35

GST Amount is calculated from individual line(s)

Veron Chen (LKKAUTO)

From: Jeshurueben Rao Thomas <jeshurueben@honda.com.sg>
Sent: Wednesday, 9 January 2019 10:28 AM
To: Marcus Chua (LKKAUTO)
Cc: Admin-D (LKKAUTO); Admin A; Admin-B
Subject: Pre-Invoice Of Vehicle No: SKC5858M For Finalising
Attachments: 3254_001.pdf

Dear Marcus,

We enclosed the total final repair costs of...

Vehicle No. SKC5858M
Final Repair Costs (include GST) \$10,889.35 (AFTER DEDUCTION \$800 EXCESS)
Repair Period*(Working Day) 6 days
*Note: Repair period does not include Sunday And Public Holiday.

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thank You

Warmest Regards

Jeshurueben Rao Thomas (Rueben)
Bodyshop Service Advisor
Kah Motor Body Repair Centre
15, Ubi Road 4
Singapore 408610
Tel : 68465672
Hp : 90721766



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Dec 2018		21 Dec 2018 09:12 Edit Adj Rpt	\$10,976.94 Edit Estimates	\$10,976.94 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LIM CHAY LUNG CATHERINE , ID: S15144311, Tel: +6596398050, Email: c.goh@firsthiace.com									
Vehicle Reg. No.: SKC5858M		Date of Loss: 20/12/2018 11:00 - :59 [31 Months and 11 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / CMTD1805618		Policy/Cover Note No.: D18MTPV01008162 (Comprehensive)							
		Excess: S\$800.00							
Repairer: Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671									
Handling Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by NGO SAU WEI SHAWN - 6329 5202]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 03/01/2019]									
Driver/Custodian: LIM CHAY LUNG CATHERINE (57 / Female), NRIC: S15144311, Tel: +6596398050									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- SOMPO_SG (27/12/2018): Alert - Adj Mandate Approved (\$10973.32) - SKC5858M - Claim Handler: NGO SAU WE... - SOMPO_SG (27/12/2018): Alert - Adj Mandate Approved (\$11773.32) - SKC5858M - Claim Handler: NGO SAU WE...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKC5858M (CMTD1805618)
OD
Dec 20 2018 11:00AM
[LIM CHAY LUNG CATHERINE]
Kah Motor Co Sdn Bhd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View View in Browser

Video				1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail		Print
1	20/12/18 14:52	Video - Accident [Linked Accident Report Documents]	1 Load MP4		

Assessment Reports				1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail		Print
1	20/12/18 15:08	Accident Statement	1 Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail		Print
1	21/12/18 14:41	Adjuster Immediate Advice	1 Load HTM		

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail		Print
1	21/12/18 14:06	General View	1 Load JPG		☒
2	21/12/18 14:06	General View	1 Load JPG		☒
3	21/12/18 14:06	General View	1 Load JPG		☒
4	21/12/18 14:06	General View	1 Load JPG		☒
5	21/12/18 14:06	General View	1 Load JPG		☒
6	21/12/18 14:06	General View	1 Load JPG		☒
7	21/12/18 14:06	General View	1 Load JPG		☒
8	21/12/18 14:06	General View	1 Load JPG		☒
9	21/12/18 14:06	General View	1 Load JPG		☒
10	21/12/18 14:06	General View	1 Load JPG		☒
11	21/12/18 14:06	General View	1 Load JPG		☒
12	21/12/18 14:06	General View	1 Load JPG		☒
13	21/12/18 14:06	General View	1 Load JPG		☒
14	21/12/18 14:06	General View	1 Load JPG		☒
15	21/12/18 14:06	General View	1 Load JPG		☒
16	21/12/18 14:06	General View	1 Load JPG		☒
17	21/12/18 14:06	General View	1 Load JPG		☒
18	21/12/18 14:06	General View	1 Load JPG		☒
19	21/12/18 14:06	General View	1 Load JPG		☒
20	21/12/18 14:06	General View	1 Load JPG		☒
21	21/12/18 14:06	General View	1 Load JPG		☒
22	21/12/18 14:06	General View	1 Load JPG		☒
23	21/12/18 14:06	General View	1 Load JPG		☒
24	21/12/18 14:06	General View	1 Load JPG		☒
25	21/12/18 14:06	General View	1 Load JPG		☒
26	21/12/18 14:06	General View	1 Load JPG		☒
27	21/12/18 14:06	General View	1 Load JPG		☒
28	21/12/18 14:06	General View	1 Load JPG		☒
29	21/12/18 14:06	General View	1 Load JPG		☒
30	21/12/18 14:06	General View	1 Load JPG		☒

Video			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
				☒
31	21/12/18 14:06	General View	 Load JPG	☒
32	21/12/18 14:06	General View	 Load JPG	☒
33	21/12/18 14:06	General View	 Load JPG	☒
34	21/12/18 14:06	General View	 Load JPG	☒
35	21/12/18 14:06	General View	 Load JPG	☒
36	21/12/18 14:06	General View	 Load JPG	☒
37	21/12/18 14:06	General View	 Load JPG	☒
38	21/12/18 14:06	General View	 Load JPG	☒
39	21/12/18 14:06	General View	 Load JPG	☒
40	21/12/18 14:06	General View	 Load JPG	☒
41	21/12/18 14:06	General View	 Load JPG	☒
42	21/12/18 14:06	General View	 Load JPG	☒
43	21/12/18 14:06	General View	 Load JPG	☒
44	21/12/18 14:06	General View	 Load JPG	☒
45	21/12/18 14:06	General View	 Load JPG	☒
46	21/12/18 14:06	General View	 Load JPG	☒
47	21/12/18 14:06	General View	 Load JPG	☒
48	21/12/18 14:06	General View	 Load JPG	☒
49	21/12/18 14:06	General View	 Load JPG	☒
50	21/12/18 14:06	General View	 Load JPG	☒
51	21/12/18 14:06	General View	 Load JPG	☒
52	21/12/18 14:06	General View	 Load JPG	☒
53	21/12/18 14:06	General View	 Load JPG	☒
54	21/12/18 14:06	General View	 Load JPG	☒
55	21/12/18 14:06	General View	 Load JPG	☒
56	21/12/18 14:06	General View	 Load JPG	☒
57	21/12/18 14:06	General View	 Load JPG	☒
58	21/12/18 14:06	General View	 Load JPG	☒
59	21/12/18 14:06	General View	 Load JPG	☒
60	21/12/18 14:06	General View	 Load JPG	☒
61	21/12/18 14:06	General View	 Load JPG	☒
62	21/12/18 14:06	General View	 Load JPG	☒
63	21/12/18 14:06	General View	 Load JPG	☒
64	21/12/18 14:06	General View	 Load JPG	☒
65	21/12/18 14:06	General View	 Load JPG	☒
66	21/12/18 14:06	General View	 Load JPG	☒
67	21/12/18 14:06	General View	 Load JPG	☒
68	21/12/18 14:06	General View	 Load JPG	☒
69	21/12/18 14:06	General View	 Load JPG	☒
70	21/12/18 14:06	General View	 Load JPG	☒
71	21/12/18 14:06	General View	 Load JPG	☒
72	21/12/18 14:06	General View	 Load JPG	☒
73	09/01/19 16:27	Reinspection Photo	 Load JPG	☒
74	09/01/19 16:27	Reinspection Photo	 Load JPG	☒
75	09/01/19 16:27	Reinspection Photo	 Load JPG	☒
76	09/01/19 16:27	Reinspection Photo	 Load JPG	☒
77	09/01/19 16:27	Reinspection Photo	 Load JPG	☒
78	09/01/19 16:27	Reinspection Photo	 Load JPG	☒
79	09/01/19 16:27	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
80	09/01/19 16:27	Reinspection Photo	 Load JPG	☒
81	09/01/19 16:27	Reinspection Photo	 Load JPG	☒
82	09/01/19 16:27	Reinspection Photo	 Load JPG	☒
83	09/01/19 16:27	Reinspection Photo	 Load JPG	☒
84	09/01/19 16:27	Reinspection Photo	 Load JPG	☒
85	09/01/19 16:27	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	20/12/18 15:23	Certificate Schedule	 Load PDF	
2	21/12/18 09:08	Repair Estimates / E-File	 Load PDF	

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	20/12/18 14:52	Video - Accident	 Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	20/12/18 15:08	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	20/12/18 15:07	Accident Photo	 Load JPG	☒
2	20/12/18 15:07	Accident Photo	 Load JPG	☒
3	20/12/18 15:07	Accident Photo	 Load JPG	☒
4	20/12/18 15:07	Accident Photo	 Load JPG	☒
5	20/12/18 15:07	Accident Photo	 Load JPG	☒
6	20/12/18 15:07	Accident Photo	 Load JPG	☒
7	20/12/18 15:07	Accident Photo	 Load JPG	☒
8	20/12/18 15:07	Accident Photo	 Load JPG	☒
9	20/12/18 15:07	Accident Photo	 Load JPG	☒
10	20/12/18 15:07	Accident Photo	 Load JPG	☒
11	20/12/18 15:07	Accident Photo	 Load JPG	☒
12	20/12/18 15:07	Accident Photo	 Load JPG	☒
13	20/12/18 15:07	Accident Photo	 Load JPG	☒
14	20/12/18 15:07	Accident Photo	 Load JPG	☒
15	20/12/18 15:07	Accident Photo	 Load JPG	☒
16	20/12/18 15:07	Accident Photo	 Load JPG	☒
17	20/12/18 15:07	Accident Photo	 Load JPG	☒
18	20/12/18 15:07	Accident Photo	 Load JPG	☒
19	20/12/18 15:07	Accident Photo	 Load JPG	☒
20	20/12/18 15:07	Accident Photo	 Load JPG	☒
21	20/12/18 15:07	Accident Photo	 Load JPG	☒
22	20/12/18 15:07	Accident Photo	 Load JPG	☒
23	20/12/18 15:07	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	20/12/18 15:08	Accident Sketch Plan	 Load TIF	
2	20/12/18 15:08	Accident Sketch Plan	 Load TIF	

Video			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
3	20/12/18 15:08	certificate of insurance		Load TIF
4	20/12/18 15:08	insurer's nric & license		Load TIF
5	20/12/18 15:08	insurer's nric & license		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg No: 199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06, Singapore Land Tower
Singapore 048623

Our File No: CS/SMO18022883/UVD3E2

Date: 11/01/2019

REFERENCE

Insured/Claimant: LIM CHAY LUNG CATHERINE Policy No: D18MTPV01008162
Date of Loss: 20/12/2018 Nature of Claim: OD Claim No: CMTD1805618

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKC5858M**
Make & Model: HONDA ODYSSEY, 2.4 EXV-S CVT SR (A) Engine No: K24W72011313
Reg. Date: 09/05/2016 (Man. Year: 2016) Chassis No: JHMRC1890GC202948
Colour: Grey Odometer: 19310 km
Engine Capacity: 2356 cc
Market Value/New Car Price: S\$99,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 8 mm
Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,670.82	6,301.94	368.88	5.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,980.00	4,675.00	2,305.00	33.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,650.82	10,976.94	2,673.88	19.59
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	12,850.82	10,176.94	2,673.88	20.81
+ GST 7.00/7.00% (S\$)	899.56	712.39	187.17	20.81
Nett Amount (S\$)	13,750.38	10,889.33	2,861.05	20.81

INSPECTION

Date of Assignment: 21/12/2018
Date Inspected: 21/12/2018 Inspected At: Kah Motor Co Sdn Bhd (Ubi)
15 Ubi Road 4
Singapore 408610
Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Jan 2019)
Parts:	M1-SUV	HONDA ODYSSEY 2.4 EXV-S CVT SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKC5858M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE,FR.BUMPER	Distorted	525.00 FS	*525.00 FS
2	1		*CLIP, BUMPER (14PCS)	Necessary	24.15 FS	*24.15 FS
3	1		*SPACERL.FR.BUMPER SIDE	Not Necessary	8.85 FS	*- FS
4	1		*SPACERR.FR.BUMPER SIDE	Cracked	8.85 FS	*8.85 FS
5	1		*BEAMR.FR.BUMPER UPPER	Not Necessary	26.17 FS	*- FS
6	1		*SPOILER ASSYR.FR.SIDE	Cut	70.80 FS	*70.80 FS
7	1		*GARNISHR.FR.BUMPER	Grazed	34.57 FS	*34.57 FS
8	1		*HEADLIGHT ASSYR.WITH LED	Cracked	1,711.42 FS	*1,711.42 FS
9	1		*TANKWASHER	Not Necessary	53.17 FS	*- FS
10	1		*FENDER COMPR.FR.	Distorted	411.45 FS	*411.45 FS
11	1		*MOLDING ASSYR.FR.CORNER	Bent	65.77 FS	*65.77 FS
12	1		*GARNISHR.FR.FENDER	Not Necessary	24.82 FS	*- FS
13	1		*FENDER ASSYR.FR.INNER	Torn	90.52 FS	*90.52 FS
14	1		*ENCLOSURER.FR.FENDER	Not Necessary	19.72 FS	*- FS
15	1		*PANEL COMPR.FR.DOOR	Dented / Bent	671.40 FS	*671.40 FS
16	1		*TAPE,R.FR.DOOR SA	Necessary	27.97 FS	*27.97 FS
17	1		*TAPE SETR.FR.DOOR SASH INNER	Necessary	28.80 FS	*28.80 FS
18	1		*SET MIRROR ASSY,R.	Grazed	919.80 FS	*919.80 FS
19	1		*CAPR.SKULL	Repair	49.50 FS	*- FS
20	1		*PANEL COMPR.SLIDE DOOR	Dented / Bent	750.37 FS	*750.37 FS
21	1		*TAPE SETR.RR.DOOR SASH INNER	Necessary	42.82 FS	*42.82 FS
22	1		*DISK ALUMINIUM WHEEL 17X7J	Cut	686.25 FS	*686.25 FS
23	1		*BEARING ASSYFR.HUB	Not Necessary	103.65 FS	*- FS
24	1		*DUNLOP TYRE (80%)	Cut	265.00 FS	*212.00 FS
25	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
Total Parts (S\$)					6,670.82	6,301.94

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WHEEL ALIGNMENT X4	New	180.00	180.00
2	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	100.00	80.00
3	REMOVE & RENEW RH WING MIRROR ASSY	New	320.00	0.00
4	RESET VEHICLE SMART ENTRY SYSTEM	New	320.00	300.00
5	REMOVE & TRANSFER ITEMS TO NEW FR R DR. ADJUST	New	350.00	350.00
6	REMOVE & TRANSFER ITEMS TO NEW RR R SLIDING DR	New	450.00	450.00
7	REMOVE & REPLACE FR R UNDERCARRIAGE PARTS	New	560.00	0.00
8	STRAIGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS	New	1,800.00	840.00
9	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	New	2,900.00	2,475.00
Gross Labour Cost (S\$)			6,980.00	4,675.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >