

Surveyor:

REF: CS1/SPF18022884/B4bs2

Special Instruction:

P/P: \$ 6835.34

ASSIGNMENT (Office)

From (Person): Frankie Thay of SPF Date/Time: 20-12-2018

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: Priority Services

Workshop: MG Solution

OD/TP Re-inspection / (Evaluation)

To Inspect Vehicle No: SLR 7190B

Insured: Public Liability

at Workshop m/s MG Solution

Tel:

of 23 Kaki Bukit Ave 4 #02-03

Policy No:

Claim No: AEMD/105/009/2018/173

Sum Insured:

Excess:

Make of Veh:

D.O.A. 02-06-2018

(Client's Record)

Do Not Finalize

H.O.D. Enforcement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 5 days)

Date/Time: 26/12/18 Submit Final Fig 5246: 22, 2 days (Red \$ 15812, 23 %; Original 5 days)

Date/Time	Action/Instruction
	SLR 7190B - X
	Public Liability - X
	Range 5,000/2 - 6,000/2 (Repair Range)
	Duration of Repair 4.8 days
	RECEIVED 27 DEC 2018
	26/12/2018
	Tr Lim
	26/12/18

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

300

1) Date/Time 26/12/18 File Pass to Typist

3) Date/Time File Pass to

5) Date/Time File Pass to

2) Date/Time

4) Date/Time

6) Date/Time

File Return to

File Return to

File Return to



Catherine Chong <catherinechong90.cc@gmail.com>

RE: Post Survey for SLR 7190B

1 message

Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>

To: Catherine Chong <catherinechong90.cc@gmail.com>, assignments <assignments@lkkauto.com> 20 December 2018 at 14:27

Cc: "Olivia Lau (LKKAuto)" <olivialau@lkkauto.com>

Your reference : SLR7190B

Our reference : AEMD/105/009/2018/173

Catherine,

Please conduct a post survey for vehicle SLR7190B and provide assessment with upper range repair cost.

Thanks.

Frankie Thay (Mr)
Safe Driving Manager

Automotive Engineering & Management Division

Police Logistics Department

Singapore Police Force

DID: (65) 6478 4841 | FAX: (65) 6478 4848

**HOME TEAM**
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

3 attachments **2018-173 GIA.pdf**
2506K **2018-173 PHOTOS FOR SLR7190.pdf**
14121K

12/21/2018

Gmail - RE: Post Survey for SLR 7190B



2018-173 SURVEY FOR SLR7190.pdf
2775K

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/06/2018 15:14
Date Of Accident	02/06/2018 10:40
Exact Location Of Accident	PREMISES NO22 ORANGE GROVE RDSHANGRI-LA HOTEL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR7190B
Insured/Policyholder	
Name Of Registered Owner	GURPREET KAUR D/O JAGJIT SINGH
NRIC No	S8511539A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92366788
Alternative Phone No	OTHERS-92366788

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	CLA180-1.6 AMG (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA260687/1
Cover Note Number	

Driver

Name of Driver	AARVIN GIOVANNI
NRIC No	S8119145Z
Date Of Birth	25/06/1981
Occupation	INDOOR
Date Of Driving Pass	20/12/2010
Driving Experience	7 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81109145
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

BLK 863 TAMPINES STREET 83 #10-490

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured SPOUSE

Vehicle Registration Number of Driver's Own Vehicle

-
-
-
-
-

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

HIT BY FALLEN TREE / OTHER OBJECTS

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? NO

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 3

Passenger 1

NAME: : GURPREET KAUR D/O JAGJIT SINGH

GENDER: : FEMALE

Passenger 2

NAME: : BABY

GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name

TAMPINES NEIGHBOURHOOD POLICE CENTRE

Police Station Address

ROAD: 6 TAMPINES AVE 4 , POSTCODE: 529682 , COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-5871999 - FAX NO: 65871699

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN/POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Officer.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of the report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (a) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for the purpose(s) of the above Purpose(s);
 - (b) my Personal Information may/are disclosed to all of the Insurers and/or GIA to facilitate some sort of processing or operation relating to my vehicle, my personal information, my vehicle(s) involved in this accident and the above Purpose(s);
 - (c) my Personal Information may/are collected and used to compile all the necessary forms and/or data for the Insurers' Records Management Centre and/or for the GIA;
 - (d) my Personal Information may/are used to assist in the investigation of the accident;
 - (e) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulations, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (f) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature:
Date & Time:

Driver's Signature:
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: J. K. Lim
NRIC/ID No.: S7040331A

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

attached Report No. 9/20180602/2151

DECLARATION

We declare the foregoing particulars are true and correct.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name: J. L. L. L.
NRIC No: 224037711

Police Report



SINGAPORE
POLICE FORCE



G/20180602/2131

1 of 2

POLICE REPORT (NP299)

Report No. G/20180602/2131

Police Station Of Origin
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

Date/Time Report Made 02/06/2018 19:53	Vide Report No. E/20180602/0113	Station Diary No. 94
Name Of Informant AARVIN GIOVANNI	Address APT BLK 863 TAMPINES STREET 83 #10-490 SINGAPORE 520863	
ID Type / ID No. NRIC NO / S8119145Z	Contact No. Home/Office Mobile 81119145	
Nationality SINGAPORE CITIZEN	Email Address	
Occupation PRIVATE BANKER	Sex Male	Age 36
Institution/School Name	Date of Birth 25/06/1981	Race Sikh
Date/Time Of Incident 02/06/2018 10:40	Location Of Incident 22 ORANGE GROVE ROAD SHANGRI-LA HOTEL SINGAPORE 258350	

Brief details.

On 02/06/2018, I drove into (SLR7190B) Shangri-La Hotel and there were a few security pit stops. I went through the screening point twice as I was searching for the car park. As I was about to turn into the car park, a crash barrier suddenly elevated and lifted the mid-portion of my vehicle. My wife (Gurpreet Kaur D/O Jagjit Singh, S8511539A) and 18-month old daughter were also inside the vehicle. We managed to exit from the vehicle ourselves and we were not injured.

Signature Of Officer Recording The Report: G / Sgt 3 SOPHIA SIM SHI MEI	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 02/06/2018 19:53
Officer In-Charge Of Case: TANGLIN POLICE DIVISION ONG ZHIWEI Contact No.: 63914697	Classification Of Case:

Authentication Stamp

Police Report



SINGAPORE
POLICE FORCE



G/20180602/2131

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20180602/2131

Subsequently, the police officers who were already deployed at the location came over and attended to the scene. I was told by the officers that there were CCTVs installed at the vicinity.

There were damages underneath my vehicle which I am not able to assess the full extent of the damages, and my vehicle's right skirting came off.

I was given a police note by Investigation Officer Ong Zhiwei (Incident number: E/20180602/0113, Email: Ong_Zhiwei@spf.gov.sg, Tel: 63914697 / 1800-3910000) of Tanglin Division HQ and advised to lodge a police report if I require it for insurance claim purpose.

In addition, IO Ong Zhiwei also mentioned that he will be looking into the matter and be rest assured that the invoice can be forwarded to Kerk_Teck_Long@spf.gov.sg for payment thereafter.

Signature Of Officer Recording The Report: G / Sgt 3 SOPHIA SIM SHI MEI	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 02/06/2018 19:53
Officer In-Charge Of Case: TANGLIN POLICE DIVISION ONG ZHIWEI Contact No.: 63914697	Classification Of Case:
Authentication Stamp 	



PRIORITY SERVICES

Insurance Loss Adjusters And Motor Appraisers
Block 779 Yishun Avenue 2 #01-1545 Singapore 760779
Tel : 62934822 Fax : 62963283

Messrs. Gurpreet Kaur D/O Jagjit Singh
Block 863, #10-490
Tampines Street 83
Singapore 520863

Bill No. DN/TP/18/0099/MG
22/06/2018

Dr.

To

Survey Fee (S \$) :

Photographs (S \$) :

Transport (S \$) :

Resurvey (S \$) :

Site-Survey (S \$) :

Services rendered including photographs and transport charges

(S \$) 458.00

Our reference : TP/0073/18

Insured :

Policy / Cert. No. :

Your Claim No. : Third Party Claim

Vehicle : Mercedes Benz CLA 180 AMG (A) - SLR 7190 B

Dollars : Four Hundred Fifty Eight Only

Checked by

for PRIORITY SERVICES

E. & O. E.

Only our official receipt will be recognised for payment made on this account



PRIORITY SERVICES

Insurance Loss Adjusters And Motor Appraisers

Block 779 Yishun Avenue 2 #01-1545 Singapore 760779

Tel : 62934822 Fax : 62963283

VEHICLE INSPECTION REPORT

Report No. TP/0073/18	Date of Report	: 22 June 18
To : Gurpreet Kaur D/O Jagjit Singh	Date of Request	: 7 June 18
	Report requested by	: Gurpreet Kaur D/O Jagjit Singh
Block 863, #10-490	Date of Accident	: 2 June 18
Tampines Street 83	Date of Inspection	: 7 June 18
Singapore 520863	Claim No.	: Third Party Claim

PARTICULARS OF DAMAGED VEHICLE

Registration Plate No	: SLR 7190 B	Odometer Reading	: 9,688 km
Make	: Mercedes Benz	Carrying Capacity	: 4
Model	: CLA 180 AMG (A)	Radio / Cassette / CD	: Yes
Year of Manufacture	: 2017	Air-Conditioner	: Yes
Colour	: Metallic Black	Wing Mirror	: Yes
Engine Capacity	: 1,595 cc	Clock	: Yes
Engine No	: --	Seat Belts	: Yes
Chassis / Frame No	: WDD1173422N496929	Others	: Nil

TYRE CONDITION

Front Left	: 9mm	Front Right	: 9mm
Make	: Continental	Make	: Continental
Rear Left	: 9mm	Rear Right	: 9mm
Make	: Continental	Make	: Continental
Spare	:	Road Wheels Type	: Alloy

(The above represents the approximate remaining life of tyre treads)

Jack & Tools	: Intact	Spare Tyre	: No
--------------	----------	------------	------

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Body Work	: Good
Paint Work	: Good
Handbrake	: Serviceable
Footbrake	: Serviceable
Steering	: Serviceable
Apparent engine modification	: Nil

This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore.

ASSESSMENT

	<u>Repairer's Estimate (S \$)</u>	<u>Our Recommendation (S \$)</u>
Spare Parts :	5,615.86	5,385.34
Labour Charges :	2,350.00	600.00 1,200.00
Paint Work :	1,000.00	100.00 250.00
Towing Charges :	0.00	0.00
Others :	0.00	0.00
Totals :	8,965.86	6,835.34

Reduction (S \$) : 2,130.52

Recommended Reserve (S \$) : 6,835.34

Estimated Normal Period of Repairs : 5 working days

CONTRIBUTIONS BY INSURED

Excess (S \$) : N/A

Others : --

Duration of Repairs 4 days

*TCM
26/12/18*

GENERAL REMARKS

WITHOUT PREJUDICE

Continuation Sheet

The Assignment

The survey was conducted at MG Solution Pte Ltd, 23, Kaki Bukit Avenue 4, (South Wing) #02-03, Singapore 415933.

Point of Impact

At the front underside, stretching towards the rear.

Damages

The front bumper under cover, engine under cover, front side undercarriage covers, RH side skirt, rear RH wheel cowling, exhaust silencer, etc.

Other parts were also found damaged. (see schedule for details)

Adjustment / Recommendation

We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle and we list the breakdown of our findings and our recommendation as per schedule attached.


Our adjusted amount for the cost of repairs is \$6,835.34


Conclusion

The repairer has agreed to undertake repairs at our adjusted amount of \$6,835.34 corresponding to labour charges, spray painting and replacement of parts.

We now revert to you for your decision on repairs.

Very truly yours
PRIORITY SERVICES


JIMMY S. T. LEE AMSOE, AMIRTE, AMSAE-AUS, MSAAA
Motor Appraiser


LAWRENCE NG
Motor Appraiser

Encl. Photographs of the damaged vehicle taken by us during inspection.

Replacement of Parts	Condition	Repairer's Estimate (S S)	Dist.%	Our Recommendation (S S)	Dist.%
To Supply :					
1pc. Front bumper under cover	Cracked	280.00	10	280.00	ACT✓10
1pc. Engine under cover	Cracked	385.20	10	385.20	ACT✓10
2pcs. Front undercarriage covers R/L 1pc	Cracked	490.60	10	237.34 490.60	CRA✓10
1pc. Side skirt RH	Broken / Dislodged / Missing	1,306.50	10	1,306.50	MIS✓10
1pc. Side skirt rubber stopper	Broken / Dislodged / Missing	85.00	10	85.00	MIS✓10
1pc. Rear wheel cowling RH	Cracked	235.10	10	235.10	CRA✓10
1pc. Exhaust pipe	Dented	2,680.20	10	1890.00 2,680.20	DD✓10
2pcs. Exhaust pipe connectors	Necessary	360.00	10	360.00	NEC✓10
1pc. Exhaust pipe insulator	Dented / Repair	222.80	10	--	10
Sub-Total :		6,045.40		5,822.60	
Total Discount :-		604.54		582.26	
		5,440.86		5,240.34	
Special Nett Items :-					
1set. Bumper under cover clips	Necessary	30.00		30.00	NEC✓
1set. Engine under cover clips	Necessary	25.00		25.00	
1sets. Undercarriage under cover clips	Necessary	60.00		60.00	NEC✓
1set. Side skirt clips	Not Necessary	30.00		--	
1set. Rear wheel cowling clips	Necessary	30.00		30.00	NEC✓
Total For Parts :-		5,615.86		5,385.34	
Labour Charges :					
Panel beating, removing & replacing parts.		1,000.00		400.00 600.00	
Remove & refix rear exhaust pipe.		550.00		250.00	
Labour for cutting & replacing exhaust pipe reconnection.		800.00		200 350.00	
Pray Painting :					
Pray painting to affected areas.		1,000.00		200.00 250.00	
Grand Total :-		8,965.86		6,835.34	

Surveyed By : Lawrence Ng



Your Ref: AEMD/105/009/2018/173

Date: 28th December 2018

Our Ref: CS1/SPF18022884/Btbs2

M/s Automotive Engineering & MGT Division

Accident Claim Section

(Spore Police Force)

1 Mount Pleasant Road

Blk 8 Old Police Academy

Singapore 298333

(The Motor Claims Department)

Attn: Frsnkie Thay

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SLR 7190B INSURED VEHICLE: PUBLIC LIABILITY ACCIDENT DATE: 02/06/2018**

We thank you for your instruction on 20/12/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLR 7190B from M/s Priority Services.
- b) Singapore Accident Statement of Vehicle SLR 7190B.
- c) Colour damaged vehicle photographs of SLR 7190B.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLR 7190B
Make & Model	: Mercedes Benz CLA 180 AMG (A)
Year of Registration	: 2017
Chassis Number	: WDD1173422N496929
Engine Capacity	: 1595 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 7190B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER UNDER COVER	CUT	280.00	280.00
1	ENGINE UNDER COVER	CUT	385.20	385.20
2	FRONT UNDERCARRIAGE COVERS R/L	CRACKED 1PC ONLY	490.60	237.34
1	SIDE SKIRT RH	MISSING	1,306.50	1,306.50
1	SIDE SKIRT RUBBER STOPPER	MISSING	85.00	85.00
1	REAR WHEEL COWLING RH	CRACKED	235.10	235.10
1	EXHAUST PIPE	DENTED	2,680.20	1,890.00
2	EXHAUST PIPE CONNECTORS	NECESSARY	360.00	360.00
1	EXHAUST PIPE INSULATOR	TO REPAIR SEE LABOUR	222.80	-
	LESS 10% DISCOUNT		-604.54	-477.92
			5,440.86	4,301.22
SPECIAL NETT ITEMS				
1	SET BUMPER UNDER COVER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET ENGINE UNDER COVER CLIPS (SN)	NECESSARY	25.00	25.00
2	SETS UNDERCARRIAGE UNDER COVER CLIPS (SN)	NECESSARY	60.00	60.00
1	SET SIDE SKIRT CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET REAR WHEEL COWLING CLIPS (SN)	NECESSARY	30.00	30.00
			175.00	145.00
LABOUR				
	PANEL BEATING, REMOVING & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF EXHAUST PIPE INSULATOR.		1,000.00	400.00
	REMOVE & REFIX REAR EXHAUST PIPE. }		550.00	200.00
	LABOUR TO CUTTING & REPLACING EXHAUST PIPE RECONNECTION. }		800.00	-
	SPRAY PAINTING TO AFFECTED AREAS.		1,000.00	200.00
			3,350.00	800.00
GRAND TOTAL			8,965.86	5,246.22
RECOMMENDED COST OF REPAIRS				5,246.22

Report Ref No. CS1/SPF18022884/Btbs2



Report Ref No. CS1/SPF18022884/Btbs2

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

LIM TEOW GUAN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.