



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 20/12/2018

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS ; REPAIR REAR ENGINE DOOR PANEL , REAR ENGINE DOOR STRUC	\$2,120.00	
Total Labour	\$2,120.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$728.00	
Total Spray Painting & Panel Beating	\$728.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			STICKER SMRT	1.00	\$200.00	0.00	\$200.00	Replace NEC	/
6009999	BODY LH	A01001-CW555	PANEL, SIDE L5, FOR MAN A22 BUS	1.00	\$1,776.80	10.00	\$1,599.12	Replace DI	/
	DOOR	GV124M03	RUBBER, EXIT DOOR FOR MAN A22 BUS	1.00	\$750.00	10.00	\$675.00	Replace DEF	/
	DOOR	GV124M03	RUBBER, EXIT DOOR FOR MAN A22 BUS	1.00	\$750.00	10.00	\$675.00	Replace SCR	/
6010001	BODY LH	A01001-CW557	PANEL, SIDE L7, FOR MAN A22 BUS	1.00	\$330.70	100.00	\$0.00	Repair	/
6010002	BODY LH	A01001-CW558	PANEL, SIDE L8, FOR MAN A22 BUS	1.00	\$330.70	100.00	\$0.00	Repair	/
6010004	BODY LH	A01001-GW560	PANEL, SIDE L10, W/ FRAME, FOR MAN A22 BUS	1.00	\$980.40	100.00	\$0.00	Repair	/
4006313	CONSUMABLE	SIKA® Primers 206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace NEC	/
4006314	CONSUMABLE	Sikaflex-265	ADHESIVE DIRECT GLAZING	10.00	\$37.00	0.00	\$370.00	Replace NEC	/
Total					\$5,235.60		\$3,599.12		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 20/12/2018

User ID : BoonChewTay

Section A - Accident Details	
Registration Number	SMB1540L
Case Reference Number	BUS/12/18/1024
Registration Date	12/12/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Lou Weibin
Type of Accident	Head To Side
Accident Date and Time	16/12/2018 10:10 AM
Accident Reported Date and Time	16/12/2018 12:15 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1540L - LEFT CENTRE TO REAR PORTION SBB788B (TP) AIG- FRONT LEFT PORTION
Prepared Date and Time	20/12/2018 10:57 AM
Chassis Number	WMAA22ZZ3E7002421
Mileage	
Work Shop	
Repair Completion Date and Time	

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - Summary of Repair Estimates		
Summary of Repair Estimates	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,420.00 1590 /	\$0.00
Total Spray Cost	\$720.00 616 /	\$0.00
Total Spare Part Cost	\$2,879.30	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$5,727.30	\$0.00
Lump Sum Total	\$5,750.00	\$0.00
Number of Repair Days	20 4	
Prepared / Adjusted By	Boon Chew Tay	Hwee jie
ARC / Surveyor Sign Off Date	20/12/2018 11:24 AM	
Signature		Hwee Jie - LKK 20/12/18 @1630
Remarks		

91803151
hweejie@lkkauto.com

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	