


SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A: SHD 1569D

B: CB 6477Y

*[A large diagonal line is drawn across the remaining lines of this section.]*

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Handwritten signature]*

81799458A

20 DEC 2018

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

*[Handwritten signature]*

**Describe Circumstance of the Accident.**

**ON 20/12/2018 @ 0520HRS, I WAS DRIVING MY TAXI ( SHD 1569 D ), TRAVELLING ALONG THE TRAFFIC LIGHT JUNCTION OF TAMPINES AVE 5 & TAMPINES AVE 1 & AVE 2 WITH A PASSENGER ONBOARD, IN THE LEFT LANE.**

**I STOPPED MY TAXI AS TRAFFIC LIGHT WAS RED AT THE POINT OF TIME.**

**WHILE STATIONARY FOR MORE THAN 10SECONDS, SUDDENLY I FELT AN IMPACT FROM THE REAR.**

**WHEN INSPECTED, I DISCOVERED THAT VEHICLE B ( CB 6477 Y – PTE BUS ) WHICH WAS BEHIND ME, HAD COLLIDED ONTO THE REAR OF MY TAXI.**


**DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE REAR PORTION AND VEHICLE B HAD DAMAGES ON THE FRONT PORTION.**

**AS A RESULT, I FELT SOME DISCOMFORT & WILL SEEK FOR MEDICAL TREATMENT SOON. NO AMBULANCE AT SCENE.**

**VEHICLE B HAD SOME WORKERS ONBOARD.**

**\*VIDEO FOOTAGE CAPTURED & SCENE PHOTOS TAKEN.**

**AMAGES FOUND ON VEHICLE A & VEHICLE B**



**Driver's Signature & NRIC Number**

**@ 9:21:53 AM**

**( attended by**

**S1799458A**