

ASS. REC. BY:

REF:

CS/AIG18022935/And3ⁿ²

Special Instruction:

Surveyor:
Munnen

Adrian

4119 1026

ASSIGNMENT (Office)

From (Person): Azlan Syazairina of

AIG

Date/Time: 21/12/18 @ 3:53pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH 1378M

Insured:

SV 1297U

at Workshop m/s

MCS Garage

Tel:

9270 0917 / Ah. Hock

of

10 kaki Bukit Rd 2 # 03-25 First East Centre

8285 7623

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/12/18

CA / REV / REP. / REV 24 HRS ^{1up}

H.O.D. Endorsement:

Date/Time: 4:19pm @ 21/12/18

Person Contacted:

Kendrick

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBH 1378M-X

SV 1297U-X

15/1/19

@ 1:06pm Ah Hock said don't want do D/S, pass to lawyer

17/1/19

Adrian confirmed LS \$5000 (Red 9684.99, 66%)

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Vehicle: IN / OUT

Date:

Person Contacted:

D.O.A.

06

D.O.A.

D.O.I.

21/12/18

Survey held at

MCS Garage

Des. of Damages: Frt / Rear (O/S) / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP AIG.

COE Expiry: 31/08/22.

5.5 x 3.5 x 1.9K

MV: 1.9K. (Depreciation 55K per annum).

PV: 1.32K.

Nett: 5.8K.

RECEIVED 17 APR 2019

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

7

8776E.

1)

☐

Final Report

Resurvey No. of Trip:

2

Survey Fee:

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$)

Transportation:

) \$ + RS. SI

) Photos

) Others

Report Format:

Lump Sum / I.B.I. (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

TOTAL

250
10

260