

20000000

ASK REC BY

REP 05/SMO18022968/Used301

General Instruction

SURVEYOR
Merimen

Marus

ASSIGNMENT (Office)

From (Person)

Chun Shui hui agnes

of

SMO

Date/Time

24/12/18 @ 9:32am

Estimated Cost

Bill to

OD

TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKU 4777A

Insured:

at Workshop w/s

Autolution

Tel:

96450079

of

19 ubi Road 4

Policy No:

D18MTpro1012043

Claim No:

CM1D180563

Sum Insured:

Excess:

0

Make of Veh:
(Client's Record)

D.O.A

20/12/2018.

CA /

REV

REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time

9:37am @ 24/12/18

Person Contacted:

Hamzah

Vehicle

IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKU 4777A - X
24/12/18	@ 17:53p.m. revised IA to Agnes chas via merimen.
24/12/18	@ 17:54 p.m. mandate requested authorize repair to Agnes Chas via merimen.
26/12/18	Rec approved from Agnes via merimen
27/12/18	Informed Hamzah c/A on IBI not exceeding \$14,000; ex \$0 by email

REF: SMO

ASSIGNMENT

From: Date 24/12/18

Estimated Cost

JD / P / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No. SKU 4777A

at Workshop no. Autolution
19 Ubi Road 4

Insured

Policy No

Claims No

Sum Insured Excess: 7BA

(Client's Record)

Makes of Veh: Before 1pm
stunzah

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

NIS	O/S

Bal. or Market Value: 75/2

IDAC Accident Report Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 10 days Res: Yes or No

Lump Sum: 1.9% 3 Val: Yes or No

CA (REV) REP. 24 HRS LTA 60222
Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKU 4777A Reg: 7.15

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: NISSAN X-trail cc 1997

Colour: Orange A/C Insured / Std / NI / NA

Sp. Reading: 63461 T/Radio: Insured / Std / NI / NA

Eng/No

C/N: JN1JANT3280000663

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/60 R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 8 mm R/Bal: 8 mm

L/Bal: 8 mm L/Bal: 8 mm

D.O.A: 20/12/18 D.O.I: 24/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Front N/S, O/S, Body & The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	6 yrs. rule. net 14778 cost plus 10% Gear box housing cracked limited repair cost no markup with
13/02/19	Continued r/p \$ 14,774.10 @ 10 days with Marcus (E 2,716.70 red 16%)

RECEIVED 22 FEB 2019

Date/Time: File Pass to?

22/02/19

1) Typist
Date/Time: File Returns to?

Prelim. Report

Final Report

Days Of Repair: 10

Resurvey No. of Trip: 3

Survey Fee:

Transportation

S + RE: \$

Photos

Other:

1012

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Insp (\$)

Weekend (\$)

Report Format :

Lump Sum / L.B.I: (\$) 14,774.10 r/p

450
10
460

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Dec 2018		24 Dec 2018 09:32 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	HUANG HUIBIN SYLVIA, ID: S8440832H, Tel: +6598274873, Email: sylvia.globetrekker@gmail.com		
Vehicle Reg. No.:	SKU4777A	Date of Loss:	20/12/2018 15:00 - :59
Claim Type:	OD / CMTD1805632	Policy/Cover Note No.:	D18MTPV01012043 (Comprehensive)
		Excess:	
Repairer:	Autolution Industrial Pte Ltd (Ubi) 19 Ubi Road 4, 408623 Ubi - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/01/2019]		
Driver/Custodian:	HUANG HUIBIN SYLVIA (34 / Female), NRIC: S8440832H, Tel: +6598274873		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0832H
Vehicle Details	
Vehicle No.:	SKU4777A
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Dec 2018
Vehicle Make:	NISSAN
Vehicle Model:	X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR
Primary Colour:	Orange
Manufacturing Year:	2015
Engine No.:	MR20725011B
Chassis No.:	JN1JANT32Z0000663
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$21,934.00
Original Registration Date:	29 Jul 2015
First Registration Date:	29 Jul 2015
Transfer Count:	0
Actual ARF Paid:	\$22,708.00 <i>11 354</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jul 2025
PARF Rebate Amount:	\$17,031.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jul 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$65,501.00
COE Rebate Amount:	\$43,191.00
Total Rebate Amount:	\$60,222.00

The information contained herein is correct as at 24 Dec 2018

OK



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Audi A4 2.0A TFSI Quattro S-Tronic.



Low Mileage, Immaculate Condition, Cheapest In Town, High Paper Value.
Direct Owner StarAd

PRIME MOTOR & LEASING
SHOW YOUR OWN DOCUMENTS (P&ID) GROUP OF COMPANIES
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

Sort by Date Posted 20 results/page

7 vehicles

Nissan X-Trail

Advanced Search Submit

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Nissan X-Trail		Any	Any	2015	Any	Any	Any	Available
	Nissan X-Trail 2.0A	\$81,800	\$11,130 /yr	31-Mar-2015	1,997 cc	48,800 km	SUV	Available
1 Owner Unit, Full Tan Chong Agent Service History. Beautifully Maintained. Low Mileage. Buy With An Added Peace Of Mind From Vantage Pre-owned, A Member Of The Sims Darby Group. Complete With A Compr... Vantage Pre-Owned Posted: 24-Dec-2018 Tags: 2015 Nissan X-Trail, 2015 nissan x-trail, Nissan X-Trail, nissan x-trail, Nissan, X-Trail, x-trail, Used Nissan								
	Nissan X-Trail 2.0A Premium 7-Seater	\$79,888	\$10,300 /yr	19-Aug-2015	1,997 cc	51,448 km	SUV	Available
\$0 Drive Away Available! \$1500 Servicing Credit. 160 Points Check Done. Agent Maintained Since Day 1. Warranty Till August 2018. Beautiful Interior With Smooth Running Gearbox And Engine. Massive Savi... Incharge Pre-Owned Posted: 22-Dec-2018 Tags: 2015 Nissan X-Trail, 2015 nissan x-trail, Nissan X-Trail, nissan x-trail, Nissan, X-Trail, x-trail, Used Nissan								
	Nissan X-Trail 2.0A Premium 7-Seater	\$77,800	\$9,840 /yr	23-Sep-2015	1,997 cc	-	SUV	Available
Pearl White Beauty! Currently 1 Of The Lowest Price In The Market Despite Its Near Perfect Condition. Spacious 7 Seater SUV. Fully Original Condition. Very Well Equipped Unit With Original GPS, Keyless... Posted: 21-Dec-2018 Tags: 2015 Nissan X-Trail, 2015 nissan x-trail, Nissan X-Trail, nissan x-trail, Nissan, X-Trail, x-trail, Used Nissan								
	Nissan X-Trail 2.0A 7-Seater	\$80,800	\$10,670 /yr	26-Jun-2015	1,997 cc	60,000 km	SUV	Available
Well Maintained By Owner, Original Paint, Clean And Beautiful Exterior And Interior, High Loan Available, Please Call Our Friendly Sale For More Info On Car And Loan. Posted: 21-Dec-2018 Tags: 2015 Nissan X-Trail, 2015 nissan x-trail, Nissan X-Trail, nissan x-trail, Nissan, X-Trail, x-trail, Used Nissan								
	Autoaid Pte Ltd - Repair & Servicing Specialises in servicing and repairing of Nissan make vehicles especially in engine overhaul. More info about this shop							
	Nissan X-Trail 2.0A Premium 7-Seater	\$76,800	\$9,470 /yr	26-Nov-2015	1,997 cc	63,123 km	SUV	Available
One Owner With Warranty From Agent. Car Like New. High Trade In And High In House Loan Available. Posted: 15-Dec-2018 Tags: 2015 Nissan X-Trail, 2015 nissan x-trail, Nissan X-Trail, nissan x-trail, Nissan, X-Trail, x-trail, Used Nissan								
	Nissan X-Trail 2.0A Premium 7-Seater	\$77,800	\$9,760 /yr	14-Oct-2015	1,997 cc	45,000 km	SUV	Available
X-Trail Give A Far Sexier Alternative To A People Carrier And Appealing Enough 7s Family Car, Multi Functional SUV With 3rd Row Seats.Features Include Selectable 2 Wheel Or 4 Wheel Drive For The Ultim... Compare Car Buyers Automotive Pte Ltd								

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 22 February 2019 1:41 PM
To: 'Hamzah'
Cc: Admin A; Admin-D (LKKAuto); Marcus Chua (LKKAuto)
Subject: RE: SKU4777A - Final repair copy

Dear Hamzah,

Confirmed final fig \$ 14,774.10 @ 10 days of repairs before excess \$0/- & GST.

Final invoice and all supporting documents sent over to Sompo Insurance Singapore Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hamzah [mailto:hamzah_saad@tanchong.com]
Sent: Tuesday, 12 February 2019 4:21 PM
To: Marcus Chua (LKKAuto) <MarcusChua@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Subject: Re: SKU4777A - Final repair copy

Finalise re-send.

Regards

Hamzah Sa'ad
Service Supervisor
Autolution Industrial Pte Ltd
19 Ubi Road 4
S408623
TEL: +65 67038680 DID: +65 67038690 FAX: +65 68467483
Hp: +65 96450079 Email: hamzah_saad@tanchong.com

From: Hamzah
Sent: Tuesday, February 12, 2019 3:23:57 PM
To: Marcus Chua (LKKAuto)
Cc: Admin A; Catherine Chong (LKK Auto)
Subject: SKU4777A - Final repair copy

Bro,

Veron Chen (LKKAuto)

From: Hamzah <hamzah_saad@tanchong.com>
Sent: Tuesday, 12 February 2019 4:21 PM
To: Marcus Chua (LKKAuto)
Cc: Admin A; Admin-D (LKKAuto)
Subject: Re: SKU4777A - Final repair copy
Attachments: sku4777a-finalise 201218.pdf

Finalise re-send.

Regards

Hamzah Sa'ad
Service Supervisor
Autolution Industrial Pte Ltd
19 Ubi Road 4
S408623
TEL: +65 67038680 DID: +65 67038690 FAX: +65 68467483
Hp: +65 96450079 Email: hamzah_saad@tanchong.com

From: Hamzah
Sent: Tuesday, February 12, 2019 3:23:57 PM
To: Marcus Chua (LKKAuto)
Cc: Admin A; Catherine Chong (LKK Auto)
Subject: SKU4777A - Final repair copy

Bro,

Attachment final repair copy and supplementary.

Kindly revert for invoicing.

Regards

Hamzah Sa'ad
Service Supervisor
Autolution Industrial Pte Ltd
19 Ubi Road 4
S408623
TEL: +65 67038680 DID: +65 67038690 FAX: +65 68467483
Hp: +65 96450079 Email: hamzah_saad@tanchong.com

Veron Chen (LKKAuto)

From: Hamzah <hamzah_saad@tanchong.com>
Sent: Thursday, 27 December 2018 9:13 AM
To: Veron Chen (LKKAuto); SUR
Subject: Re: SKU 4777A-DOA: 20/12/2018 (SOMPO OD)

Dear Veron,

Thanks you.

Regards

Hamzah Sa'ad
Service Supervisor
Autolution Industrial Pte Ltd
19 Ubi Road 4
S408623
TEL: +65 67038680 DID: +65 67038690 FAX: +65 68467483
Hp: +65 96450079 Email: hamzah_saad@tanchong.com

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Thursday, December 27, 2018 8:47:35 AM
To: Hamzah; SUR
Subject: SKU 4777A-DOA: 20/12/2018 (SOMPO OD)

Dear Hamzah,

As instructed by our client, please proceed to repair the insured vehicle **SKU 4777A not exceeding part by part \$14,000/- or which ever lower (Excess \$0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 27 December 2018 8:48 AM
To: hamzah_saad@tanchong.com; SUR
Subject: SKU 4777A-DOA: 20/12/2018 (SOMPO OD)

Dear Hamzah,

As instructed by our client, please proceed to repair the insured vehicle **SKU 4777A not exceeding part by part S14,000/- or which ever lower (Excess S0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SKU4777A (CMTD1805632)**
OO
Dec 20 2018 3:00PM
[HUANG HUIBIN SYLVIA]
Autolution Industrial Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Sompo Insurance Singapore Pte. Ltd. (SOMPO_SG), sent on 21/02/2019 12:39 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$14774.10) - SKU4777A - Claim Handler: CHAN SHU HUI AGNES

Approved:14774.10.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SKU4777A (CMTD1805632)**
OD
Dec 20 2018 3:00PM
[HUANG HUIBIN SYLVIA]
Autolution Industrial Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Sompo Insurance Singapore Pte. Ltd. (SOMPO_SG), sent on 26/12/2018 08:42 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$14516.88) - SKU4777A - Claim Handler: CHAN SHU HUI AGNES

Approved:14516.88.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: CHAN SHU HUI AGNES	Date: 13 Feb 2019
<u>Preliminary Advice</u>	

Vehicle No	: SKU4777A	Accident Date	: 20/12/2018
Make	: NISSAN X-TRAIL	Policy No.	: D18MTPV01012043
Assignment Date	: 24/12/2018	Excess	: S\$0.00
Date of Inspection	: 24/12/2018	Est. Duration of Repair	: 10
Inspection At	: AUTOLUTION INDUSTRIAL PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and o/s body. The undercarriage affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,490.80 (incl.supplementary\$1976.30)
Revised Amount	:S\$	14,774.10 (incl.supplementary \$1976.30)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	14,774.10

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	75,000.00
COE / PARF Rebate	:S\$	60,222.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,778.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompco Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 24 Dec 2018

Preliminary Advice

Vehicle No	: SKU4777A	Accident Date	: 20/12/2018
Make	: NISSAN X-TRAIL	Policy No.	: D18MTPV01012043
Assignment Date	: 24/12/2018	Excess	: S\$0.00
Date of Inspection	: 24/12/2018	Est. Duration of Repair	: 10 days
Inspection At	: Autolution Industrial Pte Ltd (Ubi) 19 Ubi Road 4 Singapore 408623		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion, o/s body , undercarriage affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,514.50
Revised Amount	:S\$	9,326.64
Check Items (Estimated)	:S\$	5,190.24
Total	:S\$	14,516.88
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	75,000.00
COE / PARF Rebate	:S\$	60,222.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,778.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	21/12/2018 08:45
Date Of Accident	20/12/2018 15:00
Exact Location Of Accident	302 PASIR PANJANG ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKU4777A
Insured/Policyholder	
Name Of Registered Owner	HUANG HUIBIN SYLVIA
NRIC No	S8440832H
Email Address	SYLVIA.GLOBETREKKER@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98274873
Alternative Phone No	OTHERS-92706264
Vehicle Particulars	
Manufacturer	NISSAN
Model	X-TRAIL-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE, LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01012043
Cover Note Number	
Driver	
Name of Driver	HUANG HUIBIN SYLVIA
NRIC No	S8440832H
Date Of Birth	15/12/1984
Occupation	INDOOR
Date Of Driving Pass	22/10/2003
Driving Experience	15 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-98274873
Fax Number	
Contact Number	OTHERS-92706264
Email Address	SYLVIA.GLOBETREKKER@GMAIL.COM

Address	20L EAST COAST AVENUE
Postcode	459221
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGP3122U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG BOH KHOON
NRIC/Passport Number	S1574333F
Contact Number	91008040
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

20/12/18

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name: Aurion INDUSTRIAL PTE LTD

NRIC/FIN No: 9028682212

NO. 40923

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
1181 ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6546 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/OFS1718
DATE : 21-DEC-2018

M/S SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
S1048623
TEL : 64616555
FAX : 62213147
ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME : MISS HUANG HUIBIN, SYLVIA MRS SYLVIA TSUKAHOSHI
ADDRESS : 19 LORONG 4 TELUK KURAU
#05-08
S1425145
TELEPHONE NO : 68920067/92706264

TYPE OF CLAIM : OD OR OD RECOVERY CLAIM
POLICY NO : O 38MTP901812943
VEHICLE NO : 5G04777A
MODEL CODE : JDR88R2T322JA-----
MODEL/YEAR : X-TRAIL 2.0L ALL MODE (44)
ENGINE NO : M9207250118
CHASSIS NO : JN1JANF3220000663
MILEAGE : 63463 KM
DATE IN : 21/12/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAKZAH
ACCIDENT DATE : 20/12/2018

- 96450079

*Not Authorized
to take
Excess?
10 days.
to the photo before painting.
maybe TOTAL LOSS.*

Insurance notice notify
the following:
Insurance spray painting
Insurance (s) during resurvey
Insurance subject to confirmation
Insurance on a "Without Prejudice" basis
Insurance (s) is allowed
Insurance (s) must be resurveyed and
subject to final approval from Insurance Company
Not controlled by Roadtax

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKW4777A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	22/001	LABOUR CHARGES TO REPAIR RADIATOR SUPPORT, LH HOODLEGE, LH FRT DOOR, LH FRONT PILLAR, RH FRONT	1400.00	720
2	22/002	FENDER, BONNET, R/T PILLAR, RENEW FRONT BUMPER, FRT BUMPER OVERRIDER AND LH FRONT FENDER.		
3	22/003	CHARGES TO SPRAY PAINTING SAME.	1700.00	1260
4	22/004	RENEW DAMAGED HEADLAMP AND FOCUS.	48.00	✓
5	22/005	RENEW LH FRT WHEEL RIN AND TYRE AND WHEEL BALANCING.	15.00	✓
6	22/006	CHECK AND ADJUST WHEEL ALIGNMENT.	95.00	50
7	22/007	REMOVE AND INSTALL LH FRONT SUSPENSION TO CHECK FOR DAMAGED - RENEW IF NEC.	340.00	✓
8	22/008	RENEW FRONT SUSPENSION MEMBER IF NEC.	340.00	✓
9	22/009	RENEW STEERING RACK & PINION IF NEC.	200.00	✓
10	22/011	REMOVE AND INSTALL ENGINE TO RENEW ENGINE BRACKET AND OIL SUMP.	480.00	360
11	22/012	TOWING CHARGES BY AUTOSWIFT WITH USAGE OF KING DOLLY, W/O: T157957	180.00	Fee X
12	22/10	RENEW LH FRONT DRIVE SHAFT.	100.00	✓
TOTAL LABOUR CHARGES			4638.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO 9KUA777A

S/N	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	SUNDRIES	NPN		11	100.00 X
2	ENGINE OIL	ENGINE OIL		nm	110.00 X
3	STEERING RACK & PINION	48001-4860A ✓	scrap	brn	1257.90 2/
4	FRT SUSPENSION MEMBER	54400-4C80B ✓		scrap	387.00 X
5	STABILISER SIDE ROD FRT LH	54668-2A8E ✓		brn	21.50 2/
6	SEAT STRUCT FRT LH	54035-4B80A ✓		scrap	25.70 2/
7	BUMPER STRUCT FRT LH	54050-4C10B ✓		scrap	30.30 2/
8	STOPPER STRUCT FRT LH	54325-0000B ✓		scrap	57.20 2/
9	STRUT KIT-FRONT LH	54300-ACE1C ✓		scrap	289.10 2/
10	FRT LOWER LINK LH	54501-2CA0A ✓		crn	159.50 /
11	FRT WHEEL HUB FRT LH	40202-4B40A ✓		brn	209.60 2/
12	KNUCKLE FRT LH	40015-4C20A ✓		brn	396.00 2/
13	DRIVE SHAFT FRONT LH	39101-4880B ✓		scrap	819.50 2/
14	INSULATOR ENGINE MNTG REAR	11220-4880A ✓		brn	65.90 2/
15	ENGINE MNTG SUPPORT BRACKET LH	11254-4880A X		11	116.30 X
16	ENGINE MNTG BRKT LH	11253-4880A ✓		crn	113.80 2/
17	ENGINE MNTG ROD	11360-4B40B ✓		brn	62.50 2/
18	INSULATOR ENGINE MNTG RH	11210-4880B ✓		brn	138.40 2/
19	FRT BUMPER GUARD OVER-RIDER	05890-4C10A ✓		scrap	510.00 561.60
20	235/50R18 DUNLOP TYRE	TYRE ✓		part	360.00 90% = 3x2
21	WHEEL RIM FRONT LH	00300-4E11A ✓		brn	1136.20 /
22	R/F DOOR SASH MOLD	80282-4C40A ✓		crn	63.70 /
23	R/F FENDER ARC MOLD	63860-4C20A ✓		crn	102.90 /
24	R/F DOOR MIRROR COVER	96373-4C40A		11	60.30 X
25	R/F DOOR OUTER MIRROR WITH LHM	96301-4C40A ✓		brn/crn	1068.60 /

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKW4777A

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
25	HEADLAMP LH	25060-4C45C ✓	holder cr	1086.00	✓
27	ENGINE OIL SUMP	31110-4B61C	11	300.10	✗
28	CLIF LOWER COVER # 12.50 EACH	01553-09241 ✓	scr	4.00	✓
29	ENGINE LOWER COVER	76892-4C20A	11	108.90	✗
30	LH SILL PANEL DASHISH	76851-4C20A ✓	D.S	398.00	✓
31	L/F FENDER ARC MOLD	63861-4C20A ✓	scr	102.90	✓
32	CLIF PROTECTOR COVER # 10.70 EACH	01553-09333 ✓	scr	4.20	✓
33	L/F FENDER PROTECTOR COVER	63843-4C80A ✓	To 11	49.40	✓
34	FENDER FRONT LH	73101-4C20A ✓	B/Bul	353.00	✓
35	FRT BUMPER LOWER COVER	62660-4C15E ✓	as 11	353.40	✓
36	FRT BUMPER CHROME MOLDING	62072-4B40A ✗	11	92.70	✗
37	FRT BUMPER SIDE BRKT LH	62223-4C15A ✓	Bul	32.70	✓
38	CLIF FRT BUMPER # 10.70 EACH	01553-10501 ✓	scr	4.20	✓
39	FRONT BUMPER FASCIA	62002-4C20A ✓	(4)	323.50	✓
GUE TOTAL			0.00	0.00	10876.50
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			0.00	0.00	0.00
GRAND TOTAL			0.00	0.00	10876.50
OVERALL TOTAL			10876.50		

LEGEND: REMARKS (✓) = APPROVED, REMARKS (✗) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO 3694777A

TOTAL LABOUR CHARGES	4638.00
TOTAL SPARE PARTS CHARGES	10878.50
GROSS TOTAL	15516.50

17490.30

* All charges do not include GST.

SURVEYOR'S PARTICULARS

12562 40

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.



Autolution Industrial Pte Ltd

Tan Chong Motor Sales Pte Ltd's Authorized Dealer
19 Ubi Road 4
Singapore 408623
Tel: (65) 64909888 / 67036880
Fax: (65) 69467483
Business Reg. No.: 199500871B

04-February-2019

INS/SC/H/0076/19

Sompo Insurance Singapore Pte Ltd
50 Raffles Place, #05-01/06 S'pore Land Tower
Singapore 048623

Attn : Motor Claim Manager
Claim Dept

Dear Sir

SUPPLEMENTARY CLAIM

REGN. NO. : SKU4777A
POLICY NO: D 18MTPV01012043

Further to our claim INS/IC/H/0751/18 we are submitting a supplementary claim for the below mentioned labour and part for the above mentioned case.

Labour charges


1 R/I A/Transmission to renew casing including part. 1,240.00 1189

Replacement of Damaged Items AD

1. A/Transmission CVT oil 88.70 S/Nett
2. Sensor height 647.60 S/Nett

We trust the above supplementary claim will meet with your kind approval and we will forward to you the final repair bill together with the satisfaction note on completion repairs.

Yours faithfully
AUTOLUTION INDUSTRIAL PTE LTD


Hamzah Sa'ad
Insurance Claim Dept

Cc: Surveryor- LKK Auto Consultant



LS TYRES & AUTOMOTIVE PTE LTD

53 UBI AVE 1 #01-04/05 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934

TEL: (65) 6744 4280 (65) 6748 1472 FAX: (65) 6748 3822

Reg & GST No: 200616874E

Tax Invoice No: LS164488

Invoice To :

CASH

Singapore

Date: 03-Sep-18

Credit Terms: Cash Only

Vehicle Type: NISSAN

Vehicle Model: X-TRAIL

Vehicle No: SKU4777A

Mileage: 57425

Stockcode	Description	Quantity	Unitprice	Amount
DUSP050-14	DU SPORTMAXX 050+ 235/6018 107W JPN	2	\$210.28	\$420.56

Remarks:

TOTAL \$420.56

7% GST \$29.44

GRAND TOTAL \$450.00

1. Any irregularity of delivery should be reported within 7 days, otherwise no claim will be entertained.
2. All cheques are to be crossed "A/C Payee/ Not Negotiable" made payable to "L S Tyres & Automotive Pte Ltd".
3. 1% interest per month will be charged for overdue payments.

Sold By

Customer Signature

UKK - Marcus

12/2/2019 e-mail
re-send.

AUTOTECH INDUSTRIAL PTE. LTD.

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/MD/151/18
DATE : 21-DEC-2018

M/S SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/05 SINGAPORE LAND TOWER
S(048623)
TEL : 64618555
FAX : 62213147
ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME : MISS HUANG HUIBIN, SILVIA MRS SILVIA TSURAKOSHI
ADDRESS : 12 ANDER GARDENS
#05-07
S(438595)
TELEPHONE NO : 68920057/92700264

TYPE OF CLAIM : 02 OR 03 RECOVERY CLAIM
POLICY NO : D 18MTPV01012043
VEHICLE NO : SWJ4777A
MODEL CODE : J0N9R2T32EWA
MODEL/YEAR : X-TRAIL 2.0L ALL MODE 4441
ENGINE NO : 9R207250118
CHASSIS NO : JH1JANT3220000663
MILEAGE : 63461 KM
DATE IN : 21/12/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HANZAH
ACCIDENT DATE : 20/12/2018

10 days

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SHM777A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	22/001	LABOUR CHARGES TO REPAIR RADIATOR SUPPORT, LH HOODLEDGE, LH FRT DOOR, LH FRONT PILLAR, RH FRONT	1400.00	720.00
2	22/002	FENDER, BONNET, R/T PILLAR, RENEW FRONT BUMPER, FRT BUMPER OVERRIDER AND LH FRONT FENDER.		
3	22/003	CHARGES TO SPRAY PAINTING SAME.	1700.00	1260.00
4	22/004	RENEW DAMAGED HEADLAMP AND FOCUS.	48.00	48.00
5	22/005	RENEW LH FRT WHEEL RIM AND TYRE AND WHEEL BALANCING.	15.00	15.00
6	22/006	CHECK AND ADJUST WHEEL ALIGNMENT.	95.00	50.00
7	22/007	RENEW LH FRT SUSPENSION STRUCT, L/F LOWER LINK, L/F WHEEL HUB, L/F KNUCKLE AND STRUCT MOUNTING.	240.00	240.00
8	22/008	REMOVE AND INSTALL FRONT SUSPENSION CROSS MEMBER.	240.00	240.00
9	22/009	RENEW STEERING RACK & PINION.	200.00	200.00
10	22/011	REMOVE AND INSTALL ENGINE TO RENEW ENGINE BRACKET AND OIL SUPP.	480.00	260.00
11	22/012	TIMING CHARGES BY AUTOWAFT WITH USAGE OF KING DOLLY, W/D: TESTEST.	120.00	.30
12	22/013	REMOVE AND INSTALL 4/TRANSMISSION TO RENEW CASING INCLUDE PARTS.	1500.00	1199.00
13	22/10	RENEW LH FRONT DRIVE SHAFT.	100.00	100.00
TOTAL LABOUR CHARGES			6138.00	4432.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SHM777A

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	A/TRANSMISSION OIL	KL53-0004		88.70	OK
2	SENSOR HEIGHT	53010-4B0A		647.60	OK
3	FRT BUMPER GUARD OVER WIDER	05090-4C03A		551.60	OK
4	SUNSHIES	NPI		100.00	X
5	ENGINE OIL	ENGINE OIL		110.00	X
6	STEERING RACK & PINION	48001-4B0A		1057.90	OK
7	FRT SUSPENSION MEMBER	54400-4C0B		387.00	X
8	STABILISER SIDE ROD FRT LH	54660-1A0E		21.50	OK
9	SEAT STRUCT FRT LH	54035-4B0A		25.70	OK
10	BUMPER STRUCT FRT LH	54050-4C0B		30.30	OK
11	STOPPER STRUCT FRT LH	54325-000B		57.20	OK
12	STRUT KIT-FRONT LH	54303-4C0C		389.30	OK
13	FRT LOWER LINK LH	54501-4C0A		159.50	OK
14	FRT WHEEL HUB FRT LH	40202-4B0A		209.60	OK
15	WHEEL FRT LH	40015-4C0A		396.00	OK
16	DRIVE SHAFT FRONT LH	39101-4B0B		819.50	OK
17	INSULATOR ENGINE MNTG REAR	11220-4B0A		65.80	OK
18	ENGINE MNTG SUPPORT BRACKET LH	11254-4B0A		116.20	X
19	ENGINE MNTG BRKT LH	11253-4B0A		113.00	OK
20	ENGINE MNTG ROD	11360-4B0B		52.60	OK
21	INSULATOR ENGINE MNTG RH	11210-4B0B		130.40	OK
22	235/60R15 DUNLOP TYRE MKK OF 1300.00	TYRE		342.00	OK
23	WHEEL RIM FRONT LH	06300-4C1A		1136.20	OK
24	R/F DOOR SASH HLDG	80282-4C0A		83.70	OK
25	R/F FENDER ARC HLDG	63860-4C0A		102.90	OK

MATERIAL LIST FOR ACCIDENT VEHICLE REG# NO SK4777A

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
25	R/F DOOR MIRROR COVER	96373-4C49A			89.30 F
27	R/F DOOR OUTER MIRROR WITH LEN	96391-4C49A			1066.60 OK
28	HEADLAMP LH	29000-4C49C			1086.80 OK
29	ENGINE OIL SUPP	11150-4881C			300.10 X
30	CLIP LOWER COVER @ 47.50 EACH	01553-09241			6.00 OK
31	ENGINE LOWER COVER	19882-4C85A			108.90 F
32	LH SILL PANEL GARNISH	75851-4C5DA			398.00 OK
33	L/F FENDER ARC MOLD	63051-4C5DA			182.90 OK
34	CLIP PROTECTOR COVER @ 40.70 EACH	01553-05933			4.20 OK
35	L/F FENDER PROTECTOR COVER	63843-4C85A			49.40 OK
36	FENDER-FRONT LH	F3101-4C09A			353.00 OK
37	FRT BUMPER LOWER COVER	52585-4C50B			353.40 OK
38	FRT BUMPER CHROME MOLDING	62073-49A0A			92.70 F
39	FRT BUMPER SIDE BRKT LH	62223-4C10A			12.70 OK
40	CLIP FRT BUMPER @ 40.70 EACH	01553-10501			4.20 OK
41	FRONT BUMPER FASCIA	62072-4C10H			323.50 OK
SUB TOTAL			0.00	0.00	10342.10
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			0.00	0.00	0.00
GRAND TOTAL			0.00	0.00	10342.10
OVERALL TOTAL			10342.10		

(LEGEND) REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SA04777A

NETT ITEM	0.00
LESS 20.00%	0.00
NETT AMOUNT	0.00
LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	10342.10
LESS 0.00%	0.00
SPECIAL NETT AMOUNT	10342.10
TOTAL LABOUR CHARGES	4432.00
TOTAL SPARE PARTS CHARGES	10342.10
TOTAL CHARGES	14774.10
ADD 7 % GST	1034.19
GROSS TOTAL	15808.29

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Dec 2018		24 Dec 2018 10:50 Edit Adj Rpt	S\$14,774.10 Edit Estimates	S\$14,774.10 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	HUANG HUIBIN SYLVIA, ID: S8440832H, Tel: +6598274873, Email: sylvia.globetrekker@gmail.com								
Vehicle Reg. No.:	SKU4777A	Date of Loss:	20/12/2018 15:00 - :59 [40 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / CMTD1805632	Policy/Cover Note No.:	D18MTPV01012043 (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	Autolution Industrial Pte Ltd (Ubi) 19 Ubi Road 4, 408623 Ubi - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 04/01/2019]								
Driver/Custodian:	HUANG HUIBIN SYLVIA (34 / Female), NRIC: S8440832H, Tel: +6598274873 Email: sylvia.globetrekker@gmail.com								
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail						
<ul style="list-style-type: none"> SOMPO_SG (21/02/2019): Alert - Adj Mandate Approved (S\$14774.10) - SKU4777A - Claim Handler: CHAN SHU H... SOMPO_SG (26/12/2018): Alert - Adj Mandate Approved (S\$14516.88) - SKU4777A - Claim Handler: CHAN SHU H... SOMPO_SG (24/12/2018): Cancellation of Assignment: SKU4777A SOMPO_SG (24/12/2018): Cancellation of Assignment: SKU4777A 									
ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKU4777A (CMTD1805632)
OD
Dec 20 2018 3:00PM
[HUANG HUIBIN SYLVIA]
Autolution Industrial Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser	
Video										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)				Thumbnail	Print				
1	21/12/18 09:55	Video - Accident <small>[Linked Accident Report Documents]</small>					Load MOV				
2	21/12/18 09:55	Video - Accident <small>[Linked Accident Report Documents]</small>					Load MOV				
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)				Thumbnail	Print				
1	21/12/18 11:47	Accident Statement					Load HTM				
2	21/12/18 12:05	Addendum Sheet					Load TIF				
3	21/12/18 12:07	Accident Statement Addm. #1					Load HTM				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print				
1	24/12/18 17:25	Adjuster Immediate Advice					Load HTM				
2	24/12/18 17:53	Adjuster Immediate Advice					Load HTM				
3	13/02/19 10:37	Adjuster Immediate Advice					Load HTM				
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print				
1	24/12/18 17:58	Odometer Reading					Load JPG		<input checked="" type="checkbox"/>		
2	24/12/18 17:58	Chassis Number					Load JPG		<input checked="" type="checkbox"/>		
3	24/12/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>		
4	24/12/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>		
5	24/12/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>		
6	24/12/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>		
7	24/12/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>		
8	24/12/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>		
9	24/12/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>		
10	24/12/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>		
11	24/12/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>		
12	24/12/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>		
13	24/12/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>		
14	24/12/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>		
15	24/12/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>		
16	24/12/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>		
17	24/12/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>		
18	24/12/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>		
19	24/12/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>		
20	24/12/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>		
21	24/12/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>		
22	24/12/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>		
23	24/12/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>		
24	24/12/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>		
25	24/12/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
26	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
27	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
28	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
29	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
30	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
31	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
32	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
33	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
34	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
35	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
36	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
37	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
38	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
39	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
40	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
41	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
42	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
43	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
44	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
45	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
46	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
47	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
48	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
49	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
50	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
51	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
52	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
53	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
54	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
55	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
56	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
57	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
58	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
59	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
60	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
61	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
62	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
63	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
64	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
65	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
66	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
67	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
68	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
69	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
70	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
71	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
72	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
73	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
74	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
75	24/12/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
76	24/12/18 17:58	General View		<input checked="" type="checkbox"/>
77	24/12/18 17:58	General View		<input checked="" type="checkbox"/>
78	24/12/18 17:58	General View		<input checked="" type="checkbox"/>
79	24/12/18 17:58	General View		<input checked="" type="checkbox"/>
80	24/12/18 17:58	General View		<input checked="" type="checkbox"/>
81	24/12/18 17:58	General View		<input checked="" type="checkbox"/>
82	24/12/18 17:58	General View		<input checked="" type="checkbox"/>
83	24/12/18 17:58	General View		<input checked="" type="checkbox"/>
84	24/12/18 17:58	General View		<input checked="" type="checkbox"/>
85	24/12/18 17:58	General View		<input checked="" type="checkbox"/>
86	24/12/18 17:58	General View		<input checked="" type="checkbox"/>
87	24/12/18 17:58	General View		<input checked="" type="checkbox"/>
88	24/12/18 17:58	General View		<input checked="" type="checkbox"/>
89	24/12/18 17:58	General View		<input checked="" type="checkbox"/>
90	24/12/18 17:58	General View		<input checked="" type="checkbox"/>
91	24/12/18 17:58	General View		<input checked="" type="checkbox"/>
92	24/12/18 17:58	General View		<input checked="" type="checkbox"/>
93	24/12/18 17:58	General View		<input checked="" type="checkbox"/>
94	24/12/18 17:58	General View		<input checked="" type="checkbox"/>
95	24/12/18 17:58	General View		<input checked="" type="checkbox"/>
96	24/12/18 17:58	General View		<input checked="" type="checkbox"/>
97	24/12/18 17:58	General View		<input checked="" type="checkbox"/>
98	24/12/18 17:58	General View		<input checked="" type="checkbox"/>
99	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
100	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
101	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
102	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
103	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
104	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
105	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
106	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
107	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
108	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
109	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
110	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
111	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
112	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
113	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
114	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
115	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
116	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
117	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
118	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
119	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
120	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
121	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
122	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
123	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
124	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
125	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
126	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
127	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
128	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
129	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
130	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
131	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
132	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
133	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
134	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
135	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
136	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
137	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
138	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
139	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
140	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
141	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
142	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
143	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
144	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
145	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
146	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
147	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
148	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
149	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
150	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
151	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
152	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
153	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
154	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
155	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
156	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
157	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
158	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
159	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
160	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
161	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
162	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
163	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
164	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
165	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
166	13/02/19 10:26	Reinspection Photo		<input checked="" type="checkbox"/>
167	13/02/19 10:27	Reinspection Photo		<input checked="" type="checkbox"/>
168	13/02/19 10:27	Reinspection Photo		<input checked="" type="checkbox"/>
169	13/02/19 10:27	Reinspection Photo		<input checked="" type="checkbox"/>
170	13/02/19 10:27	Reinspection Photo		<input checked="" type="checkbox"/>
171	13/02/19 10:27	Reinspection Photo		<input checked="" type="checkbox"/>
172	13/02/19 10:27	Reinspection Photo		<input checked="" type="checkbox"/>
173	13/02/19 10:27	Reinspection Photo		<input checked="" type="checkbox"/>
174	13/02/19 10:27	Reinspection Photo		<input checked="" type="checkbox"/>
175	13/02/19 10:27	Reinspection Photo		<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
176	13/02/19 10:27	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
177	13/02/19 10:27	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
178	13/02/19 10:27	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
179	13/02/19 10:27	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
180	13/02/19 10:27	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	21/12/18 13:40	Certificate Schedule		Load PDF
2	24/12/18 08:47	EMAIL - AUTOLUTION		Load HTM
3	24/12/18 08:47	Repair Estimates		Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/12/18 17:57	ESTIMATE .pdf		Load PDF
2	12/02/19 16:27	SUPPLEMENTARY		Load PDF
3	13/02/19 10:37	SUPPLEMENTARY MARKING		Load PDF

Linked Accident Report Documents

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
1	21/12/18 09:55	Video - Accident		Load MOV
2	21/12/18 09:55	Video - Accident		Load MOV
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
1	21/12/18 11:47	Accident Statement		Load HTM
2	21/12/18 12:05	Addendum Sheet		Load TIF
3	21/12/18 12:07	Accident Statement Addm. #1		Load HTM
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
1	21/12/18 10:00	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	21/12/18 10:00	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	21/12/18 10:00	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	21/12/18 10:00	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	21/12/18 10:00	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	21/12/18 10:00	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	21/12/18 10:00	Accident Photo		Load JPG <input checked="" type="checkbox"/>
8	21/12/18 10:00	Accident Photo		Load JPG <input checked="" type="checkbox"/>
9	21/12/18 10:01	Accident Photo		Load JPG <input checked="" type="checkbox"/>
10	21/12/18 10:01	Accident Photo		Load JPG <input checked="" type="checkbox"/>
11	21/12/18 10:01	Accident Photo		Load JPG <input checked="" type="checkbox"/>
12	21/12/18 10:01	Accident Photo		Load JPG <input checked="" type="checkbox"/>
13	21/12/18 10:01	Accident Photo		Load JPG <input checked="" type="checkbox"/>
14	21/12/18 11:05	Accident Photo		Load JPG <input checked="" type="checkbox"/>
15	21/12/18 11:05	Accident Photo		Load JPG <input checked="" type="checkbox"/>
16	21/12/18 11:05	Accident Photo		Load JPG <input checked="" type="checkbox"/>
17	21/12/18 11:05	Accident Photo		Load JPG <input checked="" type="checkbox"/>
18	21/12/18 11:05	Accident Photo		Load JPG <input checked="" type="checkbox"/>
19	21/12/18 11:05	Accident Photo		Load JPG <input checked="" type="checkbox"/>
20	21/12/18 11:05	Accident Photo		Load JPG <input checked="" type="checkbox"/>
21	21/12/18 11:05	Accident Photo		Load JPG <input checked="" type="checkbox"/>
22	21/12/18 11:06	Accident Photo		Load JPG <input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
				<input checked="" type="checkbox"/>
23	21/12/18 11:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
24	21/12/18 11:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
25	21/12/18 11:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
26	21/12/18 11:09	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
27	21/12/18 11:09	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
28	21/12/18 11:09	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
29	21/12/18 11:09	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
30	21/12/18 11:09	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
31	21/12/18 11:09	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
32	21/12/18 11:09	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
33	21/12/18 11:09	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
34	21/12/18 11:09	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
35	21/12/18 11:09	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
36	21/12/18 11:09	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
37	21/12/18 11:09	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
38	21/12/18 11:10	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
39	21/12/18 11:10	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
40	21/12/18 11:10	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
1	21/12/18 09:55	Sketch Plan	Load TIF	
2	21/12/18 09:55	Sketch Plan #2	Load TIF	
3	21/12/18 09:56	ICDL	Load TIF	
4	21/12/18 09:56	CI	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06, Singapore Land Tower
Singapore 048623

Our File No: CS/SMO18022968/USD3E2

Date: 25/02/2019

REFERENCE

Insured/Claimant: HUANG HUIBIN SYLVIA Policy No: D18MTPV01012043
Date of Loss: 20/12/2018 Nature of Claim: OD Claim No: CMTD1805632

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKU4777A**
Make & Model: NISSAN X-TRAIL, 2.0 (A) Engine No: MR20725011B
Reg. Date: 29/07/2015 (Man. Year: 2015) Chassis No: JN1JANT32Z0000663
Colour: Orange Odometer: 63461 km
Engine Capacity: 1997 cc
Market Value/New Car Price: S\$75,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18
Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 8 mm
Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,664.40	10,342.10	1,322.30	11.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,878.00	4,432.00	1,446.00	24.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,542.40	14,774.10	2,768.30	15.78
+ GST 7.00/7.00% (S\$)	1,227.97	1,034.19	193.78	15.78
Nett Amount (S\$)	18,770.37	15,808.29	2,962.08	15.78

INSPECTION

Date of Assignment: 24/12/2018
Date Inspected: 24/12/2018 Inspected At: Autolution Industrial Pte Ltd (Ubi)
19 Ubi Road 4
Singapore 408623

Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Feb 2019)	
Parts: M1-MPV	NISSAN X-TRAIL 2.0 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code: (Unsubmitted, no print-code for SKU4777A)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Not Necessary	100.00 FS	*- FS
2	1		*ENGINE OIL	Not Necessary	110.00 FS	*- FS
3	1		*STEERING RACK & PINION	Bent / Jammed	1,257.90 FS	*1,257.90 FS
4	1		*FRT SUSPENSION MEMBER	Serviceable	387.00 FS	*- FS
5	1		*STABILISER SIDE ROD FRT LH	Bent	21.50 FS	*21.50 FS
6	1		*SEAT STRUCT FRT LH	Necessary	25.70 FS	*25.70 FS
7	1		*BUMPER STRUCT FRT LH	Necessary	30.30 FS	*30.30 FS
8	1		*STOPPER STRUCT FRT LH	Necessary	57.20 FS	*57.20 FS
9	1		*STRUT KIT-FRONT LH	Bent	289.10 FS	*289.10 FS
10	1		*FRT LOWER LINK LH	Cracked	159.50 FS	*159.50 FS
11	1		*FRT WHEEL HUB FRT LH	Bent	209.60 FS	*209.60 FS
12	1		*KNUCKLE FRT LH	Bent	396.00 FS	*396.00 FS
13	1		*DRIVE SHAFT FRONT LH	Broken	819.50 FS	*819.50 FS
14	1		*INSULATOR ENGINE MNTG REAR	Torn	65.80 FS	*65.80 FS
15	1		*ENGINE MMTG SUPPORT BRACKET LH	Not Necessary	116.30 FS	*- FS
16	1		*ENGINE MNTG BRKT LH	Cracked	113.80 FS	*113.80 FS
17	1		*ENGINE MNTG ROD	Damaged	52.60 FS	*52.60 FS
18	1		*INSULATOR ENGINE MNTG RH	Torn	138.40 FS	*138.40 FS
19	1		*FRT BUMPER GUARD OVER-RIDER	Missing	561.60 FS	*561.60 FS
20	1		*235/60R18 DUNLOP TYRE (90%)	Punctured	380.00 FS	*342.00 FS
21	1		*WHEEL RIM FRONT LH	Dented	1,136.20 FS	*1,136.20 FS
22	1		*R/F DOOR SASH MLDG	Cut	63.70 FS	*63.70 FS
23	1		*R/F FENDER ARC MLDG	Cut	102.90 FS	*102.90 FS
24	1		*R/F DOOR MIRROR COVER	Not Necessary	69.30 FS	*- FS
25	1		*R/F DOOR OUTER MIRROR WITH LEN	Dented / Cracked	1,068.60 FS	*1,068.60 FS
26	1		*HEADLAMP LH	Holder Cracked	1,086.60 FS	*1,086.60 FS
27	1		*ENGINE OIL SUMP	Not Necessary	300.10 FS	*- FS
28	1		*CLIP LOWER COVER	Necessary	6.00 FS	*6.00 FS
29	1		*ENGINE LOWER COVER	Not Necessary	108.90 FS	*- FS
30	1		*LH SILL PANEL GARNISH	Distorted	398.00 FS	*398.00 FS
31	1		*L/F FENDER ARC MLDG	Grazed	102.90 FS	*102.90 FS
32	6		*CLIP PROTECTOR COVER	Necessary	4.20 FS	*4.20 FS
33	1		*L/F FENDER PROTECTOR COVER	Torn	49.40 FS	*49.40 FS
34	1		*FENDER - FRONT LH	Dented / Buckled	353.00 FS	*353.00 FS
35	1		*FRT BUMPER LOWER COVER	Missing	353.40 FS	*353.40 FS
36	1		*FRT BUMPER CHROME MOULDING	Not Necessary	92.70 FS	*- FS
37	1		*FRT BUMPER SIDE BRKT LH	Bent	12.70 FS	*12.70 FS
38	6		*CLIP FRT BUMPER	Necessary	4.20 FS	*4.20 FS
39	1		*FRONT BUMPER FASCIA	Cut	323.50 FS	*323.50 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*A/TRANSMISSION CVT OIL	Necessary	88.70 FS	*88.70 FS
41	1		*SENSOR HEIGHT	Damaged / Necessary	647.60 FS	*647.60 FS
Total Parts (S\$)					11,664.40	10,342.10

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REPAIR RADIATOR SUPPORT, LH HOODLEDGE, LH FRT DOOR, LH FRONT PILLAR, RH FRONT	New	1,400.00	720.00
2	CHARGES TO SPRAY PAINTING SAME	New	1,700.00	1,260.00
3	RENEW DAMAGED HEADLAMP AND FOCUS	New	48.00	48.00
4	RENEW LH FRT WHEEL RIM AND TYRE AND WHEEL BALANCING	New	15.00	15.00
5	CHECK AND ADJUST WHEEL ALIGNMENT	New	95.00	50.00
6	REMOVE AND INSTALL LH FRONT SUSPENSION TO CHECK FOR DAMAGED - RENEW IF NEC	New	240.00	240.00
7	RENEW FRONT SUSPENSION MEMBER IF NEC	New	240.00	240.00
8	RENEW STEERING RACK & PINION OF NEC	New	200.00	200.00
9	REMOVE AND INSTALL ENGINE TO RENEW ENGINE BRACKET AND OIL SUMP	New	480.00	360.00
10	TOWING CHARGES BY AUTOSWIFT WITH USAGE OF KING DOLLY, W/O : T157557	New	120.00	0.00
11	RENEW LH FRONT DRIVE SHAFT	New	100.00	100.00
12	R/I A/TRANSMISSION TO RENEW CASING INCLUDING PART	New	1,240.00	1,199.00
Gross Labour Cost (S\$)			5,878.00	4,432.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >