

INS. CASE OWNER:

CC

4, Asm 180

23075, 11

has 9

LKK:

IDAC

84732

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II : \$5

D.G.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(VL: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call Of:

After call Itr to Of: 14/15/2016

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to Of:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: Tanti

Repair Cost:

\$5650.00

(8 days)

Reduction: \$14,650.00 % 72

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

\$5

Loss of Rental (LOR):

\$5

(days)

Loss of Use (LOU):

\$5

(\$ x

days)

Loss of Income (LOI):

\$5

(\$ x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost

\$5

Total:

\$5

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

Name 1:

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

WP

\$250/-

COPY SENT
30/8/17

Taufik

REF: ASM (AXA)

7243

ASSIGNMENT

From Date: 27-12-2013

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: PA 7700Y
at Workshop n/s: UCB Engineering
of: 2c Jin Pesawat Jombang

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

1pm - 1.30pm

N/S	O/S

Bal. or Market Value:

887K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

PA 7700Y

Yr Regn:

2014 April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Coaster

CC : 4009

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

22892

T/Radio: Insured / Std / NI / NA

Eng/No:

C/Nr:

JT 9EP53810600864

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 2.5 / 70 R17.5
R: (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 0 mm

R/Bal: 6/6 mm

L/Bal: 6 mm

L/Bal: 6/6 mm

D.O.A:

D.O.I:

27/12/10c 130pm

Survey held at

UCB Eng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

4/5 \$5050/- (Rtd = \$14,650 / 72.7)

Date/Time: File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ Site Insp (\$

) S + RS SI

☐ Interview (\$

) Photos

☐ Tech. Invs (\$

) Others

☐ Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL:



UCB Engineering Pte Ltd

GST Registration Number: 19-9501338-G

Business Reg. No. 199501338G

Our ref: 181202.RGT(PA7700Y)

24th December 2018

Ready Go Trading
25 Elias Road
#07-12 Ris Grandeur
Singapore 519831

QUOTATION
without Prejudice

Dear Sir,

COST OF REPAIR FOR PA 7700 Y

QTY	DESCRIPTIONS	PRICE S\$
1 pc	LHS panel <i>check part price less 25%</i>	13,800.00 <i>4000</i> <i>25% - 930</i>
4 pcs	Labour charges for dismantle & assemble side window Glass	1,200.00 <i>700</i>
	Labour charges for remove & replace the above damaged parts Dismantle & assemble the passenger seat & checking alignment <i>350</i>	4,200.00 <i>2280</i>
	To putty & spray painting onto complete RHS body panel	1,400.00 <i>900</i>
Total		20,300.00 <i>3000</i> <i>4080</i>

(SGD: Twenty Thousand Three Hundred Only)

Price quoted above is subjected to 7% GST

Yours faithfully,
Tan Tiong Chia

UKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Tiong Chia 97495744
WP
77/12/18
8 days - 9 days
umpson
Resurvey after repair
sure/ukanto.com
7080
4/5/5650
8 days



UCB Engineering Pte Ltd

GST Registration Number: 19-9501338-G

Business Reg. No. 199501338G

Our ref: 181202.RGT(PA7700Y)

24th December 2018

Ready Go Trading
25 Elias Road
#07-12 Ris Grandeur
Singapore 519931

QUOTATION
without Prejudice

Dear Sir,

COST OF REPAIR FOR PA 7700 Y

QTY	DESCRIPTIONS	PRICE S\$
1 pc	LHS panel <i>* check part price less 25%</i>	13,500.00 <i>ht -</i>
4 pcs	Labour charges for dismantle & assemble side window Glass	1,200.00 <i>900</i>
	Labour charges for remove & replace the above damaged parts Dismantle & assemble the passenger seat & checking alignment <i>380</i>	4,200.00 <i>2280</i>
	To putty & spray painting onto complete RHS body panel	1,400.00 <i>900</i>
Total		20,300.00

(SGD: Twenty Thousand Three Hundred Only)

Price quoted above is subjected to 7% GST

Yours faithfully,
Tan Tiong Chia

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Tan Tiong Chia 97495744
'wp'
77/12/18e*

8 days - 9 days

*umpsum
resurvey after repair*

sure@lkkauto.com

Annex A

Transaction ref 20181013090011370730

The owner and vehicle particulars for Vehicle No. PC2540P as at 13 Oct 2018 are as follows:

1. Name	: READY.GO TRADING
2. Identification No. Type	: Business
3. Identification No.	: 52974672K
4. Country/Region	: -
5. Vehicle No.	: PC2540P
6. Previous Vehicle No.	: -
7. Effective Date of Ownership	: 13 Oct 2018
8. Original Registration Date	: 30 Apr 2014
9. First Registration Date	: 30 Apr 2014
10. Vehicle Type	: Z20 - Private Hire (Chauffeur) Bus/Coach/Minibus
11. Vehicle Scheme	: Public Service Vehicle (Others)
12. Attachment 1	: Air-Conditioned
13. Attachment 2	: -
14. Attachment 3	: -
15. Vehicle Make	: TOYOTA
16. Vehicle Model	: COASTER 23 SEATER ABS
17. Year of Manufacture	: 2014
18. Primary Colour	: White
19. Secondary Colour	: -
20. Passenger Capacity	: 23
21. Chassis/Trailer Chassis No.	: JTGEP538106000864 / -
22. Propellant	: Diesel
23. Engine No./Motor No.	: N04CUH17652 / -
24. Engine Capacity(cc)/Power Rating(kW)	: 4009 / -
25. Maximum Power Output(kW/bhp)	: - / -
26. Unladen Weight(kg)	: 3760



Service Request Details

Claim

S8M017UZ

Reference

None

Loss Date

22 December 2018

Request Date

26 December 2018

Due Date

2 January 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

26.12.2018 @ 9:12am
Ah Sheng verified in

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

PA7700Y

Make

TPVD TOYOTA



Service Address

...

Primary Contact/Insured

SJ AUTO PTE LTD

170 UPPER BUKIT TIMAH ROAD, #03-50, BUKIT TIMAH SHOPPING CENTRE, 588179, Singapore

Claim Handler

NG Stacey

6568804351

stacey.ng@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: unitedcb <Unitedcb@singnet.com.sg>
Sent: Monday, 24 December, 2018 4:51 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: RE: Accident involving PA 7700 Y and SLV 1032 T on 22/12/2018
Attachments: PA7700Y.pdf

Categories: Mateen

Dear Sir

I refer to the above matter.

Enclose all document for your reference. Kindly sent the surveyor survey the vehicle ASAP.

Thank you
Ah Siang
HP 91773084

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	4672K
Vehicle Details	
Vehicle No.:	PA7700Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COASTER 23 SEATER ABS
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	N04CUH17652
Chassis No.:	JTGEP538106000864
Maximum Power Output:	-
Open Market Value:	\$80,015.00
Original Registration Date:	30 Apr 2014
First Registration Date:	30 Apr 2014
Transfer Count:	1
Actual ARF Paid:	\$4,001.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Apr 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$56,302.00
COE Rebate Amount:	\$30,755.00
Total Rebate Amount:	\$30,755.00

The information contained herein is correct as at 26 Dec 2018

OK

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Tuesday, 14 May 2019 10:15 AM
To: Agnes.ung@sjmotor.sg
Cc: Admin A
Subject: ROAD TRAFFIC ACCIDENT INVOLVING SLV 1032T AND PA 7700Y ALONG PARK HOTEL DRIVE WAY ON 22.12.2018
Attachments: TP video; PA7700Y; PA7700Y(1)

SJ AUTO PTE LTD
Policy Holder

Attn: Ms Agnes

Dear Sir/Madam,

OUR REF : CC4/ASM18023075/T1fa3
YOUR REF : SLV 1032J
ROAD TRAFFIC ACCIDENT INVOLVING SLV 1032T AND PA 7700Y ALONG PARK HOTEL DRIVE WAY ON 22.12.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s UCB Engineering Pte Ltd, acting on behalf of the owner of PA 7700Y against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2132 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



TP PASSED CASE TO LAWYER

Type

🔗 Question

Message

PLEASE SUBMIT WP REPORT

Reply

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18023075/T1ga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:STACEY NG

Date : 03-09-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLV 1032T	Veh. Inspected	PA 7700Y
Policy No.	VFX/P2198100	Coverage (\$)	0.00
Claim No.	S8M017UZ	Excess (\$)	0.00
Assign From		Assign Date	26/12/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA COASTER	c.c	4009
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTGEP538106000864	Colour	WHITE
Odometer	22892	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/70 R17.5	BRIDGESTONE	6 mm
L/H Front Tyre	215/70 R17.5	BRIDGESTONE	6 mm
R/H Rear Tyre	215/70 R17.5 (D)	BRIDGESTONE	6/6 mm
L/H Rear Tyre	215/70 R17.5 (D)	BRIDGESTONE	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	22/12/2018	Inspection Date	27/12/2018
Survey held at	UCB ENGINEERING PTE LTD 2C, JALAN PESAWAT, JURONG, SINGAPORE 619359		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 7700Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REPLACEMENT OF PARTS	BENT		
	LHS PANEL (CONSISTENT)		13,500.00	4,000.00
	LESS 25% DISCOUNT		-	-1,000.00
			13,500.00	3,000.00
	LABOUR			
	LABOUR CHARGES FOR DISMANTLE & ASSEMBLE SIDE WINDOW GLASS.		1,200.00	900.00
	LABOUR CHARGES FOR REMOVE & REPLACE THE ABOVE DAMAGED PARTS DISMANTLE & ASSEMBLE THE PASSENGER SEAT & CHECKING ALIGNMENT.		4,200.00	2,280.00
	TO PUTTY & SPRAY PAINTING ONTO COMPLETE RHS BODY PANEL.		1,400.00	900.00
			6,800.00	4,080.00
GRAND TOTAL			20,300.00	7,080.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,650.00

Report Ref No. CC4/ASM18023075/T1ga3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice 1.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
LKKInspection (3).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
LKKAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
LKK PHOTO.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
VA7700Y - video.mp4	Evidence	Video	LKK AUTO CONSULTANTS PTE LTD (TP)	10 January 2019
VA7700Y (2).jpeg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	10 January 2019
VA7700Y (1).jpeg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	10 January 2019
TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	10 January 2019
EMAIL FROM WORKSHOP (THIRD PARTY PRIL.msg	Letters and Correspondence	Workshop	KADRI Maimun	26 December 2018
P2198100_NB_00001_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	NG Stacey	26 December 2018
P2198100_CL_TP XS \$1500.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	NG Stacey	26 December 2018