## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

 Our Ref
 305253798
 Via Fax

 Date
 241218
 Your Insured: SKR 75045

 Time of Fax:
 Date of Acc: 231218

Attn: Motor Claims Department

Aig Asia

**Dear Sirs** 

## SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH\_C \$5087

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:-

Lim Kwok Eng
Jumani Bin Masudin
Lim Tien Siong
Chiang Liat Choon
Larry Ng Nyuk Phin
Fauzy Bin Mokhtar
Tel: 6214 8316 or HP: 9635 5305
Tel: 6214 8398 or HP: 9635 8546
Tel: 6214 8314 or HP: 9296 6006
Tel: 6214 8315 or HP: 9230 2824
Tel: 6214 8319 or HP: 8125 9176

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

Fax no. 6546 8156

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

Lim Tien Stong

for Vice President Crash Repairs & Claims Recovery

# COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

**VEHICLE NO: SHC 8508P** 

MAKE

MODEL : HYUNDAI i40



IS

DATE 24/12/2018

	Туре			
Rear Bumper		<u> </u>	\$	553.00
Rear Bumper Clip 10 pcs	ļ		\$	22.00
1				
SUB TOTAL			\$	575.00
LESS 20%			\$	115.00
DISCOUNTED TOTAL			\$	460.00
Rear Bumper Advertisement Logo	!		\$	50.00
	;		\$	50.00
Labour Charge				
Panel Beating			\$	380.00
Spray Painting Charge			\$	250.00
Wiring Charge			\$	50.00
Towing Fees			\$	60.00
Remove/Refix Reverse Sensor			\$	80.00
TOTAL LABOUR			\$	820.00
ESTIMATE TOTAL			\$	1,330.00
This is an initial estimate based on a visual inspection of th	ne above vel	nicle. The final repai	ir quantı	ım will

#### SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT				
Date Of Report	24/12/2018 10:33				
Date Of Accident	23/12/2018 21:55				
Exact Location Of Accident	SPC KIOSK @ JURONG WEST AVE 1				
Country/State of Loss	SINGAPORE				
	ETAILS OF OWN VEHICLE				
Vehicle Registration Number	SHC8508P				
Insured/Policyholder					
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD				
Co Reg No	199303821R				
Email Address	FLEETSAFETY@CDGTAXI.COM.SG				
Mobile Phone No					
Alternative Phone No	OFFICE-65508768				
Vehicle Particulars					
Manufacturer	HYUNDAI				
Model	140				
Exact Purpose for which vehicle was being used at time of accident					
Are you claiming under your own insurance policy for repair to your vehicle?	NO				
If No, Please state action to be taken	THIRD PARTY				
Vehicle Category	TAXI				
Insurance Company					
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD				
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT				
Fleet Policy	YES				
Policy Number	D-18088936MFSH				
Cover Note Number					
Driver					
Name of Driver	LEE HAN SENG (LI HANCHENG)				
NRIC No	S7136168C				
Date Of Birth	20/10/1971				
Occupation	OUTDOOR				

09/07/1990 Date Of Driving Pass

28 YEARS AND 5 MONTHS **Driving Experience** 

Gender MALE

(LOCAL) +65-91786969 Mobile Number

Fax Number Contact Number

JEFFREY.LHS@GMAIL.COM **EMail Address** 

Address BLK 403 YISHUN AVENUE 6 #04-1214 760403 Postcode Was driver an employee of the Insured's Company NO If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER Vehicle Registration Number of Driver's Own Vehicle Insurance Company of Driver's Own Vehicle General Information of the Accident Type Of Accident SIDE SWIPE CLEAR Weather Conditions Road Surface DRY Other Information Was any foreign vehicle involved in this accident? NO Number of vehicles (including own vehicle) 2 involved in the accident Was any body injured in the Accident? NO Was any injured conveyed to hospital by NO ambulance? Was any other material or property damaged? YES I have been approached by unknown person(s) NO soliciting/offering accident claims assistance. Number of Passengers (Including Driver) 1 **Details of Police Action** NO Was the accident reported to the police? If Yes, Please state which Police Station Was notice of intended Prosecution given? NO If Yes, against whom? **Circumstances of Accident** PLS REFER TO ATTACHED Attachment(s) Are accident photos available for attachment? YES Was there any video captured by Car Camera? YES Remarks/ Reasons: Was there any audio recorded? NO **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number SKR7504S Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category PRIVATE CAR Name of Driver KOH GUAN SEIW S0227934G NRIC/Passport Number

Contact Number

Address Postcode

Insurance Company Name

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Nature Of Damage FRT LEFT

No. Of Passenger (Including Driver)

#### Sketch Plan Pg. 1

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LED

CO. REG. NO. 199303821R

Policyholder's Signature Date & Time: Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signati

Name:

NRIC/FIN No.:

GIARMC SketchPlanForm\_V3

43 b 6

1

ŀ

SKETCH PLAN								
CITTLE TO THE BALL BALL THE								
	<del>╎</del> ┼┼┼┼┼┼┼┼┼┼┼┼┼┼							
┡╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫╫								
╶ <del>╎╸┼╶╎╶╎╎┋┋┋┋┋┋┋┋┋┋┋┋</del> ╇	CHARDP							
	77777777777							
┝╫ <del>╒╫┋</del> ╫╫╫╫╫╫╫╫								
	1-1-1-131/21-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1							
<u>┡╃╀╀┼╫╁╬╅</u> ┢╢╃╏╸	<del></del>							
111111111111111111111111111111111111111								
1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-								
	<del></del>							
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT								
On 23/12/180215Th while I ha	d parked my							
	- #: . · · · · · · · · · · · · · · · · · ·							
	Ho I de Ma							
beh A along the driveway to	attend to the							
toilet be cause of low many vie	hider parked at							
the designifed lots. Van B	bolided on the							
the designifed lots. Vah B collided on the								
a At read morphon of my walide whole								
aght rear porpoi of my vehicle whele								
aligning his vahide to pr	mys fuel when							
	aligning his vahide to puny fired. When							
It was the I six was a did	ingue I was							
If was the driver was aligning I was								
Standing begide my vehicle	and was about to							
enter my valricle.								
DECLARATION								
I/We declare the foregoing particulars are true in every respect.	S.R. Monitor I							
CO. REG. NO. 199303821R	CSC 04/2/1							
CO. REG. NO. 1880030270	7 7 7 10							
Policyholder's Signature Driver's Signature	Reporting Centre Personnel's Signature							
Date & Time: (If driver is not the policyholder) Date & Time:	Name: NRIC/FIN No.:							

GIABRAC SteachPlanForm, Va.

Page 4 of 17